




# SOUTH WEST

## Contents

HERITAGE AT RISK	3
Reducing the risks	7
Publications and guidance	10
THE REGISTER	12
Content and assessment criteria	12
Key to the entries	15
South West heritage assets at risk	17
Bath and North East Somerset (UA) Bournemouth (UA) Bristol, City of (UA) Cornwall (UA) Devon Dorset Gloucestershire Isles of Scilly (UA) North Somerset (UA) Plymouth, City of (UA) Poole (UA) Somerset South Gloucestershire (UA) Swindon (UA) Torbay (UA) Wiltshire (UA)	9 22 24 55  19  58  72  76  77  80  81  94  96  98 200



In its fourth year, the Heritage at Risk Register now includes grade I and II\* listed buildings, listed places of worship, scheduled monuments, registered parks and gardens, registered battlefields, protected wreck sites and conservation areas known to be at risk as a result of neglect, decay or inappropriate development. This year, for the first time, we have published a list of 'priority sites': important heritage at risk sites where we will focus our resources to secure their futures.

This Register is published at a time of significant change in the heritage sector. Alongside the impacts of the global recession are the effects of the 2010 Spending Review, proposed changes to the planning system, and the continued emphasis on the Big Society. The Register reminds us that the challenge of securing sustainable futures for vulnerable heritage assets is here to stay.

Whilst we have cause for celebration this year, with I 3 grade I and II\* buildings removed from the Register, no protected wreck sites at risk, and more data on the condition of our conservation areas, we know that future success depends on adapting to rapidly changing circumstances. The I 6 new grade I and II\* listed buildings added to our 2011 Register remind us that for every building secured, another awaits an urgent solution.

As the South West economy makes tentative steps toward recovery, we continue to encourage developers to invest in vulnerable historic buildings. High profile buildings at risk such as Tone Mills near Taunton, Somerset remain mothballed, and will be a priority for us in the coming year. Many public sector funding sources have been cut or reduced; smaller awards, particularly our own, must be carefully targeted and invested strategically. Heritage assets with little or no ability to generate revenue funding depend on such public subsidy, and have been a priority for our limited grants this year.

What will change in the planning system mean for heritage at risk? The shift to community-led plan-making could benefit the way that local heritage assets are understood, used and cared for. We could learn lessons from places like Chudleigh, Devon, whose community masterplanning exercise might help address the issues which have placed its conservation area at risk. Communities, trusts and voluntary organisations play crucial roles in saving historic buildings. With the reduction in public resources taking effect, their roles may become even more crucial. Trusts like the Cullompton Walronds Preservation Trust in Devon, the community of Maker-with-Rame in Cornwall and the church council of St Peter and St Paul, Wincanton, Somerset are all engaged in major repair schemes to secure local heritage assets at risk. And our research with the UK Association of Preservation Trusts on the work of the region's building preservation trusts will inform joint working on heritage at risk in the future.

In the midst of so much change, the value of expert advice cannot be underestimated. It helps establish appropriate courses of action, accurate costings and sensitive repair techniques; it provides reassurance to communities and funders tackling major heritage at risk projects. This was the case at Birnbeck Pier; North Somerset, where English Heritage technical advice was instrumental in informing a phased repair programme for this long-term building at risk.

The value of the Heritage at Risk Register is clear at this time: it provides a fixed point of reference, sets out the priorities for action, and reminds us that securing a sustainable future for historic assets is often a long process which can and must weather economic and political change.

Andrew Vines, Planning Director SOUTH WEST

#### **BUILDINGS AT RISK**

- Nationally, 3.0% of grade I and II\* listed buildings are at risk. In the South West this falls to 2.1%, representing 154 sites.
- 13 sites have been removed from the 2010 Register, but 16 have been added.
- 58% of entries (106 buildings) on the baseline 1999 Register for the South West have been removed as their futures have been secured, compared to the national figure of 53% (757 buildings).
- Nationally, £5.2m was offered to 71 sites on the Register during 2010/11. In the South West we awarded grants totalling £509k to 4 sites.
- 21 listed places of worship are included on our Register this year. We estimate the cost of repairing these buildings is £2.9m.

#### SCHEDULED MONUMENTS

- 16.9% (3,339) of England's 19,748 scheduled monuments are at risk, compared to 20.3% (1,419 sites) in the South West.
- In the South West, 84 sites have been removed from the 2010 Register, but 93 sites have been added.
- 8.5% of entries (121 sites) on the baseline 2009 Register for the South West have been removed due to positive reasons, compared to the national figure of 11.9% (399 sites).
- Arable ploughing and unrestricted plant, scrub or tree growth account for nearly two thirds of sites at risk nationally. The proportion is similar in the South West.
- Nationally, 82% of scheduled monuments at risk are in private ownership, this falls to 75% in the South West.
- Of the £357k offered by English Heritage to owners of scheduled monuments at risk in 2010/11, £71k was to 27 sites in the South West.

#### **REGISTERED PARKS AND GARDENS**

- 103 of England's 1,610 registered parks and gardens are at risk, an increase from 6.2% (99) in 2010 to 6.4% this year. In the South West, 18 of our 293 sites are at risk (6.1%).
- Nationally, 6 sites have been added and 2 removed from the 2010 Register. In the South West, 2 sites have been added.

#### **REGISTERED BATTLEFIELDS**

• Of the 43 registered battlefields in England, 6 are at risk, 2 less than the 2008 baseline. None of the 8 registered battlefields in the South West are at risk.

#### PROTECTED WRECK SITES

• Of the 46 protected wreck sites off England's coast, 7 are at risk, 3 less that the 2008 baseline. None of the 23 protected wreck sites off the coast of the South West are at risk.

#### **CONSERVATION AREAS**

- 288 local planning authorities (86%) have taken part in the national survey of conservation areas, of which 35 are in the South West. This is 90% of our local planning authorities.
- We now have information on the condition of 7,841 of England's 9,600 designated conservation areas and 516 (6.6%) are at risk.
- Of the 1,089 conservation areas surveyed in the South West, 88 (8.1%) are at risk.



LITERARY AND SCIENTIFIC INSTITUTE, BRIDPORT, WEST DORSET Making progress: The Bridport Area Development Trust will develop a project to repair the Literary and Scientific Institute and to find a new use consistent with its original purpose.

© Bridport LSI copyright Crystal Johnson

#### IN THE SOUTH WEST:









## INDUSTRIAL HERITAGE

Britain was the world's first industrial nation and has a wealth of industrial heritage but many industrial sites have been lost or are at risk due to functional redundancy. Our survey has shown that the percentage of listed industrial buildings at risk is three times greater than the national average for listed buildings at risk.

The conservation of industrial sites can pose considerable challenges. However, industrial sites often have great potential for re-use. Our research shows that the best way of saving industrial buildings is, where possible, to find an adaptive new use. We know this isn't easy, and is not always possible, but we hope those who own or are thinking of developing an industrial building will find our new web pages an invaluable source of information.

Voluntary groups and owners have saved a number of key industrial sites, often sites which contain working machinery. However, research has shown that many of these groups need support to encourage more and younger members to achieve the rescue of the site.

Building preservation trusts can provide the answer for industrial buildings where there is no apparent commercial solution by repairing the site and then selling it, or retaining and letting the space.

#### What we know

- 4% of listed buildings and scheduled monuments are industrial
- Nationally there are proportionally more grade II\* industrial listed buildings than grade II (4.6% compared to 4.4%)
- 10.6% of industrial grade I and II\* listed buildings are at risk, making industrial buildings over three times more likely to be at risk than the national average for grade I and II\* listed buildings
- The average estimated conservation deficit (cost of repair in excess of the end value) of industrial buildings at risk is twice that of non-industrial buildings at risk
- About 10% of industrial buildings at risk are economic to repair, compared to 13% of non-industrial buildings at risk
- Approximately 40% of industrial buildings at risk are capable of beneficial use, compared to 44% of non-industrial buildings at risk
- 10.9% of industrial scheduled monument are at risk, making industrial scheduled monuments less likely to be at risk than the national average for scheduled monuments
- 3% of conservation areas were designated because of their industrial significance
- Industrial conservation areas in the North West and West Midlands are over twice are likely to be at risk than the national average
- In the last 10 years, English Heritage has offered grants totalling  $\pounds 25m$  to industrial sites



#### ROBINSON'S SHAFT, SOUTH CROFTY, CORNWALL

Robinson's Shaft complex is an early C20 development at the last working tin mine in Europe. The complex has suffered from redundancy, neglect and vandalism, but with significant public funding, it will be the centrepiece of a regeneration project to provide work, employment and greenspace for former mining communities

#### What are we doing?

- Providing new guidance for owners on maintaining vacant historic buildings.
- Publishing a developers' portal on the English Heritage website where advice for all types of heritage asset including industrial sites can be found.
- Funding a new Industrial Heritage Support Officer, who will build capacity for industrial museums.
- Publishing an industrial themed issue of Conservation Bulletin in October 2011.
- Supporting a new Architectural Heritage Fund grant scheme which aims to encourage local groups to take on industrial buildings.
- Publishing an updated Stopping the Rot: a guide to enforcement action to save historic buildings.
- Using the National Heritage Protection Programme (2011-2015) to shape an industrial designation programme.


If you are a developer, member of a building preservation trust, work in a local authority, own a visitor attraction or have an interest in England's industrial heritage, visit our website for more information:

www.english-heritage.org.uk/industrial-heritage-at-risk

#### **PRIORITY SITES**

- Academy Theatre and Great Western Hotel (Palace Theatre), Union Street, Stonehouse, Plymouth
- Birnbeck Pier, Weston-Super-Mare, North Somerset
- Carriage Works, 104 Stokes Croft, Bristol
- Cloth finishing works at Tone Mills, north range, Langford Budville, Somerset
- Former Saxon church to west of Priory House, Leonard Stanley, Stroud, Gloucestershire
- Grenville Battery 550yds (500m) SSW of Maker Farm, Maker-with-Rame, Cornwall
- Guns Mill Barn, Littledean, Gloucestershire
- Medieval moated site and Romano-British settlement at White Walls Wood, Easton Grey, Wiltshire
- The Mechanics Institute, Emlyn Square, Swindon
- Torbay Cinema, Torbay Road, Paignton, Torbay

CONTACT: Kara Fitzhugh, Business Manager, English Heritage South West, 29/30 Queen Square, Bristol, BS1 4ND. Fax: 0117 975 0706 Telephone: 0117 975 0700 Email: kara.fitzhugh@english-heritage.org.uk



For more information on Heritage at Risk visit **www.english-heritage.org.uk/risk** 

If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1 181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk



When you have finished with this report please recycle it

75% recycled This report is printed on 75% recycled paper

#### COVER IMAGE: Carriage Works, Bristol

Carriage Works, Bristol, Building at Risk and Priority Site

## Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our national plan for the protection of England's historic environment (National Heritage Protection Plan 2011-2015). This will be challenging given the number of assets now on the Register and the different kinds of risk they face. Each asset type and individual case will require its own approach and solution.

There are, however, some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential if they are not to become at risk, and to prevent those that are already at risk from decaying further and thereby escalating the cost of their repair and consolidation. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found. English Heritage has published guidance for owners on options for maintaining vacant buildings (*Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing*).

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website **www.helm.org.uk**.

## LISTED BUILDINGS Buildings at risk

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities, owners and developers. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk. In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some local authorities have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair. For this reason, English Heritage has published revised guidance (Stopping the Rot) for local planning authorities on taking action to save historic buildings.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs grant schemes to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works Notices and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, the Georgian Group, The Victorian Society and the Twentieth Century Society.

#### Places of worship at risk

Regular maintenance helps to keep buildings and places of worship in good condition but those that are in poor or very bad condition need help to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing that congregations can do as it stops small problems in the building fabric developing into unnecessary crises. English Heritage supports the Society for the Protection of Ancient Buildings's Faith in Maintenance scheme, giving volunteers practical local training and on-going support. It also encourages the establishment of gutter-clearance projects, enabling congregations to get good quality work done at reasonable prices by reputable contractors.

Where major structural repairs are required, the Repair Grants for Places of Worship scheme helps under resourced buildings in urgent need. The Listed Places of Worship scheme is another source of funding for repairs and maintenance that is available more widely, while local and national charities can offer small grants.

Many congregations wish to adapt and change their places of worship to encourage wider community use alongside worship and faith-focussed events. English Heritage supports the efforts of congregations to keep their places of worship in use wherever possible and welcomes proposals for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character.

English Heritage is aware of the need for practical, hands-on help to be given to individual congregations and is working with partner organisations to enable this. Support Officers are employed by local denominational groups but part-funded by English Heritage. They give advice and encouragement to congregations so that they can achieve repair projects, develop necessary new facilities or re-engage with the wider community, depending on local circumstances and needs.

### SCHEDULED MONUMENTS

The continuing success in reducing the number of monuments at risk, even in difficult economic times, demonstrates the value of the dialogue that the initiative has fostered between English Heritage, owners, managers and other partners. More and more owners and managers of scheduled monuments are addressing their long-term care on a regular basis. Over half of all scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship agri-environment scheme, administered on behalf of Defra. Work in the coming years with Defra and Natural England will concentrate upon ensuring that the right options are being used in the correct way, maximising the conservation benefits whilst at the same time delivering value for money. We will also work closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Progress is also reliant upon better understanding. As a result, as part of the National Heritage Protection Plan – which sets out English Heritage's commitment to safeguarding heritage up to 2015 – the Conservation of Scheduled Monuments in Cultivation project will be rolled out nationally from 2011 onwards. The project, already successfully trialled amongst farmers in the East Midlands, will address what is still the biggest threat by far to monuments – their gradual degradation and loss through arable cultivation. Some causes of risk are neither so obvious nor dramatic in their effects however. Heritage at risk shows that unmanaged tree, scrub and bracken growth is the most widespread cause of long term damage to both urban and rural monuments, even if the effects are not as visible or immediately destructive as other processes. Further work will therefore be needed to better understand how these effects can be minimised.

In all cases, however – whether for rural or urban monuments – close co-operation with owners and land managers is still key to making further progress in ever more challenging circumstances.

### REGISTERED PARKS AND GARDENS

Inclusion on the *Register of Historic Parks and Gardens* of Special Historic Interest brings no additional statutory controls, but there is a presumption in favour of the conservation of all designated assets in the planning system. The Government's Planning Policy Statement 5 *Planning for the Historic Environment* (PPS 5) and its supporting Practice Guide helps planning authorities to assess and mitigate the impact of development on our irreplaceable heritage of designed landscapes.

English Heritage can engage only with the proposals for change to the highest graded designed landscapes and where the impact on historic significance is greatest. Our landscape architects can help tailor plans and funding packages for individual landscape features as well as strategies for the whole site. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

English Heritage encourages the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We are keen for bursars and estate teams to use management plans to help conserve important but fragile landscapes in the care of schools, hospitals, hotels and other institutional owners.

### REGISTERED BATTLEFIELDS

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in Planning Policy Statement 5.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

#### PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@english-heritage.org.uk) and from www.helm.org.uk

### CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners. Looking after them is a responsibility shared by those of us who own homes and businesses in them and those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The conservation area survey provides us with an understanding of what is particularly affecting the character and appearance of our conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas are critical in managing change in these areas. This is difficult at a time when local authorities across the country are reducing the number of staff managing changes in conservation areas. There are, of course, opportunities for members of the local community to engage, either individually or through groups such as civic societies or conservation area advisory committees which are proven to help achieve positive action.

Armed with the information provided by the surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk. We will also want to target those with the greatest potential to improve the quality of life and economic prospects of people in the villages, towns and cities of which they are such crucially important components.

## Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) - a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2011 – national report and summaries for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Heritage at Risk Register 2011 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Saving Historic Buildings Through Enforcement Action (2011)

The Monuments at Risk initiative 2003–08 (2010)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

## HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit **www.english-heritage.org.uk/risk** where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website **www.english-heritage.org.uk/heritageprotection**. Details of all nationally designated historic places in England are now available in one place on the National Heritage List for England online database: **http://list.english-heritage.org.uk** 

#### CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous helpful guidance documents now available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010).

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181 Fax: 01793 414926 Email: customers@english-heritage.org.uk

## THE REGISTER Content and criteria

### DESIGNATION

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some 1,610 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

## LISTED BUILDINGS Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II\* and II. Grade I and II\* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II. Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

### Criteria for inclusion on this Register

Buildings (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II\*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the Register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The Register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the Register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied or in use.

#### Listed places of worship

Places of worship are the largest single group of non-domestic historic buildings still in use primarily for the purpose for which they were built. Their complex development over centuries is a testament to the changes in social, political and liturgical attitudes over time. This reflects the developing mission of congregations and means that they protect a wide range of fittings and furnishings of national and international, importance. Their architectural, archaeological, aesthetic and historic significance is outstanding but so too is their value as the record of the endeavours and experiences of individuals and communities.

To date English Heritage has assessed only a small proportion of the 14,500 listed places of worship so the number identified so far as 'at risk' and included on this year's Register is small. In the coming years an increasing number of places of worship will be assessed to identify those that are at risk. Future registers will provide stronger evidence and build up our understanding of the challenges.

#### Criteria for inclusion on this Register

Places of worship considered for inclusion on this Register must be listed grade I, II\* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register. Places of worship previously included on the Register may be in any condition category.

Once on the Register, all places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

#### Priority for action

Once a building is identified as at risk or vulnerable and included on the Register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

#### SCHEDULED MONUMENTS Definition

Scheduled monuments include archaeological sites and landscapes, and 19,731 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

### Criteria for inclusion on this Register

Scheduled monuments included on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

## REGISTERED PARKS AND GARDENS Definition

There are 1,610 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest*. These registered landscapes are graded I, II\* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II\* and the Garden History Society on sites of all grades.

### Criteria for inclusion on this Register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the Register once plans are put in place to address issues and positive progress is being made.

## REGISTERED BATTLEFIELDS Definition

English Heritage's Register of Historic Battlefields has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields is sensitive and appropriate.

#### Criteria for inclusion on this Register

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

## PROTECTED WRECK SITES Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

### Criteria for inclusion on this Register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

### CONSERVATION AREAS Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,300 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

#### Criteria for inclusion on this Register

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with more limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

## Key to the entries

## This register includes the following heritage assets at risk:

- grade I and II\* listed buildings and structural scheduled monuments
- grade I, II\* and II listed places of worship
- scheduled monuments
- registered parks and gardens
- registered battlefields (where applicable)
- protected wreck sites (where applicable)
- conservation areas

#### ORDER

Entries are grouped and ordered alphabetically first by County or Unitary Authority, and then by Local Planning Authority (Unitary Authority/National Park/District or Borough).

Asset types are grouped within the relevant planning authority in the following order:

- listed buildings and structural scheduled monuments
- places of worship
- scheduled monuments
- registered parks and gardens
- conservation areas

Within each asset type, sites are ordered alphabetically by parish, locality, street/site name.

### DESIGNATION

The principal designation is noted for each entry, and includes:

- Listed Building (LB) grade I, II\* or II
- Listed Place of Worship grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II\* or II
- Registered Battlefield
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The National Heritage List for England reference number is noted for scheduled monuments.

## CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

#### OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

### VULNERABILITY

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub / tree growth
- visitor erosion.

For registered parks and gardens, registered battlefields, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

## PRIORITY

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- **E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

If the priority category has changed since the 2010 Register, the previous category is given in brackets.

## TREND

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

### OWNERSHIP

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

## CONTACT

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA' on the Register).

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

#### ABBREVIATIONS

CA	Conservation Area
EH	English Heritage
HLF	Heritage Lottery Fund
LA/LPA	Local Planning Authority
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site

## South West heritage assets at risk

	Buildings at risk	Places of worship at risk	Scheduled monuments at risk	Registered parks and gardens at risk	Registered battlefields at risk	Protected wreck sites at risk	Conservation areas at risk
BATH AND NORTH EAS	T SOMERSET	(UA)					
Bath and North East Somerset (UA)	5	2	8	0	0	0	9
BOURNEMOUTH (UA)							
Bournemouth (UA)	0	0		0	0	0	0
BRISTOL, CITY OF (UA)							
Bristol, City of (UA)	11	0	3	0	0	0	1
Bristol, City of (UA) / Bath and North East Somerset (UA)*	0	0	0	1	0	0	0
CORNWALL (UA)							
Cornwall (UA)	26	5	206		0	0	
DEVON							
Dartmoor (NP)		0	253	0	0	0	1
East Devon	3	0	60	0	0	0	0
Exeter	0	0		0	0	0	3
Exmoor (NP)	0	0	13	0	0	0	0
Mid Devon			17	0	0	0	6
North Devon	2	2	4	0	0	0	1
South Hams	7	0	36	0	0	0	0
Teignbridge	1	1	8	3	0	0	3
Torridge	2	0	41	0	0	0	2
West Devon	4	I	10	0	0	0	6
DORSET							
Christchurch	0	0	2	0	0	0	0
East Dorset	3	0	42		0	0	0
North Dorset	3		45	0	0	0	3
Purbeck		0	69	0	0	0	6
West Dorset	9		112		0	0	23
Weymouth and Portland GLOUCESTERSHIRE	4	0	2	0	0	0	
		0		0		0	
Cheltenham Cotswold	0	0	0	0	0	0	0
Forest of Dean	6	2	39	0	0	0	0
Gloucester	6	0	0	0	0	0	0
Stroud	5	0	8	0	0	0	0
Tewkesbury	6	0	12	0	0	0	0
ISLES OF SCILLY (UA)	0	0	12	0	0	0	0
Isles of Scilly (UA)		0	29	0	0	0	0
NORTH SOMERSET (UA)			27		0		
North Somerset (UA)	4	0	0	0	0	0	5
PLYMOUTH, CITY OF (U							
Plymouth, City of (UA)	10	0	12	0	0	0	

POOLE (UA)							
	0	0	1	0	0	0	
Poole (UA)	0	0		0	0	0	5
SOMERSET							
Exmoor (NP)	0	0	15	0	0	0	0
Mendip	3	0	25	L	0	0	0
Sedgemoor	2	0	9	L	0	0	0
South Somerset	9	L	8	3	0	0	4
Taunton Deane	5	0	6	0	0	0	0
West Somerset		0	7	1	0	0	0
SOUTH GLOUCESTERSH	HIRE (UA)						
South Gloucestershire							
(UA)	6	1	5	1	0	0	2
SWINDON (UA)							
Swindon (UA)	2	I	15	0	0	0	0
TORBAY (UA)							
Torbay (UA)	3	0	4	2	0	0	3
WILTSHIRE (UA)							
Wiltshire (UA)	17	0	247	I	0	0	1
Wiltshire (UA) /							
New Forest (ŃP)*	0	0	I	0	0	0	0
TOTAL	174	21	1398	18	0	0	88

\*Sites that cross LPA boundaries boundaries

HERITAGE AT RISK 2011 / SOUT	h west / <b>ba</b>	TH AND NORTH EAST SOMERSET (UA)	
BATH AND NORTH E	AST SOM	1ERSET (UA)	
-	SITE NAME:	King Edwards School, Broad Street, Bath	School, 1752. A scheme for use as a hotel was submitted but withdrawn in 2006. Works to repair the roof have been successfully completed. The threat of decay has therefore diminished but the building remains vacant.
	DESIGNATION:	Listed Building Grade II*, CA, WHS	Permission granted 2010 for hotel use.
	CONDITION:	Fair	
TITLE THE TAXABLE AND	OCCUPANCY:	Vacant	
	PRIORITY:	E (E)	
the state	OWNER TYPE:	Company	Contact: Isla Macneal 0117 975 0742
	SITE NAME:	Cleveland Baths, Hampton Row, Bath	Dating from 1815, Cleveland Baths are believed to be the oldest surviving public outdoor swimming pools in England. A diminutive Georgian crescent houses the changing rooms and Caretakers Cottage.
	DESIGNATION:	Listed Building Grade II*, CA, WHS	The Cleveland Pool Trust has recently completed a
	CONDITION:	Very bad	business plan, condition survey and scheme design
	OCCUPANCY:	Vacant	with English Heritage grant aid.
	PRIORITY:	D (C)	
	OWNER TYPE:	Local authority	Contact: Sarah Ball 0117 975 0666
ASA	SITE NAME:	Victoria Bridge, Victoria Bridge Road, Bath	Suspension bridge by Dredge c1836. Bridge deemed to be dangerous and currently closed for public use. Council has undertaken survey which identifies need for extensive magin
	DESIGNATION:	Listed Building Grade II*, CA, WHS	for extensive repair.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Local authority	Contact: Isla Macneal 0117 975 0742
	SITE NAME:	Hinton Priory, Hinton Charterhouse Listed Building Grade I, SM	Early C13 Carthusian monastery, chapter house and refectory still standing. Later stables, coachhouse and garden buildings incorporate earlier material and follow original complex layout of cloister and cells. All structures
	CONDITION:	Poor	in use except chapterhouse. Some parts in need of condition assessment.
	OCCUPANCY:		
	PRIORITY:	C (C)	
The second second	OWNER TYPE:		Contact:Veryan Heal 0117 975 0717
	SITE NAME:	St Thomas a Beckett Church, Pensford, Publow	Parish church. Late C14 tower. The remainder of the church was rebuilt 1869. The tower and nave of this church are in separate ownership. The tower is owned by the Churches Conservation Trust which repairs and
A THE C	DESIGNATION:	Listed Building Grade II*, CA	by the Churches Conservation Trust which repairs and opens the tower to the public. Planning permission and
	CONDITION:	Fair	listed building consent were granted for conversion to
	OCCUPANCY:	N/A	a single family dwelling in October 2008 and some work has been carried out on site.
	PRIORITY:	F (F)	has been carried out off site.
	OWNER TYPE:	Private	Contact: Isla Macneal 0117 975 0742
	SITE NAME:	Church of St Andrew, Aller	Very significant small church. Saxon origins with C12 / C13, C15 and major restoration 1861-1862 by H John Norton. The church has recently undertaken patch repair to the nave roof which is suffering from nail sickness and this will need proper repair in the near future. The church
A THE REPORT OF A DESCRIPTION	DESIGNATION:	Listed Place of Worship Grade II*	was visited in 1997 and again in 2010 to assess the issue
	CONDITION:	Poor	of cracking through tower parapet stonework and to the staircase turret. This will need repair.
An	PRIORITY:	B (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Nicola Lauder 0117 975 0674

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

ATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2011 / SOUTH WEST / BATH AND NORTH EAST SOMERSET (UA)

	SITE NAME: Holy Trinity, Main Road, Cleeve	have iron fe columns.Th vertical spli strapped to	ch by Maners of Bath. Large belfry openings errumenta bars running through central stone ne rusting of these bars has caused large ts in the columns which have had to be o stop pieces of stone falling. A Repair Grant
RALL A	DESIGNATION: Listed Place of Worship Grade II*	for Places of	of Worship has been offered for repairs.
RAMA AND	condition: Very bad		
1	priority: B (New entry)		
	OWNER TYPE: Religious organisation	Contact: N	icola Lauder 0117 975 0674
SITE NAME:	Wansdyke: section 1230yds (1120m) eastwar	rds from Burnt H	louse Inn
DESIGNATION:	Scheduled Monument (No. 1007003)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Gardening	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Camerton Romano-British town and associa	ted Prehistoric a	nd early medieval monuments, Camerton
DESIGNATION:	Scheduled Monument (No. 1013881)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Roman road 720yds (660m) long, north of A	bbey Farm, Hinto	on Charterhouse
DESIGNATION:	Scheduled Monument (No. 1005421)	CONDITION:	Extensive significant problems
		contamorta	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	Stantonbury camp and adjacent sections of V	•	,
designation:	Scheduled Monument (No. 1002487)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Lansdown Roman camp, North Stoke		
DESIGNATION:	Scheduled Monument (No. 1005422)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Little Down camp, North Stoke		
DESIGNATION:	Scheduled Monument (No. 1004677)	CONDITION:	Extensive significant problems
	``````````````````````````````````````		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Wansdyke: south east of Newbarn Farm, No	orton Malreward	
DESIGNATION:	Scheduled Monument (No. 1003066)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VUI NFRABII ITY	Arable clipping	TREND	Declining
PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable clipping Private	TREND: CONTACT:	Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Concentration

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

#### HERITAGE AT RISK 2011 / SOUTH WEST / BATH AND NORTH EAST SOMERSET (UA)

SITE NAME:	Roman villa at Upper Hayes, We	ellow		
DESIGNATION:	Scheduled Monument (No. 1007	7002) condition	/	,
			but with minor	localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTAC	T: Business Manag	er 0117 975 0700
SITE NAME:	Batheaston			
DESIGNATION:	Conservation Area	CONDITIO		
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	lan Lund (LPA) 01225 477 687	NEW ENT	rry?: No	
SITE NAME:	Chew Magna			
DESIGNATION:	Conservation Area	CONDITIO	on: Poor	
VULNERABILITY:	High	TREND:	No significant c	hange
CONTACT:	lan Lund (LPA) 01225 477 687	NEW ENT		
SITE NAME:	Corston			
DESIGNATION:	Conservation Area	CONDITIO	on: Fair	
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	lan Lund (LPA) 01225 477 687	NEW ENT		
SITE NAME:	Keynsham High Street, Keynsha	m		
DESIGNATION:	Conservation Area	CONDITIO	on: Very bad	
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	lan Lund (LPA) 01225 477 687	NEW ENT		
SITE NAME:	Midsomer Norton and Welton			
DESIGNATION:	Conservation Area	CONDITIO	on: Poor	
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	lan Lund (LPA) 01225 477 687	NEW ENT	rry?: No	
SITE NAME:	Paulton (including Paulton Basin	)		
		,	D	
DESIGNATION:	Conservation Area	CONDITIO		
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	lan Lund (LPA) 01225 477 687	NEW ENT	rry?: No	
SITE NAME:	Radstock (including Braysdown	and Clandown)		
DESIGNATION:	Conservation Area	CONDITIO	on: Very bad	
VULNERABILITY:	High	TREND:	Deteriorating	
CONTACT:	lan Lund (LPA) 01225 477 687	NEW ENT		
site name:	South Stoke			
DESIGNATION:	Conservation Area	CONDITIO	on: Poor	
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	lan Lund (LPA) 01225 477 687	NEW ENT	NI	
SITE NAME:	Wellow			
	Conservation Area		on: <b>Poor</b>	
DESIGNATION:	Medium			
VULNERABILITY:		TREND:	Deteriorating	
CONTACT:	lan Lund (LPA) 01225 477 687	NEW ENT	rry?: No	
PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution	<ul> <li>D Slow decay; solution agreed but not yet implemented.</li> <li>E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no</li> </ul>	Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not	NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.	ABBREVIATIONS C.A. Conservation Area LB/LBs Listed Building/s LPA Local Planning Authority NP National Park RPG Registered Park and Gard SM/SM Cabed Monumout 6

B immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

with new use agreed but not yet implemented.

 NP
 National Park

 RPG
 Registered Park and Garden

 SM/SMs
 Scheduled Monument/s

 UA
 Unitary Authority

 WHS
 World Heritage Site

BOURNEMOUTH (U	A)			
SITE NAME:	Two round	d barrows 300yds (270m) north west	of Double D	ykes, Hengistbury Head, Bournemouth
DESIGNATION:	Scheduled Monument (No. 1002397)		CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tre	e growth	TREND:	Declining
DWNER TYPE:	Local Auth	ority	CONTACT:	Business Manager 0117 975 0700
BRISTOL, CITY OF (U	JA)		Di	
	SITE NAME:	Lower Lodge to Ashton Court, Ashton Road, Bristol	Picturesque Gothic style entrance lodge built 1805 by Henry Wood. Limestone ashlar, two storeys wit wrought iron gates. Vacant with hole in main roof and signs of structural distress in ashlar. Doors and	
	DESIGNATION:	Listed Building Grade II*, CA, RPG II	windows bl	locked on ground floor but upper storey
- Aller Syns	CONDITION:	Very bad	open to we	eather.
	OCCUPANCY:	Vacant		
	PRIORITY:	A (A)		
	OWNER TYPE:	Local authority	Contact: Jus	stin Ayton 0117 975 0687
	SITE NAME:	Mortimer House, Clifton Down Road, Bristol	in hospital there has b	nid C18 palladian suburban villa, until recently use, now vacant. Roofs are deteriorating and een significant water ingress. Discussions wit
	DESIGNATION:	Listed Building Grade II*, CA	new owner	rs have commenced.
Marker The Table	CONDITION:	Poor		
	OCCUPANCY:	Vacant		
	PRIORITY:	C (C)		
	OWNER TYPE:	Private	Contact: Jus	stin Ayton 0117 975 0687
	site name:	Swing Bridge over North Entrance Lock, Cumberland Basin, Bristol	supporting 1873. It has	on bridge c1844 by IK Brunel with tubular members. Moved to current location in been redundant and decaying on dock
	DESIGNATION:	Listed Building Grade II*, CA	Discussions	ruction of Plimpsoll Bridge in C20. s ongoing for repair and reuse of bridge
I Withow I	CONDITION:	Very bad	as part of c	cycling network.
Alle Alle alle	OCCUPANCY:	N/A		
	PRIORITY:	D (New entry)		
	OWNER TYPE:	Local authority	Contact: Jus	stin Ayton 0117 975 0687
信義	SITE NAME:	Church of St Michael and attached railings, St Michaels Hill, Bristol	the mid CI by classical The church	puilt in 1775-77 in a Gothick style, but retaini 5 tower; the interior is divided in three aisle colonnades and has some late C19 fittings. 1 has been vacant for over six years. A schem roposed for new denominational church use
	DESIGNATION:	Listed Building Grade II*, CA		ations are ongoing.
	CONDITION:	Poor		
	OCCUPANCY:	Vacant		
	PRIORITY:	B (B)		
	OWNER TYPE:	Religious organisation	Contact: Jus	stin Ayton 0117 975 0687
ALL TRADAD	SITE NAME:	Carriage Works, 104 Stokes Croft, Bristol	recognised site includir	orks, 1862. A notable building in a manner as particular to the city. Large and complex ig 4 Ashley Road (grade II) also in very bad
111	DESIGNATION:	Listed Building Grade II*, CA	and other p	Discussions with the Local Planning Authority parties about the future of the building
	CONDITION:	Very bad	are ongoing	
	OCCUPANCY:	Vacant		
	PRIORITY:	A (A)		
		Private		stin Ayton 0117 975 0687

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Concentration
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

	SITE NAME:	The Trinity Centre, Holy Trinity Church, Trinity Road, Bristol	church c18 1980s, floor	29. Since church w has been inserted	vival Commissioners as made redundant in d across the large former
	DESIGNATION:	Listed Building Grade II* Poor	for use as a	arts venue. EH grar	nity Arts Ltd lease building nt aided condition survey sle is corroding. EH grant
		Occupied	offered in 2	2011 for repair of s	south aisle roof and
ATT.	PRIORITY:	D (New entry)		udy for whole buil	-
	OWNER TYPE:	Local authority	Contact: Sa	rah Ball 0117 975	0666
THUR	SITE NAME:	Clifton Observatory, Clifton, Bristol	camera obs up to obsci	scura early C19. Int ura and down to a	obscura. Built C18, terior winding stair leads tunnel leading to Ghyston's
	DESIGNATION:	Listed Building Grade II*, CA	negotiation	s, a scheme of repa	Gorge. Following extensive air and conversion is advance
	CONDITION:	Fair	and consen	it has been given to	o restore the observatory
		Part occupied		onjunction with res	laurant use.
	PRIORITY: OWNER TYPE:	F (F) Private	Contact: lui	stin Ayton 0117 97	75 0687
	OWNER I TPE:	TTVALE	Contact. Jus		5 0007
	SITE NAME:	Stair turret (Holy Cross) Inns Court Vicarage, Inns Court Green, Knowle, Bristol	middle of a	housing estate.Th It a long term use	C20 building. Situated in le roof has recently been is still being sought for
		Listed Building Grade II* Fair		, ,	
	CONDITION: OCCUPANCY:				
	PRIORITY:	D (D)			
	OWNER TYPE:	Religious organisation	Contact: Jus	stin Ayton 0117 97	75 0687
	SITE NAME:	28 Portland Square, St Paul, Bristol	complete C ashlar, brick	Georgian square, c l stacks, slate mansa	uses located in a largely 789-1820. Limestone ard roofs, double-depth plan.
	DESIGNATION:	Listed Building Grade I, CA			eys with attic and basement. ers with broken windows and
	CONDITION:	Poor	leaking roo	f. Consent for conv	version to mixed use granted
	OCCUPANCY:		recently cha		ted and ownership has
	PRIORITY:	C (C) Company	Contact: lus	stin Ayton 0117 97	75 0687
	of the state of th	company	Contactifu		
	SITE NAME:	31 and 32 Portland Square, St Paul, Bristol	Terraced houses, 1789-1820. Emergency repairs carried out with English Heritage grant aid. Wind and weathertight, but masonry continues to decay. There h		
	DESIGNATION:	Listed Building Grade I, CA	been a partial collapse of the facade. Consent has b given for repair and residential conversion but has r		l conversion but has been
	CONDITION:	Very bad		plemented.	
	OCCUPANCY:				
	PRIORITY:	D (D) Private	Contactulu	stin Ayton 0117 97	75 0487
	OWNER TYPE:	TTVate	Contact. Jus		5 0007
	SITE NAME:	Timber Lodge, Blaise Castle Estate, Henbury Road, Henbury	Early C19 cottage ornée, finely detailed and of une design. Repairs were grant-aided by English Heritag the building has subsequently been vandalised. Roo		led by English Heritage but been vandalised. Roof now
A PORT	DESIGNATION	Listed Building Grade II*, CA, RPG II*	explored b	y Bristol City Cour	Options for use are being ncil.
	CONDITION:	Poor		. ,	
	OCCUPANCY: PRIORITY:	Vacant C (C)			
(The Later	OWNER TYPE:	Local authority	Contact: Jus	stin Ayton 0117 97	75 0687
SITE NAME:	Anti-aircr	aft gun site, Purdown, Bristol			
DESIGNATION:	Scheduled	Monument (No. 1004531)	CONDITION:	Generally unsati	sfactory
				with major local	,
PRINCIPAL VULNERABILITY:		tion — in need of management	TREND:	Declining	
OWNER TYPE:	Private		CONTACT:	Business Manage	er 0117 975 0700
PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	but not ye	y; solution agreed <b>F</b> Repair scheme in progra and (where applicable) end use or user identific bair or in fair to good	lf the	E: priority category hanged since the 2010	ABBREVIATIONS C.A. Conservation Area LB/LBs Listed Building/s LPA Local Planning Authority NB Distional Park

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets. 
 ABBREVIATIONS

 CA
 Conservation Area

 LB/LBs
 Listed Building's

 LPA
 Local Planning Authority

 NP
 National Park

 RPG
 Registered Park and Garden

 SM/SMs
 Scheduled Monument's

 UA
 Unitary Authority

 WHS
 World Heritage Site

SITE NAME:	Civil War earthworks on Brandon Hill, Bristol		
DESIGNATION:	Scheduled Monument (No. 1006989)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Heavy Anti-aircraft battery 520m east of Holes M	1outh, Bristol	
DESIGNATION:	Scheduled Monument (No. 1021291)	CONDITION:	Generally unsatisfactory
DESIGNATION:			Ocherally unsatisfactory
DESIGNATION:	```'		with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	, , ,
DESIGNATION:			, , ,

#### BRISTOL, CITY OF (UA) / BATH AND NORTH EAST SOMERSET (UA)

|--|

SITE NAME:	Brislington House, Bristol
DESIGNATION:	Registered Park and Garden Grade II*, also CA, 5 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	

#### One of the first and most influential asylum landscapes in Britain. Now subdivided between a sixth form college, private residential development in the former asylum building, commercial sports facilities, industrial units and a management training centre. Nevertheless, some components of the designed landscape survive. Currently its designation is being re-evaluated by English Heritage. Part of the park is in Bath and North East Somerset Unitary Authority. Contact: Kim Auston 0117 975 0696

#### BRISTOL, CITY OF (UA)

SITE NAME:	Stokes Croft		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Kingsley Fulbrook (LPA) 0117 9222966	NEW ENTRY?:	No

#### CORNWALL (UA)

sr		Codda Farmhouse, Bolventor, Altarnun	Farmhouse. C17 or earlier. Partly collapsed. Although some repairs to the habitable part of the house have been undertaken, the shippon and ancillary buildings are in poor condition. The temporary roof has recently been
	ESIGNATION:	Listed Building Grade II*	renewed and listed building consent granted for repair of the collapsing gable end and conversion of associated
	ONDITION:	Poor	of the collapsing gable end and conversion of associated sheds to ancillary uses.
	CCUPANCY:	Part occupied	
		F(C)	
	WNER TYPE:	Private	Contact: Francis Kelly 0117 975 0725



SITE NAME:	Antony	A programme of works to remove vegetation and rotting timber has been carried out, the main gates have been repaired and there is a commitment to
	Listed Building Grade II, SM	renew the bridge. The blocked drains in the south moat
CONDITION:	Poor	have been cleared. Further works are required to stop
OCCUPANCY:	Vacant	water ingress west of the entrance. A conservation plan was prepared for the site in April 2005.
PRIORITY:	F (F)	was prepared for the site in April 2005.
OWNER TYPE:	Government	Contact: Michael Turner 020 7973 3808
SITE NAME:	Tregantle Fort, Antony	Fort, built 1858-1865. The Keep is vacant, with no end use identified. A phased programme of repairs to the roof is complete. The interior is still in poor condition, but now drains out Poolscompt windows and doors have been
DESIGNATION:	Listed Building Grade II, SM	drying out. Replacement windows and doors have been agreed and partially carried out. Further window



SITE NAME:	Tregantle Fort, Antony	Fort, built 1858-1865. The Keep is vacant, identified. A phased programme of repair complete. The interior is still in poor con- drying out. Replacement windows and do
DESIGNATION:	Listed Building Grade II, SM	agreed and partially carried out. Further
CONDITION:	Fair	replacement is proposed for 2011-12.
OCCUPANCY:	Vacant	
PRIORITY:	F (F)	
OWNER TYPE:	Government	Contact: Michael Turner 020 7973 3808

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

CITE NIAME.

Scraesdon Fort

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).


F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

Built 1868 used for military training purposes

ABBREVIATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

STANCE       Strandout 40 metros south east of Trensmer Meer, Budie Stratton       Barde tendencial bard in Consult in a from Budie Approximately and think in the common Point Consumer       Barde tendencial bardie (Stratton)         STANCE       Stratton       Barde tendencial bardie (Stratton)       Barde tendencial bardie (Stratton)         Consumer       Name       Barde tendencial bardie (Stratton)       Barde tendencial bardie (Stratton)         Consumer       Point       Barde tendencial bardie (Stratton)       Barde tendencial bardie (Stratton)         Stratton       Point       Barde tendencial bardie (Stratton)       Barde tendencial bardie (Stratton)         Stratton       Point       Barde tendencial bardie (Stratton)       Barde tendencial bardie (Stratton)         Stratton       Barde Bardie (Stratton)       Bardie touse to pump regime, ball 1902, Baldess to an outstratton grand device on obligation consumer       Baller touse to pump regime, ball 1902, Baldess to an outstratton, Barde Touse is uncoded and internal devices on the obligation of course on white part at Stratton Barde (Bardie) (WMIS consumer)       Baller touse to pump regime, ball 1902, Baldess to an outstratton, Barde (Bardie) (WMIS consumer)         Stratton       Baller Baller (Stratton)       Baller (Baller (Stratton)       Consumer)       Baller (Baller (Stratton)         Stratton       Baller (Baller)       Consumer)       Consumer)       Consumer)       Consumer)         Stratton       <				
Instrume         Listed balance Grade Info         Free Historic element not in use and poor condition. Sectarsian Viscanti           Instrume         Contrasting Viscanti         Boole Three Weights         Sectarsian Viscanti           Instrume         Provide Three Historic element not in use and the poor condition. Sectarsian Viscanti         Sectarsian Viscanti         Sectarsian Viscanti           Instrume         Provide Three Historic element not in use and the poor condition. Sectarsian Viscanti         Boole House to Robinson's Shift, and South Confy Mine, Station Road, Pool. Cam Brea         Booler House to Robinson's Shift, and South Confy Mine, Station Road, Pool. Cam Brea           Instrume         Listel Building Crade IP. WHS confision Road Pool         Booler House to Robinson's Staft, an extrama Listel Building Grade IP. WHS confision Road Pool. Cam Brea         Booler House to pump engine, built 1903. Relates to an outstanding group of Early C2D building and the origination and the confision Road Pool. Cam Brea Instrume         Booler House to Robinson's Staft, South Confy Mine, Station Road, Pool. Cam Brea Instrume         Booler House to Robinson's Staft, South Confy Mine, Station Road, Pool. Cam Brea Instrume         Compressor House and associated South Confy Mine, Station Road, Pool. Cam Brea Instrume         Compressor House and associated South Confy Mine, Station Road, Pool. Cam Brea Instrume         Wim engine House and complex the not start complete surviver part of South Confy Mine, Station Road, Pool. Cam Brea South Confy Mine, Station Road, Pool. Cam Brea Instrume         Display Historic Mine, Station Road, Pool. Cam Brea Instrume         Display Historic Mine, Station		SITE NAME:	of Tremaer, Maer,	hamlet now dominated by a popular caravan site not far from Bude. Approximately one third of the historic
Similar cob built rear wing nonfex and collapsing.       Similar cob built rear wing nonfex and collapsing.         Winter Vision       Cocket rear Vision Road, Pool Corn Brea Robinson's Shaft, South Cordy Mine, Station Road, Pool Corn Brea Robinson's Shaft, South Cordy Mine, Station Road, Pool Corn Brea Robinson's Shaft, South Cordy Mine, Station Road, Pool Corn Brea Robinson's Cord Mine, South Cordy Mine, South Cordy Mine, South Cordy Mine, South Cord, Wine Remarkable for its Corners F (F)         Winter Wine Vision       Contact: Simon Road, Pool Corn Brea Robinson's Shaft, South Cordy Mine, So	THE PARTY	DESIGNATION:	Listed Building Grade II*	root of cruck type (rare in Cornwall) survived late C20
Image: Second			•	
Incerne         P(L)           Inverse         Baller House to Robinson's Shift as uth Cordy Mine, Station Road, Pool Cam Bea         Salier House to pump engine, built 1903. Relates to an utstanding group of early Cold building scrude pool Cam Bea           Image: Pool Cam Bea         Baller House to Robinson's Shift as utstanding group of early Cold building scrude pool Cam Bea         Salier House to pump engine, built 1903. Relates to an utstanding group of early Cold building scrude pool Cam Bea           Image: Pool Counce: Poor Counce: Poor Counce: Poor Counce: Poor Counce: Poor Counce: Poor Counce: Poor Counce: Counce: Structure Poor Counce: Poor Counce: Counce Station Cool Poor Counce: Counce: Counce Counce: Cou	and the second s	OCCUPANCY:	Vacant	Remainder re-roofed in corrugated iron and last
Ownerse Private         Central: Francis Kelly 0117 975 0725           Image: State St		PRIORITY:	С (С)	used as riding stables.
Vision         Description         South Crofty Mine, State Real, Pool, Carn Bras         Boler House to Robinson's Shaf, South Crofty Mine, State Real, Pool, Carn Bras         Boler House to Robinson's Shaf, South Crofty Mine, Remarkable for to degree of the a heritage centre are underway and are expected to be completed autumn 2011.           Image: State Real Real Real Real Real Real Real Rea		OWNER TYPE:		Contact: Francis Kelly 0117 975 0725
at South Crofty Mine, Station Read, Pool. Carn Bras Deservation. Used Building Grade II*/WHS Countrow Poor Countrow Poor Countor Poor Countrow Poor Countrow Poor Countrow Poor				
Image: Source is uncoded and internal machinery at risk Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed atturn 2011.       Image: Source Robinson's Robinson's Robinson's Robinson's Robinson's Complex into a heritage centre are underway and are expected to be completed atturn 2011.         Image: Robinson's Robinson'		SITE NAME:	at South Crofty Mine, Station Road,	an outstanding group of early C20 buildings around Robinson's Shaft, the most complete surviving part
Image: Second		DESIGNATION:	Listed Building Grade II*, WHS	preservation. Boiler house is unroofed and internal
Image: F(f)       ownersme Local authority       Contact: Simon Ramsden 0117 975 0676         Image: F(f)       ownersme Local authority       Contact: Simon Ramsden 0117 975 0676         Image: F(f)       contact: Simon Ramsden 0117 975 0676		CONDITION:	Poor	machinery at risk. Works to convert Robinson's complex
Image: Product		OCCUPANCY:	Vacant	into a heritage centre are underway and are expected
STERNER         Cargenters' shop, workshops and Crofty Station Road, Pool, Cam Brea Decuments         Cargenters' shop, sawmill, workshop and forge, built for great Robinson's Shaff, South Crofty Station Road, Pool, Cam Brea Decuments         Cargenters' shop, sawmill, workshop and forge, built for great Robinson's Complex, the most complete surviving part of the South Crofty mine, remarkable for is degree of preservation. Works to convert Robinson's complex, the most complete surviving part of the South Crofty mine, remarkable for is degree of preservation. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.           WILLING         Contract Simon Ramsden 0117 975 0676           WILLING         Poor Coccurse           Decurserse         Local authority           Decurserse         Poor Coccurse           Decurserse         Local authority           Decurserse         Poor Coccurse           Decurserse         Poor Poor Station Road, Pool, Cam Brea Station Road, Pool, Cam Brea Station Road, Pool, Cam Brea Station Road, Pool, Cam Brea Decurserse           Decurserse         Local authority         Contact: Simon Ramsden 0117 975 0676		PRIORITY:	F (F)	to be completed autumn 2011.
forge at Robinson's Shaft, South Crofty, Station Road, Pool. Can Brea Decouvers       1903-10.Building not secure or weathertight and the missing and deteriorating timber boarding is a concern. Part of the Robinson's complex, the most complete submissing and deteriorating timber boarding is a concern. Part of the Robinson's complex, the most complete submissing and deterioration. Work's to convert Robinson's concerner.         Image: State		OWNER TYPE:	Local authority	Contact: Simon Ramsden 0117 975 0676
forge at Robinson's Shaft, South Crofty, Station Road, Pool. Can Brea Detrawation       1903-10. Building not secure or weathertight and the missing and deteriorating timber boarding is a concern. Part of the Robinson's complex, the most complete south Crofty mine, remarkable for its degree of preservation. Work's to convert Robinson's occurrence Peor occurrence Peor occurrence Peor occurrence Peor occurrence Peor occurrence Compressor House and associated buildings at Robinson's Shaft, South Crofty Mine, Station Road, Peol, Can Brea       White engine house and compressor house, chinney and electricity sub-station (1908-09). Part of the Robinson's contract: Simon Ramsden 0117 975 0676         Image: Station Road, Peol, Can Brea       Station Road, Peol, Can Brea       White engine house and compressor house, chinney and electricity sub-station (1908-09). Part of the Robinson's contract: Simon Ramsden 0117 975 0676         Image: Station Road, Peol, Can Brea       Discover Robinson's Complex ite most complete surviving part of South Crofty workings the last working tim mine in Europe. Site is concurrence. Poor concurrence. Part concurrence. Part occupied mourn: F (f) concurrence. Part occupied mourn: F (f) concurrence. Part occupied mourn: F (f) concurrence. Part occupied mourn: F (f) concurrence. Poor concurrence. Poor concurence. Poor cocurrence. Poor concurence. Poor concurrence. Poor con				
Image: Another Listed Building Grade IP, WHS       Surviving part of the South Crofty mine, remarkable for its degree of preservation. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.         Image: Construction of the South Crofty with the South Crofty withing the South Crofty working the South Cr			forge at Robinson's Shaft, South Crofty, Station Road, Pool, Carn Brea	1903-10. Building not secure or weathertight and the missing and deteriorating timber boarding is a concern.
Image: Second			•	surviving part of the South Crofty mine, remarkable for
PROVETY:       F(f)         CONTENT:       F(f)         CONTENT:       F(f)         CONTENT:       F(f)         CONTENT:       Compressor House and associated buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea       Whim engine house and compressor house, chimney and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.         CONTINCE       Poor         CONTINCE       Pump Engine House at Robinson's Shaft, could complex, which is the most complete surviving part of South Crofty Mine, Station Raad, Pool, Carn Brea         PROPT:       F(f)         CONTINCE       Pump Engine House at Robinson's Shaft, south Crofty Mine, Station Raad, Pool, Carn Brea         PROPT:       Vacant         PROPT:       Vacant         PROPT:       Vacant         PROPT:       Vacant         PROPT:       Contact: Simon Ramsden 0117 975 0676         PROPT:       Vacant         PROPT:       Vacant         PROPT:       Vacant         PROPT:       Vacant         PROPT:       Contact: Simon Ramsden 0117 975 0676         PROPT:       Vacuew				its degree of preservation. Works to convert Robinson's
PROMITY:       F (F)         OWNERTITYE:       Local authority         Contact: Simon Ramsden 0117 975 0676         Whim engine house and compressor house, chinney and electritity sub-station (1908-09), Part of the Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carm Brea       Whim engine house and compressor house, chinney and electritity sub-station (1908-09), Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty Workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.         Image: Station Road, Pool, Carm Brea       Pump Engine House at Robinson's Shaft complex, which is the most complete surviving tim in guard of South Crofty Workings, the last working tim interest from vandalism. Works to convert Robinson's Shaft complex, which is the most complete surviving in the station Road, Pool, Carm Brea         Image: Station Road, Pool, Carm Brea       Pump Engine House at Robinson's Shaft complex, which is the most complete surviving in the appendix of south Crofty workings, the last working tim mine in Europe. Remarkable for its degree of preservation.         Image: Station Road, Pool, Carm Brea       Pump Engine House at Robinson's Shaft complex, which is the most complete surviving in the appendix of the Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.         Image: Station Road, Pool, Carm Brea       Desonverce:       Vacant         Image: Station Road, Pool, Carm Brea       Contact: Simon Ramsden 0117 975 0676         Im		OCCUPANCY:		expected to be completed autumn 2011.
STE NAME       Compressor House and associated buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea       Whim engine house and compressor house, chimney and electricity sub-station (1908-09). Part of the Robinson's Shaft, South Crofty Workings, the last working tin mine in Europe. Site is Compressor House. Listed Building Grade II*, WHS         COMDITION:       Poor         COMMERTINE:       Listed Building Grade II*, WHS         COMDITION:       Poor         COMMERTINE:       Local authority         CONTROL:       F(F)         OWNERTINE:       Local authority         CONTROL:       F(F)         OWNERTINE:       Local authority         CONTROL:       Shaft, South Crofty Mine, Station Road, Pool, Carn Brea         DESCANTION:       F(F)         OWNERTINE:       Listed Building Grade II*, WHS         COMDITION:       Poor         CONTROL:       F(F)         OWNERTINE:       Listed Building Grade II*, WHS         COMDITION:       Poor         CONTROL:       Shaft, South Crofty Mine, Station Road, Pool, Carn Brea         DESCANTION:       Listed Building Grade II*, WHS         COMDITION:       Poor         COULINANCY:       Vacant         PROWERTINE:       Listed Building Grade II*, WHS         COMDITION:       Poor <td>CONTRACTOR OF THE OWNER</td> <td></td> <td></td> <td></td>	CONTRACTOR OF THE OWNER			
buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea       and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.         Image: Construct threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.         Image: Construct threat from vandalism. Works to convert Robinson's Shaft, South Crofty Mine, Static Road, Pool, Carn Brea Static Road, Pool, Carn Brea Designation.       Pump Engine House at Robinson's Shaft, South Crofty Mine, Static Road, Pool, Carn Brea Station Road, Pool, Carn Brea Designation.       Pump Engine House at Robinson's Shaft, South Crofty Mine, Static Road, Pool, Carn Brea Designation.       Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Designation.       Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Designation.       Pump Engine House at Robinson's Shaft, South Crofty Wine, Station Road, Pool, Carn Brea Designation.       Pump Engine House at Robinson's Shaft, South Crofty Wine, Station Road, Pool, Carn Brea Designation.       Pump Engine House at Robinson's Shaft, South Crofty Wine, Station Road, Pool, Carn Brea Designation.       Pump Engine House at Robinson's Shaft, South Crofty Wine, Station Road, Pool, Contact: Simon Ramsden 0117 975 0676         Image: Province Pool Cocumence Fool Cocumence Fool Cocumence Fool Cocumence Fool Cocumence Fool Cocumence Fool Cocumence Pool Cocumence Pool Cocumence Fool Cocumence Fool Cocumence Fool Co		OWNER TYPE:	Local authority	Contact: Simon Ramsden 0117 975 0676
CONDITION:       Poor       and are expected to be completed autumn 2011.         OCCUPANCY:       Part occupied       PRORTY::       F (F)         OWNERTYPE:       Local authority       Contact: Simon Ramsden 0117 975 0676         STEINAME:       Pump Engine House at Robinson's Shaft, South Crofty Mine, station Road, Pool, Carm Brea       Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft, South Crofty Mine, station Road, Pool, Carm Brea         DESIGNATION:       Listed Building Grade II*, WHS       Contact: Simon Ramsden 0117 975 0676         OCCUPANCY:       Vacant       Poor         OCCUPANCY:       Vacant       Prior         PRORTY:       F (F)       Contact: Simon Ramsden 0117 975 0676         STEINAME:       Steinantow:       Listed Building Grade II*, WHS       Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.         PRIORITY:       F (F)       Contact: Simon Ramsden 0117 975 0676         STEINAME:       Church of St Rumon, Ruan Major, Grade Ruan       Mediaeval former parish church, now chapel of ease in picturesque churchyard, Redundant since 1963.         PRIORITY:       Condition:       Poor       Contact: Simon Ramsden 0117 975 0676         STEINAME:       Church of St Rumon, Ruan Major, Grade Ruan       Mediaeval former parish church, now chapel of ease in picturesque ch				
Image: Second and the second and th		SITE NAME:	buildings at Robinson's Shaft, South Crofty Mine, Station Road,	and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is
Image: Property in the image: Property interpretation in theready inteready interpretation inteready interpretation	Real Provide State		buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea	and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway
OWNERTIME       Local authority       Contact: Simon Ramsden 0117 975 0676         Image: Control of Contrel of Control of		DESIGNATION:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS	and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway
SITE NAME:       Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea       Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.         Image: Conduction of the Nonerry E       F(F)         OWNERTYPE       Local authority         STE NAME:       Church of St Rumon, Ruan Major, Grade Ruan         DESIGNATION:       Listed Building Grade I condition:         STE NAME:       Church of St Rumon, Ruan Major, Grade Ruan         DESIGNATION:       Listed Building Grade I condition:         Designation:       Listed Building Grade I condition:         COUPTION:       Poor         Occuration:       Listed Building Grade I condition:         Condition:       Poor         Occuration:       Listed Building Grade I condition:         Condition:       Poor         Occuration:       Listed Building Grade I condition:         Condition:       Poor         Occuration:       Site I autority		DESIGNATION:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor	and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway
Shaft, South Crofty Mine, Station Road, Pool, Carn Brea       Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.         PRIORITY:       F (F) OWNER TYPE       Church of St Rumon, Ruan Major, Grade Ruan         DESIGNATION:       SITE NAME:       Church of St Rumon, Ruan Major, Grade Ruan         DESIGNATION:       Listed Building Grade I COLUPANCY:       Vacant         PRIORITY:       F (C) COLUPANCY:       Contact: Simon Ramsden 0117 975 0676         VENTORIE TYPE:       Church of St Rumon, Ruan Major, Grade Ruan       Mediaeval former parish church, now chapel of ease in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level.         DESIGNATION:       POOR COLUPANCY:       Vacant         PRIORITY:       C (New entry)       POOR		DESIGNATION: CONDITION: OCCUPANCY:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied	and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway
Shaft, South Crofty Mine, Station Road, Pool, Carn Brea       Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.         PRIORITY:       F (F) OWNER TYPE       Church of St Rumon, Ruan Major, Grade Ruan         DESIGNATION:       SITE NAME:       Church of St Rumon, Ruan Major, Grade Ruan         DESIGNATION:       Listed Building Grade I COLUPANCY:       Vacant         PRIORITY:       F (C) COLUPANCY:       Contact: Simon Ramsden 0117 975 0676         VENTORIE TYPE:       Church of St Rumon, Ruan Major, Grade Ruan       Mediaeval former parish church, now chapel of ease in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level.         DESIGNATION:       POOR COLUPANCY:       Vacant         PRIORITY:       C (New entry)       POOR		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F)	and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.
Designation:       Listed Building Grade II*, WHS       Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.         PRORITY:       F (F)       OWNERTYPE       Local authority         OWNERTYPE       Local authority       Contact: Simon Ramsden 0117 975 0676         OFFENDED       STE NAME:       Church of St Rumon, Ruan Major, Grade Ruan       Mediaeval former parish church, now chapel of ease in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level.         PRORITY:       C (New entry)       PRORITY:       C (New entry)		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F)	and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.
OCCUPANCY:       Vacant       and are expected to be completed autumn 2011.         PRIORITY:       F (F)       Contact: Simon Ramsden 0117 975 0676         OWNER TYPE       Local authority       Contact: Simon Ramsden 0117 975 0676         Image: Stre NAME:       Church of St Rumon, Ruan Major, Grade Ruan       Mediaeval former parish church, now chapel of ease in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level.         DESIGNATION:       Listed Building Grade I       to the tower which has a tree growing out of it at high level.		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine,	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin</li> </ul>
Image: Streen and Streen		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation.</li> </ul>
OWNER TYPE       Local authority       Contact: Simon Ramsden 0117 975 0676         Image: Stre NAME       Church of St Rumon, Ruan Major, Grade Ruan       Mediaeval former parish church, now chapel of ease in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level.         DESIGNATION:       Listed Building Grade I       Image: Condition to the low walls but not to the tower which has a tree growing out of it at high level.		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway</li> </ul>
SITE NAME       Church of St Rumon, Ruan Major, Grade Ruan       Mediaeval former parish church, now chapel of ease in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level.         DESIGNATION:       Listed Building Grade I         CONDITION:       Poor         OCCUPANCY:       Vacant         PRIORITY:       C (New entry)		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway</li> </ul>
Ruan Major, Grade Ruan       in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level.         DESIGNATION:       Poor         OCCUPANCY:       Vacant         PRIORITY:       C (New entry)		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Vacant	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> </ul>
Ruan Major, Grade Ruan       in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level.         DESIGNATION:       Poor         OCCUPANCY:       Vacant         PRIORITY:       C (New entry)		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Vacant F (F)	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> </ul>
DESIGNATION:       Listed Building Grade I       to the tower which has a tree growing out of it at high level.         CONDITION:       Poor       high level.         OCCUPANCY:       Vacant         PRIORITY:       C (New entry)		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Vacant F (F)	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> </ul>
OCCUPANCY: Vacant PRIORITY: C (New entry)		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Vacant F (F) Local authority Church of St Rumon, Ruan Major, Grade Ruan	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Mediaeval former parish church, now chapel of ease in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has</li> </ul>
PRIORITY: C (New entry)		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Vacant F (F) Local authority Church of St Rumon, Ruan Major, Grade Ruan Listed Building Grade I	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Mediaeval former parish church, now chapel of ease in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at</li> </ul>
		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Vacant F (F) Local authority F (F) Local authority Church of St Rumon, Ruan Major, Grade Ruan Listed Building Grade I Poor	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Mediaeval former parish church, now chapel of ease in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at</li> </ul>
OWNERTYPE: Religious organisation Contact: Francis Kelly 0117 975 0725		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Vacant F (F) Local authority F (F) Local authority Church of St Rumon, Ruan Major, Grade Ruan Listed Building Grade I Poor Vacant	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Mediaeval former parish church, now chapel of ease in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at</li> </ul>
		DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	buildings at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Part occupied F (F) Local authority Pump Engine House at Robinson's Shaft, South Crofty Mine, Station Road, Pool, Carn Brea Listed Building Grade II*, WHS Poor Vacant F (F) Local authority Church of St Rumon, Ruan Major, Grade Ruan Listed Building Grade I Poor Vacant Church of St Rumon, Ruan Major, Grade Ruan	<ul> <li>and electricity sub-station (1908-09). Part of the Robinson's Shaft complex, the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Site is under constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Pump engine house to tin mine, built in 1903. Part of the Robinson's Shaft complex, which is the most complete surviving part of South Crofty workings, the last working tin mine in Europe. Remarkable for its degree of preservation. Site faces constant threat from vandalism. Works to convert Robinson's complex into a heritage centre are underway and are expected to be completed autumn 2011.</li> <li>Contact: Simon Ramsden 0117 975 0676</li> <li>Mediaeval former parish church, now chapel of ease in picturesque churchyard. Redundant since 1963. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level.</li> </ul>



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

Handa S			
	SITE NAME:	13 High Street,	Jettied and timber-framed corner house, prominent on town's market square. Roof structure is in very poor
		Launceston	condition with partial collapse. Some of the structural
	DESIGNATION	Listed Building Grade II*	work begun but condition of building remains serious.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	A (A)	
	OWNER TYPE:	<b>^</b>	Contact: Francis Kelly 0117 975 0725
	SITE NAME:	Freemasons Hall.	CI3 former hall of the Duchy Palace, a masonic hall
		Quay Street,	since 1878. A building preservation trust has acquired
3.3		Lostwithiel	the building; an options appraisal has been carried out and proposals for its re-use are being developed.
	DESIGNATION:	0	English Heritage has offered grant for investigation
	CONDITION:	Fair	and repair.
	OCCUPANCY:		
	PRIORITY:	E (E)	
	OWNER TYPE:	Trust	Contact: Chris Miners 0117 975 0700
	SITE NAME:	Maker Heights Barracks Block,	Built in 1804-1808 as a barracks for a line of earlier
		Maker with Rame	redoubts built to protect Devonport Dockyard in 1782. It is the most complete and unaltered small garrison
	DECIDINATION	Listed Building Crade II*	barracks from this significant period. The two storey
		Listed Building Grade II* Very bad	block was altered in the mid C19 when the formerly
	CONDITION:	Part occupied	tile-hung first floor was rebuilt in brick.
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Trust	Contact: Phil McMahon 0117 975 0699
	0111211112		
		Maker Heights Guard House	Built in 1804-1808 as Barracks for a line of earlier
	SITE NAME:	Maker Heights Guard House, boundary wall and attached ancillary	Built in 1804-1808 as Barracks for a line of earlier redoubts built to protect Devonport Dockyard in 1782.
1	SITE NAME:	Maker Heights Guard House, boundary wall and attached ancillary buildings, Maker with Rame	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and
		boundary wall and attached ancillary	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor
		boundary wall and attached ancillary buildings, Maker with Rame	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and
	DESIGNATION:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash
	DESIGNATION: CONDITION:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier:
ALA	DESIGNATION: CONDITION: OCCUPANCY:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry)	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier:
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent,	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor N/A	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor N/A A (New entry)	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor decay and to prioritise repairs.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor N/A A (New entry)	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor N/A A (New entry) Religious organisation	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor decay and to prioritise repairs. Contact: Francis Kelly 0117 975 0725
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor N/A A (New entry)	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor decay and to prioritise repairs. Contact: Francis Kelly 0117 975 0725 Early to mid C19 mould and casting buildings. This is the main furnace building. Impressive and surprisingly intact.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor N/A A (New entry) Religious organisation Dry sand and green sand shop,	<ul> <li>redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier.</li> <li>Contact: Phil McMahon 0117 975 0699</li> <li>C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor decay and to prioritise repairs.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>Early to mid C19 mould and casting buildings. This is the main furnace building. Impressive and surprisingly intact. Urgent repairs carried out early 2005. Listed building</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor N/A A (New entry) Religious organisation Dry sand and green sand shop, Perran Foundry, Perran Wharf, Mylor	<ul> <li>redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier.</li> <li>Contact: Phil McMahon 0117 975 0699</li> <li>C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor decay and to prioritise repairs.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>Early to mid C19 mould and casting buildings. This is the main furnace building. Impressive and surprisingly intact. Urgent repairs carried out early 2005. Listed building consent and planning permission for repair and conversion</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor N/A A (New entry) Religious organisation Dry sand and green sand shop, Perran Foundry, Perran Wharf, Mylor Listed Building Grade II*	<ul> <li>redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier.</li> <li>Contact: Phil McMahon 0117 975 0699</li> <li>C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor decay and to prioritise repairs.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>Early to mid C19 mould and casting buildings. This is the main furnace building. Impressive and surprisingly intact. Urgent repairs carried out early 2005. Listed building</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor N/A A (New entry) Religious organisation Dry sand and green sand shop, Perran Foundry, Perran Wharf, Mylor Listed Building Grade II* Very bad	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor decay and to prioritise repairs. Contact: Francis Kelly 0117 975 0725 Early to mid C19 mould and casting buildings. This is the main furnace building. Impressive and surprisingly intact. Urgent repairs carried out early 2005. Listed building consent and planning permission for repair and conversion granted 2008 and now starting to be implemented in a
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor N/A A (New entry) Religious organisation Dry sand and green sand shop, Perran Foundry, Perran Wharf, Mylor Listed Building Grade II* Very bad N/A B (B)	<ul> <li>redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier.</li> <li>Contact: Phil McMahon 0117 975 0699</li> <li>C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor decay and to prioritise repairs.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>Early to mid C19 mould and casting buildings. This is the main furnace building. Impressive and surprisingly intact. Urgent repairs carried out early 2005. Listed building consent and planning permission for repair and conversion granted 2008 and now starting to be implemented in a phased manner, with an expected completion date of 2016.</li> </ul>
	DESIGNATION: CONDITION PRIORITY: OWNER TYPE SITE NAME: CONDITION: OCCUPANCY: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION:	boundary wall and attached ancillary buildings, Maker with Rame Listed Building Grade II* Very bad Part occupied A (New entry) Trust Boundary wall to Lanherne Carmelite Convent, Mawgan in Pydar Listed Building Grade II*, CA Poor N/A A (New entry) Religious organisation Dry sand and green sand shop, Perran Foundry, Perran Wharf, Mylor Listed Building Grade II* Very bad N/A B (B)	redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Canopier. Contact: Phil McMahon 0117 975 0699 C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor decay and to prioritise repairs. Contact: Francis Kelly 0117 975 0725 Early to mid C19 mould and casting buildings. This is the main furnace building. Impressive and surprisingly intact. Urgent repairs carried out early 2005. Listed building consent and planning permission for repair and conversion granted 2008 and now starting to be implemented in a

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

	SITE NAME:	Engineers Shop, Perran Foundry, Perran Wharf, Mylor	Engineers shop, boring mill and pattern shop circa early/mid C18. Listed building consent and planning permission for repair and conversion granted 2008
	DESIGNATION:	Listed Building Grade II*	and now starting to be implemented in a phased manner, with an expected completion date of 2016.
	CONDITION:	Very bad	manner, with an expected completion date of 2016.
	OCCUPANCY:	,	
	PRIORITY:	B (B)	
A REAL PROPERTY OF A REAL PROPER	OWNER TYPE:	Private	Contact: Simon Ramsden 0117 975 0676
	SITE NAME:	New Pattern Shop, Perran Foundry, Perran Wharf, Mylor	Early C19 pattern shop. It is one of the most visually exciting buildings on site and despite serious problems retains most of its original structural fabric.
	DESIGNATION:	Listed Building Grade II*	Urgent repairs carried out early 2005. Permissions for repair and conversion granted 2008 and now starting
	CONDITION:	Very bad	to be implemented in a phased manner, with an
	OCCUPANCY:	N/A	expected completion date of 2016.
	PRIORITY:	B (B)	
	OWNER TYPE:	Private	Contact: Simon Ramsden 0117 975 0676
The way is a second	SITE NAME:	Warehouse (formerly listed as office), Perran Foundry, Perran Wharf, Mylor	Mid C19 warehouse serving the former iron foundry, subsequently used as offices. It forms part of the Perran Foundry site which was established in 1791. Urgent repairs
	DESIGNATION:	Listed Building Grade II*	were carried out early 2005. Permissions for repair and conversion granted 2008 and now starting to be
	CONDITION:	Very bad	implemented in a phased manner, with an expected
	OCCUPANCY:	N/A	completion date of 2016.
	PRIORITY:	B (B)	
and a state of the	OWNER TYPE:	Private	Contact: Simon Ramsden 0117 975 0676
	SITE NAME:	Trinity Methodist Chapel,	Redundant Nonconformist Wesleyan chapel circa 1834,
9		Chywoone Hill, Newlyn, Penzance	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious
		Chywoone Hill, Newlyn,	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and
		Chywoone Hill, Newlyn, Penzance	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious
	DESIGNATION:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for
	DESIGNATION:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C)	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review. Contact: Francis Kelly 0117 975 0725 C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review. Contact: Francis Kelly 0117 975 0725 C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are in train with
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth Listed Building Grade II* Very bad	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review. Contact: Francis Kelly 0117 975 0725 C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth Listed Building Grade II* Very bad N/A	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review. Contact: Francis Kelly 0117 975 0725 C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are in train with Cornwall Council to identify an appropriate strategy to
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION: PRIORITY:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth Listed Building Grade II* Very bad N/A A (A)	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review. Contact: Francis Kelly 0117 975 0725 C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are in train with Cornwall Council to identify an appropriate strategy to secure the building and prevent further deterioration.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth Listed Building Grade II* Very bad N/A A (A)	enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review. Contact: Francis Kelly 0117 975 0725 C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are in train with Cornwall Council to identify an appropriate strategy to
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION: PRIORITY:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth Listed Building Grade II* Very bad N/A A (A)	<ul> <li>enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are in train with Cornwall Council to identify an appropriate strategy to secure the building and prevent further deterioration.</li> <li>Contact: Phil McMahon 0117 975 0699</li> <li>Redundant Wesleyan chapel (1827) and attached schoolroom (mid C19). No longer used for worship. Building weathertight. Listed building consent granted</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth Listed Building Grade II* Very bad N/A A (A) Private Charlestown Methodist Church, Charlestown Road, St Austell	<ul> <li>enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are in train with Cornwall Council to identify an appropriate strategy to secure the building and prevent further deterioration.</li> <li>Contact: Phil McMahon 0117 975 0699</li> <li>Redundant Wesleyan chapel (1827) and attached schoolroom (mid C19). No longer used for worship. Building weathertight. Listed building consent granted for conversion of rear school block and stabilisation</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth Listed Building Grade II* Very bad N/A A (A) Private Charlestown Methodist Church, Charlestown Road, St Austell Listed Building Grade II*, CA, WHS	<ul> <li>enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are in train with Cornwall Council to identify an appropriate strategy to secure the building and prevent further deterioration.</li> <li>Contact: Phil McMahon 0117 975 0699</li> <li>Redundant Wesleyan chapel (1827) and attached schoolroom (mid C19). No longer used for worship. Building weathertight. Listed building consent granted</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth Listed Building Grade II* Very bad N/A A (A) Private Charlestown Methodist Church, Charlestown Road, St Austell Listed Building Grade II*, CA, WHS Very bad	<ul> <li>enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are in train with Cornwall Council to identify an appropriate strategy to secure the building and prevent further deterioration.</li> <li>Contact: Phil McMahon 0117 975 0699</li> <li>Redundant Wesleyan chapel (1827) and attached schoolroom (mid C19). No longer used for worship. Building weathertight. Listed building consent granted for conversion of rear school block and stabilisation</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth Listed Building Grade II* Very bad N/A A (A) Private Charlestown Methodist Church, Charlestown Road, St Austell Listed Building Grade II*, CA, WHS Very bad	<ul> <li>enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are in train with Cornwall Council to identify an appropriate strategy to secure the building and prevent further deterioration.</li> <li>Contact: Phil McMahon 0117 975 0699</li> <li>Redundant Wesleyan chapel (1827) and attached schoolroom (mid C19). No longer used for worship. Building weathertight. Listed building consent granted for conversion of rear school block and stabilisation</li> </ul>
	DESIGNATION: CONDITION PRIORITY: OWNER TYPE SITE NAME: CONDITION: CONDITION: OWNER TYPE SITE NAME: SITE NAME: CONDITION: CONDITION:	Chywoone Hill, Newlyn, Penzance Listed Building Grade II*, CA Poor N/A C (C) Religious organisation Sara's Foundry, Tolgus Place, Redruth Listed Building Grade II* Very bad N/A A (A) Private Charlestown Methodist Church, Charlestown Road, St Austell Listed Building Grade II*, CA, WHS Very bad Vacant B (B)	<ul> <li>enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are in train with Cornwall Council to identify an appropriate strategy to secure the building and prevent further deterioration.</li> <li>Contact: Phil McMahon 0117 975 0699</li> <li>Redundant Wesleyan chapel (1827) and attached schoolroom (mid C19). No longer used for worship. Building weathertight. Listed building consent granted for conversion of rear school block and stabilisation</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

Aller	SITE NAME:	Hockings House Bible Christian Chapel, St Cleer	Chapel dated 1846. Exceptionally well-preserved interior with gallery and good quality original fittings including leaders' pew. Now separated from the small Sunday school.
	DESIGNATION:	Listed Building Grade II*	Plans for modest conversion agreed.
	CONDITION:	Very bad	
	OCCUPANCY:	,	
	PRIORITY:	B (A)	
70000-3.000	OWNER TYPE:	Private	Contact: Francis Kelly 0117 975 0725
	SITE NAME:	Calf House at Lithiack and stable adjacent to North, Port Eliot Estate, St Germans	Late C18/early C19 Estate agricultural building. Attributed to Soane for the Port Eliot Estate. Owner is in discussion with the Local Authority regarding future use of the building.
	DESIGNATION:	Listed Building Grade II*	regarding luture use of the building.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Francis Kelly 0117 975 0725
	SITE NAME:	Porthmeor Pilchard Cellars and Studios, I 3, I 5 and I 7 Back Road West, St Ives	Built in the C19 and extended around 1900, the Studios were home to many important artists of the internationally known St Ives School. The net lofts below retain rare pilchard
	DESIGNATION:	Listed Building Grade II*, CA	processing tanks. The building is still in use today, but requires
	CONDITION:	Poor	extensive repair. English Heritage grant-aided work on first phase of roof and structural repairs currently on site.
	OCCUPANCY:	Occupied	Phase II grant-aided works due to start summer 2011.
AND THE ADDRESS OF THE OWNER	PRIORITY:	F (B)	
the second second second	OWNER TYPE:	( )	Contact: Simon Ramsden 0117 975 0676
and a state of the			
	SITE NAME:	Gatehouse to Trenethick Barton Farmhouse, Wendron	Gatehouse or barbican, C16. Granite ashlar gatehouse with scantle slate roof. Comprehensive repairs underway summer 2011.
		Trenethick Barton Farmhouse,	with scantle slate roof. Comprehensive repairs underway
		Trenethick Barton Farmhouse, Wendron	with scantle slate roof. Comprehensive repairs underway
	DESIGNATION:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad	with scantle slate roof. Comprehensive repairs underway
	DESIGNATION:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad	with scantle slate roof. Comprehensive repairs underway
	DESIGNATION: CONDITION: OCCUPANCY:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B)	with scantle slate roof. Comprehensive repairs underway
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel,	with scantle slate roof. Comprehensive repairs underway summer 2011. Contact: Francis Kelly 0117 975 0725 Redundant 1866 Wesleyan Methodist chapel.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis,	with scantle slate roof. Comprehensive repairs underway summer 2011. Contact: Francis Kelly 0117 975 0725 Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis, Wendron	with scantle slate roof. Comprehensive repairs underway summer 2011. Contact: Francis Kelly 0117 975 0725 Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis, Wendron Listed Building Grade II*	with scantle slate roof. Comprehensive repairs underway summer 2011. Contact: Francis Kelly 0117 975 0725 Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is negotiating potential for conversion to residential
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis, Wendron Listed Building Grade II* Poor	with scantle slate roof. Comprehensive repairs underway summer 2011. Contact: Francis Kelly 0117 975 0725 Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis, Wendron Listed Building Grade II* Poor Part occupied	with scantle slate roof. Comprehensive repairs underway summer 2011. Contact: Francis Kelly 0117 975 0725 Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is negotiating potential for conversion to residential
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis, Wendron Listed Building Grade II* Poor Part occupied C (C)	with scantle slate roof. Comprehensive repairs underway summer 2011. Contact: Francis Kelly 0117 975 0725 Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is negotiating potential for conversion to residential use with Cornwall County Council and English Heritage.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis, Wendron Listed Building Grade II* Poor Part occupied C (C)	with scantle slate roof. Comprehensive repairs underway summer 2011. Contact: Francis Kelly 0117 975 0725 Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is negotiating potential for conversion to residential
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis, Wendron Listed Building Grade II* Poor Part occupied C (C)	<ul> <li>with scantle slate roof. Comprehensive repairs underway summer 2011.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is negotiating potential for conversion to residential use with Cornwall County Council and English Heritage.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>A large suburban Anglican parish church fronting the estuary north of Falmouth. It was built in 1827 to the design of R Grout and has remained substantially unaltered since. There are major roof leaks in several</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis, Wendron Listed Building Grade II* Poor Part occupied C (C) Private Church of St Michael, Stratton Terrace, Falmouth	<ul> <li>with scantle slate roof. Comprehensive repairs underway summer 2011.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is negotiating potential for conversion to residential use with Cornwall County Council and English Heritage.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>A large suburban Anglican parish church fronting the estuary north of Falmouth. It was built in 1827 to the design of R Grout and has remained substantially unaltered since. There are major roof leaks in several places that have caused internal decay. A Repair Grant</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis, Wendron Listed Building Grade II* Poor Part occupied C (C) Private Church of St Michael, Stratton Terrace, Falmouth	<ul> <li>with scantle slate roof. Comprehensive repairs underway summer 2011.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is negotiating potential for conversion to residential use with Cornwall County Council and English Heritage.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>A large suburban Anglican parish church fronting the estuary north of Falmouth. It was built in 1827 to the design of R Grout and has remained substantially unaltered since. There are major roof leaks in several</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis, Wendron Listed Building Grade II* Poor Part occupied C (C) Private Church of St Michael, Stratton Terrace, Falmouth Listed Place of Worship Grade II, CA Poor	with scantle slate roof. Comprehensive repairs underway summer 2011. Contact: Francis Kelly 0117 975 0725 Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is negotiating potential for conversion to residential use with Cornwall County Council and English Heritage. Contact: Francis Kelly 0117 975 0725 A large suburban Anglican parish church fronting the estuary north of Falmouth. It was built in 1827 to the design of R Grout and has remained substantially unaltered since. There are major roof leaks in several places that have caused internal decay. A Repair Grant for Places of Worship has been offered for the repairs
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Trenethick Barton Farmhouse, Wendron Listed Building Grade I Very bad Vacant F (B) Private Wesleyan Chapel, Porkellis, Wendron Listed Building Grade II* Poor Part occupied C (C) Private Church of St Michael, Stratton Terrace, Falmouth Listed Place of Worship Grade II, CA	with scantle slate roof. Comprehensive repairs underway summer 2011. Contact: Francis Kelly 0117 975 0725 Redundant 1866 Wesleyan Methodist chapel. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is negotiating potential for conversion to residential use with Cornwall County Council and English Heritage. Contact: Francis Kelly 0117 975 0725 A large suburban Anglican parish church fronting the estuary north of Falmouth. It was built in 1827 to the design of R Grout and has remained substantially unaltered since. There are major roof leaks in several places that have caused internal decay. A Repair Grant for Places of Worship has been offered for the repairs

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

		Church of St lamos	A three stat	led church with a tall wort towar in the control
	SITE NAME:	Church of St James, Jacobstow	of a tiny vill are leaking, long overdu	led church with a tall west tower in the centre lage. The tower roof and the north valley gutter the latter very badly due to a temporary repair use for replacement. A grant offer for repairs to
		Listed Place of Worship Grade I	the roots ar	nd gutters has been made.
	CONDITION:			
21/1 53-13	PRIORITY:	B (New entry)		
C DIN		Religious organisation	Contact: Ch	nris Miners 0117 975 0700
	of the contract of the contrac	nongio de longarine de long	Contact of	
	SITE NAME:	Church of St Philip and St James, Maryfield, St Antony	overlooking stone spire loose pinna	church near to Antony House (National Trust) g the estuary of the river Tamar in Cornwall. The has structural problems with damp ingress and icles and spire apex. There is a very real danger conework. A repair grant has been offered to
The way	DESIGNATION:	Listed Place of Worship Grade II*		stonework.
	CONDITION:	Very bad		
C C C C C C C C C C C C C C C C C C C	PRIORITY:	B (New entry)		
	OWNER TYPE:	Religious organisation	Contact: Ch	nris Miners 0117 975 0700
	SITE NAME:	St Buryan Church, St Buryan	famous mai leaking, caus internal arcs	ee aisled church with a tall tower that is a ritime landmark. The lead valley gutters are sing active decay to the wall heads above the ades. A repair grant has been offered to renew utters and repair the inner slate roof slopes.
N. S. Barris	DESIGNATION:	Listed Place of Worship Grade I, CA	une vaney g	utters and repair the inner state roor slopes.
	CONDITION:	Very bad		
	PRIORITY:	B (New entry)		
	OWNER TYPE:	Religious organisation	Contact: Cł	nris Miners 0117 975 0700
T	SITE NAME:	St Stithians Church, Stithians	mining villag wet interna ends are sta	ee aisled church on the edge of a large former ge. The tall granite west tower is exceptionally Ily as it lets in and retains rainwater. The beam arting to decay where they are embedded in
	DESIGNATION:	Listed Place of Worship Grade II*	has been of	walls. A grant for the repair of the tower walls ffered.
	CONDITION:	Very bad		
	PRIORITY:	D (New entry)		
	OWNER TYPE:	Religious organisation	Contact: Cł	nris Miners 0117 975 0700
SITE NAME:	Black Hea	d promontory fort		
		d promontory fort		Concerlly unceticfactory
SITE NAME: DESIGNATION:		<b>d promontory fort</b> Monument (No. 1004391)	CONDITION:	Generally unsatisfactory
DESIGNATION:	Scheduled	Monument (No. 1004391)		with major localised problems
		Monument (No. 1004391)	CONDITION: TREND: CONTACT:	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Scrub / tre Private	Monument (No. 1004391) ee growth	TREND: CONTACT:	with major localised problems Stable
DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE: SITE NAME:	Scheduled Scrub / tre Private	Monument (No. 1004391) ee growth ircles 400m WSW of Furhouse, Advent	TREND: CONTACT:	with major localised problems Stable Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Scrub / tre Private	Monument (No. 1004391) ee growth	TREND: CONTACT:	with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE: SITE NAME:	Scheduled Scrub / tre Private Two hut c Scheduled	Monument (No. 1004391) ee growth ircles 400m WSW of Furhouse, Advent	TREND: CONTACT:	with major localised problems Stable Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Scrub / tre Private Two hut c Scheduled	Monument (No. 1004391) ee growth i <b>rcles 400m WSW of Furhouse, Advent</b> Monument (No. 1004657)	TREND: CONTACT:	with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Scrub / tre Private Two hut c Scheduled Extensive Private	Monument (No. 1004391) ee growth <b>ircles 400m WSW of Furhouse, Advent</b> Monument (No. 1004657) vehicle damage/erosion	TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Scrub / tre Private Scheduled Extensive Private	Monument (No. 1004391) ee growth <b>ircles 400m WSW of Furhouse, Advent</b> Monument (No. 1004657) vehicle damage/erosion	TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERTYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERTYPE: SITE NAME:	Scheduled Scrub / tre Private Scheduled Extensive Private	Monument (No. 1004391) ee growth irrcles 400m WSW of Furhouse, Advent Monument (No. 1004657) vehicle damage/erosion	TREND: CONTACT: CONDITION: TREND: CONTACT: CONTACT:	with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 d boundaries on Carne Down, Altarnun Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERTYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERTYPE: SITE NAME:	Scheduled Scrub / tre Private Scheduled Extensive Private Co-axial f	Monument (No. 1004391) ee growth irrcles 400m WSW of Furhouse, Advent Monument (No. 1004657) vehicle damage/erosion	TREND: CONTACT: CONDITION: TREND: CONTACT: CONTACT:	with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 d boundaries on Carne Down, Altarnun Generally unsatisfactory

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Cross on Halvana Moor, Altarnun		
DESIGNATION:	Scheduled Monument (No. 1004399)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Deserted medieval settlement and field sys field system and post-medieval farmhouse r		•
DESIGNATION:	Scheduled Monument (No. 1007775)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Nine Stones stone circle 1.03km NNW of E	Bowhayland Farm,	Altarnun
DESIGNATION:	Scheduled Monument (No. 1008631)	CONDITION:	Generally unsatisfactory
		CONDITION.	with major localised problems
RINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Stable
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			0
ITE NAME:	Platform cairn with rim bank and central ca on the summit of Carne Down, Altarnun	irn, and a seconda	ary cairn,
DESIGNATION:	Scheduled Monument (No. 1011781)	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Prehistoric coaxial field system, incorporate		
DITE NAME:	linear boundaries and medieval settlement	on Fox Tor and Tr	eburland Farm, Altarnun
			eburland Farm, Altarnun Generally unsatisfactory
DESIGNATION:	linear boundaries and medieval settlement Scheduled Monument (No. 1008245)	on Fox Tor and Tr CONDITION:	eburland Farm, Altarnun Generally unsatisfactory with major localised problems
DESIGNATION: RINCIPAL VULNERABILITY:	linear boundaries and medieval settlement	on Fox Tor and Tr	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	linear boundaries and medieval settlement Scheduled Monument (No. 1008245) Scrub / tree growth	ON FOX TOT and Tr CONDITION: TREND:	eburland Farm, Altarnun Generally unsatisfactory with major localised problems
DESIGNATION: RINCIPAL VULNERABILITY:	linear boundaries and medieval settlement Scheduled Monument (No. 1008245) Scrub / tree growth	ON Fox Tor and Tr CONDITION: TREND: CONTACT: rcle settlement w	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245) Scrub / tree growth Private Prehistoric irregular field system and hut ci	ON Fox Tor and Tr CONDITION: TREND: CONTACT: rcle settlement w	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst un Generally unsatisfactory
DESIGNATION: RINCIPAL VULNERABILITY: WWNER TYPE: ITE NAME:	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245)         Scrub / tree growth         Private         Prehistoric irregular field system and hut ci and deserted settlement south east of Tres         Scheduled Monument (No. 1007776)	CONDITION: TREND: CONTACT: rcle settlement w ibbet Farm, Altarr	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst un Generally unsatisfactory with major localised problems
ESIGNATION: RINCIPAL VULNERABILITY: WINER TYPE: TE NAME: ESIGNATION:	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245)         Scrub / tree growth         Private         Prehistoric irregular field system and hut ci and deserted settlement south east of Tres         Scheduled Monument (No. 1007776)         Scrub / tree growth	CONDITION: TREND: CONTACT: rcle settlement w ibbet Farm, Altarr	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst un Generally unsatisfactory with major localised problems Improving
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245)         Scrub / tree growth         Private         Prehistoric irregular field system and hut ci and deserted settlement south east of Tres         Scheduled Monument (No. 1007776)	ON Fox Tor and Tr CONDITION: TREND: CONTACT: rcle settlement w ibbet Farm, Altarn CONDITION:	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst un Generally unsatisfactory with major localised problems
DESIGNATION: 'RINCIPAL VULNERABILITY: DWNER TYPE:	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245)         Scrub / tree growth         Private         Prehistoric irregular field system and hut ci and deserted settlement south east of Tres         Scheduled Monument (No. 1007776)         Scrub / tree growth	ON Fox Tor and Tr CONDITION: TREND: CONTACT: rcle settlement w ibbet Farm, Altarn CONDITION: TREND: CONTACT:	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst nun Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE:	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245)         Scrub / tree growth         Private         Prehistoric irregular field system and hut ci and deserted settlement south east of Tres         Scheduled Monument (No. 1007776)         Scrub / tree growth         Private	ON Fox Tor and Tr CONDITION: TREND: CONTACT: rcle settlement w ibbet Farm, Altarn CONDITION: TREND: CONTACT:	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst un Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: DESIGNATION:	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245)         Scrub / tree growth         Private         Prehistoric irregular field system and hut ci and deserted settlement south east of Tres         Scheduled Monument (No. 1007776)         Scrub / tree growth         Private         Prehistoric stone alignment Ikm SSE of East	on Fox Tor and Tr CONDITION: TREND: CONTACT: rcle settlement w ibbet Farm, Altarn CONDITION: TREND: CONTACT: tmoorgate, Altarn	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst nun Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700 un Generally unsatisfactory
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE: DITE NAME:	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245)         Scrub / tree growth         Private         Prehistoric irregular field system and hut ci and deserted settlement south east of Tres         Scheduled Monument (No. 1007776)         Scrub / tree growth         Private         Prehistoric stone alignment Ikm SSE of East         Scheduled Monument (No. 1012228)	In Fox Tor and Tr CONDITION: TREND: CONTACT: Trele settlement wibbet Farm, Altarn CONDITION: TREND: CONTACT: TREND: CONTACT:	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst un Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700 un Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPA	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245)         Scrub / tree growth         Private         Prehistoric irregular field system and hut ci and deserted settlement south east of Tres         Scheduled Monument (No. 1007776)         Scrub / tree growth         Private         Prehistoric stone alignment Ikm SSE of East         Scheduled Monument (No. 1012228)         Moderate stock erosion	on Fox Tor and Tr CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION:	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst ith adjacent medieval regular field syst ith major localised problems Improving Business Manager 0117 975 0700 un Generally unsatisfactory with major localised problems Stable
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPA	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245)         Scrub / tree growth         Private         Prehistoric irregular field system and hut ci and deserted settlement south east of Tres         Scheduled Monument (No. 1007776)         Scrub / tree growth         Private         Prehistoric stone alignment Ikm SSE of East         Scheduled Monument (No. 1012228)         Moderate stock erosion	In Fox Tor and Tr CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONTACT:	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst mu Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700 un Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 regular field systems,
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245)         Scrub / tree growth         Private         Prehistoric irregular field system and hut ci and deserted settlement south east of Tres         Scheduled Monument (No. 1007776)         Scrub / tree growth         Private         Prehistoric stone alignment Ikm SSE of East         Scheduled Monument (No. 1012228)         Moderate stock erosion         Private	In Fox Tor and Tr CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONTACT:	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst mu Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700 un Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 regular field systems,
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE	linear boundaries and medieval settlement of Scheduled Monument (No. 1008245)         Scrub / tree growth         Private         Prehistoric irregular field system and hut ci and deserted settlement south east of Tres         Scheduled Monument (No. 1007776)         Scrub / tree growth         Private         Prehistoric stone alignment Ikm SSE of East         Scheduled Monument (No. 1012228)         Moderate stock erosion         Private         Two adjacent prehistoric coaxial field system	on Fox Tor and Tr CONDITION: TREND: CONTACT: CONTACT: TREND: CONDITION: TREND: CONTACT: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONTACT:	eburland Farm, Altarnun Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ith adjacent medieval regular field syst nun Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700 un Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 regular field systems, d Ridge, Altarnun Generally unsatisfactory

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Hut circle group and enclosure north east o	of Carwen, Blislan	d
DESIGNATION:	Scheduled Monument (No. 1004659)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Castle Pencaire hillfort, two rounds and a fi	ield system, Tregor	nning Hill, Breage
DESIGNATION:	Scheduled Monument (No. 1007293)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of round barrows south east of Mid	dle Taphouse, Broa	adoak
DESIGNATION:	Scheduled Monument (No. 1004433)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
5ITE NAME:	Group of round barrows south of Penadlak	e, Broadoak	
DESIGNATION:	Scheduled Monument (No. 1004436)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow 310yds (280m) south of Kilr	nansag, Broadoak	
DESIGNATION:	Scheduled Monument (No. 1004434)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrows west of West Taphouse, Bro	oadoak	
	Round barrows west of West Taphouse, Bro Scheduled Monument (No. 1004617)	condition:	Generally satisfactory
DESIGNATION:	Scheduled Monument (No. 1004617)	CONDITION:	but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	•		but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004617) Arable clipping	CONDITION: TREND:	but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1004617) Arable clipping Private Two round barrows north west of Middle T	CONDITION: TREND: CONTACT:	k
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No. 1004617) Arable clipping Private Two round barrows north west of Middle T Scheduled Monument (No. 1003077)	CONDITION: TREND: CONTACT:	k Extensive significant problems i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1004617) Arable clipping Private Two round barrows north west of Middle T Scheduled Monument (No. 1003077) Arable ploughing	CONDITION: TREND: CONTACT: Taphouse, Broadoa	k Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004617) Arable clipping Private Two round barrows north west of Middle T Scheduled Monument (No. 1003077)	CONDITION: TREND: CONTACT: Taphouse, Broadoa CONDITION:	k Extensive significant problems i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1004617) Arable clipping Private Two round barrows north west of Middle T Scheduled Monument (No. 1003077) Arable ploughing	CONDITION: TREND: CONTACT: Taphouse, Broadoa CONDITION: TREND: CONTACT:	k Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1004617) Arable clipping Private Two round barrows north west of Middle T Scheduled Monument (No. 1003077) Arable ploughing Private	CONDITION: TREND: CONTACT: Taphouse, Broadoa CONDITION: TREND: CONTACT:	k Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1004617)         Arable clipping         Private         Two round barrows north west of Middle T         Scheduled Monument (No. 1003077)         Arable ploughing         Private         Okeltor 19th century arsenic, copper and time	CONDITION: TREND: CONTACT: Taphouse, Broadoa CONDITION: TREND: CONTACT: in mine, Calstock	but with significant localised problems Declining Business Manager 0117 975 0700 k Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally satisfactory

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Tamar Canal, Gunnislake, Calstock		
DESIGNATION:	Scheduled Monument (No. 1007302)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ownextite.	Thrace	CONIACI.	
SITE NAME:	Carvannel cliff castle, Camborne		
DESIGNATION:	Scheduled Monument (No. 1004390)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of round barrows north of Grey Ma	re Lodge, Cardinł	nam
DESIGNATION:	Scheduled Monument (No. 1003080)	CONDITION:	Generally satisfactory
	Ample clippis -		but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	St Bellarmin's Chapel, Cardinham		
DESIGNATION:	Scheduled Monument (No. 1004442)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Trezance Holy Well and chapel enclosure, C	ardinham	
	Trezance Holy Well and chapel enclosure, C Scheduled Monument (No. 1018494)	ardinham	Generally satisfactory
	· ·		Generally satisfactory but with significant localised problems
DESIGNATION:	· ·		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018494)	CONDITION:	but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018494) Scrub / tree growth	CONDITION: TREND:	but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1018494) Scrub / tree growth Private Carn Brea Castle, Carn Brea	CONDITION: TREND:	but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1018494) Scrub / tree growth Private	CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: GITE NAME: DESIGNATION:	Scheduled Monument (No. 1018494) Scrub / tree growth Private Carn Brea Castle, Carn Brea Scheduled Monument (No. 1006704)	CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018494) Scrub / tree growth Private Carn Brea Castle, Carn Brea	CONDITION: TREND: CONTACT: CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1018494)         Scrub / tree growth         Private         Carn Brea Castle, Carn Brea         Scheduled Monument (No. 1006704)         Scrub / tree growth         Local Authority	CONDITION: TREND: CONTACT: CONDITION: TREND:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Stable
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No. 1018494) Scrub / tree growth Private Carn Brea Castle, Carn Brea Scheduled Monument (No. 1006704) Scrub / tree growth Local Authority Wheal Busy, Chacewater	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No. 1018494)         Scrub / tree growth         Private         Carn Brea Castle, Carn Brea         Scheduled Monument (No. 1006704)         Scrub / tree growth         Local Authority         Wheal Busy, Chacewater         Scheduled Monument (No. 1021392)	CONDITION: TREND: CONTACT: CONDITION: TREND:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: OWNER TYPE: SITE NAME: DESIGNATION: DESIGNATION:	Scheduled Monument (No. 1018494) Scrub / tree growth Private Carn Brea Castle, Carn Brea Scheduled Monument (No. 1006704) Scrub / tree growth Local Authority Wheal Busy, Chacewater Scheduled Monument (No. 1021392) Deterioration – in need of management	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018494)         Scrub / tree growth         Private         Carn Brea Castle, Carn Brea         Scheduled Monument (No. 1006704)         Scrub / tree growth         Local Authority         Wheal Busy, Chacewater         Scheduled Monument (No. 1021392)	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018494) Scrub / tree growth Private Carn Brea Castle, Carn Brea Scheduled Monument (No. 1006704) Scrub / tree growth Local Authority Wheal Busy, Chacewater Scheduled Monument (No. 1021392) Deterioration – in need of management	CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1018494) Scrub / tree growth Private Carn Brea Castle, Carn Brea Scheduled Monument (No. 1006704) Scrub / tree growth Local Authority Wheal Busy, Chacewater Wheal Busy, Chacewater Scheduled Monument (No. 1021392) Deterioration – in need of management Private Melangoose camp, Colan	CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1018494)         Scrub / tree growth         Private         Carn Brea Castle, Carn Brea         Scheduled Monument (No. 1006704)         Scrub / tree growth         Local Authority         Wheal Busy, Chacewater         Scheduled Monument (No. 1021392)         Deterioration – in need of management         Private	CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018494) Scrub / tree growth Private Carn Brea Castle, Carn Brea Scheduled Monument (No. 1006704) Scrub / tree growth Local Authority Wheal Busy, Chacewater Wheal Busy, Chacewater Scheduled Monument (No. 1021392) Deterioration – in need of management Private Melangoose camp, Colan	CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Round 300yds (270m) WSW of High Cross,	Constantine	
DESIGNATION:	Scheduled Monument (No. 1004270)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
Swinextife.	Thrace	CONTACT.	
SITE NAME:	Killibury Castle later Prehistoric hillfort, Eglo	oshayle	
DESIGNATION:	Scheduled Monument (No. 1010439)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Tregeare camp, Egloskerry		
DESIGNATION:	Scheduled Monument (No. 1006711)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Jewish and Congregationalist cemeteries at l	Ponsharden, Falm	outh
DESIGNATION:	Scheduled Monument (No. 1020815)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow I20m south east of Parkwoo	d Hill, Feock	
DESIGNATION:	Scheduled Monument (No. 1019087)	CONDITION:	Generally satisfactory
		Contoniona	but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cliff castle west of Gunwalloe Church, Gunv	valloe	
	Cliff castle west of Gunwalloe Church, Gunv Scheduled Monument (No. 1004265)		Generally satisfactory
	Scheduled Monument (No. 1004265)		but with significant localised problems
DESIGNATION:	Scheduled Monument (No. 1004265) Coastal erosion		but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004265)	CONDITION:	but with significant localised problems
designation: Principal Vulnerability: Owner Type:	Scheduled Monument (No. 1004265) Coastal erosion	CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: 5ITE NAME:	Scheduled Monument (No. 1004265) Coastal erosion Private	CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1004265) Coastal erosion Private Rectangular camp south west of Trevarnon I Scheduled Monument (No. 1004468)	CONDITION: TREND: CONTACT: Round, Gwinear-G	but with significant localised problems Declining Business Manager 0117 975 0700 Gwithian Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004265) Coastal erosion Private Rectangular camp south west of Trevarnon I	CONDITION: TREND: CONTACT: Round, Gwinear-( CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 Gwithian Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004265) Coastal erosion Private Rectangular camp south west of Trevarnon I Scheduled Monument (No. 1004468) Arable ploughing	CONDITION: TREND: CONTACT: Round, Gwinear-( CONDITION: TREND:	but with significant localised problems Declining Business Manager 0117 975 0700 Gwithian Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1004265) Coastal erosion Private Rectangular camp south west of Trevarnon I Scheduled Monument (No. 1004468) Arable ploughing	CONDITION: TREND: CONTACT: Round, Gwinear-4 CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 Gwithian Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1004265) Coastal erosion Private Rectangular camp south west of Trevarnon I Scheduled Monument (No. 1004468) Arable ploughing Private	CONDITION: TREND: CONTACT: Round, Gwinear-4 CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 Gwithian Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1004265)         Coastal erosion         Private         Rectangular camp south west of Trevarnon I         Scheduled Monument (No. 1004468)         Arable ploughing         Private         Round near Lower Nanterrow, Gwinear-Gw         Scheduled Monument (No. 1007303)	CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 Gwithian Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1004265)         Coastal erosion         Private         Rectangular camp south west of Trevarnon I         Scheduled Monument (No. 1004468)         Arable ploughing         Private         Round near Lower Nanterrow, Gwinear-Gw	CONDITION: TREND: CONTACT: Round, Gwinear-4 CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 Gwithian Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Trevarnon Round, Gwithian, Gwinear-Gwith	lian	
DESIGNATION:	Scheduled Monument (No. 1006696)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Castle Kayle (earthwork), Phillack, Hayle		
DESIGNATION:	Scheduled Monument (No. 1006688)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	'Headon Barrow' near Headon Cross, Jacob	stow	
DESIGNATION:	Scheduled Monument (No. 1005434)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round 200m north west of Penventinnie, Ke	enwyn	
DESIGNATION:	Scheduled Monument (No. 1016063)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Camp north east of Northcott Park Quarry	y, Kilkhampton	
DESIGNATION:	Scheduled Monument (No. 1004382)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
	Plant growth Local Authority	TREND: CONTACT:	Declining Business Manager 0117 975 0700
OWNER TYPE:	-	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
DWNER TYPE:	Local Authority Group of four round barrows east of Bottal	contact: borough, Kilkham	Business Manager 0117 975 0700 pton Generally satisfactory
DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Local Authority Group of four round barrows east of Bottal Scheduled Monument (No. 1004402)	CONTACT: borough, Kilkham CONDITION:	Business Manager 0117 975 0700 pton Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Local Authority Group of four round barrows east of Bottal Scheduled Monument (No. 1004402) Arable ploughing	CONTACT: borough, Kilkham CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 pton Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700
DWNER TYPE:	Local Authority Group of four round barrows east of Bottal Scheduled Monument (No. 1004402) Arable ploughing Private	CONTACT: borough, Kilkham CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 pton Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 adock Generally satisfactory
DWNER TYPE:	Local Authority Group of four round barrows east of Bottal Scheduled Monument (No. 1004402) Arable ploughing Private Five bowl barrows 480m and 510m north of Scheduled Monument (No. 1019021)	CONTACT: borough, Kilkham CONDITION: TREND: CONTACT: of Hendra Farm, Li	Business Manager 0117 975 0700 pton Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 adock
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Local Authority Group of four round barrows east of Bottal Scheduled Monument (No. 1004402) Arable ploughing Private Five bowl barrows 480m and 510m north o	CONTACT: borough, Kilkham CONDITION: TREND: CONTACT: of Hendra Farm, La CONDITION:	Business Manager 0117 975 0700  pton Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700  adock Generally satisfactory but with significant localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Local Authority Group of four round barrows east of Bottal Scheduled Monument (No. 1004402) Arable ploughing Private Five bowl barrows 480m and 510m north of Scheduled Monument (No. 1019021) Scrub / tree growth	CONTACT: borough, Kilkham CONDITION: TREND: CONTACT: of Hendra Farm, La CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700  pton  Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700  adock  Generally satisfactory but with significant localised problems Stable
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Local Authority Group of four round barrows east of Bottal Scheduled Monument (No. 1004402) Arable ploughing Private Five bowl barrows 480m and 510m north o Scheduled Monument (No. 1019021) Scrub / tree growth Private	CONTACT: borough, Kilkham CONDITION: TREND: CONTACT: of Hendra Farm, La CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700  pton  Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700  adock  Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700  Generally unsatisfactory
OWNER TYPE:	Local Authority Group of four round barrows east of Bottal Scheduled Monument (No. 1004402) Arable ploughing Private Five bowl barrows 480m and 510m north of Scheduled Monument (No. 1019021) Scrub / tree growth Private Round 390m south west of Trethurffe, Lado	CONTACT: borough, Kilkham CONDITION: TREND: CONTACT: of Hendra Farm, Li CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700  pton  Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700  adock  Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Round and annexe 720m WSW of Tregear,	Ladock	
DESIGNATION:	Scheduled Monument (No. 1020179)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Neolithic settlement and hut circle on Helr	nan Tor, Lanlivery	
DESIGNATION:	Scheduled Monument (No. 1007306)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Giants Hedge, Lerryn to Lanreath, Lanreath	I	
DESIGNATION:	Scheduled Monument (No. 1006681)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Mabel Barrow, Lansallos		
DESIGNATION:	Scheduled Monument (No. 1006683)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Earlier Prehistoric hillfort, two cairns, medie		
	hut circles and transhumance huts on Stow	e's Hill, Linkinhorr	ne
DESIGNATION:	hut circles and transhumance huts on Stow	e's Hill, Linkinhorr	Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY:	hut circles and transhumance huts on Stow Scheduled Monument (No. 1012352)	e's Hill, Linkinhori condition:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE:	hut circles and transhumance huts on Stow Scheduled Monument (No. 1012352) Plant growth	e's Hill, Linkinhorr condition: trend: contact:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME:	hut circles and transhumance huts on Stow Scheduled Monument (No. 1012352) Plant growth Private	e's Hill, Linkinhorr condition: trend: contact:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION:	hut circles and transhumance huts on Stow         Scheduled Monument (No. 1012352)         Plant growth         Private         Early medieval transhumance hut 740m west	e's Hill, Linkinhorr CONDITION: TREND: CONTACT: st of Blackcoombe	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Farm, Linkinhorne Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	hut circles and transhumance huts on Stow         Scheduled Monument (No. 1012352)         Plant growth         Private         Early medieval transhumance hut 740m west         Scheduled Monument (No. 1011899)	e's Hill, Linkinhorr Condition: TREND: CONTACT: st of Blackcoombe CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Farm, Linkinhorne Generally unsatisfactory with major localised problems
SITE NAME:	hut circles and transhumance huts on Stow         Scheduled Monument (No. 1012352)         Plant growth         Private         Early medieval transhumance hut 740m west         Scheduled Monument (No. 1011899)         Plant growth	e's Hill, Linkinhorr CONDITION: TREND: CONTACT: st of Blackcoombe CONDITION: TREND: CONTACT: mines with medie	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Farm, Linkinhorne Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE: DITE NAME:	hut circles and transhumance huts on Stow         Scheduled Monument (No. 1012352)         Plant growth         Private         Early medieval transhumance hut 740m west         Scheduled Monument (No. 1011899)         Plant growth         Private         Medieval and post-medieval tin and copper	e's Hill, Linkinhorr CONDITION: TREND: CONTACT: st of Blackcoombe CONDITION: TREND: CONTACT: mines with medie	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Farm, Linkinhorne Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: DESIGNATION:	hut circles and transhumance huts on Stow         Scheduled Monument (No. 1012352)         Plant growth         Private         Early medieval transhumance hut 740m west         Scheduled Monument (No. 1011899)         Plant growth         Private         Medieval and post-medieval tin and copper on the middle and lower northern slopes of	e's Hill, Linkinhorr CONDITION: TREND: CONTACT: st of Blackcoombe CONDITION: TREND: CONTACT: mines with medie f Caradon Hill, Lin	e       Generally satisfactory         but with significant localised problems         Declining         Business Manager 0117 975 0700         e         Farm, Linkinhorne         Generally unsatisfactory         with major localised problems         Declining         Business Manager 0117 975 0700         eval field system         kinhorne         Generally satisfactory
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: RITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DESIGNATION: RINCIPAL VULNERABILITY: RINCIPAL VULNERABILITY:	hut circles and transhumance huts on Stow         Scheduled Monument (No. 1012352)         Plant growth         Private         Early medieval transhumance hut 740m west         Scheduled Monument (No. 1011899)         Plant growth         Private         Medieval and post-medieval tin and copper on the middle and lower northern slopes of Scheduled Monument (No. 1020942)	e's Hill, Linkinhorr CONDITION: TREND: CONTACT: t of Blackcoombe CONDITION: TREND: CONTACT: mines with medie of Caradon Hill, Lin CONDITION:	Generally satisfactory         but with significant localised problems         Declining         Business Manager 0117 975 0700         E Farm, Linkinhorne         Generally unsatisfactory         with major localised problems         Declining         Business Manager 0117 975 0700         Eval field system         nkinhorne         Generally satisfactory         but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: DWINER TYPE: D	hut circles and transhumance huts on Stow         Scheduled Monument (No. 1012352)         Plant growth         Private         Early medieval transhumance hut 740m west         Scheduled Monument (No. 1011899)         Plant growth         Private         Medieval and post-medieval tin and copper on the middle and lower northern slopes of Scheduled Monument (No. 1020942)         Plant growth	e's Hill, Linkinhorr CONDITION: TREND: CONTACT: St of Blackcoombe CONDITION: TREND: CONTACT: mines with medie of Caradon Hill, Lin CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: CONDITION: TREND: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Farm, Linkinhorne Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 eval field system hkinhorne Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 te field systems,
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE	hut circles and transhumance huts on Stow         Scheduled Monument (No. 1012352)         Plant growth         Private         Early medieval transhumance hut 740m west         Scheduled Monument (No. 1011899)         Plant growth         Private         Medieval and post-medieval tin and copper on the middle and lower northern slopes of Scheduled Monument (No. 1020942)         Plant growth         Private         Medieval and post-medieval tin and copper on the middle and lower northern slopes of Scheduled Monument (No. 1020942)         Plant growth         Private         Neolithic long cairn, Prehistoric regular and	e's Hill, Linkinhorr CONDITION: TREND: CONTACT: St of Blackcoombe CONDITION: TREND: CONTACT: mines with medie of Caradon Hill, Lin CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: CONDITION: TREND: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Farm, Linkinhorne Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 eval field system hkinhorne Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 te field systems,
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: DWNER TYPE: DITE NAME:	hut circles and transhumance huts on Stow         Scheduled Monument (No. 1012352)         Plant growth         Private         Early medieval transhumance hut 740m west         Scheduled Monument (No. 1011899)         Plant growth         Private         Medieval and post-medieval tin and copper on the middle and lower northern slopes of Scheduled Monument (No. 1020942)         Plant growth         Private         Neolithic long cairn, Prehistoric regular and linear boundaries and medieval enclosure 6	e's Hill, Linkinhorr CONDITION: TREND: CONTACT: st of Blackcoombe CONDITION: TREND: CONTACT: mines with medie f Caradon Hill, Lin CONDITION: TREND: CONTACT:	Generally satisfactory         but with significant localised problems         Declining         Business Manager 0117 975 0700         E Farm, Linkinhorne         Generally unsatisfactory         with major localised problems         Declining         Business Manager 0117 975 0700         Eval field system         nkinhorne         Generally satisfactory         but with significant localised problems         Declining         Business Manager 0117 975 0700         Eval field system         nkinhorne         Generally satisfactory         but with significant localised problems         Declining         Business Manager 0117 975 0700         Et field systems, kcoombe Farm, Linkinhorne         Generally unsatisfactory

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Prehistoric funerary cist 1.275km north wes	st of Wardbrook I	Farm, Linkinhorne	
DESIGNATION:	Scheduled Monument (No. 1012043)	CONDITION:	Generally unsatisfactory with major localised problems	
RINCIPAL VULNERABILITY:	Flooding	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Prehistoric linear boundaries, cairn and enc	losure I.225km no	orth west of Wardbrook Farm, Linkinhorn	
DESIGNATION:	Scheduled Monument (No. 1008982)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
TE NAME:	Prehistoric linear boundary and field system, medieval enclosure and tin miners' caches I.06km north west of Wardbrook Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 1015975)	CONDITION:	Generally satisfactory but with significant localised problems	
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
TE NAME:	Prehistoric round cairn on Caradon Hill, 31	0m west of Heath	ner House, Linkinhorne	
DESIGNATION:	Scheduled Monument (No. 1020939)	CONDITION:	Generally satisfactory but with significant localised problems	
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
DITE NAME:	Prehistoric unenclosed hut circle settlement incorporating a medieval tin miners' cache and medieval shelter I.285km north west of Wardbrook Farm, Linkinhorne			
DESIGNATION:	Scheduled Monument (No. 1008848)	CONDITION	Generally satisfactory	
	Scheduled Flohument (140. 10000-0)	CONDITION:	but with minor localised problems	
	Plant growth	TREND:	but with minor localised problems Stable	
RINCIPAL VULNERABILITY:			but with minor localised problems	
RINCIPAL VULNERABILITY: DWNER TYPE:	Plant growth	TREND: CONTACT:	but with minor localised problems Stable Business Manager 0117 975 0700	
RINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION:	Plant growth Private	TREND: CONTACT:	but with minor localised problems Stable Business Manager 0117 975 0700	
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION:	Plant growth Private Round cairn 580m north west of Wardbrod	trend: contact: ok Farm, Linkinhoi	but with minor localised problems Stable Business Manager 0117 975 0700 The Generally satisfactory	
RINCIPAL VULNERABILITY: WINER TYPE ITE NAME: PESIGNATION: RINCIPAL VULNERABILITY:	Plant growth Private Round cairn 580m north west of Wardbrood Scheduled Monument (No. 1009737)	trend: contact: ok Farm, Linkinhoi condition:	but with minor localised problems Stable Business Manager 0117 975 0700	
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Plant growth Private Round cairn 580m north west of Wardbrood Scheduled Monument (No. 1009737) Plant growth	TREND: CONTACT: ok Farm, Linkinhon CONDITION: TREND: CONTACT:	but with minor localised problems Stable Business Manager 0117 975 0700	
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Plant growth Private Round cairn 580m north west of Wardbrood Scheduled Monument (No. 1009737) Plant growth Private	TREND: CONTACT: ok Farm, Linkinhon CONDITION: TREND: CONTACT:	but with minor localised problems Stable Business Manager 0117 975 0700	
RINCIPAL VULNERABILITY: WINER TYPE TTE NAME: PESIGNATION: WINER TYPE: TTE NAME: PESIGNATION: PES	Plant growth Private Round cairn 580m north west of Wardbrood Scheduled Monument (No. 1009737) Plant growth Private Round cairn 775m north west of Wardbrood	TREND: CONTACT: OK Farm, Linkinhoo CONDITION: TREND: CONTACT: OK Farm, Linkinhoo	but with minor localised problems Stable Business Manager 0117 975 0700 me Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 me Generally satisfactory	
RINCIPAL VULNERABILITY: WINER TYPE ITE NAME: ESIGNATION: WINER TYPE ITE NAME: ESIGNATION: RINCIPAL VULNERABILITY: RINCIPAL VULNERABILITY: RINCIPAL VULNERABILITY:	Plant growth         Private         Round cairn 580m north west of Wardbrood         Scheduled Monument (No. 1009737)         Plant growth         Private         Round cairn 775m north west of Wardbrood         Scheduled Monument (No. 1010308)	TREND: CONTACT: OK Farm, Linkinhon CONDITION: TREND: CONTACT: OK Farm, Linkinhon	but with minor localised problems Stable Business Manager 0117 975 0700 me Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 me Generally satisfactory but with minor localised problems	
RINCIPAL VULNERABILITY: PWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DWNER TY	Plant growth         Private         Round cairn 580m north west of Wardbrood         Scheduled Monument (No. 1009737)         Plant growth         Private         Round cairn 775m north west of Wardbrood         Scheduled Monument (No. 1010308)         Plant growth	TREND: CONTACT: OK Farm, Linkinhon TREND: CONTACT: OK Farm, Linkinhon CONDITION: TREND: CONDITION:	but with minor localised problems Stable Business Manager 0117 975 0700 me Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 me Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700	
PRINCIPAL VULNERABILITY: DWNER TYPE: JITE NAME:	Plant growth         Private         Round cairn 580m north west of Wardbrood         Scheduled Monument (No. 1009737)         Plant growth         Private         Round cairn 775m north west of Wardbrood         Scheduled Monument (No. 1010308)         Plant growth         Private	TREND: CONTACT: OK Farm, Linkinhon TREND: CONTACT: OK Farm, Linkinhon CONDITION: TREND: CONDITION:	but with minor localised problems Stable Business Manager 0117 975 0700 me Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 me Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700	
PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE: DWNER TYPE: DWNER TYPE: DWNER TYPE: DWNER TYPE:	Plant growth         Private         Round cairn 580m north west of Wardbrood         Scheduled Monument (No. 1009737)         Plant growth         Private         Round cairn 775m north west of Wardbrood         Scheduled Monument (No. 1010308)         Plant growth         Private         Round cairn 775m north west of Wardbrood         Scheduled Monument (No. 1010308)         Plant growth         Private         Round cairn with central cist on Bearah Comparison	TREND: CONTACT: OK Farm, Linkinhoo CONDITION: TREND: CONTACT: OK Farm, Linkinhoo CONDITION: TREND: CONTACT:	but with minor localised problems Stable Business Manager 0117 975 0700 me Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 me Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 morth of Wardbrook Farm, Linkinhorne Generally satisfactory	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### ABBREVIATIONS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Stone hut circle 812m north west of Ward	brook Farm, Linki	nhorne
DESIGNATION:	Scheduled Monument (No. 1009739)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two adjacent transhumance huts on Carado	on Hill, 450m nor	th of East Caradon Farm, Linkinhorne
DESIGNATION:	Scheduled Monument (No. 1011900)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round 450yds (405m) north west of Lower	r Chellew Farm, L	udgvan
DESIGNATION:	Scheduled Monument (No. 1004262)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Ancient village and fields at Boswarva Carn	, Madron	
DESIGNATION:	Scheduled Monument (No. 1004466)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Barrow 800yds (730m) WNW of Boswens	Farm, Madron	
DESIGNATION:	Scheduled Monument (No. 1004286)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bosullow Trehyllys (hut circles), Madron		
DESIGNATION:	Scheduled Monument (No. 1006697)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Chun Downs prehistoric landscape comple Chun Castle, and barrow 200yds (180m) sc		
DESIGNATION:	Scheduled Monument (No. 1007264)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Courtyard house 200yds (180m) NNE of T	ry Farm, Madron	
	Scheduled Monument (No. 1004352)	CONDITION:	Generally satisfactory
DESIGNATION:			but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	but with significant localised problems Stable

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Courtyard house 300yds (270m) north wes	st of Middle Carna	aquidden, Madron
DESIGNATION:	Scheduled Monument (No. 1004353)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Courtyard houses north east of Newmill, M	1adron	
DESIGNATION:	Scheduled Monument (No. 1004356)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hut circles with associated field system 400	)yds (360m) south	n west of Little Higher Bosullow, Madror
DESIGNATION:	Scheduled Monument (No. 1004316)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round 300yds (270m) north east of Newm	ill, Madron	
DESIGNATION:	Scheduled Monument (No. 1004627)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow 530yds (480m) north west o	of Nancothan Cot	tages, Madron
SITE NAME: DESIGNATION:	Round barrow 530yds (480m) north west of Scheduled Monument (No. 1004311)	of Nancothan Cot	tages, Madron Extensive significant problems i.e. under plough, collapse
	, , <i>,</i>		Extensive significant problems
DESIGNATION:	Scheduled Monument (No. 1004311)	CONDITION:	Extensive significant problems i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004311) Arable ploughing	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1004311) Arable ploughing Private	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 en, Madron Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1004311) Arable ploughing Private Settlement 450yds (400m) north west of M	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004311) Arable ploughing Private Settlement 450yds (400m) north west of M Scheduled Monument (No. 1003100)	CONDITION: TREND: CONTACT: Iiddle Carnaquidd CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 en, Madron Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1004311) Arable ploughing Private Settlement 450yds (400m) north west of M Scheduled Monument (No. 1003100) Scrub / tree growth	CONDITION: TREND: CONTACT: iddle Carnaquidd CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 en, Madron Generally unsatisfactory with major localised problems Stable
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1004311)         Arable ploughing         Private         Settlement 450yds (400m) north west of M         Scheduled Monument (No. 1003100)         Scrub / tree growth         Private	CONDITION: TREND: CONTACT: iddle Carnaquidd CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 en, Madron Generally unsatisfactory with major localised problems Stable
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1004311) Arable ploughing Private Settlement 450yds (400m) north west of M Scheduled Monument (No. 1003100) Scrub / tree growth Private Cawsand Fort, Maker-with-Rame	CONDITION: TREND: CONTACT: Idddle Carnaquidd CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 en, Madron Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1004311)         Arable ploughing         Private         Settlement 450yds (400m) north west of M         Scheduled Monument (No. 1003100)         Scrub / tree growth         Private         Cawsand Fort, Maker-with-Rame         Scheduled Monument (No. 1016102)	CONDITION: TREND: CONTACT: Idddle Carnaquidd CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 en, Madron Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004311)         Arable ploughing         Private         Settlement 450yds (400m) north west of M         Scheduled Monument (No. 1003100)         Scrub / tree growth         Private         Cawsand Fort, Maker-with-Rame         Scheduled Monument (No. 1016102)         Development requiring planning permission	CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 en, Madron Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1004311)         Arable ploughing         Private         Settlement 450yds (400m) north west of M         Scheduled Monument (No. 1003100)         Scrub / tree growth         Private         Cawsand Fort, Maker-with-Rame         Scheduled Monument (No. 1016102)         Development requiring planning permission         Private	CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 en, Madron Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1004311)         Arable ploughing         Private         Settlement 450yds (400m) north west of M         Scheduled Monument (No. 1003100)         Scrub / tree growth         Private         Cawsand Fort, Maker-with-Rame         Scheduled Monument (No. 1016102)         Development requiring planning permission         Private         Earthwork redoubts Nos. 1, 2 and 3, Maker-	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 en, Madron Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Grenville Battery 550yds (500m) SSW of Make	er Farm, Maker	-with-Rame
designation:	Scheduled Monument (No. 1003114)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Incomplete Palmerstonian fort 650yds (600m)	west of Forde	r, Maker-with-Rame
DESIGNATION:	Scheduled Monument (No. 1007299)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Mount Edgcumbe round barrow, Maker-with-F	Rame	
DESIGNATION:	Scheduled Monument (No. 1004496)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	No. 5 redoubt 450yds (410m) north west of N	1aker Farm, Ma	lker-with-Rame
	Scheduled Monument (No. 1004255)		Generally satisfactory
DESIGNATION:		CONDITION:	but with significant localised problems
	Development requiring planning permission	TREND:	Declining
PRINCIPAL VULNIFRABILLEY		CONCERNES.	
PRINCIPAL VULNERABILITY: OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	Private		
OWNER TYPE:	Private Mawgan Cross early Christian memorial stone	e and wayside c	ross shaft, Mawgan-in-Meneage
OWNER TYPE:	Private		rross shaft, Mawgan-in-Meneage Generally satisfactory
OWNER TYPE:	Private Mawgan Cross early Christian memorial stone Scheduled Monument (No. 1010852)	e and wayside c	ross shaft, Mawgan-in-Meneage
OWNER TYPE: SITE NAME: DESIGNATION:	Private Mawgan Cross early Christian memorial stone	e and wayside c	Generally satisfactory but with significant localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Mawgan Cross early Christian memorial stone Scheduled Monument (No. 1010852) Moderate vehicle damage/erosion Local Authority	e and wayside c CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private Mawgan Cross early Christian memorial stone Scheduled Monument (No. 1010852) Moderate vehicle damage/erosion Local Authority Round barrow 500yds (460m) west of Trevass	e and wayside c CONDITION: TREND: CONTACT: sack, Mawgan-in	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Mawgan Cross early Christian memorial stone Scheduled Monument (No. 1010852) Moderate vehicle damage/erosion Local Authority	e and wayside c CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 
OWNER TYPE:	Private Mawgan Cross early Christian memorial stone Scheduled Monument (No. 1010852) Moderate vehicle damage/erosion Local Authority Round barrow 500yds (460m) west of Trevass Scheduled Monument (No. 1004499)	e and wayside c CONDITION: TREND: CONTACT: sack, Mawgan-in CONDITION:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Meneage Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Mawgan Cross early Christian memorial stone Scheduled Monument (No. 1010852) Moderate vehicle damage/erosion Local Authority Round barrow 500yds (460m) west of Trevass	e and wayside c CONDITION: TREND: CONTACT: sack, Mawgan-in	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Meneage Generally unsatisfactory with major localised problems Declining
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Mawgan Cross early Christian memorial stone Scheduled Monument (No. 1010852) Moderate vehicle damage/erosion Local Authority Round barrow 500yds (460m) west of Trevass Scheduled Monument (No. 1004499) Permitted development	e and wayside c CONDITION: TREND: CONTACT: sack, Mawgan-in CONDITION: TREND:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Meneage Generally unsatisfactory with major localised problems
OWNER TYPE:	Private Mawgan Cross early Christian memorial stone Scheduled Monument (No. 1010852) Moderate vehicle damage/erosion Local Authority Round barrow 500yds (460m) west of Trevass Scheduled Monument (No. 1004499) Permitted development Private Hillfort at Blacketon Farm, Menheniot	e and wayside c CONDITION: TREND: CONTACT: sack, Mawgan-in CONDITION: TREND:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private         Mawgan Cross early Christian memorial stone         Scheduled Monument (No. 1010852)         Moderate vehicle damage/erosion         Local Authority         Round barrow 500yds (460m) west of Trevass         Scheduled Monument (No. 1004499)         Permitted development         Private         Hillfort at Blacketon Farm, Menheniot         Scheduled Monument (No. 1007296)	e and wayside c CONDITION: TREND: CONTACT: sack, Mawgan-in CONDITION: TREND:	Fross shaft, Mawgan-in-Meneage         Generally satisfactory         but with significant localised problems         Stable         Business Manager 0117 975 0700    Heneage          Generally unsatisfactory         with major localised problems         Declining         Business Manager 0117 975 0700
OWNER TYPE:	Private         Mawgan Cross early Christian memorial stone         Scheduled Monument (No. 1010852)         Moderate vehicle damage/erosion         Local Authority         Round barrow 500yds (460m) west of Trevass         Scheduled Monument (No. 1004499)         Permitted development         Private         Hillfort at Blacketon Farm, Menheniot         Scheduled Monument (No. 1007296)         Other	e and wayside c CONDITION: TREND: CONTACT: Sack, Mawgan-in CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 
OWNER TYPE:	Private         Mawgan Cross early Christian memorial stone         Scheduled Monument (No. 1010852)         Moderate vehicle damage/erosion         Local Authority         Round barrow 500yds (460m) west of Trevass         Scheduled Monument (No. 1004499)         Permitted development         Private         Hillfort at Blacketon Farm, Menheniot         Scheduled Monument (No. 1007296)	a and wayside of condition: TREND: CONDITION: CONTACT: CONDITION: TREND: CONDITION: CONDITION:	Fross shaft, Mawgan-in-Meneage         Generally satisfactory         but with significant localised problems         Stable         Business Manager 0117 975 0700    Heneage          Generally unsatisfactory         with major localised problems         Declining         Business Manager 0117 975 0700
OWNER TYPE:	Private         Mawgan Cross early Christian memorial stone         Scheduled Monument (No. 1010852)         Moderate vehicle damage/erosion         Local Authority         Round barrow 500yds (460m) west of Trevass         Scheduled Monument (No. 1004499)         Permitted development         Private         Hillfort at Blacketon Farm, Menheniot         Scheduled Monument (No. 1007296)         Other	a and wayside of CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONDITION: CONDITION:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 
OWNER TYPE:	Private         Mawgan Cross early Christian memorial stone         Scheduled Monument (No. 1010852)         Moderate vehicle damage/erosion         Local Authority         Round barrow 500yds (460m) west of Trevass         Scheduled Monument (No. 1004499)         Permitted development         Private         Hillfort at Blacketon Farm, Menheniot         Scheduled Monument (No. 1007296)         Other         Private	a and wayside of CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONDITION: CONDITION:	ross shaft, Mawgan-in-Meneage Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 
OWNER TYPE:	Private         Mawgan Cross early Christian memorial stone         Scheduled Monument (No. 1010852)         Moderate vehicle damage/erosion         Local Authority         Round barrow 500yds (460m) west of Trevass         Scheduled Monument (No. 1004499)         Permitted development         Private         Hillfort at Blacketon Farm, Menheniot         Scheduled Monument (No. 1007296)         Other         Private         Inswork Chapel, Millbrook         Scheduled Monument (No. 1003095)	a and wayside of CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONTACT: TREND: CONDITION:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Meneage Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 
OWNER TYPE:	Private         Mawgan Cross early Christian memorial stone         Scheduled Monument (No. 1010852)         Moderate vehicle damage/erosion         Local Authority         Round barrow 500yds (460m) west of Trevass         Scheduled Monument (No. 1004499)         Permitted development         Private         Hillfort at Blacketon Farm, Menheniot         Scheduled Monument (No. 1007296)         Other         Private         Inswork Chapel, Millbrook	a and wayside of CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONTACT: TREND: CONDITION:	ross shaft, Mawgan-in-Meneage Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Croftoe British village, Morvah		
DESIGNATION:	Scheduled Monument (No. 1006740)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow on Bin Down, Morval		
DESIGNATION:	Scheduled Monument (No. 1006651)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Trevelgue promontory camp and two barro	ows, Newquay	
DESIGNATION:	Scheduled Monument (No. 1006712)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
DWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Hut circle settlement 975m north east of T	rewortha Farm, N	lorth Hill
DESIGNATION:	Scheduled Monument (No. 1009806)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Platform cairn 667m ENE of Trewortha Far	m, North Hill	
DESIGNATION:	Scheduled Monument (No. 1017846)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric co-axial and regular aggregate fi adjacent hut circle settlements on Bastreet		
DESIGNATION:	Scheduled Monument (No. 1011558)	CONDITION:	Generally unsatisfactory
JESIGINATION.	Scheddied Hondment (140. 1011350)	CONDITION.	with major localised problems
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round cairn 1.175km WSW of East Castick	Farm, North Hill	
designation:	Scheduled Monument (No. 1010412)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
DITE NAME:	Round cairn 617m ENE of Trewortha Farm	, North Hill	
DESIGNATION:	Scheduled Monument (No. 1009780)	CONDITION:	Generally unsatisfactory with major localised problems
	Scrub / tree growth	TREND:	
PRINCIPAL VULNERABILITY:	Scrub / tree growth Private	TREND: CONTACT:	Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Round cairn 800m WSW of Tolcarne Farm,	North Hill	
DESIGNATION:	Scheduled Monument (No. 1011507)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round cairn 910m WSW of Tolcarne Farm,	North Hill	
DESIGNATION:	Scheduled Monument (No. 1011508)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Round cairn with central cist I.05km east o	f Trewortha Farm	, North Hill
DESIGNATION:	Scheduled Monument (No. 1009735)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Round cairn with central cist 970m ENE of	Trewortha Farm,	North Hill
DESIGNATION:	Scheduled Monument (No. 1009734)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round cairn with double orthostatic kerb a Scheduled Monument (No. 1009688)		th east of Trewortha Farm, North Hill Generally satisfactory
SITE NAME: DESIGNATION:	Scheduled Monument (No. 1009688)	and cist 497m sou	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:		ind cist 497m sou	th east of Trewortha Farm, North Hill Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1009688) Scrub / tree growth Private	CONDITION: TREND: CONTACT:	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1009688) Scrub / tree growth Private Stone hut circle 1.225km WSW of East Case	Ind cist 497m sou CONDITION: TREND: CONTACT: tick Farm, North	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No. 1009688) Scrub / tree growth Private	CONDITION: TREND: CONTACT:	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1009688) Scrub / tree growth Private Stone hut circle 1.225km WSW of East Case Scheduled Monument (No. 1010414)	Ind cist 497m sou CONDITION: TREND: CONTACT: tick Farm, North	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1009688)         Scrub / tree growth         Private         Stone hut circle 1.225km WSW of East Case         Scheduled Monument (No. 1010414)         Scrub / tree growth	and cist 497m sou CONDITION: TREND: CONTACT: tick Farm, North I CONDITION: TREND:	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill Generally satisfactory but with significant localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1009688) Scrub / tree growth Private Stone hut circle 1.225km WSW of East Case Scheduled Monument (No. 1010414)	Ind cist 497m sou CONDITION: TREND: CONTACT: tick Farm, North	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1009688)         Scrub / tree growth         Private         Stone hut circle 1.225km WSW of East Case         Scheduled Monument (No. 1010414)         Scrub / tree growth	Ind cist 497m sou CONDITION: TREND: CONTACT: tick Farm, North I CONDITION: TREND: CONTACT: es on Bearah Tor,	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE: DWNER TYPE: DWNER TYPE:	Scheduled Monument (No. 1009688) Scrub / tree growth Private Stone hut circle 1.225km WSW of East Case Scheduled Monument (No. 1010414) Scrub / tree growth Private Three adjoining Prehistoric linear boundarie	Ind cist 497m sou CONDITION: TREND: CONTACT: tick Farm, North I CONDITION: TREND: CONTACT: es on Bearah Tor,	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill Generally satisfactory but with significant localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME: DESIGNATION: SITE NAME: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1009688)         Scrub / tree growth         Private         Stone hut circle 1.225km WSW of East Case         Scheduled Monument (No. 1010414)         Scrub / tree growth         Private         Three adjoining Prehistoric linear boundarie         687m south west of Nodmans Bowda Farm	and cist 497m sou CONDITION: TREND: CONTACT: tick Farm, North CONDITION: TREND: CONTACT: es on Bearah Tor, North Hill	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1009688)         Scrub / tree growth         Private         Stone hut circle 1.225km WSW of East Case         Scheduled Monument (No. 1010414)         Scrub / tree growth         Private         Three adjoining Prehistoric linear boundarie         687m south west of Nodmans Bowda Farm         Scheduled Monument (No. 1010220)	and cist 497m sou CONDITION: TREND: CONTACT: tick Farm, North CONDITION: TREND: CONTACT: es on Bearah Tor, North Hill CONDITION:	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1009688)         Scrub / tree growth         Private         Stone hut circle 1.225km WSW of East Case         Scheduled Monument (No. 1010414)         Scrub / tree growth         Private         Three adjoining Prehistoric linear boundarie         687m south west of Nodmans Bowda Farm         Scheduled Monument (No. 1010220)         Scrub / tree growth	and cist 497m sou CONDITION: TREND: CONTACT: tick Farm, North CONDITION: TREND: CONTACT: es on Bearah Tor, North Hill CONDITION: TREND: CONDITION:	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1009688)         Scrub / tree growth         Private         Stone hut circle 1.225km WSW of East Case         Scheduled Monument (No. 1010414)         Scrub / tree growth         Private         Three adjoining Prehistoric linear boundarie         687m south west of Nodmans Bowda Farm         Scheduled Monument (No. 1010220)         Scrub / tree growth         Private	and cist 497m sou CONDITION: TREND: CONTACT: tick Farm, North CONDITION: TREND: CONTACT: es on Bearah Tor, North Hill CONDITION: TREND: CONDITION:	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: SITE NAME:	Scheduled Monument (No. 1009688)         Scrub / tree growth         Private         Stone hut circle 1.225km WSW of East Case         Scheduled Monument (No. 1010414)         Scrub / tree growth         Private         Three adjoining Prehistoric linear boundarie         687m south west of Nodmans Bowda Farm         Scheduled Monument (No. 1010220)         Scrub / tree growth         Private         Three stone hut circles 1.06km north east of	and cist 497m sou CONDITION: TREND: CONTACT: tick Farm, North I CONDITION: TREND: CONTACT: es on Bearah Tor, North Hill CONDITION: TREND: CONDITION: TREND: CONTACT:	th east of Trewortha Farm, North Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Two stone hut circles and adjacent Prehistoric 575m west of West Berriow Farm, North Hill	boundary wal	
DESIGNATION:	Scheduled Monument (No. 1010218)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		contraction	
SITE NAME:	Unenclosed hut circle settlement and adjacent 800m SSE of Trewortha Farm, North Hill	Prehistoric lin	ear boundary
DESIGNATION:	Scheduled Monument (No. 1008958)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Unenclosed hut circle settlement with incorpc I.5km north west of Wardbrook Farm, North		re
DESIGNATION:	Scheduled Monument (No. 1008954)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Three barrows 550m ENE of Cansford, Otter	nam	
DESIGNATION:	Scheduled Monument (No. 1005463)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Roundago, hut circle and field system on Casta	ıllack Carn, Pau	ıl
DESIGNATION:	Scheduled Monument (No. 1004654)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bake Rings later prehistoric-Roman round with	n attached enc	losure and outwork, Pelynt
DESIGNATION:	Scheduled Monument (No. 1017682)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of three round barrows north of Hend	ra, Pelynt	
DESIGNATION:	Scheduled Monument (No. 1004621)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			-
SITE NAME:	Hall Rings, Pelynt		
DESIGNATION:	Scheduled Monument (No. 1006682)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing Private	TREND:	Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Ten barrows south of Wilton Mill, Pelynt		
DESIGNATION:	Scheduled Monument (No. 1004465)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	St Piran's Oratory and associated early med	dieval cemetery, Po	erranzabuloe
DESIGNATION:	Scheduled Monument (No. 1018955)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Flooding	TREND:	Declining
DWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Clapper Bridge, Quethiock		
DESIGNATION:	Scheduled Monument (No. 1004482)	CONDITION:	Generally satisfactory
	````		but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	The Tolgus arsenic works 80m south east o	f East Tolgus Hou	se, Redruth
DESIGNATION:	Scheduled Monument (No. 1021240)	CONDITION:	Generally unsatisfactory
			with major localised problems
			Declining
RINCIPAL VULNERABILITY:	Other	TREND:	Decining
PRINCIPAL VULNERABILITY: OWNER TYPE:	Other Private	TREND: CONTACT:	Business Manager 0117 975 0700
		CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Private D-Day landing craft maintenance site, I70m	contact: north of Saltash	Business Manager 0117 975 0700 Pier, Saltash
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory
DWNER TYPE:	Private D-Day landing craft maintenance site, I70m	contact: north of Saltash	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems
DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private D-Day landing craft maintenance site, 170m Scheduled Monument (No. 1020053) Moderate visitor erosion	CONTACT: north of Saltash I CONDITION:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining
OWNER TYPE:	Private D-Day landing craft maintenance site, 170m Scheduled Monument (No. 1020053)	CONTACT: north of Saltash I CONDITION: TREND:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private D-Day landing craft maintenance site, 170m Scheduled Monument (No. 1020053) Moderate visitor erosion	CONTACT: north of Saltash I CONDITION: TREND:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining
DWNER TYPE:	Private D-Day landing craft maintenance site, 170m Scheduled Monument (No. 1020053) Moderate visitor erosion Local Authority	CONTACT: north of Saltash I CONDITION: TREND:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining
DWNER TYPE:	Private D-Day landing craft maintenance site, 170m Scheduled Monument (No. 1020053) Moderate visitor erosion Local Authority Caer Bran, Sancreed	CONTACT: north of Saltash I CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DWNER TYPE:	Private D-Day landing craft maintenance site, 170m Scheduled Monument (No. 1020053) Moderate visitor erosion Local Authority Caer Bran, Sancreed	CONTACT: north of Saltash I CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
DWNER TYPE:	Private D-Day landing craft maintenance site, 170m Scheduled Monument (No. 1020053) Moderate visitor erosion Local Authority Caer Bran, Sancreed Scheduled Monument (No. 1006717)	CONTACT: north of Saltash I CONDITION: TREND: CONTACT: CONDITION:	Business Manager 0117 975 0700  Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700  Generally unsatisfactory with major localised problems
OWNER TYPE:	Private D-Day landing craft maintenance site, 170m Scheduled Monument (No. 1020053) Moderate visitor erosion Local Authority Caer Bran, Sancreed Scheduled Monument (No. 1006717) Scrub / tree growth	CONTACT: north of Saltash I CONDITION: TREND: CONTACT: TREND: CONTACT: CONTACT:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Improving
DWNER TYPE:	Private  D-Day landing craft maintenance site, 170m Scheduled Monument (No. 1020053)  Moderate visitor erosion Local Authority  Caer Bran, Sancreed Scheduled Monument (No. 1006717) Scrub / tree growth Private	CONTACT: north of Saltash I CONDITION: TREND: CONTACT: TREND: CONTACT: CONTACT:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700 Generally unsatisfactory
DWNER TYPE:	Private         D-Day landing craft maintenance site, 170m         Scheduled Monument (No. 1020053)         Moderate visitor erosion         Local Authority         Caer Bran, Sancreed         Scheduled Monument (No. 1006717)         Scrub / tree growth         Private         Field system on Boswens Common, Sancreed         Scheduled Monument (No. 1007268)	CONTACT: north of Saltash I CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Business Manager 0117 975 0700  Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700  Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700  Generally unsatisfactory with major localised problems
OWNER TYPE:	Private         D-Day landing craft maintenance site, 170m         Scheduled Monument (No. 1020053)         Moderate visitor erosion         Local Authority         Caer Bran, Sancreed         Scheduled Monument (No. 1006717)         Scrub / tree growth         Private         Field system on Boswens Common, Sancreed         Scheduled Monument (No. 1007268)         Scrub / tree growth	CONTACT: north of Saltash I CONDITION: TREND: CONTACT: TREND: CONTACT: CONTACT: CONTACT:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
OWNER TYPE:	Private         D-Day landing craft maintenance site, 170m         Scheduled Monument (No. 1020053)         Moderate visitor erosion         Local Authority         Caer Bran, Sancreed         Scheduled Monument (No. 1006717)         Scrub / tree growth         Private         Field system on Boswens Common, Sancreed         Scheduled Monument (No. 1007268)	CONTACT: NOOTH OF Saltash I CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Business Manager 0117 975 0700  Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700  Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700  Generally unsatisfactory with major localised problems
OWNER TYPE:	Private         D-Day landing craft maintenance site, 170m         Scheduled Monument (No. 1020053)         Moderate visitor erosion         Local Authority         Caer Bran, Sancreed         Scheduled Monument (No. 1006717)         Scrub / tree growth         Private         Field system on Boswens Common, Sancreed         Scheduled Monument (No. 1007268)         Scrub / tree growth	CONTACT: NOOTH OF Saltash I CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
DWNER TYPE:	Private         D-Day landing craft maintenance site, 170m         Scheduled Monument (No. 1020053)         Moderate visitor erosion         Local Authority         Caer Bran, Sancreed         Scheduled Monument (No. 1006717)         Scrub / tree growth         Private         Field system on Boswens Common, Sancreed         Scheduled Monument (No. 1007268)         Scrub / tree growth         Private	CONTACT: NOOTH OF Saltash I CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems
DWNER TYPE:	Private         D-Day landing craft maintenance site, 170m         Scheduled Monument (No. 1020053)         Moderate visitor erosion         Local Authority         Caer Bran, Sancreed         Scheduled Monument (No. 1006717)         Scrub / tree growth         Private         Field system on Boswens Common, Sancreed         Scheduled Monument (No. 1007268)         Scrub / tree growth         Private         Goldherring British village, Sancreed         Scheduled Monument (No. 1004651)	CONTACT: north of Saltash I CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONDITION: CONDITION:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private         D-Day landing craft maintenance site, 170m         Scheduled Monument (No. 1020053)         Moderate visitor erosion         Local Authority         Caer Bran, Sancreed         Scheduled Monument (No. 1006717)         Scrub / tree growth         Private         Field system on Boswens Common, Sancreed         Scheduled Monument (No. 1007268)         Scrub / tree growth         Private         Goldherring British village, Sancreed	CONTACT: north of Saltash I CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONDITION: CONDITION:	Business Manager 0117 975 0700 Pier, Saltash Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Improving Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Hut circle north of Botrea, Sancreed		
DESIGNATION:	Scheduled Monument (No. 1003072)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hut circles and field system on north west	edge of Boswens	Common, Sancreed
DESIGNATION:	Scheduled Monument (No. 1007267)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bolster Bank, St Agnes		
DESIGNATION:	Scheduled Monument (No. 1016444)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Wheal Kitty 20th century tin processing wo	rks, St Agnes	
DESIGNATION:	Scheduled Monument (No. 1021164)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Promontory fort and Civil War battery, Littl	e Dennis Head, S	t Anthony-in-Meneage
DESIGNATION:	Scheduled Monument (No. 1004431)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Deserted village of Garrow, St Breward		
DESIGNATION:	Scheduled Monument (No. 1021445)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric to post-medieval settlement, and on the middle and lower slopes west and so		
DESIGNATION:	Scheduled Monument (No. 1019172)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
DITE NAME:	Stannon Stone Circle, prehistoric field syste linear boundaries and medieval building nor		
DESIGNATION:	Scheduled Monument (No. 1007764)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
	0		

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

	Stone circle on Emblance Common, St Brev	ward		
DESIGNATION:	Scheduled Monument (No. 1004459)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Camp 900yds (820m) south east of St Bury	van village, St Bury	an	
DESIGNATION:	Scheduled Monument (No. 1004483)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Round barrow 200yds (180m) north of the Merry Maidens, St Buryan			
DESIGNATION:	Scheduled Monument (No. 1004358)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
DITE NAME:	Earlier Prehistoric hillfort, adjacent round c and tor cairn on Tregarrick Tor, St Cleer	airn with incorpo	rated shelter,	
DESIGNATION:	Scheduled Monument (No. 1009698)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving	
	Private		Rusiness Managan 0117 975 0700	
OWNER TYPE:	Frivate	CONTACT:	Business Manager 0117 975 0700	
	Embanked platform cairn with central mou			
SITE NAME:				
SITE NAME: DESIGNATION:	Embanked platform cairn with central mou	nd 375m north w	est of Trewalla Farm, St Cleer Generally satisfactory	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Embanked platform cairn with central moun Scheduled Monument (No. 1015976)	nd 375m north we	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	<b>Embanked platform cairn with central moun</b> Scheduled Monument (No. 1015976) Scrub / tree growth	nd 375m north we CONDITION: TREND: CONTACT:	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME:	<b>Embanked platform cairn with central moun</b> Scheduled Monument (No. 1015976) Scrub / tree growth Private	nd 375m north we CONDITION: TREND: CONTACT:	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700	
SITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Embanked platform cairn with central mount Scheduled Monument (No. 1015976) Scrub / tree growth Private Kerbed platform cairn with kerbed central	nd 375m north we CONDITION: TREND: CONTACT: mound and outer	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 bank 600m east of Trewalla Farm, St Cleer Generally satisfactory	
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Embanked platform cairn with central mount         Scheduled Monument (No. 1015976)         Scrub / tree growth         Private         Kerbed platform cairn with kerbed central         Scheduled Monument (No. 1010323)	nd 375m north we CONDITION: TREND: CONTACT: mound and outer CONDITION:	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 bank 600m east of Trewalla Farm, St Cleer Generally satisfactory but with significant localised problems	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Embanked platform cairn with central mount         Scheduled Monument (No. 1015976)         Scrub / tree growth         Private         Kerbed platform cairn with kerbed central         Scheduled Monument (No. 1010323)         Vandalism	nd 375m north we CONDITION: TREND: CONTACT: mound and outer CONDITION: TREND: CONTACT:	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 bank 600m east of Trewalla Farm, St Cleer Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Embanked platform cairn with central mount         Scheduled Monument (No. 1015976)         Scrub / tree growth         Private         Kerbed platform cairn with kerbed central         Scheduled Monument (No. 1010323)         Vandalism         Private	nd 375m north we CONDITION: TREND: CONTACT: mound and outer CONDITION: TREND: CONTACT:	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 bank 600m east of Trewalla Farm, St Cleer Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE: DESIGNATION:	Embanked platform cairn with central mount         Scheduled Monument (No. 1015976)         Scrub / tree growth         Private         Kerbed platform cairn with kerbed central         Scheduled Monument (No. 1010323)         Vandalism         Private         Platform cairn with central mound 760m Estimation	nd 375m north we CONDITION: TREND: CONTACT: mound and outer CONDITION: TREND: CONTACT: SE of Lambadla Fa	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 bank 600m east of Trewalla Farm, St Cleer Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 rm, St Cleer Generally satisfactory	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Embanked platform cairn with central mount         Scheduled Monument (No. 1015976)         Scrub / tree growth         Private         Kerbed platform cairn with kerbed central         Scheduled Monument (No. 1010323)         Vandalism         Private         Platform cairn with central mound 760m Est         Scheduled Monument (No. 1010327)	nd 375m north we CONDITION: TREND: CONTACT: mound and outer CONDITION: TREND: CONTACT: SE of Lambadla Fa	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 bank 600m east of Trewalla Farm, St Cleer Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 rm, St Cleer Generally satisfactory but with significant localised problems	
OWNER TYPE:	Embanked platform cairn with central mount         Scheduled Monument (No. 1015976)         Scrub / tree growth         Private         Kerbed platform cairn with kerbed central         Scheduled Monument (No. 1010323)         Vandalism         Private         Platform cairn with central mound 760m Est         Scheduled Monument (No. 1010327)         Plant growth	nd 375m north we CONDITION: TREND: CONTACT: mound and outer CONDITION: TREND: CONTACT: SE of Lambadla Fa	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 bank 600m east of Trewalla Farm, St Cleer Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 rm, St Cleer Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700	
STE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: SITE NAME:	Embanked platform cairn with central mount         Scheduled Monument (No. 1015976)         Scrub / tree growth         Private         Kerbed platform cairn with kerbed central         Scheduled Monument (No. 1010323)         Vandalism         Private         Platform cairn with central mound 760m ES         Scheduled Monument (No. 1010327)         Plant growth         Private	nd 375m north we CONDITION: TREND: CONTACT: mound and outer CONDITION: TREND: CONTACT: SE of Lambadla Fa	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 bank 600m east of Trewalla Farm, St Cleer Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 rm, St Cleer Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Embanked platform cairn with central mount         Scheduled Monument (No. 1015976)         Scrub / tree growth         Private         Kerbed platform cairn with kerbed central         Scheduled Monument (No. 1010323)         Vandalism         Private         Platform cairn with central mound 760m Est         Scheduled Monument (No. 1010327)         Platform cairn with central mound 760m Est         Plant growth         Private         Platform cairn with central mound 900m Est	nd 375m north we CONDITION: TREND: CONTACT: mound and outer CONDITION: TREND: CONTACT: SE of Lambadla Fa CONDITION: TREND: CONTACT:	est of Trewalla Farm, St Cleer Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 bank 600m east of Trewalla Farm, St Cleer Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 rm, St Cleer Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 rm, St Cleer Generally satisfactory	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Prehistoric enclosure 325m west of Trewall	a Farm, St Cleer	
DESIGNATION:	Scheduled Monument (No. 1010434)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	- The second sec	contract.	
SITE NAME:	Prehistoric enclosure and field system, two 350m south east of Sparretts Farm, St Clee		arts of a medieval field system
DESIGNATION:	Scheduled Monument (No. 1013216)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric enclosure containing a stone hu 500m south east of Sparretts Farm, St Clee		of a medieval field system,
DESIGNATION:	Scheduled Monument (No. 1013199)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric irregular aggregate field system 375m SSE of Sparretts Farm, St Cleer	with incorporated	d stone hut circles
DESIGNATION:	Scheduled Monument (No. 1008765)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric irregular and regular aggregate f 750m ENE of Siblyback Farm, St Cleer	ield systems with	incorporated stone hut circles
DESIGNATION:	Scheduled Monument (No. 1011315)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric irregular and regular aggregate f cairnfield and kerbed boulder 750m ESE of		
DESIGNATION:	Scheduled Monument (No. 1010060)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Prehistoric regular aggregate field system w and an adjacent enclosure 550m WSW of T		
DESIGNATION:	Scheduled Monument (No. 1009731)	CONDITION:	Generally satisfactory
			but with significant localised problems
	Plant growth	TREND:	Declining
PRINCIPAL VULNERABILITY:			0

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Prehistoric to medieval settlements, field sys with post-medieval boundary and railway on			
DESIGNATION:	Scheduled Monument (No. 1018629)	CONDITION:	Generally unsatisfactory with major localised problems	
RINCIPAL VULNERABILITY:	Forestry	TREND:	Improving	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Prehistoric to post-medieval field systems, bo Smallacoombe Parks and north eastern Sibly			
DESIGNATION:	Scheduled Monument (No. 1018631)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Stable	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Round cairn 450m east of Sparretts Farm, St	Cleer		
DESIGNATION:	Scheduled Monument (No. 1009838)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Round cairn 472m SSW of Caradon Hill sum	mit, St Cleer		
DESIGNATION:	Scheduled Monument (No. 1011824)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Round cairn 480m SSW of Caradon Hill sum	mit, St Cleer		
DESIGNATION:	Scheduled Monument (No. 1011825)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Round cairn 525m east of Trewalla Farm, St	Cleer		
DESIGNATION:	Scheduled Monument (No. 1012041)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Round cairn 527m SSW of Caradon Hill sum	mit, St Cleer		
DESIGNATION:	Scheduled Monument (No. 1011840)	CONDITION:	Generally satisfactory but with minor localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
	Private	CONTACT:	Business Manager 0117 975 0700	
	Pound coins EE7m SSW of Coundon Hill summit St Close			
OWNER TYPE:	Round cairn 557m SSW of Caradon Hill sum	mit, St Cleer		
OWNER TYPE:	Round cairn 557m SSW of Caradon Hill sum Scheduled Monument (No. 1011844)	mit, St Cleer	Generally satisfactory but with significant localised problems	
OWNER TYPE:			Generally satisfactory but with significant localised problems Declining	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

SITE NAME:	Round cairn 725m ESE of Trewalla Farm, St	Cleer	
DESIGNATION:	Scheduled Monument (No. 1011992)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round cairn 740m SSW of Caradon Hill sur	nmit, St Cleer	
DESIGNATION:	Scheduled Monument (No. 1011774)	CONDITION:	Generally satisfactory
		CONDITION.	but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round cairn 800m ESE of Lambadla Farm, S	t Cleer	
DESIGNATION:	Scheduled Monument (No. 1010326)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round cairn 812m ESE of Trewalla Farm. St	Cleer	
			Conorally entire stars
DESIGNATION:	Scheduled Monument (No. 1011991)	CONDITION:	Generally satisfactory
	Plant growth		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth Private	TREND: CONTACT:	Declining Business Manager 0117 975 0700
SITE NAME:	Round cairn 840m south east of Trewalla Fa	arm, St Cleer	
DESIGNATION:	Scheduled Monument (No. 1011995)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round cairn and shelters 812m SSW of Car	radon Hill summit	St Cleer
	Round cairn and shelters 812m SSW of Car Scheduled Monument (No. 1011784)	adon Hill summit	<b>St Cleer</b> Generally satisfactory
DESIGNATION:			Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1011784)	CONDITION:	Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1011784) Public utilities	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1011784) Public utilities Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Il summit, St Cleer Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1011784) Public utilities Private Round cairn with peripheral berm 402m SS Scheduled Monument (No. 1011822)	CONDITION: TREND: CONTACT: W of Caradon Hi CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Il summit, St Cleer Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1011784) Public utilities Private Round cairn with peripheral berm 402m SS Scheduled Monument (No. 1011822) Moderate vehicle damage/erosion	CONDITION: TREND: CONTACT: W of Caradon Hi CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Il summit, St Cleer Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1011784) Public utilities Private Round cairn with peripheral berm 402m SS Scheduled Monument (No. 1011822)	CONDITION: TREND: CONTACT: W of Caradon Hi CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Il summit, St Cleer Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1011784) Public utilities Private Round cairn with peripheral berm 402m SS Scheduled Monument (No. 1011822) Moderate vehicle damage/erosion	CONDITION: TREND: CONTACT: W of Caradon Hi CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Il summit, St Cleer Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No. 1011784) Public utilities Private Round cairn with peripheral berm 402m SS Scheduled Monument (No. 1011822) Moderate vehicle damage/erosion Private	CONDITION: TREND: CONTACT: W of Caradon Hi CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Il summit, St Cleer Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1011784) Public utilities Private Round cairn with peripheral berm 402m SS Scheduled Monument (No. 1011822) Moderate vehicle damage/erosion Private South Caradon 19th century copper mine, S	CONDITION: TREND: CONTACT: W of Caradon Hi CONDITION: TREND: CONTACT: St Cleer	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Il summit, St Cleer Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Stone hut circle 425m south east of Sparre	tts Farm, St Cleer	
DESIGNATION:	Scheduled Monument (No. 1013211)	CONDITION:	Generally satisfactory
			but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone hut circle 685m south east of Trewal	la Farm, St Cleer	
DESIGNATION:	Scheduled Monument (No. 1011907)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone hut circle 750m ESE of Trewalla Farm	n, St Cleer	
DESIGNATION:	Scheduled Monument (No. 1011909)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone hut circle 800m ESE of Trewalla Farm	n, St Cleer	
DESIGNATION:	Scheduled Monument (No. 1011989)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone hut circle centred 460m ESE of Spari	retts Farm, St Clee	er
	Stone hut circle centred 460m ESE of Spari Scheduled Monument (No. 1009839)	retts Farm, St Clea	Generally satisfactory
DESIGNATION:	•		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1009839)	CONDITION:	Generally satisfactory but with minor localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1009839) Plant growth	CONDITION: TREND: CONTACT:	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1009839) Plant growth Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1009839) Plant growth Private The Tinners' Dyke 160yds (150m) in length	CONDITION: TREND: CONTACT: south of Henders	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 grove Wood, St Cleer Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1009839) Plant growth Private The Tinners' Dyke 160yds (150m) in length Scheduled Monument (No. 1004364)	CONDITION: TREND: CONTACT: south of Henders CONDITION:	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 grove Wood, St Cleer Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1009839) Plant growth Private The Tinners' Dyke 160yds (150m) in length Scheduled Monument (No. 1004364) Arable ploughing	CONDITION: TREND: CONTACT: south of Henders CONDITION: TREND: CONTACT:	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 grove Wood, St Cleer Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No. 1009839) Plant growth Private The Tinners' Dyke 160yds (150m) in length Scheduled Monument (No. 1004364) Arable ploughing Private	CONDITION: TREND: CONTACT: south of Henders CONDITION: TREND: CONTACT:	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 grove Wood, St Cleer Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1009839) Plant growth Private The Tinners' Dyke 160yds (150m) in length Scheduled Monument (No. 1004364) Arable ploughing Private Tor cairn with adjacent sub-rectangular hut	CONDITION: TREND: CONTACT: South of Henders CONDITION: TREND: CONTACT:	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 grove Wood, St Cleer Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 mradon Hill summit, St Cleer Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1009839)         Plant growth         Private         The Tinners' Dyke 160yds (150m) in length         Scheduled Monument (No. 1004364)         Arable ploughing         Private         Tor cairn with adjacent sub-rectangular hut         Scheduled Monument (No. 1011793)	CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION:	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 www.www.www.www.www.www.www.www.www.
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1009839)         Plant growth         Private         The Tinners' Dyke 160yds (150m) in length         Scheduled Monument (No. 1004364)         Arable ploughing         Private         Tor cairn with adjacent sub-rectangular hut         Scheduled Monument (No. 1011793)         Plant growth	CONDITION: TREND: CONTACT: South of Henderg CONDITION: TREND: CONTACT: 5650m SSVV of Ca CONDITION:	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 www.www.www.www.www.www.www.www.www.
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: OWNER TYPE:	Scheduled Monument (No. 1009839)         Plant growth         Private         The Tinners' Dyke 160yds (150m) in length         Scheduled Monument (No. 1004364)         Arable ploughing         Private         Tor cairn with adjacent sub-rectangular hut         Scheduled Monument (No. 1011793)         Plant growth         Private         Two adjacent stone hut circles 265m WNW	CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No. 1009839)         Plant growth         Private         The Tinners' Dyke 160yds (150m) in length         Scheduled Monument (No. 1004364)         Arable ploughing         Private         Tor cairn with adjacent sub-rectangular hut         Scheduled Monument (No. 1011793)         Plant growth         Private	CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 grove Wood, St Cleer Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 tradon Hill summit, St Cleer Generally satisfactory but with minor localised problems Stable Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1009839)         Plant growth         Private         The Tinners' Dyke 160yds (150m) in length         Scheduled Monument (No. 1004364)         Arable ploughing         Private         Tor cairn with adjacent sub-rectangular hut         Scheduled Monument (No. 1011793)         Plant growth         Private         Two adjacent stone hut circles 265m WNW	CONDITION: TREND: CONTACT: SOUTH OF Henders CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONDITION: CONTACT:	Generally satisfactory but with minor localised problems Improving Business Manager 0117 975 0700 grove Wood, St Cleer Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 madon Hill summit, St Cleer Generally satisfactory but with minor localised problems Stable Business Manager 0117 975 0700 m, St Cleer

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Two adjacent stone hut circles 290m west of	of Trewalla Farm,	St Cleer
DESIGNATION:	Scheduled Monument (No. 1009703)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two cairns 550m and 587m ENE of Trewall	a Farm and two a	djacent small clearance cairns, St Cleer
DESIGNATION:	Scheduled Monument (No. 1010311)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two platform cairns 750m and 785m east c	of Sparretts Farm,	St Cleer
DESIGNATION:	Scheduled Monument (No. 1010325)	CONDITION:	Generally satisfactory
	``````````````````````````````````````		but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two round cairns 455m and 475m north w	est of Trewalla Fa	rm, St Cleer
DESIGNATION:	Scheduled Monument (No. 1010324)	CONDITION:	Generally satisfactory
	``````````````````````````````````````		but with minor localised problems
			•
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
PRINCIPAL VULNERABILITY: OWNER TYPE:	Scrub / tree growth Private	TREND: CONTACT:	Declining Business Manager 0117 975 0700
	-	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Private Two stone hut circles and an adjoining Preh	CONTACT:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory
OWNER TYPE: SITE NAME: DESIGNATION:	Private <b>Two stone hut circles and an adjoining Preh</b> Scheduled Monument (No. 1012000)	CONTACT: historic boundary CONDITION:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Two stone hut circles and an adjoining Preh	CONTACT:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private <b>Two stone hut circles and an adjoining Preh</b> Scheduled Monument (No. 1012000) Plant growth	CONTACT: istoric boundary CONDITION: TREND:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private <b>Two stone hut circles and an adjoining Preh</b> Scheduled Monument (No. 1012000) Plant growth	CONTACT: iistoric boundary CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private <b>Two stone hut circles and an adjoining Preh</b> Scheduled Monument (No. 1012000) Plant growth Private	CONTACT: iistoric boundary CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private Two stone hut circles and an adjoining Preh Scheduled Monument (No. 1012000) Plant growth Private Round 340m north west of Tresawle Farm,	CONTACT: iistoric boundary CONDITION: TREND: CONTACT: St Columb Major	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:	Private Two stone hut circles and an adjoining Preh Scheduled Monument (No. 1012000) Plant growth Private Round 340m north west of Tresawle Farm,	CONTACT: iistoric boundary CONDITION: TREND: CONTACT: St Columb Major	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Two stone hut circles and an adjoining Preh Scheduled Monument (No. 1012000) Plant growth Private Round 340m north west of Tresawle Farm, Scheduled Monument (No. 1020864)	CONTACT: iistoric boundary CONDITION: TREND: CONTACT: St Columb Major CONDITION:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Two stone hut circles and an adjoining Preh Scheduled Monument (No. 1012000) Plant growth Private Round 340m north west of Tresawle Farm, Scheduled Monument (No. 1020864) Arable ploughing	CONTACT: iistoric boundary CONDITION: TREND: CONTACT: St Columb Major CONDITION: TREND:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining
OWNER TYPE:	Private Two stone hut circles and an adjoining Preh Scheduled Monument (No. 1012000) Plant growth Private Round 340m north west of Tresawle Farm, Scheduled Monument (No. 1020864) Arable ploughing Private	CONTACT: iistoric boundary CONDITION: TREND: CONTACT: St Columb Major CONDITION: TREND:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally satisfactory
OWNER TYPE:	Private Two stone hut circles and an adjoining Preh Scheduled Monument (No. 1012000) Plant growth Private Round 340m north west of Tresawle Farm, Scheduled Monument (No. 1020864) Arable ploughing Private Bury camp, St Dominick	CONTACT: iistoric boundary CONDITION: TREND: CONTACT: St Columb Major CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems
OWNER TYPE:	Private         Two stone hut circles and an adjoining Preh         Scheduled Monument (No. 1012000)         Plant growth         Private         Round 340m north west of Tresawle Farm,         Scheduled Monument (No. 1020864)         Arable ploughing         Private         Bury camp, St Dominick         Scheduled Monument (No. 1004393)	CONTACT: istoric boundary CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining
OWNER TYPE:	Private         Two stone hut circles and an adjoining Preh         Scheduled Monument (No. 1012000)         Plant growth         Private         Round 340m north west of Tresawle Farm,         Scheduled Monument (No. 1020864)         Arable ploughing         Private         Bury camp, St Dominick         Scheduled Monument (No. 1004393)         Localised/limited stock erosion	CONTACT: istoric boundary CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems
OWNER TYPE:	Private         Two stone hut circles and an adjoining Preh         Scheduled Monument (No. 1012000)         Plant growth         Private         Round 340m north west of Tresawle Farm,         Scheduled Monument (No. 1020864)         Arable ploughing         Private         Bury camp, St Dominick         Scheduled Monument (No. 1004393)         Localised/limited stock erosion	CONTACT: istoric boundary CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleen Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining
OWNER TYPE:	Private         Two stone hut circles and an adjoining Preh         Scheduled Monument (No. 1012000)         Plant growth         Private         Round 340m north west of Tresawle Farm,         Scheduled Monument (No. 1020864)         Arable ploughing         Private         Bury camp, St Dominick         Scheduled Monument (No. 1004393)         Localised/limited stock erosion         Private	CONTACT: istoric boundary CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining
OWNER TYPE:	Private         Two stone hut circles and an adjoining Preh         Scheduled Monument (No. 1012000)         Plant growth         Private         Round 340m north west of Tresawle Farm,         Scheduled Monument (No. 1020864)         Arable ploughing         Private         Bury camp, St Dominick         Scheduled Monument (No. 1004393)         Localised/limited stock erosion         Private         Warren's Barrow, St Erme	CONTACT: istoric boundary CONDITION: CONDITION: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:	Private         Two stone hut circles and an adjoining Preh         Scheduled Monument (No. 1012000)         Plant growth         Private         Round 340m north west of Tresawle Farm,         Scheduled Monument (No. 1020864)         Arable ploughing         Private         Bury camp, St Dominick         Scheduled Monument (No. 1004393)         Localised/limited stock erosion         Private         Warren's Barrow, St Erme	CONTACT: istoric boundary CONDITION: CONDITION: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Business Manager 0117 975 0700 wall 470m east of Trewalla Farm, St Cleer Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Enclosures east of Gurlyn, St Erth		
DESIGNATION:	Scheduled Monument (No. 1007282)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		contract.	
SITE NAME:	Promontory fort north of village, St Gennys		
DESIGNATION:	Scheduled Monument (No. 1003097)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Gunpowder storage complex at Kennall Vale	, St Gluvias	
designation:	Scheduled Monument (No. 1020441)	CONDITION:	Generally unsatisfactory
		CONDITION.	with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Gunpowder works at Kennall Vale, St Gluvias	;	
DESIGNATION:	Scheduled Monument (No. 1020143)	CONDITION:	Generally satisfactory
			but with significant localised problems
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Camp 500yds (460m) west of Trenance, St Is	sey	
DESIGNATION:	Scheduled Monument (No. 1004235)	CONDITION:	Generally satisfactory
DESIGNATION:		CONDITION:	but with significant localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
Owner TIFE.	Thvate	CONTACT.	
SITE NAME:	Tokenbury camp, St Ive		
DESIGNATION:	Scheduled Monument (No. 1004469)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:			Declining
	Extensive animal burrowing	TREND:	
	Extensive animal burrowing Private	TREND: CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	-		
OWNER TYPE:	Private		Business Manager 0117 975 0700 Generally unsatisfactory
DWNER TYPE:	Private Hut circles, Higher Bussow, St Ives Scheduled Monument (No. 1006689)	CONTACT:	Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Hut circles, Higher Bussow, St Ives	CONTACT: CONDITION:	Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Hut circles, Higher Bussow, St Ives Scheduled Monument (No. 1006689) Scrub / tree growth	CONTACT: CONDITION: TREND:	Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Hut circles, Higher Bussow, St Ives Scheduled Monument (No. 1006689) Scrub / tree growth	CONTACT: CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
OWNER TYPE:	Private Hut circles, Higher Bussow, St Ives Scheduled Monument (No. 1006689) Scrub / tree growth Private	CONTACT: CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
DWNER TYPE:	Private Hut circles, Higher Bussow, St Ives Scheduled Monument (No. 1006689) Scrub / tree growth Private Whitesand Bay (or Tregonhawke) battery, St Scheduled Monument (No. 1004664)	CONTACT: CONDITION: TREND: CONTACT: John CONDITION:	Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Hut circles, Higher Bussow, St Ives Scheduled Monument (No. 1006689) Scrub / tree growth Private Whitesand Bay (or Tregonhawke) battery, St	CONTACT: CONDITION: TREND: CONTACT: John	Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Chambered barrow 100yds (90m) east of K	errow Farm, St Ju	st	
DESIGNATION:	Scheduled Monument (No. 1004637)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Holed stones on Kenidjack Common, St Jus	st		
DESIGNATION:	Scheduled Monument (No. 1006755)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Hut circles 50yds (45m) west of Carnyorth	Farm, St Just		
DESIGNATION:	Scheduled Monument (No. 1004277)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Round barrow 550yds (500m) north of Chycarne, St Just			
DESIGNATION:	Scheduled Monument (No. 1004245)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Standing stone 200yds (180m) west of Chy	carne, St Just		
DESIGNATION:	Scheduled Monument (No. 1003116)	CONDITION:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Two barrows on Carn Bean 300yds (270m)	NNE of Higher I	Botallack, St Just	
DESIGNATION:	Scheduled Monument (No. 1004279)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Two barrows on Woon Gumpus Common 700yds (640m) NNW of Boslow Farm, St Just			
DESIGNATION:	Scheduled Monument (No. 1004287)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Chapel enclosure 150yds (140m) south of 1	Frelease Farm, St k	Keverne	
	Scheduled Monument (No. 1004334)	CONDITION:	Extensive significant problems	
DESIGNATION:	Scheduled Monument (NO. 1004554)		i.e. under plough, collapse	
DESIGNATION: PRINCIPAL VULNERABILITY:	Other	TREND:	<b>.</b> .	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Cliff castle at Winecove Point, St Merryn		
DESIGNATION:	Scheduled Monument (No. 1004234)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Hut circle village 330yds (300m) west of W	est Northwood F	arm, St Neot
DESIGNATION:	Scheduled Monument (No. 1004662)	CONDITION:	Generally unsatisfactory
	`````		with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Improving
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Medieval homestead and fields on Redhill D	owns, St Neot	
ESIGNATION:	Scheduled Monument (No. 1003074)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining Business Manager 0117 975 0700
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Prehistoric field systems, enclosure, hut circ longhouse and field system on Higher Lange		
DESIGNATION:	Scheduled Monument (No. 1007475)	CONDITION:	Generally unsatisfactory
	``````````````````````````````````````		with major localised problems
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	Prehistoric settlements and field system wit	th adjacent medie	val settlement,
ite name:		th adjacent medie	val settlement, Gelly Downs, St Neot Generally unsatisfactory
TE NAME: ESIGNATION:	Prehistoric settlements and field system with field systems, boundaries and tin streamwore	th adjacent medie rks on the Brown	val settlement, Gelly Downs, St Neot
TE NAME: ESIGNATION: RINCIPAL VULNERABILITY:	Prehistoric settlements and field system wit field systems, boundaries and tin streamwor Scheduled Monument (No. 1007770)	th adjacent medie rks on the Brown CONDITION:	val settlement, Gelly Downs, St Neot Generally unsatisfactory with major localised problems
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNRET TYPE:	Prehistoric settlements and field system wit field systems, boundaries and tin streamwor Scheduled Monument (No. 1007770) Scrub / tree growth	th adjacent medie rks on the Brown CONDITION: TREND: CONTACT:	val settlement, Gelly Downs, St Neot Generally unsatisfactory with major localised problems Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Prehistoric settlements and field system wit field systems, boundaries and tin streamwor Scheduled Monument (No. 1007770) Scrub / tree growth Private	th adjacent medie rks on the Brown CONDITION: TREND: CONTACT:	val settlement, Gelly Downs, St Neot Generally unsatisfactory with major localised problems Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION:	Prehistoric settlements and field system wit field systems, boundaries and tin streamwor Scheduled Monument (No. 1007770) Scrub / tree growth Private Round barrow on Goonzion Down, St Neo	th adjacent medie rks on the Brown CONDITION: TREND: CONTACT:	val settlement, Gelly Downs, St Neot Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory
ITE NAME: PESIGNATION: RINCIPAL VULNERABILITY: PESIGNATION: RINCIPAL VULNERABILITY:	Prehistoric settlements and field system wit field systems, boundaries and tin streamwood Scheduled Monument (No. 1007770) Scrub / tree growth Private Round barrow on Goonzion Down, St Neo Scheduled Monument (No. 1004360)	th adjacent medie rks on the Brown CONDITION: TREND: CONTACT: t CONDITION:	val settlement, Gelly Downs, St Neot Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE: DWNER TYPE: D	Prehistoric settlements and field system with field systems, boundaries and tin streamwood Scheduled Monument (No. 1007770)         Scrub / tree growth         Private         Round barrow on Goonzion Down, St Neo Scheduled Monument (No. 1004360)         Plant growth	th adjacent medie rks on the Brown CONDITION: TREND: CONTACT: t CONDITION: TREND: CONDITION: TREND: CONTACT:	val settlement, Gelly Downs, St Neot Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Prehistoric settlements and field system with field systems, boundaries and tin streamwood Scheduled Monument (No. 1007770)         Scrub / tree growth         Private         Round barrow on Goonzion Down, St Neo         Scheduled Monument (No. 1004360)         Plant growth         Local Authority	th adjacent medie rks on the Brown CONDITION: TREND: CONTACT: t CONDITION: TREND: CONDITION: TREND: CONTACT:	val settlement, Gelly Downs, St Neot Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700
TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WINER TYPE: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WINER TYPE: TE NAME: ESIGNATION:	Prehistoric settlements and field system with field systems, boundaries and tin streamwood         Scheduled Monument (No. 1007770)         Scrub / tree growth         Private         Round barrow on Goonzion Down, St Neo         Scheduled Monument (No. 1004360)         Plant growth         Local Authority         Round cairn 1.062km south west of Higher	th adjacent medier rks on the Brown CONDITION: TREND: CONTACT: t CONDITION: TREND: CONTACT: Langdon Farm, St	val settlement, Gelly Downs, St Neot Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Neot Generally satisfactory
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Prehistoric settlements and field system with field systems, boundaries and tin streamwood Scheduled Monument (No. 1007770)         Scrub / tree growth         Private         Round barrow on Goonzion Down, St Neo         Scheduled Monument (No. 1004360)         Plant growth         Local Authority         Round cairn 1.062km south west of Higher         Scheduled Monument (No. 1007476)	th adjacent medier rks on the Brown CONDITION: TREND: CONTACT: trenD: CONDITION: TREND: CONTACT: Langdon Farm, St	val settlement,         Gelly Downs, St Neot         Generally unsatisfactory         with major localised problems         Declining         Business Manager 0117 975 0700         Generally satisfactory         but with minor localised problems         Declining         Business Manager 0117 975 0700         Veot         Generally satisfactory         but with minor localised problems         Declining         Business Manager 0117 975 0700
SITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: SWNER TYPE:	Prehistoric settlements and field system with field systems, boundaries and tin streamwood Scheduled Monument (No. 1007770)         Scrub / tree growth         Private         Round barrow on Goonzion Down, St Neo         Scheduled Monument (No. 1004360)         Plant growth         Local Authority         Round cairn 1.062km south west of Higher         Scheduled Monument (No. 1007476)	th adjacent medies rks on the Brown CONDITION: TREND: CONTACT: t CONDITION: TREND: CONTACT: Langdon Farm, St CONDITION: TREND: CONDITION:	val settlement, Gelly Downs, St Neot Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Neot Generally satisfactory but with minor localised problems Unknown Business Manager 0117 975 0700
DWNER TYPE:	Prehistoric settlements and field system with field systems, boundaries and tin streamwood Scheduled Monument (No. 1007770)         Scrub / tree growth         Private         Round barrow on Goonzion Down, St Neo         Scheduled Monument (No. 1004360)         Plant growth         Local Authority         Round cairn 1.062km south west of Higher         Scheduled Monument (No. 1007476)         Other         Private	th adjacent medies rks on the Brown CONDITION: TREND: CONTACT: t CONDITION: TREND: CONTACT: Langdon Farm, St CONDITION: TREND: CONDITION:	val settlement, Gelly Downs, St Neot Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Neot Generally satisfactory but with minor localised problems Unknown Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DWNER TYPE:	Prehistoric settlements and field system with         field systems, boundaries and tin streamwood         Scheduled Monument (No. 1007770)         Scrub / tree growth         Private         Round barrow on Goonzion Down, St Neo         Scheduled Monument (No. 1004360)         Plant growth         Local Authority         Round cairn 1.062km south west of Higher         Scheduled Monument (No. 1007476)         Other         Private         Round cairn 1.17km south west of Higher Local	th adjacent medier rks on the Brown CONDITION: TREND: CONTACT: CONTACT: TREND: CONTACT: Langdon Farm, St CONDITION: TREND: CONTACT:	val settlement, Gelly Downs, St Neot Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Neot Generally satisfactory but with minor localised problems Unknown Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS

SITE NAME:	Bofarnel Downs round barrows, St Winnow		
DESIGNATION:	Scheduled Monument (No. 1004437)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Respryn Bridge, St Winnow		
DESIGNATION:	Scheduled Monument (No. 1006701)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Limited/ localised vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two round barrows north east of Fairy Cros	s, St Winnow	
DESIGNATION:	Scheduled Monument (No. 1004439)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Condolden Barrow, Tintagel		
	ç		Concernilly activity at any
DESIGNATION:	Scheduled Monument (No. 1004652)	CONDITION:	Generally satisfactory but with significant localised problems
	l ocalised/limited stock erosion	TREND	
PRINCIPAL VULNERABILITY:	Private	TREND: CONTACT:	Declining Business Manager 0117 975 0700
State the		CONTACT.	
SITE NAME:	The Ballast Pond, Torpoint		
DESIGNATION:	Scheduled Monument (No. 1007261)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Carne Beacon round barrow 320m north of	Carne Farm, Ver	yan
SITE NAME:	Carne Beacon round barrow 320m north of Scheduled Monument (No. 1019745)	Carne Farm, Ver	yan Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION:			Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019745)	CONDITION:	Generally satisfactory but with significant localised problems
	Scheduled Monument (No. 1019745) Extensive animal burrowing	CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1019745) Extensive animal burrowing Private	CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1019745) Extensive animal burrowing Private Warbstow Bury camp, Warbstow Scheduled Monument (No. 1006710)	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019745) Extensive animal burrowing Private Warbstow Bury camp, Warbstow	CONDITION: TREND: CONTACT: CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019745) Extensive animal burrowing Private Warbstow Bury camp, Warbstow Scheduled Monument (No. 1006710) Scrub / tree growth	CONDITION: TREND: CONTACT: CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019745)         Extensive animal burrowing         Private         Warbstow Bury camp, Warbstow         Scheduled Monument (No. 1006710)         Scrub / tree growth         Local Authority         Ancient village south of Carburrow Tor, Warl	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1019745)         Extensive animal burrowing         Private         Warbstow Bury camp, Warbstow         Scheduled Monument (No. 1006710)         Scrub / tree growth         Local Authority	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019745)         Extensive animal burrowing         Private         Warbstow Bury camp, Warbstow         Scheduled Monument (No. 1006710)         Scrub / tree growth         Local Authority         Ancient village south of Carburrow Tor, Warl	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: eggan	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

HERITAGE AT RISK 2011 / SOUTH WEST / CORNWALL (UA) / DARTMOOR (NP)

SITE NAME:	Trelill Wel	l Chapel, near Helston, Wendron			
DESIGNATION:	Scheduled	Monument (No. 1006743)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Deteriorat	tion – in need of management	TREND:	Declining	
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Porthmeo	r ancient village, Zennor			
DESIGNATION:	Scheduled Monument (No. 1003071) c		CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tre	ee growth	TREND:	Declining	
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700	
site name:	Treen Cor	nmon barrows, Zennor			
DESIGNATION:	Scheduled	Monument (No. 1004473)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant grow	/th	TREND:	Declining	
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700	
	SITE NAME:	<b>Carclew,</b> <b>Mylor</b> Registered Park and Garden Grade II,	together wi house burn	rmal terraced and water gardens, th an C18 landscape park.The main t down in 1934 and the site is now in nership. Infill residential development	
		also CA, 5 LBs	in the park belts, substantial areas of woodland have been cleared and many individual parkland		
	CONDITION:	Extensive significant problems	trees have b		
	TREND:	Stable			
	OWNER TYPE:	Private, multiple owners	Contact: Kir	n Auston 0117 975 0696	
SITE NAME:	Bodmin				
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor	
VULNERABILITY:	Low		TREND:	Deteriorating	
CONTACT:	Alyson Co	ooper (LPA) 01872 224242	NEW ENTRY?:	No	
DEVON					
DARTMOOR (NP)					
-	SITE NAME:	Higher Sigford, Sweet's Sigford, Ilsington, Teignbridge	which has b recent years have been o	nple of a longhouse in a farmstead context been used for agricultural storage in more s. Some internal and external stabilisation wo carried out though further works are needed	
- AND TRACE	CONDITION: OCCUPANCY:		Conditional been grante	consents for re-occupation of the house haved. New owner is negotiating the consent.	
	PRIORITY: OWNER TYPE:	D (D) Private	Contact: Fra	ancis Kelly 0117 975 0725	
SITE NAME:	Agglomera	ated enclosure on the west side of the	Erme Valley	below Stalldown, Cornwood, South Hams	
		NA (N.L. 1012740)	,		

DESIGNATION:	Scheduled Monument (No. 1012740)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Concentration

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

PRINCIPAL VULNERABILITY: Pla OWNER TYPE: Priv SITE NAME: End DESIGNATION: Sch PRINCIPAL VULNERABILITY: Pla OWNER TYPE: Priv SITE NAME: Me DESIGNATION: Sch PRINCIPAL VULNERABILITY: Scr OWNER TYPE: Priv SITE NAME: The DESIGNATION: Sch PRINCIPAL VULNERABILITY: Pla OWNER TYPE: Priv	heduled Monument (No. 1002628) ant growth vate closure on the west side of the Erme vall heduled Monument (No. 1012767) ant growth vate edieval settlement on Ford Waste, Cornw heduled Monument (No. 1002627) rub / tree growth vate re southern of three enclosures north of heduled Monument (No. 1012700) ant growth vate	CONDITION: TREND: CONTACT: rood, South Hams CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700		
OWNER TYPE: Privestee Privestee Privestee Name: Encoursestee Name: Schernicipal Vulnerability: Plai Owner Type: Privestee Name: Mee Designation: Schernicipal Vulnerability: Screment Schernicipal Vulnerability: Screment Privestee Privestee Name: The Designation: Schernicipal Vulnerability: Plai Owner Type: Privestee	vate closure on the west side of the Erme vall heduled Monument (No. 1012767) ant growth vate edieval settlement on Ford Waste, Cornw heduled Monument (No. 1002627) rub / tree growth vate e southern of three enclosures north of heduled Monument (No. 1012700) ant growth	CONTACT: ley below Stalldov CONDITION: TREND: CONTACT: rood, South Hams CONDITION: TREND: CONDITION: Ford Waste, Corr CONDITION:	Declining Business Manager 0117 975 0700 wn, Cornwood, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 wood, South Hams Generally satisfactory but with minor localised problems		
OWNER TYPE: Priv	vate closure on the west side of the Erme vall heduled Monument (No. 1012767) ant growth vate edieval settlement on Ford Waste, Cornw heduled Monument (No. 1002627) rub / tree growth vate e southern of three enclosures north of heduled Monument (No. 1012700) ant growth	CONTACT: ley below Stalldov CONDITION: TREND: CONTACT: rood, South Hams CONDITION: TREND: CONDITION: Ford Waste, Corr CONDITION:	Business Manager 0117 975 0700 wn, Cornwood, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 mwood, South Hams Generally satisfactory but with minor localised problems		
SITE NAME: Encodesignation: Sch PRINCIPAL VULNERABILITY: Pla DOWNER TYPE: Prive SITE NAME: Me DESIGNATION: Sch PRINCIPAL VULNERABILITY: Scr DOWNER TYPE: Prive SITE NAME: The DESIGNATION: Sch PRINCIPAL VULNERABILITY: Pla DOWNER TYPE: Prive	closure on the west side of the Erme val heduled Monument (No. 1012767) ant growth vate edieval settlement on Ford Waste, Cornw heduled Monument (No. 1002627) rub / tree growth vate esouthern of three enclosures north of heduled Monument (No. 1012700) ant growth	ley below Stalldov CONDITION: TREND: CONTACT: vood, South Hams CONDITION: TREND: CONTACT: Ford Waste, Corr	wn, Cornwood, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 hwood, South Hams Generally satisfactory but with minor localised problems		
DESIGNATION: Sch PRINCIPAL VULNERABILITY: Pla DWNER TYPE: Priv BITE NAME: Me DESIGNATION: Sch PRINCIPAL VULNERABILITY: Scr DWNER TYPE: Priv DESIGNATION: Sch PRINCIPAL VULNERABILITY: Pla DWNER TYPE: Priv	heduled Monument (No. 1012767) ant growth vate edieval settlement on Ford Waste, Cornw heduled Monument (No. 1002627) rub / tree growth vate re southern of three enclosures north of heduled Monument (No. 1012700) ant growth	CONDITION: TREND: CONTACT: rood, South Hams CONDITION: TREND: CONTACT: Ford Waste, Corr CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 wood, South Hams Generally satisfactory but with minor localised problems		
PRINCIPAL VULNERABILITY: Pla DWNER TYPE: Priv SITE NAME: Me DESIGNATION: Sch PRINCIPAL VULNERABILITY: Scr DWNER TYPE: Priv SITE NAME: The DESIGNATION: Sch PRINCIPAL VULNERABILITY: Pla DWNER TYPE: Priv	edieval settlement on Ford Waste, Cornw heduled Monument (No. 1002627) rub / tree growth vate e southern of three enclosures north of heduled Monument (No. 1012700) ant growth	TREND: CONTACT: Yood, South Hams CONDITION: TREND: CONTACT: Ford Waste, Corr	but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 wood, South Hams Generally satisfactory but with minor localised problems		
PRINCIPAL VULNERABILITY: Pla owner type: Priv site name: Me designation: Sch principal vulnerability: Scr owner type: Priv site name: The designation: Sch principal vulnerability: Pla owner type: Priv	edieval settlement on Ford Waste, Cornw heduled Monument (No. 1002627) rub / tree growth vate e southern of three enclosures north of heduled Monument (No. 1012700) ant growth	CONTACT: rood, South Hams CONDITION: TREND: CONTACT: Ford Waste, Corr CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 wood, South Hams Generally satisfactory but with minor localised problems		
DWNER TYPE: Privester Privester Name: Me Designation: Sch PRINCIPAL VULNERABILITY: Scr DWNER TYPE: Privester Privester Sch Designation: Sch PRINCIPAL VULNERABILITY: Pla DWNER TYPE: Privester Prive	edieval settlement on Ford Waste, Cornw heduled Monument (No. 1002627) rub / tree growth vate e southern of three enclosures north of heduled Monument (No. 1012700) ant growth	CONTACT: rood, South Hams CONDITION: TREND: CONTACT: Ford Waste, Corr CONDITION:	Declining Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 wood, South Hams Generally satisfactory but with minor localised problems		
OWNER TYPE: Privestee Privestee Privestee Name: Meedesignation: Schernicipal vulnerability: Screen Privestee Privestee Privestee Privestee Schernicipal vulnerability: Privestee	edieval settlement on Ford Waste, Cornw heduled Monument (No. 1002627) rub / tree growth vate e southern of three enclosures north of heduled Monument (No. 1012700) ant growth	vood, South Hams CONDITION: TREND: CONTACT: Ford Waste, Corr CONDITION:	Business Manager 0117 975 0700 Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 wood, South Hams Generally satisfactory but with minor localised problems		
DESIGNATION: Sch PRINCIPAL VULNERABILITY: Scr DWINER TYPE: Priv SITE NAME: The DESIGNATION: Sch PRINCIPAL VULNERABILITY: Play DWINER TYPE: Priv	heduled Monument (No. 1002627) rub / tree growth vate ne southern of three enclosures north of heduled Monument (No. 1012700) ant growth	CONDITION: TREND: CONTACT: Ford Waste, Corr CONDITION:	Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 wood, South Hams Generally satisfactory but with minor localised problems		
PRINCIPAL VULNERABILITY: Scr DWNER TYPE: Priv SITE NAME: The DESIGNATION: Sch PRINCIPAL VULNERABILITY: Pla DWNER TYPE: Priv	rub / tree growth vate ne southern of three enclosures north of neduled Monument (No. 1012700) ant growth	TREND: CONTACT: Ford Waste, Corr CONDITION:	but with minor localised problems Declining Business Manager 0117 975 0700 wood, South Hams Generally satisfactory but with minor localised problems		
OWNER TYPE: Priv	vate ne southern of three enclosures north of heduled Monument (No. 1012700) unt growth	CONTACT: Ford Waste, Corr CONDITION:	Declining Business Manager 0117 975 0700 wood, South Hams Generally satisfactory but with minor localised problems		
OWNER TYPE: Priv	vate ne southern of three enclosures north of heduled Monument (No. 1012700) unt growth	CONTACT: Ford Waste, Corr CONDITION:	Business Manager 0117 975 0700 wood, South Hams Generally satisfactory but with minor localised problems		
DESIGNATION: Sch PRINCIPAL VULNERABILITY: PIA DWINER TYPE: Priv	neduled Monument (No. 1012700) Int growth	CONDITION:	Generally satisfactory but with minor localised problems		
principal vulnerability: Pla owner type: Prin	int growth		but with minor localised problems		
principal vulnerability: Pla owner type: Prin	int growth	TREND:	but with minor localised problems		
OWNERTYPE: Priv	-	TREND:	Declining		
	vate				
		CONTACT:	Business Manager 0117 975 0700		
	Three unenclosed stone hut circles on the west side of the Erme Valley, north of Lower Piles, Cornwood, South Hams				
designation: Sch	neduled Monument (No. 1012768)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY: Pla	int growth	TREND:	Declining		
OWNER TYPE: Priv	vate	CONTACT:	Business Manager 0117 975 0700		
	o hut circles on the south east slope of S	Stalldown, Cornw	ood, South Hams		
designation: Sch	neduled Monument (No. 1012766)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY: Pla	int growth	TREND:	Declining		
	vate	CONTACT:	Business Manager 0117 975 0700		
SITE NAME: Un	Unenclosed stone hut settlement north east of Yadsworthy, Cornwood, South Hams				
designation: Sch	neduled Monument (No. 1012771)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY: Pla	int growth	TREND:	Declining		
OWNER TYPE: Priv	vate	CONTACT:	Business Manager 0117 975 0700		
	closure and hut circles east of Huntingdo	on Ford, Dean Pric	or, South Hams		
designation: Sch	neduled Monument (No. 1002536)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY: Pla	int growth	TREND:	Declining		
	vate	CONTACT:	Business Manager 0117 975 0700		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Hut circles and two enclosures on Dean M	oor, near River Av	on, Dean Prior, South Hams
DESIGNATION:	Scheduled Monument (No. 1003828)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Agglomerated enclosure with hut circles, so	outh of Lower Pile	es, Harford, South Hams
DESIGNATION:	Scheduled Monument (No. 1009578)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Blowing house at junction of Hook Lake an	d River Erme. Ha	ford. South Hams
DESIGNATION:	Scheduled Monument (No. 1002605)	CONDITION:	Generally satisfactory
JESIGNATION:	Scheddied Hohdment (140. 1002005)	CONDITION:	but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Blowing house north of Dry Lake, Harford,	South Hams	
DESIGNATION:	Scheduled Monument (No. 1002609)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cairn in north east corner of Lower Piles, I	Harford, South Ha	ıms
DESIGNATION:	Scheduled Monument (No. 1009575)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Enclosure and hut circles at Piles Corner, H	larford, South Har	ns
	Enclosure and hut circles at Piles Corner, H Scheduled Monument (No. 1013108)	larford, South Har	ns Generally unsatisfactory
	·	,	
DESIGNATION:	·	,	Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1013108)	CONDITION:	Generally unsatisfactory with major localised problems
designation: Principal Vulnerability: Owner Type:	Scheduled Monument (No. 1013108) Plant growth	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: 5ITE NAME:	Scheduled Monument (No. 1013108) Plant growth Private	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1013108) Plant growth Private Enclosure with hut circles east of Addicomt Scheduled Monument (No. 1012484)	CONDITION: TREND: CONTACT: Dee, Harford, South	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1013108) Plant growth Private Enclosure with hut circles east of Addicomb	CONDITION: TREND: CONTACT: De, Harford, South CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1013108) Plant growth Private Enclosure with hut circles east of Addicomt Scheduled Monument (No. 1012484) Plant growth	CONDITION: TREND: CONTACT: Dee, Harford, South CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1013108) Plant growth Private Enclosure with hut circles east of Addicomt Scheduled Monument (No. 1012484) Plant growth	CONDITION: TREND: CONTACT: De, Harford, South CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1013108) Plant growth Private Enclosure with hut circles east of Addicome Scheduled Monument (No. 1012484) Plant growth Private	CONDITION: TREND: CONTACT: De, Harford, South CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1013108)         Plant growth         Private         Enclosure with hut circles east of Addicomb         Scheduled Monument (No. 1012484)         Plant growth         Private         Enclosure with hut circles east of Addicomb         Scheduled Monument (No. 1012484)         Scheduled Monument (No. 1012484)         Scheduled Monument (No. 1012484)	CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONTACT: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1013108)         Plant growth         Private         Enclosure with hut circles east of Addicomt         Scheduled Monument (No. 1012484)         Plant growth         Private         Enclosure with hut circles east of Addicomt         Plant growth         Private         Enclosure with hut circles east of Addicomt	CONDITION: TREND: CONTACT: De, Harford, South CONDITION: TREND: CONTACT: De, Harford, South	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Enclosure with hut circles in Higher Piles n	critane, i latioi d, s	
DESIGNATION:	Scheduled Monument (No. 1013110)	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Enclosure with hut circles to the north eas	t of Piles Copse, H	Harford, South Hams
DESIGNATION:	Scheduled Monument (No. 1013106)	CONDITION:	Generally satisfactory
	Plant growth	70010	but with significant localised problems Declining
PRINCIPAL VULNERABILITY:	Plant growth Private	TREND:	Business Manager 0117 975 0700
DWNER TYPE:	FIVALE	CONTACT:	Business Manager 0117 973 0700
ITE NAME:	Hut circles and enclosure to south of Left I	Lake, Harford, Sou	th Hams
DESIGNATION:	Scheduled Monument (No. 1004574)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hut circles in Erme Pound east of River Err	ne, Harford, Soutl	n Hams
DESIGNATION:	Scheduled Monument (No. 1002604)	CONDITION:	Generally unsatisfactory
		2518.0014	with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
Swinely the L		CONTACT.	
SITE NAME:	Stone row, cairn and enclosures near Hook	Lane, Erme Valley	, Harford, South Hams
DESIGNATION:	Scheduled Monument (No. 1002493)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Unenclosed stone hut settlement on the ea north Harford Moor, Harford, South Hams	ast side of the Ern	ne Valley,
DESIGNATION:	Scheduled Monument (No. 1012747)	CONDITION:	Generally satisfactory
	Plant growth	TRENE	but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth Private	TREND:	Declining Business Manager 0117 975 0700
DWNER TYPE:	rivate	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Unenclosed stone hut settlement with encl	osures north of P	iles Copse, Harford, South Hams
DESIGNATION:	Scheduled Monument (No. 1012765)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	Eight cairns forming part of a cairn cemeter and a stone alignment immediately west of		
SITE NAME:			
SITE NAME: DESIGNATION:	Scheduled Monument (No. 1019273)	CONDITION:	Generally satisfactory but with significant localised problems
	Scheduled Monument (No. 1019273) Plant growth	CONDITION: TREND:	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

ITE NAME:	Enclosed prehistoric settlement and round 880m south west of Venford Reservoir dam		ams	
DESIGNATION:	Scheduled Monument (No. 1020095)	CONDITION:	Generally satisfactory but with significant localised problems	
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Enclosed prehistoric settlement and three r Holne. South Hams	ound cairns 870n	n south east of Horn's Cross,	
DESIGNATION:	Scheduled Monument (No. 1020096)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Four cairns 310m south of Horn's Cross fo on Holne Ridge, Holne, South Hams	rming part of a ca	irn cemetery	
DESIGNATION:	Scheduled Monument (No. 1019272)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Four cairns on Holne Lee I 140m north we	st of Greatcombe	, Holne, South Hams	
DESIGNATION:	Scheduled Monument (No. 1019268)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Holne Chase Castle, Holne, South Hams			
DESIGNATION:	Scheduled Monument (No. 1003842)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Medieval farmstead and field system, post-n and cairns north and west of Gibby Coomb			
DESIGNATION:	Scheduled Monument (No. 1019591)	CONDITION:	Generally satisfactory	
PRINCIPAL VULNERABILITY:	Plant growth	TRENID	but with significant localised problems Declining	
PRINCIPAL VOLNERABILITY:	Local Authority	TREND: CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Part of the Dartmeet coaxial field system a		logical remains	
designation:	on Holne Moor west and north west of Ver Scheduled Monument (No. 1020487)	nford Reservoir, H CONDITION:	Iolne, South Hams Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining Business Manager 0117 975 0700	
OWNER TYPE:	Local Authority	CONTACT:	Dushless Flandger 0117 775 0700	
	Partially enclosed stone hut circle settlement 350m south west of Horn's Cross, Holne, South Hams			
SITE NAME:	,			
	Scheduled Monument (No. 1019274)	CONDITION:	Generally satisfactory but with significant localised problems	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:		CONDITION: TREND:		

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ITE NAME:	Partially enclosed stone hut circle settlement 420m north west and 440m west of Horn's		uth Hams
DESIGNATION:	Scheduled Monument (No. 1020185)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Partially enclosed stone hut circle settlement	nt 560m west of I	Horn's Cross, Holne, South Hams
DESIGNATION:	Scheduled Monument (No. 1019275)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric fields and settlements north eas forming part of the Dartmeet coaxial field s		
DESIGNATION:	Scheduled Monument (No. 1020091)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric fields, settlements and cairn sou forming part of the Dartmeet coaxial field s		
DESIGNATION:	Scheduled Monument (No. 1020092)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Ringleshutes tinwork, Holne, South Hams		
DESIGNATION:	Scheduled Monument (No. 1020098)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone hut circle and length of boundary wa Holne, South Hams	lling 860m south	west of Venford Reservoir dam,
DESIGNATION:	Scheduled Monument (No. 1020094)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Three stone hut circles 780m SSW of Venfc	ord Reservoir dan	n, Holne, South Hams
	Scheduled Monument (No. 1020093)		Generally satisfactory
DESIGNATION:		CONDITION:	but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
	Two ring cairns 330m south east of Coldha	rbour Cross, Lod	diswell, South Hams
SITE NAME:		CONDITION:	Generally unsatisfactory
	Scheduled Monument (No. 1014244)	CONDITION.	, , ,
		CONDITION.	with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1014244) Dumping	TREND:	, , ,

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

ITE NAME:	A stone alignment, kerbed cairn, prehistoric a vermin trap and animal runs 720m south		wlesworthy Tor, Shaugh Prior, South Hams
DESIGNATION:	Scheduled Monument (No. 1016147)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Agglomerated enclosure with hut circles so	outh west of Ditsv	vorthy Clam, Shaugh Prior, South Hams
DESIGNATION:	Scheduled Monument (No. 1009573)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
site name:	An enclosed settlement, length of reave, tw 770m east of Trowlesworthy Warren Hous		
DESIGNATION:	Scheduled Monument (No. 1015748)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	- TIVAC	CONTACT:	
SITE NAME:	An unenclosed stone hut circle settlement Shaugh Prior, South Hams	760m north east	of Trowlesworthy Warren House,
DESIGNATION:	Scheduled Monument (No. 1014656)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
OWNERTIPE:	TTVate	CONTACT:	
SITE NAME:	Barrow near Shaugh Cross, Shaugh Prior, So	outh Hams	
DESIGNATION:	Scheduled Monument (No. 1003824)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cairn south of Mill Corner, Shaugh Prior, Sc	outh Hams	
DESIGNATION:	Scheduled Monument (No. 1013413)	CONDITION:	Generally satisfactory
		Condition	but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			5
SITE NAME:	Cairn with a cist east of Willings Walls Rea	ve, Shaugh Prior, S	outh Hams
designation:	Scheduled Monument (No. 1012209)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cairn with a cist, one of several on the wes	stern edge of Lee	Moor, Shaugh Prior, South Hams
SHE NAHE.	Schodulad Manumant (Na. 10120EL)	CONDITION:	Generally satisfactory
	Scheduled Monument (No. 1012051)	constition.	but with minor localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Plant growth	TREND:	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Cross Dyke reave, Shaugh Prior, South Ham	าร	
DESIGNATION:	Scheduled Monument (No. 1010811)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Double stone alignment with a terminal sto Shaugh Prior, South Hams	one setting south o	of Great Trowlesworthy Tor,
DESIGNATION:	Scheduled Monument (No. 1012114)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Eight pillow mounds and a vermin trap on t forming part of Trowlesworthy Warren, Sha		
DESIGNATION:	Scheduled Monument (No. 1015758)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Enclosed stone hut circle settlement and th	nree round cairns	5
DESIGNATION:	Scheduled Monument (No. 1019081)	CONDITION:	Generally satisfactory
	Plant growth	TOPUP	but with significant localised problems
PRINCIPAL VULNERABILITY:	i idill giowlii	TREND:	Declining
	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	-		
OWNER TYPE:	Private Enclosure with hut circles west of Plym Ste Scheduled Monument (No. 1012297)		
OWNER TYPE: SITE NAME: DESIGNATION:	Private Enclosure with hut circles west of Plym Ste	ps, Shaugh Prior, S	outh Hams Generally satisfactory but with significant localised problems Declining
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Enclosure with hut circles west of Plym Ste Scheduled Monument (No. 1012297)	ps, Shaugh Prior, S condition:	outh Hams Generally satisfactory but with significant localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Enclosure with hut circles west of Plym Ste Scheduled Monument (No. 1012297) Plant growth	eps, Shaugh Prior, S Condition: trend: Contact:	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:	Private Enclosure with hut circles west of Plym Ste Scheduled Monument (No. 1012297) Plant growth Private	eps, Shaugh Prior, S Condition: trend: Contact:	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory
OWNER TYPE: SITE NAME: DESIGNATION: OWNER TYPE: SITE NAME: DESIGNATION:	Private Enclosure with hut circles west of Plym Stee Scheduled Monument (No. 1012297) Plant growth Private Hut circles west of Saddlesborough, Shaugh Scheduled Monument (No. 1002520)	Pps, Shaugh Prior, S CONDITION: TREND: CONTACT: Prior, South Ham CONDITION:	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Enclosure with hut circles west of Plym Ste Scheduled Monument (No. 1012297) Plant growth Private Hut circles west of Saddlesborough, Shaugh Scheduled Monument (No. 1002520) Plant growth	Pps, Shaugh Prior, S CONDITION: TREND: CONTACT: Prior, South Ham CONDITION: TREND:	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory with major localised problems Declining
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Enclosure with hut circles west of Plym Stee Scheduled Monument (No. 1012297) Plant growth Private Hut circles west of Saddlesborough, Shaugh Scheduled Monument (No. 1002520)	Pps, Shaugh Prior, S CONDITION: TREND: CONTACT: Prior, South Ham CONDITION:	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Enclosure with hut circles west of Plym Ste Scheduled Monument (No. 1012297) Plant growth Private Hut circles west of Saddlesborough, Shaugh Scheduled Monument (No. 1002520) Plant growth	Pps, Shaugh Prior, S CONDITION: TREND: CONTACT: Prior, South Ham CONDITION: TREND: CONTACT: Of Willings Walls	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Reave, four round cairns,
OWNER TYPE:	Private Enclosure with hut circles west of Plym Ste Scheduled Monument (No. 1012297) Plant growth Private Hut circles west of Saddlesborough, Shaugh Scheduled Monument (No. 1002520) Plant growth Private Medieval farmstead and field system, length	Pps, Shaugh Prior, S CONDITION: TREND: CONTACT: Prior, South Ham CONDITION: TREND: CONTACT: Of Willings Walls	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Reave, four round cairns,
OWNER TYPE:	Private Enclosure with hut circles west of Plym Stee Scheduled Monument (No. 1012297) Plant growth Private Hut circles west of Saddlesborough, Shaugh Scheduled Monument (No. 1002520) Plant growth Private Medieval farmstead and field system, length a ring cairn and pillow mounds at Willings V	Pps, Shaugh Prior, S CONDITION: TREND: CONTACT: Prior, South Ham CONDITION: TREND: CONTACT: of Willings Walls Valls Warren, Shau	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Reave, four round cairns, igh Prior, South Hams Generally unsatisfactory
OWNER TYPE:	Private         Enclosure with hut circles west of Plym Ster         Scheduled Monument (No. 1012297)         Plant growth         Private         Hut circles west of Saddlesborough, Shaugh         Scheduled Monument (No. 1002520)         Plant growth         Private         Medieval farmstead and field system, length a ring cairn and pillow mounds at Willings V         Scheduled Monument (No. 1019083)	Pps, Shaugh Prior, S CONDITION: TREND: CONTACT: Prior, South Ham CONDITION: TREND: CONTACT: of Willings Walls Valls Warren, Shau CONDITION:	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Reave, four round cairns, ugh Prior, South Hams Generally unsatisfactory with major localised problems
OWNER TYPE:	Private         Enclosure with hut circles west of Plym Ster         Scheduled Monument (No. 1012297)         Plant growth         Private         Hut circles west of Saddlesborough, Shaugh         Scheduled Monument (No. 1002520)         Plant growth         Private         Medieval farmstead and field system, length a ring cairn and pillow mounds at Willings V         Scheduled Monument (No. 1019083)         Plant growth	Pps, Shaugh Prior, S CONDITION: TREND: CONTACT: Prior, South Ham CONDITION: TREND: CONTACT: of Willings Walls Valls Warren, Shau CONDITION:	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Reave, four round cairns, Igh Prior, South Hams Generally unsatisfactory with major localised problems Declining
OWNER TYPE:	Private         Enclosure with hut circles west of Plym Ster         Scheduled Monument (No. 1012297)         Plant growth         Private         Hut circles west of Saddlesborough, Shaugh         Scheduled Monument (No. 1002520)         Plant growth         Private         Medieval farmstead and field system, length a ring cairn and pillow mounds at Willings V         Scheduled Monument (No. 1019083)         Plant growth         Private         Medieval farmstead and field system, length a ring cairn and pillow mounds at Willings V         Scheduled Monument (No. 1019083)         Plant growth         Private         Multi-period remains at Hentor Warren, Sh	Pps, Shaugh Prior, S CONDITION: TREND: CONTACT: Prior, South Ham CONDITION: TREND: CONTACT: Of Willings Walls Valls Warren, Shau CONDITION: TREND: CONTACT:	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Reave, four round cairns, igh Prior, South Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams
OWNER TYPE:	Private         Enclosure with hut circles west of Plym Ster         Scheduled Monument (No. 1012297)         Plant growth         Private         Hut circles west of Saddlesborough, Shaugh         Scheduled Monument (No. 1002520)         Plant growth         Private         Medieval farmstead and field system, length a ring cairn and pillow mounds at Willings V         Scheduled Monument (No. 1019083)         Plant growth         Private	Pps, Shaugh Prior, S CONDITION: TREND: CONTACT: Prior, South Ham CONDITION: TREND: CONTACT: Of Willings Walls Valls Warren, Shau CONDITION: TREND: CONTACT:	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Reave, four round cairns, ugh Prior, South Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private         Enclosure with hut circles west of Plym Ster         Scheduled Monument (No. 1012297)         Plant growth         Private         Hut circles west of Saddlesborough, Shaugh         Scheduled Monument (No. 1002520)         Plant growth         Private         Medieval farmstead and field system, length a ring cairn and pillow mounds at Willings V         Scheduled Monument (No. 1019083)         Plant growth         Private         Medieval farmstead and field system, length a ring cairn and pillow mounds at Willings V         Scheduled Monument (No. 1019083)         Plant growth         Private         Multi-period remains at Hentor Warren, Sh	Pps, Shaugh Prior, S CONDITION: TREND: CONTACT: Prior, South Ham CONDITION: TREND: CONTACT: of Willings Walls Walls Warren, Shau CONDITION: TREND: CONTACT:	outh Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 s Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Reave, four round cairns, igh Prior, South Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

ITE NAME:	One of a number of cairns with cists south		-
DESIGNATION:	Scheduled Monument (No. 1012214)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	One of a number of cairns with cists south	of Shavercombe I	Brook, Shaugh Prior, South Hams
DESIGNATION:	Scheduled Monument (No. 1012172)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	One of three stone hut circles 500m SSE o	f Legis Tor, Shaugh	Prior, South Hams
DESIGNATION:	Scheduled Monument (No. 1012631)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Pillow mound 100m south east of Great Tro forming part of Trowlesworthy Warren, Sha		Hams
DESIGNATION:	Scheduled Monument (No. 1014666)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Pillow mound 160m south west of Great Tr forming part of Trowlesworthy Warren, Sha		Hams
DESIGNATION:	Scheduled Monument (No. 1014665)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Pillow mound 270m south east of Ditsword forming part of Hentor Warren, Shaugh Pri		
DESIGNATION:	Scheduled Monument (No. 1014477)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Pillow mound 530m ENE of Trowlesworthy forming part of Trowlesworthy Warren, Sha		Hams
DESIGNATION:	Scheduled Monument (No. 1014462)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Pillow mound 610m SSW of Ditsworthy Wa forming part of Willings Walls Warren, Shau		ams
DESIGNATION:	Scheduled Monument (No. 1014469)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Pillow mound 620m ESE of Legis for forming	ng part of Willings	Walls Warren, Shaugh Prior, South Hams	
DESIGNATION:	Scheduled Monument (No. 1014457)	CONDITION:	Generally satisfactory	
			but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Pillow mound 630m east of Legis Tor formi	ng part of Willing	s Walls Warren, Shaugh Prior, South Hams	
DESIGNATION:	Scheduled Monument (No. 1015742)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Pillow mound 760m ENE of Trowlesworthy forming part of Trowlesworthy Warren, Sha		Hams	
DESIGNATION:	Scheduled Monument (No. 1014611)	CONDITION:	Generally unsatisfactory	
		CONDITION.	with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
			-	
SITE NAME:	Pillow mound 790m NNE of Blackaton Cro Shaugh Prior, South Hams	oss, forming part c	of Trowlesworthy Warren,	
DESIGNATION:	Scheduled Monument (No. 1014662)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Pillow mound 840m north east of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams			
DESIGNATION:	forming part of Trowlesworthy Warren, Sha Scheduled Monument (No. 1014658)	,		
DESIGNATION:		ugh Prior, South H	Hams	
		ugh Prior, South H	Hams Generally satisfactory	
PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1014658)	ugh Prior, South H	Hams Generally satisfactory but with minor localised problems	
PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1014658) Plant growth Private Pillow mound 860m NNW of Blackaton Cr	ugh Prior, South H Condition: Trend: Contact: oss,	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700	
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No. 1014658) Plant growth Private Pillow mound 860m NNW of Blackaton Cr forming part of Trowlesworthy Warren, Sha	CONDITION: TREND: CONTACT: CONTACT:	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700	
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No. 1014658) Plant growth Private Pillow mound 860m NNW of Blackaton Cr	ugh Prior, South H Condition: Trend: Contact: oss,	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory	
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1014658) Plant growth Private Pillow mound 860m NNW of Blackaton Cr forming part of Trowlesworthy Warren, Sha Scheduled Monument (No. 1014664)	CONDITION: TREND: CONTACT: CONTACT:	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems	
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1014658) Plant growth Private Pillow mound 860m NNW of Blackaton Cr forming part of Trowlesworthy Warren, Sha	CONDITION: TREND: CONTACT: TOSS, Augh Prior, South H CONDITION:	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory	
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1014658) Plant growth Private Pillow mound 860m NNW of Blackaton Cr forming part of Trowlesworthy Warren, Sha Scheduled Monument (No. 1014664) Plant growth Private	Lugh Prior, South H CONDITION: TREND: CONTACT: CONTACT: TREND: CONDITION: TREND: CONTACT:	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems Declining	
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No. 1014658) Plant growth Private Pillow mound 860m NNW of Blackaton Cr forming part of Trowlesworthy Warren, Sha Scheduled Monument (No. 1014664) Plant growth	Lugh Prior, South H CONDITION: TREND: CONTACT: TOSS, Lugh Prior, South H CONDITION: TREND: CONTACT: Warren House,	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700	
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No. 1014658) Plant growth Private Pillow mound 860m NNW of Blackaton Cr forming part of Trowlesworthy Warren, Sha Scheduled Monument (No. 1014664) Plant growth Private Pillow mound 860m SSE of Trowlesworthy	Lugh Prior, South H CONDITION: TREND: CONTACT: TOSS, Lugh Prior, South H CONDITION: TREND: CONTACT: Warren House,	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700	
PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION:	Scheduled Monument (No. 1014658)         Plant growth         Private         Pillow mound 860m NNW of Blackaton Cr         forming part of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014664)         Plant growth         Private         Pillow mound 860m SSE of Trowlesworthy forming part of Trowlesworthy Warren, Sha	Augh Prior, South H CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: Warren House, Augh Prior, South H	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory	
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1014658)         Plant growth         Private         Pillow mound 860m NNW of Blackaton Cr         forming part of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014664)         Plant growth         Private         Pillow mound 860m SSE of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014664)         Scheduled Monument (No. 1014664)	Augh Prior, South H CONDITION: TREND: CONTACT: CONTACT: TREND: CONDITION: TREND: CONTACT: Warren House, Augh Prior, South H CONDITION:	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No. 1014658)         Plant growth         Private         Pillow mound 860m NNW of Blackaton Cr         forming part of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014664)         Plant growth         Private         Pillow mound 860m SSE of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014664)         Plant growth         Private         Pillow mound 860m SSE of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014616)         Plant growth	Augh Prior, South H CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: Warren House, Hugh Prior, South H CONDITION: TREND: CONDITION: TREND: CONDITION:	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Manager 0117 975 0700	
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1014658)         Plant growth         Private         Pillow mound 860m NNW of Blackaton Cr         forming part of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014664)         Plant growth         Private         Pillow mound 860m SSE of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014664)         Plant growth         Private         Pillow mound 860m SSE of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014616)         Plant growth         Private         Pillow mound and animal run 830m north of	Augh Prior, South H CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: Warren House, Hugh Prior, South H CONDITION: TREND: CONDITION: TREND: CONDITION:	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Manager 0117 975 0700	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1014658)         Plant growth         Private         Pillow mound 860m NNW of Blackaton Cr         forming part of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014664)         Plant growth         Private         Pillow mound 860m SSE of Trowlesworthy forming part of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014664)         Plant growth         Private         Pillow mound 860m SSE of Trowlesworthy Warren, Sha         Scheduled Monument (No. 1014616)         Plant growth         Private         Pillow mound and animal run 830m north of forming part of Trowlesworthy Warren, Sha	Augh Prior, South H CONDITION: TREND: CONTACT: TOSS, Augh Prior, South H CONDITION: TREND: CONTACT: Warren House, Jugh Prior, South H CONDITION: TREND: CONDITION: TREND: CONTACT:	Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Hams Declining Business Manager 0117 975 0700	

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Concentration
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

DITE NAME:	Pound and hut circles north of Hawk's Tor,	Shaugh Prior, Sout	:h Hams
esignation:	Scheduled Monument (No. 1002516)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Pounds and hut circles north of Saddlesbor	ough, Shaugh Prio	r, South Hams
DESIGNATION:	Scheduled Monument (No. 1002517)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Rectangular building 420m north west of H Shaugh Prior, South Hams	len Tor, forming an	outlying part of Hentor Farm,
DESIGNATION:	Scheduled Monument (No. 1020011)	CONDITION:	Generally satisfactory
			but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Round cairn on Lee Moor 950m south east	t of Great Trowles	worthy Tor, Shaugh Prior, South Hams
DESIGNATION:	Scheduled Monument (No. 1015753)	CONDITION:	Generally satisfactory but with minor localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Stone hut circle north east of Hentor Broc	ok, Shaugh Prior, So	outh Hams
DITE NAME: DESIGNATION:	Stone hut circle north east of Hentor Broc Scheduled Monument (No. 1012175)	ok, Shaugh Prior, So	Generally satisfactory
designation:		-	
DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012175)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No. 1012175) Plant growth	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Scheduled Monument (No. 1012175) Plant growth Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION:	Scheduled Monument (No. 1012175) Plant growth Private Stone hut circle north of Hentor Brook, Sh	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012175) Plant growth Private Stone hut circle north of Hentor Brook, Sh Scheduled Monument (No. 1012083)	CONDITION: TREND: CONTACT: haugh Prior, South CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems
	Scheduled Monument (No. 1012175) Plant growth Private Stone hut circle north of Hentor Brook, Sh Scheduled Monument (No. 1012083) Plant growth	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE:	Scheduled Monument (No. 1012175) Plant growth Private Stone hut circle north of Hentor Brook, Sh Scheduled Monument (No. 1012083) Plant growth Private	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 thy Tor, Shaugh Prior, South Hams Generally satisfactory
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: DESIGNATION:	Scheduled Monument (No. 1012175)         Plant growth         Private         Stone hut circle north of Hentor Brook, Sh         Scheduled Monument (No. 1012083)         Plant growth         Private         Stone hut circle settlement 600m ENE of C         Scheduled Monument (No. 1018356)	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hy Tor, Shaugh Prior, South Hams Generally satisfactory but with significant localised problems
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012175)         Plant growth         Private         Stone hut circle north of Hentor Brook, Sh         Scheduled Monument (No. 1012083)         Plant growth         Private         Stone hut circle settlement 600m ENE of Com	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: Great Trowleswort CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hy Tor, Shaugh Prior, South Hams Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIP	Scheduled Monument (No. 1012175)         Plant growth         Private         Stone hut circle north of Hentor Brook, Sh         Scheduled Monument (No. 1012083)         Plant growth         Private         Stone hut circle settlement 600m ENE of C         Scheduled Monument (No. 1018356)         Plant growth	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hy Tor, Shaugh Prior, South Hams Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE: DITE NAME:	Scheduled Monument (No. 1012175)         Plant growth         Private         Stone hut circle north of Hentor Brook, Sh         Scheduled Monument (No. 1012083)         Plant growth         Private         Stone hut circle settlement 600m ENE of C         Scheduled Monument (No. 1018356)         Plant growth	CONDITION: TREND: CONTACT: augh Prior, South CONDITION: TREND: CONTACT: Great Trowleswort CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hy Tor, Shaugh Prior, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Trowlesworthy Tor
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No. 1012175)         Plant growth         Private         Stone hut circle north of Hentor Brook, Sh         Scheduled Monument (No. 1012083)         Plant growth         Private         Stone hut circle settlement 600m ENE of C         Scheduled Monument (No. 1018356)         Plant growth         Private         Three pillow mounds and a linear gully 200	CONDITION: TREND: CONTACT: augh Prior, South CONDITION: TREND: CONTACT: Great Trowleswort CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hy Tor, Shaugh Prior, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Trowlesworthy Tor
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION:	Scheduled Monument (No. 1012175)         Plant growth         Private         Stone hut circle north of Hentor Brook, Sh         Scheduled Monument (No. 1012083)         Plant growth         Private         Stone hut circle settlement 600m ENE of C         Scheduled Monument (No. 1018356)         Plant growth         Private         Three pillow mounds and a linear gully 200 forming part of Trowlesworthy Warren, Sharpower (No. 1018)	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Hy Tor, Shaugh Prior, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Trowlesworthy Tor tams Generally satisfactory

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

SITE NAME:	Two pillow mounds 640m ENE of Trowlesw forming part of Trowlesworthy Warren, Sha		
DESIGNATION:	Scheduled Monument (No. 1015747)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two pillow mounds and a small area of tin s forming part of Willings Walls Warren, Shau		
DESIGNATION:	Scheduled Monument (No. 1014467)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two pillow mounds and a small area of tin s 770m north of Blackaton Cross, forming pa		
DESIGNATION:	Scheduled Monument (No. 1014663)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two round cairns 600m ENE of Great Trow	lesworthy Tor, Sh	augh Prior, South Hams
DESIGNATION:	Scheduled Monument (No. 1018357)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
	-		0
	Private Two stone hut circles and an enclosure 680	CONTACT: m ENE of Trowle	Business Manager 0117 975 0700 sworthy Warren House,
SITE NAME:			sworthy Warren House, Generally satisfactory
SITE NAME: DESIGNATION:	Two stone hut circles and an enclosure 680 Shaugh Prior, South Hams Scheduled Monument (No. 1014615)	m ENE of Trowle	Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Two stone hut circles and an enclosure 680 Shaugh Prior, South Hams	m ENE of Trowle	sworthy Warren House, Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Two stone hut circles and an enclosure 680 Shaugh Prior, South Hams Scheduled Monument (No. 1014615) Plant growth Private	m ENE of Trowle condition: trend: contact:	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Two stone hut circles and an enclosure 680 Shaugh Prior, South Hams Scheduled Monument (No. 1014615) Plant growth Private Two stone hut circles north of Spanish Lake	m ENE of Trowle CONDITION: TREND: CONTACT: 2, Lee Moor, Shaug	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gh Prior, South Hams
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Two stone hut circles and an enclosure 680 Shaugh Prior, South Hams Scheduled Monument (No. 1014615) Plant growth Private	m ENE of Trowle condition: trend: contact:	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gh Prior, South Hams Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Two stone hut circles and an enclosure 680         Shaugh Prior, South Hams         Scheduled Monument (No. 1014615)         Plant growth         Private         Two stone hut circles north of Spanish Lake         Scheduled Monument (No. 1013058)	m ENE of Trowle CONDITION: TREND: CONTACT: contact: condition:	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gh Prior, South Hams Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Two stone hut circles and an enclosure 680 Shaugh Prior, South Hams Scheduled Monument (No. 1014615) Plant growth Private Two stone hut circles north of Spanish Lake	m ENE of Trowle CONDITION: TREND: CONTACT: 2, Lee Moor, Shaug	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gh Prior, South Hams Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY:	Two stone hut circles and an enclosure 680         Shaugh Prior, South Hams         Scheduled Monument (No. 1014615)         Plant growth         Private         Two stone hut circles north of Spanish Lake         Scheduled Monument (No. 1013058)         Plant growth	m ENE of Trowles CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: TREND:	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gh Prior, South Hams Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE:	Two stone hut circles and an enclosure 680         Shaugh Prior, South Hams         Scheduled Monument (No. 1014615)         Plant growth         Private         Two stone hut circles north of Spanish Lake         Scheduled Monument (No. 1013058)         Plant growth	m ENE of Trowles CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT:	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gh Prior, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Two stone hut circles and an enclosure 680         Shaugh Prior, South Hams         Scheduled Monument (No. 1014615)         Plant growth         Private         Two stone hut circles north of Spanish Lake         Scheduled Monument (No. 1013058)         Plant growth         Private	m ENE of Trowles CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT:	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gh Prior, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: DWNER TYPE: DESIGNATION: DESIGNATION:	Two stone hut circles and an enclosure 680         Shaugh Prior, South Hams         Scheduled Monument (No. 1014615)         Plant growth         Private         Two stone hut circles north of Spanish Lake         Scheduled Monument (No. 1013058)         Plant growth         Private         Unenclosed stone hut circle settlement on formation	m ENE of Trowles CONDITION: TREND: CONTACT: A Lee Moor, Shaug CONDITION: TREND: CONTACT: the western edge	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gh Prior, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 e of Lee Moor, Shaugh Prior, South Hams Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Two stone hut circles and an enclosure 680         Shaugh Prior, South Hams         Scheduled Monument (No. 1014615)         Plant growth         Private         Two stone hut circles north of Spanish Lake         Scheduled Monument (No. 1013058)         Plant growth         Private         Unenclosed stone hut circle settlement on a Scheduled Monument (No. 1012116)	m ENE of Trowles CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: the western edge CONDITION:	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gh Prior, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 e of Lee Moor, Shaugh Prior, South Hams Generally satisfactory but with minor localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Two stone hut circles and an enclosure 680         Shaugh Prior, South Hams         Scheduled Monument (No. 1014615)         Plant growth         Private         Two stone hut circles north of Spanish Lake         Scheduled Monument (No. 1013058)         Plant growth         Private         Unenclosed stone hut circle settlement on scheduled Monument (No. 1012116)         Plant growth         Private	m ENE of Trowles CONDITION: TREND: CONTACT: contron: TREND: CONDITION: TREND: CONDITION: TREND: TREND:	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 prior, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 cof Lee Moor, Shaugh Prior, South Hams Generally satisfactory but with minor localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: OWNER TYPE:	Two stone hut circles and an enclosure 680         Shaugh Prior, South Hams         Scheduled Monument (No. 1014615)         Plant growth         Private         Two stone hut circles north of Spanish Lake         Scheduled Monument (No. 1013058)         Plant growth         Private         Unenclosed stone hut circle settlement on scheduled Monument (No. 1012116)         Plant growth         Private	m ENE of Trowles  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONTACT:  wlesworthy Tor	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gh Prior, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 cof Lee Moor, Shaugh Prior, South Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Two stone hut circles and an enclosure 680         Scheduled Monument (No. 1014615)         Plant growth         Private         Two stone hut circles north of Spanish Lake         Scheduled Monument (No. 1013058)         Plant growth         Private         Unenclosed stone hut circle settlement on scheduled Monument (No. 1012116)         Plant growth         Private         Unenclosed stone hut circle settlement on scheduled Monument (No. 1012116)         Plant growth         Private         Vermin trap 350m south west of Great Trov	m ENE of Trowles  CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONDITION:  TREND: CONTACT:  wlesworthy Tor	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gh Prior, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 cof Lee Moor, Shaugh Prior, South Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams Generally unsatisfactory
OWNER TYPE:	Two stone hut circles and an enclosure 680         Shaugh Prior, South Hams         Scheduled Monument (No. 1014615)         Plant growth         Private         Two stone hut circles north of Spanish Lake         Scheduled Monument (No. 1013058)         Plant growth         Private         Unenclosed stone hut circle settlement on scheduled Monument (No. 1012116)         Plant growth         Private         Vermin trap 350m south west of Great Trow forming part of Trowlesworthy Warren, Sha	m ENE of Trowles CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONTACT: Wlesworthy Tor ugh Prior, South P	sworthy Warren House, Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 prior, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 cof Lee Moor, Shaugh Prior, South Hams Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Hams

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ITE NAME:	Vermin trap 520m SSW of Trowlesworthy V forming part of Trowlesworthy Warren, Sha		Hams
DESIGNATION:	Scheduled Monument (No. 1014466)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Vermin trap 700m ENE of Trowlesworthy V forming part of Trowlesworthy Warren, Sha		
DESIGNATION:	Scheduled Monument (No. 1014612)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Vermin trap 730m ENE of Trowlesworthy V forming part of Trowlesworthy Warren, Sha		Hams
DESIGNATION:	Scheduled Monument (No. 1014613)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Vermin trap 800m south east of Trowleswo		
	forming part of Trowlesworthy Warren, Sha	ugh Prior, South H	
DESIGNATION:	Scheduled Monument (No. 1014464)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private		
Owner Tipe:	i livate	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cist with a retaining kerb north west of Co		
SITE NAME: DESIGNATION:	Cist with a retaining kerb north west of Co	orringdon Ball, Sou	uth Brent, South Hams Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	<b>Cist with a retaining kerb north west of Co</b> Scheduled Monument (No. 1010180)	orringdon Ball, Sou	u <b>th Brent, South Hams</b> Generally satisfactory but with significant localised problems
SITE NAME:	<b>Cist with a retaining kerb north west of Co</b> Scheduled Monument (No. 1010180) Plant growth	CONDITION: TREND: CONTACT:	uth Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	<b>Cist with a retaining kerb north west of Co</b> Scheduled Monument (No. 1010180) Plant growth Private	CONDITION: TREND: CONTACT:	uth Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 h Hams Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Cist with a retaining kerb north west of Co Scheduled Monument (No. 1010180) Plant growth Private Enclosure and hut circle north of Old Hill, S Scheduled Monument (No. 1003200)	CONDITION: CONDITION: TREND: CONTACT: South Brent, Sout	uth Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 h Hams
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Cist with a retaining kerb north west of Co Scheduled Monument (No. 1010180) Plant growth Private Enclosure and hut circle north of Old Hill, S	CONDITION: CONDITION: TREND: CONTACT: South Brent, South CONDITION:	uth Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 h Hams Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Cist with a retaining kerb north west of Co Scheduled Monument (No. 1010180) Plant growth Private Enclosure and hut circle north of Old Hill, S Scheduled Monument (No. 1003200) Plant growth	CONDITION: CONDITION: TREND: CONTACT: South Brent, South CONDITION: TREND: CONTACT:	Arth Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 h Hams Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Cist with a retaining kerb north west of Co Scheduled Monument (No. 1010180) Plant growth Private Enclosure and hut circle north of Old Hill, S Scheduled Monument (No. 1003200) Plant growth Private	CONDITION: CONDITION: TREND: CONTACT: South Brent, South CONDITION: TREND: CONTACT:	Ath Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 A Hams Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 A Brook, South Brent, South Hams Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: SITE NAME: DESIGNATION:	Cist with a retaining kerb north west of Co Scheduled Monument (No. 1010180) Plant growth Private Enclosure and hut circle north of Old Hill, S Scheduled Monument (No. 1003200) Plant growth Private Enclosure with hut circles and rectangular p Scheduled Monument (No. 1012775)	CONDITION: TREND: CONTACT: South Brent, South CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT:	Ath Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 H Hams Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 A Brook, South Brent, South Hams Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Cist with a retaining kerb north west of Co Scheduled Monument (No. 1010180) Plant growth Private Enclosure and hut circle north of Old Hill, S Scheduled Monument (No. 1003200) Plant growth Private Enclosure with hut circles and rectangular p	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: CONTACT: CONDITION:	Ath Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 H Hams Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 A Brook, South Brent, South Hams Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Cist with a retaining kerb north west of Co Scheduled Monument (No. 1010180) Plant growth Private Enclosure and hut circle north of Old Hill, S Scheduled Monument (No. 1003200) Plant growth Private Enclosure with hut circles and rectangular p Scheduled Monument (No. 1012775) Plant growth	CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION:	Ath Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 H Hams Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 A Brook, South Brent, South Hams Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Cist with a retaining kerb north west of Co Scheduled Monument (No. 1010180) Plant growth Private Enclosure and hut circle north of Old Hill, S Scheduled Monument (No. 1003200) Plant growth Private Enclosure with hut circles and rectangular p Scheduled Monument (No. 1012775) Plant growth	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: Pens, south of Bala	Ath Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 H Hams Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 A Brook, South Brent, South Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Cist with a retaining kerb north west of Construction         Scheduled Monument (No. 1010180)         Plant growth         Private         Enclosure and hut circle north of Old Hill, S         Scheduled Monument (No. 1003200)         Plant growth         Private         Enclosure with hut circles and rectangular private         Scheduled Monument (No. 1012775)         Plant growth         Private	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: Pens, south of Bala	Ath Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 H Hams Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 A Brook, South Brent, South Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
STE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: SITE NAME: SITE NAME:	Cist with a retaining kerb north west of Co Scheduled Monument (No. 1010180) Plant growth Private Enclosure and hut circle north of Old Hill, S Scheduled Monument (No. 1003200) Plant growth Private Enclosure with hut circles and rectangular p Scheduled Monument (No. 1012775) Plant growth Private Enclosure with hut circles north of Bala Bro	CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION:	Ath Brent, South Hams Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 H Hams Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 A Brook, South Brent, South Hams Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Brent, South Hams Generally unsatisfactory

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Enclosure with hut circles north of Bala Bro	ook intake, South	Brent, South Hams
DESIGNATION:	Scheduled Monument (No. 1012783)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Enclosures and hut circles at Petre's Pits Bo	ottom, South Bren	t, South Hams
DESIGNATION:	Scheduled Monument (No. 1004557)	CONDITION:	Generally satisfactory
	· · · ·		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
DITE NAME:	Hut circle and fields, Bishop's Mead, South I	Brent, South Ham	S
DESIGNATION:	Scheduled Monument (No. 1002537)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Hut enclosure north of Old Hill, South Bre	nt, South Hams	
DESIGNATION:	Scheduled Monument (No. 1002664)	CONDITION:	Generally satisfactory
			but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	One of several stone hut circles north of C	Corringdon Ball, Sc	outh Brent, South Hams
	One of several stone hut circles north of C Scheduled Monument (No. 1010202)	Corringdon Ball, Sc	Generally satisfactory
DESIGNATION:		-	Generally satisfactory
DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1010202)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE:	Scheduled Monument (No. 1010202) Plant growth	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining
	Scheduled Monument (No. 1010202) Plant growth Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: 51TE NAME: DESIGNATION:	Scheduled Monument (No. 1010202) Plant growth Private Riders Rings (The Rings), South Brent, Sout	CONDITION: TREND: CONTACT: h Hams	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1010202) Plant growth Private Riders Rings (The Rings), South Brent, Sout Scheduled Monument (No. 1002502)	CONDITION: TREND: CONTACT: h Hams CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: 5ITE NAME:	Scheduled Monument (No. 1010202) Plant growth Private Riders Rings (The Rings), South Brent, Sout Scheduled Monument (No. 1002502) Plant growth	CONDITION: TREND: CONTACT: H Hams CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1010202)         Plant growth         Private         Riders Rings (The Rings), South Brent, South         Scheduled Monument (No. 1002502)         Plant growth         Private	CONDITION: TREND: CONTACT: H Hams CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Ch Brent, South Hams Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DSITE NAME: DESIGNATION:	Scheduled Monument (No. 1010202)         Plant growth         Private         Riders Rings (The Rings), South Brent, South         Scheduled Monument (No. 1002502)         Plant growth         Private         Stone alignment north of Glasscombe Upper	CONDITION: TREND: CONTACT: h Hams CONDITION: TREND: CONTACT: er Plantation, Sout	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Ch Brent, South Hams Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1010202)         Plant growth         Private         Riders Rings (The Rings), South Brent, South         Scheduled Monument (No. 1002502)         Plant growth         Private         Stone alignment north of Glasscombe Upper         Scheduled Monument (No. 1013037)	CONDITION: TREND: CONTACT: h Hams CONDITION: TREND: CONTACT: er Plantation, Sout	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>H Brent, South Hams</b> Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1010202)         Plant growth         Private         Riders Rings (The Rings), South Brent, Sout         Scheduled Monument (No. 1002502)         Plant growth         Private         Stone alignment north of Glasscombe Upper         Scheduled Monument (No. 1013037)         Scrub / tree growth         Private         The northern of three stone hut circles sout	CONDITION: TREND: CONTACT: h Hams CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>th Brent, South Hams</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: D	Scheduled Monument (No. 1010202)         Plant growth         Private         Riders Rings (The Rings), South Brent, Sout         Scheduled Monument (No. 1002502)         Plant growth         Private         Stone alignment north of Glasscombe Upper         Scheduled Monument (No. 1013037)         Scrub / tree growth         Private	CONDITION: TREND: CONTACT: h Hams CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>th Brent, South Hams</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DISTE NAME: DISTE NAME: DISTE NAME: DISTE NAME:	Scheduled Monument (No. 1010202)         Plant growth         Private         Riders Rings (The Rings), South Brent, South         Scheduled Monument (No. 1002502)         Plant growth         Private         Stone alignment north of Glasscombe Upper         Scheduled Monument (No. 1013037)         Scrub / tree growth         Private         The northern of three stone hut circles south         Corringdon Ball, South Brent, South Hams	CONDITION: TREND: CONTACT: h Hams CONDITION: TREND: CONTACT: er Plantation, Sout CONDITION: TREND: CONDITION: Uth west of Corrison	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>th Brent, South Hams</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Three enclosed hut groups, Black Tor, Shiple	ey Bridge, South B	rent, South Hams
DESIGNATION:	Scheduled Monument (No. 1002505)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two conjoined huts between two enclosure	es north of Bala B	rook intake, South Brent, South Hams
DESIGNATION:	Scheduled Monument (No. 1012778)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two hut circles on the right bank of Red B	rook, South Brent	, South Hams
DESIGNATION:	Scheduled Monument (No. 1013035)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Chambered cairn in Cuckoo Ball newtake,	Ugborough, South	Hams
DESIGNATION:	Scheduled Monument (No. 1012284)	CONDITION:	Generally satisfactory
			but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Enclosure with hut circles north of Scad Br	ook, Ugborough, S	South Hams
DESIGNATION:	Scheduled Monument (No. 1012485)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Long cairn east of Butterdon Hill, Ugborou	gh, South Hams	
DESIGNATION:	Scheduled Monument (No. 1012247)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
TTE NAME:	Multiple stone alignment and associated cai Ugborough, South Hams	rns west of Glasso	combe Upper Plantation,
DESIGNATION:	Scheduled Monument (No. 1013031)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
JITE NAME:	One of a number of cairns at Black Pool, U	gborough. South F	Hams
			Generally unsatisfactory
DESIGNATION:	Scheduled Monument (No. 1012232)	CONDITION:	with major localised problems
PRINCIPAL VULNIERARII ITY.	Plant growth	TRENID	Declining
PRINCIPAL VULNERABILITY: OWNER TYPE:	Plant growth Private	TREND: CONTACT:	Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	One of a number of cairns at Black Pool, U	gborough, South H	Hams
DESIGNATION:	Scheduled Monument (No. 1012285)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone alignment and cairn south east of We	estern Beacon, Ug	borough, South Hams
designation:	Scheduled Monument (No. 1017604)	CONDITION:	Generally satisfactory
		Condition.	but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hembury Castle, West Buckfastleigh, South	Hams	
designation:	Scheduled Monument (No. 1003859)	CONDITION:	Generally satisfactory
		CONDITION.	but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			J. J
SITE NAME:	Medieval farmstead 340m south east of Co	ld East Cross, Ash	burton, Teignbridge
DESIGNATION:	Scheduled Monument (No. 1019604)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
	-		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:			
SITE NAME:	Hut circles and fields on Buckland Commo	n, Buckland in the	Moor, Teignbridge
SITE NAME:			Moor, Teignbridge Generally unsatisfactory
SITE NAME: DESIGNATION:	Hut circles and fields on Buckland Common Scheduled Monument (No. 1004589)	n, Buckland in the	Moor, Teignbridge Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Hut circles and fields on Buckland Commo	n, Buckland in the	Moor, Teignbridge Generally unsatisfactory
	Hut circles and fields on Buckland Common Scheduled Monument (No. 1004589) Plant growth	n, Buckland in the CONDITION: TREND: CONTACT:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Hut circles and fields on Buckland Common Scheduled Monument (No. 1004589) Plant growth Private Lizwell Bridge, Buckland in the Moor, Teignb	n, Buckland in the CONDITION: TREND: CONTACT: oridge	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Hut circles and fields on Buckland Common Scheduled Monument (No. 1004589) Plant growth Private	n, Buckland in the CONDITION: TREND: CONTACT:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Hut circles and fields on Buckland Common Scheduled Monument (No. 1004589) Plant growth Private Lizwell Bridge, Buckland in the Moor, Teignb Scheduled Monument (No. 1003294)	n, Buckland in the CONDITION: TREND: CONTACT: oridge CONDITION:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Hut circles and fields on Buckland Common Scheduled Monument (No. 1004589) Plant growth Private Lizwell Bridge, Buckland in the Moor, Teignb	n, Buckland in the CONDITION: TREND: CONTACT: oridge	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Hut circles and fields on Buckland Common         Scheduled Monument (No. 1004589)         Plant growth         Private         Lizwell Bridge, Buckland in the Moor, Teignb         Scheduled Monument (No. 1003294)         Extensive natural erosion	n, Buckland in the CONDITION: TREND: CONTACT: oridge CONDITION: TREND:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Hut circles and fields on Buckland Common         Scheduled Monument (No. 1004589)         Plant growth         Private         Lizwell Bridge, Buckland in the Moor, Teignb         Scheduled Monument (No. 1003294)         Extensive natural erosion	n, Buckland in the CONDITION: TREND: CONTACT: oridge CONDITION: TREND: CONTACT:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Hut circles and fields on Buckland Common         Scheduled Monument (No. 1004589)         Plant growth         Private         Lizwell Bridge, Buckland in the Moor, Teignb         Scheduled Monument (No. 1003294)         Extensive natural erosion         Private	n, Buckland in the CONDITION: TREND: CONTACT: oridge CONDITION: TREND: CONTACT:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION:	Hut circles and fields on Buckland Common         Scheduled Monument (No. 1004589)         Plant growth         Private         Lizwell Bridge, Buckland in the Moor, Teignb         Scheduled Monument (No. 1003294)         Extensive natural erosion         Private         Cairn 240m north of Crownley Parks, Ilsing	n, Buckland in the CONDITION: TREND: CONTACT: rridge CONDITION: TREND: CONTACT:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Hut circles and fields on Buckland Common         Scheduled Monument (No. 1004589)         Plant growth         Private         Lizwell Bridge, Buckland in the Moor, Teignbe         Scheduled Monument (No. 1003294)         Extensive natural erosion         Private         Cairn 240m north of Crownley Parks, Ilsing         Scheduled Monument (No. 1019588)	n, Buckland in the CONDITION: TREND: CONTACT: CONDITION: CONDITION: trend: CONTACT:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Hut circles and fields on Buckland Common         Scheduled Monument (No. 1004589)         Plant growth         Private         Lizwell Bridge, Buckland in the Moor, Teignb         Scheduled Monument (No. 1003294)         Extensive natural erosion         Private         Cairn 240m north of Crownley Parks, Ilsing         Scheduled Monument (No. 1019588)         Scrub / tree growth	n, Buckland in the CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONDITION: CONDITION:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Hut circles and fields on Buckland Common         Scheduled Monument (No. 1004589)         Plant growth         Private         Lizwell Bridge, Buckland in the Moor, Teignb         Scheduled Monument (No. 1003294)         Extensive natural erosion         Private         Cairn 240m north of Crownley Parks, Ilsing         Scheduled Monument (No. 1019588)         Scrub / tree growth	n, Buckland in the CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONTACT: CONDITION: CONDITION: CONDITION: TREND: CONDITION:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: OWNER TYPE: SITE NAME:	Hut circles and fields on Buckland Common         Scheduled Monument (No. 1004589)         Plant growth         Private         Lizwell Bridge, Buckland in the Moor, Teignb         Scheduled Monument (No. 1003294)         Extensive natural erosion         Private         Cairn 240m north of Crownley Parks, Ilsing         Scheduled Monument (No. 1019588)         Scrub / tree growth         Private	n, Buckland in the CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONTACT: CONDITION: CONDITION: CONDITION: TREND: CONDITION:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Hut circles and fields on Buckland Common         Scheduled Monument (No. 1004589)         Plant growth         Private         Lizwell Bridge, Buckland in the Moor, Teignb         Scheduled Monument (No. 1003294)         Extensive natural erosion         Private         Cairn 240m north of Crownley Parks, Ilsing         Scheduled Monument (No. 1019588)         Scrub / tree growth         Private         Pound north east of Holwell Tor, Ilsington, T	n, Buckland in the CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION:	Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS ATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Settlement on Smallacombe Rocks, Ilsingtor	n, Teignbridge	
DESIGNATION:	Scheduled Monument (No. 1002531)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Settlement west of Holwell Tor, Ilsington, Te	ignbridge	
DESIGNATION:	Scheduled Monument (No. 1002529)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Medieval strip field system, tinworks, part c a cairn and reave on Challacombe Down, M		
DESIGNATION:	Scheduled Monument (No. 1021393)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Medieval strip fields, tinworks, prehistoric s and a cairn on the lower western slopes of		inaton. Teignbridge
DESIGNATION:	Scheduled Monument (No. 1021394)		Generally satisfactory
		CONDITION:	but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Three hut circles at north end of Vogwell [	Down, Manaton, Te	
	Three hut circles at north end of Vogwell E Scheduled Monument (No. 1002595)	Down, Manaton, Te	Generally unsatisfactory
DESIGNATION:	Scheduled Monument (No. 1002595)	CONDITION:	Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1002595) Extensive stock erosion	CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1002595)	CONDITION:	Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1002595) Extensive stock erosion	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1002595) Extensive stock erosion Private	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>A, Teignbridge</b> Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1002595) Extensive stock erosion Private Enclosure south west of Hingston Rocks, M	CONDITION: TREND: CONTACT: loretonhampstead	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION:	Scheduled Monument (No. 1002595) Extensive stock erosion Private Enclosure south west of Hingston Rocks, M	CONDITION: TREND: CONTACT: loretonhampstead	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>A, Teignbridge</b> Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DOWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1002595) Extensive stock erosion Private Enclosure south west of Hingston Rocks, M Scheduled Monument (No. 1002496)	CONDITION: TREND: CONTACT: Ioretonhampstead	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 I, Teignbridge Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1002595) Extensive stock erosion Private Enclosure south west of Hingston Rocks, M Scheduled Monument (No. 1002496) Scrub / tree growth	CONDITION: TREND: CONTACT: Ioretonhampstead CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>A, Teignbridge</b> Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1002595)         Extensive stock erosion         Private         Enclosure south west of Hingston Rocks, M         Scheduled Monument (No. 1002496)         Scrub / tree growth         Private	CONDITION: TREND: CONTACT: Ioretonhampstead CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>Teignbridge</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: DESIGNATION:	Scheduled Monument (No. 1002595)         Extensive stock erosion         Private         Enclosure south west of Hingston Rocks, M         Scheduled Monument (No. 1002496)         Scrub / tree growth         Private         Wooston Castle, Moretonhampstead, Teign	CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>Teignbridge</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1002595)         Extensive stock erosion         Private         Enclosure south west of Hingston Rocks, M         Scheduled Monument (No. 1002496)         Scrub / tree growth         Private         Wooston Castle, Moretonhampstead, Teigner         Scheduled Monument (No. 1003822)	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>I. Teignbridge</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DISTE NAME:	Scheduled Monument (No. 1002595)         Extensive stock erosion         Private         Enclosure south west of Hingston Rocks, M         Scheduled Monument (No. 1002496)         Scrub / tree growth         Private         Wooston Castle, Moretonhampstead, Teignt         Scheduled Monument (No. 1003822)         Scrub / tree growth	CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>I. Teignbridge</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1002595)         Extensive stock erosion         Private         Enclosure south west of Hingston Rocks, M         Scheduled Monument (No. 1002496)         Scrub / tree growth         Private         Wooston Castle, Moretonhampstead, Teignt         Scheduled Monument (No. 1003822)         Scrub / tree growth	CONDITION: TREND: CONTACT: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>I, Teignbridge</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1002595)         Extensive stock erosion         Private         Enclosure south west of Hingston Rocks, M         Scheduled Monument (No. 1002496)         Scrub / tree growth         Private         Wooston Castle, Moretonhampstead, Teignt         Scheduled Monument (No. 1003822)         Scrub / tree growth         Private	CONDITION: TREND: CONTACT: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>A. Teignbridge</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1002595)         Extensive stock erosion         Private         Enclosure south west of Hingston Rocks, M         Scheduled Monument (No. 1002496)         Scrub / tree growth         Private         Wooston Castle, Moretonhampstead, Teigner         Scheduled Monument (No. 1003822)         Scrub / tree growth         Private         Four hut circles north of Bush Down, North	CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>A. Teignbridge</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

SITE NAME:	Prehistoric settlement and field system 240	m east of Challac	ombe Cross, North Bovey, Teignbridge
DESIGNATION:	Scheduled Monument (No. 1020097)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two hut circles north west of Bush Down,	North Bovey, Teig	nbridge
DESIGNATION:	Scheduled Monument (No. 1003198)	CONDITION:	Generally unsatisfactory
DESIGNATION:	Scheddied Hondment (140. 1003170)	CONDITION:	with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Deserted medieval settlement at Blackaton 340m and 400m north east of Lower Black	,	-in-the-Moor Teignhridge
	Scheduled Monument (No. 1021396)	CONDITION:	Generally satisfactory
DESIGNATION:	cencealed Fionament (No. Toz 1970)	CONDITION:	but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			0
SITE NAME:	Enclosure and fields north of Yar Tor, Widecombe-in-the-Moor, Teignbridge		
DESIGNATION:	Scheduled Monument (No. 1003292)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT	Pusiness Manager 0117 975 0700
OWNERTH E.	Thrace	CONTACT:	Business Manager 0117 975 0700
	Foale's Arrishes, huts and fields, Blackslade I		
SITE NAME:			e-in-the-Moor, Teignbridge Generally satisfactory
SITE NAME: DESIGNATION:	Foale's Arrishes, huts and fields, Blackslade I Scheduled Monument (No. 1003283)	Down, Widecomb	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	<b>Foale's Arrishes, huts and fields, Blackslade I</b> Scheduled Monument (No. 1003283) Plant growth	Down, Widecomb condition: trend:	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Foale's Arrishes, huts and fields, Blackslade I Scheduled Monument (No. 1003283)	Down, Widecomb	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	<b>Foale's Arrishes, huts and fields, Blackslade I</b> Scheduled Monument (No. 1003283) Plant growth	Down, Widecomb Condition: trend: Contact:	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	<b>Foale's Arrishes, huts and fields, Blackslade I</b> Scheduled Monument (No. 1003283) Plant growth Private	Down, Widecomb Condition: trend: Contact:	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 the-Moor, Teignbridge Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Foale's Arrishes, huts and fields, Blackslade I         Scheduled Monument (No. 1003283)         Plant growth         Private         Hut 700yds (640m) north west of Sharp To         Scheduled Monument (No. 1003280)	Down, Widecomb CONDITION: TREND: CONTACT: r, Widecombe-in-1	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 the-Moor, Teignbridge
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Foale's Arrishes, huts and fields, Blackslade I Scheduled Monument (No. 1003283) Plant growth Private Hut 700yds (640m) north west of Sharp To	Down, Widecomb CONDITION: TREND: CONTACT: r, Widecombe-in-1 CONDITION:	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 the-Moor, Teignbridge Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Foale's Arrishes, huts and fields, Blackslade I         Scheduled Monument (No. 1003283)         Plant growth         Private         Hut 700yds (640m) north west of Sharp To         Scheduled Monument (No. 1003280)         Plant growth	Down, Widecomb CONDITION: TREND: CONTACT: r, Widecombe-in-1 CONDITION: TREND: CONTACT:	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 the-Moor, Teignbridge Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Foale's Arrishes, huts and fields, Blackslade I         Scheduled Monument (No. 1003283)         Plant growth         Private         Hut 700yds (640m) north west of Sharp To         Scheduled Monument (No. 1003280)         Plant growth         Private	Down, Widecomb CONDITION: TREND: CONTACT: r, Widecombe-in-1 CONDITION: TREND: CONTACT:	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 the-Moor, Teignbridge Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 the-Moor, Teignbridge Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Foale's Arrishes, huts and fields, Blackslade I         Scheduled Monument (No. 1003283)         Plant growth         Private         Hut 700yds (640m) north west of Sharp To         Scheduled Monument (No. 1003280)         Plant growth         Private         Hut circles and field systems east of Mel To         Scheduled Monument (No. 1003301)	Down, Widecomb CONDITION: TREND: CONTACT: r, Widecombe-in-1 CONDITION: TREND: CONTACT:	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 the-Moor, Teignbridge Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Foale's Arrishes, huts and fields, Blackslade I         Scheduled Monument (No. 1003283)       Plant growth         Private       Private         Hut 700yds (640m) north west of Sharp To       Scheduled Monument (No. 1003280)         Plant growth       Private         Hut circles and field systems east of Mel To	Down, Widecomb CONDITION: TREND: CONTACT: r, Widecombe-in-1 CONDITION: TREND: CONTACT:	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 the-Moor, Teignbridge Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 the-Moor, Teignbridge Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Foale's Arrishes, huts and fields, Blackslade I         Scheduled Monument (No. 1003283)         Plant growth         Private         Hut 700yds (640m) north west of Sharp To         Scheduled Monument (No. 1003280)         Plant growth         Private         Hut circles and field systems east of Mel To         Scheduled Monument (No. 1003301)         Plant growth	Down, Widecomb CONDITION: TREND: CONTACT: r, Widecombe-in-1 CONDITION: TREND: CONDITION: r, Widecombe-in-1	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 the-Moor, Teignbridge Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 the-Moor, Teignbridge Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Foale's Arrishes, huts and fields, Blackslade I         Scheduled Monument (No. 1003283)         Plant growth         Private         Hut 700yds (640m) north west of Sharp To         Scheduled Monument (No. 1003280)         Plant growth         Private         Hut circles and field systems east of Mel To         Scheduled Monument (No. 1003301)         Plant growth	Down, Widecomb CONDITION: TREND: CONTACT: r, Widecombe-in-1 CONDITION: TREND: CONTACT: r, Widecombe-in-1	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 the-Moor, Teignbridge Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 the-Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Foale's Arrishes, huts and fields, Blackslade I         Scheduled Monument (No. 1003283)         Plant growth         Private         Hut 700yds (640m) north west of Sharp To         Scheduled Monument (No. 1003280)         Plant growth         Private         Hut circles and field systems east of Mel To         Scheduled Monument (No. 1003301)         Plant growth         Private	Down, Widecomb CONDITION: TREND: CONTACT: r, Widecombe-in-1 CONDITION: TREND: CONTACT: r, Widecombe-in-1	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 the-Moor, Teignbridge Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 the-Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Foale's Arrishes, huts and fields, Blackslade I         Scheduled Monument (No. 1003283)         Plant growth         Private         Hut 700yds (640m) north west of Sharp To         Scheduled Monument (No. 1003280)         Plant growth         Private         Hut circles and field systems east of Mel To         Scheduled Monument (No. 1003301)         Plant growth         Private         Hut circles and field systems east of Mel To         Scheduled Monument (No. 1003301)         Plant growth         Private         Hut circles east of Pritton, Widecombe-in-to	Down, Widecomb CONDITION: TREND: CONTACT: r, Widecombe-in-1 CONDITION: TREND: CONTACT: r, Widecombe-in-1 CONDITION: TREND: CONDITION:	e-in-the-Moor, Teignbridge Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 the-Moor, Teignbridge Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 the-Moor, Teignbridge Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 dge Generally unsatisfactory

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Hut circles east of Southway, Widecombe-ir	n-the-Moor, Teignb	oridge
DESIGNATION:	Scheduled Monument (No. 1002621)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hut circles on Bonehill Down, Widecombe	-in-the-Moor, Teigr	ıbridge
DESIGNATION:	Scheduled Monument (No. 1002619)	CONDITION:	Generally satisfactory
	× /		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hut circles on Hedge Down, Widecombe-ir	n-the-Moor, Teignb	ridge
DESIGNATION:	Scheduled Monument (No. 1002620)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			<u> </u>
SITE NAME:	Hut circles south east of Yar Tor, Widecomb	pe-in-the-Moor, Te	ignbridge
DESIGNATION:	Scheduled Monument (No. 1003291)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Pound at Newbridge, Widecombe-in-the-Me	oor Teignbridge	
SHE NAME:	-	ool, leighblidge	
DESIGNATION:	Scheduled Monument (No. 1003295)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:			
SITE INALIE.	Two cairns on Cator Common, Widecombe	e-in-the-Moor, Teig	gnbridge
	Two cairns on Cator Common, Widecombe Scheduled Monument (No. 1003297)	e-in-the-Moor, Teig	nbridge Generally satisfactory
DESIGNATION:			Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1003297)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1003297) Plant growth	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1003297) Plant growth Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>Teignbridge</b> Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1003297) Plant growth Private Yar Tor stone row and adjacent cist, Wideco Scheduled Monument (No. 1003288)	CONDITION: TREND: CONTACT: ombe-in-the-Moon	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1003297) Plant growth Private Yar Tor stone row and adjacent cist, Wideco	CONDITION: TREND: CONTACT: Ombe-in-the-Moon CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>;Teignbridge</b> Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1003297) Plant growth Private Yar Tor stone row and adjacent cist, Wideco Scheduled Monument (No. 1003288) Plant growth		Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>; Teignbridge</b> Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1003297)         Plant growth         Private         Yar Tor stone row and adjacent cist, Wideco         Scheduled Monument (No. 1003288)         Plant growth         Private         Taw River tin blowing mill, 840m south of T	CONDITION: TREND: CONTACT: Ombe-in-the-Mood CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>Teignbridge</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 West Devon
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1003297) Plant growth Private Yar Tor stone row and adjacent cist, Wideco Scheduled Monument (No. 1003288) Plant growth Private	CONDITION: TREND: CONTACT: Ombe-in-the-Mood CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>Teignbridge</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1003297)         Plant growth         Private         Yar Tor stone row and adjacent cist, Wideco         Scheduled Monument (No. 1003288)         Plant growth         Private         Taw River tin blowing mill, 840m south of T	CONDITION: TREND: CONTACT: Ombe-in-the-Moon CONDITION: TREND: CONTACT: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>Teignbridge</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>West Devon</b> Generally satisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

	Enclosure, two stone hut circles and an alig 780m north west of Little Links Tor, Bridest		
DESIGNATION:	Scheduled Monument (No. 1007648)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Hut circles and a length of enclosure wall, f 600m east of Nodden Gate, Bridestowe, W		tone hut circle settlement
DESIGNATION:	Scheduled Monument (No. 1008638)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Hut circles west of Higher Shapley, Chagfor	rd, West Devon	
DESIGNATION:	Scheduled Monument (No. 1002651)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	A double stone hut circle and enclosure 28	0m south of Dead	dlake Foot, Dartmoor Forest, West Devon
DESIGNATION:	Scheduled Monument (No. 1011569)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
	Private	CONTRACT	During and Manager OLLZ OZE OZOO
OWNER TYPE:	Trivate	CONTACT:	Business Manager 0117 975 0700
	Camp 325yds (300m) south east of Archer		
ITE NAME:			
ITE NAME: DESIGNATION:	Camp 325yds (300m) south east of Archert	ton, Dartmoor Fo	rest, West Devon Generally unsatisfactory
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Camp 325yds (300m) south east of Archert Scheduled Monument (No. 1002636)	ton, Dartmoor Fo	rest, West Devon Generally unsatisfactory with major localised problems
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWINER TYPE:	<b>Camp 325yds (300m) south east of Archert</b> Scheduled Monument (No. 1002636) Forestry	ton, Dartmoor Fo Condition: Trend: Contact:	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Camp 325yds (300m) south east of Archert Scheduled Monument (No. 1002636) Forestry Private	ton, Dartmoor Fo Condition: Trend: Contact:	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 moor Forest, West Devon Generally unsatisfactory
ITE NAME: ESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: ESIGNATION:	Camp 325yds (300m) south east of Archert Scheduled Monument (No. 1002636) Forestry Private Cist on Whitehorse Hill, 910m south east of	ton, Dartmoor Fo CONDITION: TREND: CONTACT: of Taw Head, Dart CONDITION:	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 moor Forest, West Devon Generally unsatisfactory with major localised problems
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Camp 325yds (300m) south east of Archerd Scheduled Monument (No. 1002636) Forestry Private Cist on Whitehorse Hill, 910m south east of Scheduled Monument (No. 1020871)	ton, Dartmoor Fo CONDITION: TREND: CONTACT: of Taw Head, Dart	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 moor Forest, West Devon Generally unsatisfactory with major localised problems Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Camp 325yds (300m) south east of Archert Scheduled Monument (No. 1002636) Forestry Private Cist on Whitehorse Hill, 910m south east of Scheduled Monument (No. 1020871) Extensive stock erosion	ton, Dartmoor Fo CONDITION: TREND: CONTACT: of Taw Head, Dart CONDITION: TREND:	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 moor Forest, West Devon Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Camp 325yds (300m) south east of Archert         Scheduled Monument (No. 1002636)         Forestry         Private         Cist on Whitehorse Hill, 910m south east of         Scheduled Monument (No. 1020871)         Extensive stock erosion         Private         Hut circle and field system north west of S	ton, Dartmoor Fo CONDITION: TREND: CONTACT: of Taw Head, Dart CONDITION: TREND: CONTACT:	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 moor Forest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: PESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Camp 325yds (300m) south east of Archerd Scheduled Monument (No. 1002636) Forestry Private Cist on Whitehorse Hill, 910m south east of Scheduled Monument (No. 1020871) Extensive stock erosion Private	ton, Dartmoor Fo CONDITION: TREND: CONTACT: of Taw Head, Dart CONDITION: TREND: CONTACT:	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 moor Forest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WINER TYPE: TE NAME: ESIGNATION: WINER TYPE: TE NAME: ESIGNATION:	Camp 325yds (300m) south east of Archert         Scheduled Monument (No. 1002636)         Forestry         Private         Cist on Whitehorse Hill, 910m south east of         Scheduled Monument (No. 1020871)         Extensive stock erosion         Private         Hut circle and field system north west of S	ton, Dartmoor Fo CONDITION: TREND: CONTACT: of Taw Head, Dart CONDITION: TREND: CONTACT: addle Bridge, Dart	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 moor Forest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 tmoor Forest, West Devon Generally unsatisfactory
TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WINER TYPE: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY:	Camp 325yds (300m) south east of Archert         Scheduled Monument (No. 1002636)         Forestry         Private         Cist on Whitehorse Hill, 910m south east of         Scheduled Monument (No. 1020871)         Extensive stock erosion         Private         Hut circle and field system north west of S         Scheduled Monument (No. 1002601)	ton, Dartmoor Fo CONDITION: TREND: CONTACT: of Taw Head, Dart CONDITION: TREND: CONTACT: addle Bridge, Dart	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 moor Forest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 tmoor Forest, West Devon Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Camp 325yds (300m) south east of Archerd         Scheduled Monument (No. 1002636)         Forestry         Private         Cist on Whitehorse Hill, 910m south east of         Scheduled Monument (No. 1020871)         Extensive stock erosion         Private         Hut circle and field system north west of S         Scheduled Monument (No. 1002601)         Plant growth	ton, Dartmoor Fo CONDITION: TREND: CONTACT: of Taw Head, Dart CONDITION: TREND: CONTACT: addle Bridge, Dart CONDITION: TREND: CONTACT:	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 moor Forest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 tmoor Forest, West Devon Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 ments, part of a coaxial field system,
DWINER TYPE:	Camp 325yds (300m) south east of Archerd         Scheduled Monument (No. 1002636)         Forestry         Private         Cist on Whitehorse Hill, 910m south east of         Scheduled Monument (No. 1020871)         Extensive stock erosion         Private         Hut circle and field system north west of S         Scheduled Monument (No. 1002601)         Plant growth         Private         Two irregular aggregate field systems with a	ton, Dartmoor Fo CONDITION: TREND: CONTACT: of Taw Head, Dart CONDITION: TREND: CONTACT: addle Bridge, Dart CONDITION: TREND: CONTACT:	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 moor Forest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 tmoor Forest, West Devon Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 ments, part of a coaxial field system,
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Camp 325yds (300m) south east of Archerd         Scheduled Monument (No. 1002636)         Forestry         Private         Cist on Whitehorse Hill, 910m south east of         Scheduled Monument (No. 1020871)         Extensive stock erosion         Private         Hut circle and field system north west of S         Scheduled Monument (No. 1002601)         Plant growth         Private         Two irregular aggregate field systems with a boundary stones and historic fields on Ride	ton, Dartmoor Fo CONDITION: TREND: CONTACT: of Taw Head, Dart CONDITION: TREND: CONDITION: addle Bridge, Dart CONDITION: TREND: CONDITION:	rest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 moor Forest, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 tmoor Forest, West Devon Generally unsatisfactory with major localised problems Stable Business Manager 0117 975 0700 ments, part of a coaxial field system, for Forest, West Devon Generally satisfactory

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Prestonbury Castle (hillfort), Drewsteignton	n, West Devon	
DESIGNATION:	Scheduled Monument (No. 1003861)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Chambered cairn 430m south of Buttern, G	Gidleigh, West Dev	/on
DESIGNATION:	Scheduled Monument (No. 1021217)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Chambered cairn 830m south of Buttern, C	Gidleigh, West Dev	/on
DESIGNATION:	Scheduled Monument (No. 1021216)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Coaxial field system, associated and later re Gidleigh, West Devon	emains at Throwle	igh Common and Kennon Hill,
DESIGNATION:	Scheduled Monument (No. 1018916)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Part of a coaxial field system, prehistoric se	ettlements and cai	rns on Buttern Hill, Gidleigh, West Devo
DESIGNATION:	Scheduled Monument (No. 1021215)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Stone hut circle 380m north west of North	n Creaber, Gidleig	h, West Devon
DESIGNATION:	Scheduled Monument (No. 1021220)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Stone hut circle and field system 580m nor forming part of a coaxial field system on Bu		
DESIGNATION:	Scheduled Monument (No. 1021219)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two stone hut circles and field system, 590 forming part of a coaxial field system on Bu		
DESIGNATION:	Scheduled Monument (No. 1021218)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth Private	TREND:	Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

Desidewine:         Scheduled Monument (No. 1008639)         CONDITION:         Generally satisfactory but with significant localised problems           PRINCIPAL VALUE/AUT/N         Plant growth         Tratue:         Declining           Private         Convict::         Business Manager 0117 97           Private         Convict::         Business Manager 0117 97           Private         Scheduled Monument (No. 1008656)         convict::         Business Manager 0117 97           Statissaturin:         Private         Convict::         Business Manager 0117 97           Statissaturin:         Private         Convict::         Business Manager 0117 97           Statissaturin:         Private         Convince::         Business Manager 0117 97 <th>SITE NAME:</th> <th>Stone hut circle 530m ESE of Nodden Gate forming an outlying part of a stone hut circl</th> <th></th> <th>ford, West Devon</th>	SITE NAME:	Stone hut circle 530m ESE of Nodden Gate forming an outlying part of a stone hut circl		ford, West Devon
NUMBERAUTY:       Plant, growth       TREMO       Declining         WHERE YOY:       Private       CONTACT:       Business Manager 01 17 97         THE MARK:       Scheduled Monument (No. 1008656)       CONUMORY       Generally satisfactory but with significant localise         Sector MULEXALVE:       Part growth       TREMO       CONUMORY       Generally satisfactory but with significant localise         WHERE YOR:       Private       CONUMORY       Business Manager 01 17 97         WHERE YOR:       Part growth       TREMO       CONUMORY         WHERE YOR:       Part growth       TREMO       CONUMORY         Scheduled Monument (No. 1002522)       CONUMORY       Generally satisfactory but with significant localise         WHERE YOR:       Private       CONUMORY       Business Manager 01 17 97         WHERE YOR:       Private       CONUMORY       Business Manager 01 17 97         WHERE YOR:       Private       CONUMORY       Business Manager 01 17 97         WHERE YOR:       Private       CONUMORY       Business Manager 01 17 97         WHERE YOR:       CONUMORY       Declining       CONUMORY         WHERE YOR:       CONUMORY       CONUMORY       Declining         WHERE YOR:       CONUMORY       CONUMORY       CONUMORY	DESIGNATION:	Scheduled Monument (No. 1008639)		
WHARTIME         Private         CONTROL         Business Manager 0117 97           Internation         Scone hut circle 610m ESE of Nodden Gate forming an outlying part of a stone hut circle settlement, Lydford, West Devon but with significant localise         Generally satisfactory but with significant localise           International         Scheduled Monument (No. 1008656)         continues         Generally satisfactory but with significant localise           International         Private         control         Generally satisfactory but with significant localise           International         Scheduled Monument (No. 1002522)         contonosi         Generally satisfactory but with significant localise           International         Scheduled Monument (No. 1002522)         contonosi         Generally satisfactory but with significant localise           International         Scheduled Monument (No. 1008929)         contonosi         Generally satisfactory but with significant localise           International         Scheduled Monument (No. 1008929)         contonosi         Unknown           International         Scheduled Monument (No. 100251)         continosi         Generally satisfactory but with significant localise           International         Scheduled Monument (No. 100251)         continosi         Generally satisfactory but with significant localise           International         Scheduled Monument (No. 1002551)         continosi				Declining
forming an outlying part of a stone hut circle settlement, Lydford, West Devon         sistwariowi       Scheduled Monument (No. 1008656)       control       Generally satisfactory but with significant localise         sistwariowi       Private       control       Business Manager 0117 97         te NAME       Four round barrows on Wigford Down, Meavy, West Devon       Generally satisfactory but with significant localise         sistwariowi       Scheduled Monument (No. 1002522)       control       Generally satisfactory but with significant localise         sistwariowi       Scheduled Monument (No. 1002522)       control       Business Manager 0117 97         te NAME       Plant growth       memb       Declining         west the server       Private       control       Generally satisfactory but with significant localise         server the       Plant growth       memb       Declining         re NAME       Greenwell Girt socket stone 600m SSW of Lovaton hamlet, Meavy, West Devon       Business Manager 0117 97         te NAME       Hut circle on Wigford Down, Meavy, West Devon       Business Manager 0117 97         te NAME       Hut circle on Wigford Down, Meavy, West Devon       Business Manager 0117 97         te NAME       Hut circle south east of Brisworthy, Meavy, West Devon       Business Manager 0117 97         te NAME       Hut circle south east of Brisworthy				Business Manager 0117 975 0700
escavanove Scheduled Monument (No. 1008656) consomer Generally satisfactory but with significant localise Declining watartime Private construct. Business Manager 0117 97 TENAME: Four round barrows on Wigford Down, Meavy, West Devon Generally satisfactory but with significant localise ancore Scheduled Monument (No. 1002522) consomer Generally satisfactory but with significant localise ancore Construct. Business Manager 0117 97 TENAME: Greenwell Girt socket stone 600m SSW of Lovaton hamlet, Meavy, West Devon Scheduled Monument (No. 1008929) consomer Unknown and the second of the second	TE NAME:			
but with significant localise           Inverse         Private         Declining           Revenues         Private         Convert         Business Manager 0117 97           TE NAME         Four round barrows on Wigford Down, Meavy, West Devon         Generally satisfactory but with significant localise           Revenues         Scheduled Monument (No. 1002522)         Converse         Generally satisfactory but with significant localise           Revenues         Private         Converse         Business Manager 0117 97           Revenues         Private         Converse         Business Manager 0117 97           Revenues         Other         Tesna         Declining           Revenues         Scheduled Monument (No. 1008929)         Converse         Unknown           Revenues         Other         Tesna         Unknown           Revenues         Private         Converse         Business Manager 0117 97           The NAME         Private         Converse         Business Manager 0117 97           Revenues         Private         Converse         Business Manager 0117 97           The NAME         Hut circle on Wigford Down, Meavy, West Devon         Business Manager 0117 97           The NAME         Hut circle south east of Brisworthy, Meavy, West Devon         Business Manager 0117 97			le settlement, Lyd	
WHERTIME         Private         CONTRCT:         Business Manager 0117 97           TE NAME:         Four round barrows on Wigford Down, Meavy, West Devon         Scheduled Monument (No. 1002522)         CONDITION:         Generally satisfactory but with significant localise and provide straining and strainis straining and straining and straining and strainis str	ESIGNATION:	Scheduled Monument (No. 1008656)	CONDITION:	Generally satisfactory but with significant localised problems
THE NAME         Four round barrows on Wigford Down, Meavy, West Devon           EXERCIMIENT:         Scheduled Monument (No. 1002522)         CONDITION:         Generally satisfactory but with significant localise moments.           RENAME:         Plant growth         THEND:         Declining           WINDERTYPE         Private         CONDITION:         Generally satisfactory but with significant localise moments.           THE NAME:         Greenwell Girt socket stone 600m SSW of Lovaton hamlet, Meavy, West Devon         Business Manager 0117 97           THE NAME:         Greenwell Girt socket stone 600m SSW of Lovaton hamlet, Meavy, West Devon         Unknown           Scheduled Monument (No. 1008929)         CONDITION:         Unknown           WINDERTYPE         Private         Control:         Business Manager 0117 97           WINDERTYPE         Private         Control:         Business Manager 0117 97           WINDERTYPE         Private         Control:         Business Manager 0117 97           MERCINK, WUNREABLITY:         Plant growth         THEND:         Declining           RENAME:         Hut circles south east of Brisworthy, Meavy, West Devon         Scheduled Monument (No. 1004585)         CONDITION:         Generally unsatisfactory with major localised proble           WINRERTYPE         Plant growth         THEND:         Declining	RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
Biscovertions       Scheduled Monument (No. 1002522)       covertions       Generally satisfactory but with significant localise         Biscovertions       Plant growth       TEEND       Declining         WINNERTYPE       Private       covertions       Business Manager 0117 97         WINNERTYPE       Private       covertions       Unknown         Biscovertions       Scheduled Monument (No. 1008929)       covertions       Unknown         Biscovertions       Scheduled Monument (No. 1008929)       covertions       Unknown         Biscovertions       Scheduled Monument (No. 1008929)       covertions       Unknown         Biscovertions       Scheduled Monument (No. 1002551)       covertions       Unknown         Biscovertions       Scheduled Monument (No. 1002551)       covertions       Generally satisfactory but with significant localise         Biscovertions       Scheduled Monument (No. 1004585)       covertions       Generally unsatisfactory with major localised proble         Biscovertions       Scheduled Monument (No. 1004585)       covertions       Generally unsatisfactory with major localised proble         Biscovertions       Scheduled Monument (No. 1004585)       covertions       Generally unsatisfactory with major localised proble         Biscovertions       Scheduled Monument (No. 10020241)       covertions       Generall	WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
but with significant localise but with significant localise Declining Declin	TE NAME:	Four round barrows on Wigford Down, Me	avy, West Devon	
RENCIPAL VOLUMERABUTY:       Plant: growth       TREND:       Declining         SWNER TYPE       Private       contract:       Business Manager 0117 97         ATE: NAME:       Greenwell Girt socket stone 600m SSW of Lovaton hamlet, Meavy, West Devon       contract:       Business Manager 0117 97         Decining       Greenwell Girt socket stone 600m SSW of Lovaton hamlet, Meavy, West Devon       Unknown         DesignAntone       Scheduled Monument (No. 1008929)       contract:       Unknown         Swner Type:       Private       contract:       Business Manager 0117 97         Attention:       Other       TREND:       Unknown         Scheduled Monument (No. 1002551)       contract:       Business Manager 0117 97         Declining       Scheduled Monument (No. 1002551)       contract:       Business Manager 0117 97         Declining       Private       contract:       Business Manager 0117 97         THE NAME:       Hut circles south east of Brisworthy, Meavy, West Devon       Generally unsatisfactory with major localised proble         Scheduled Monument (No. 1004585)       contract:       Business Manager 0117 97         THE NAME:       Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Measemanton:       Scheduled Monument (No. 1020241)       contract:         Scheduled Monument (No. 1020241)	DESIGNATION:	Scheduled Monument (No. 1002522)	CONDITION:	Generally satisfactory
WMERT TYPE     Private     CONTRACT:     Business Manager 0117 97       WITE NAME:     Greenwell Girt socket stone 600m SSW of Lovaton hamlet, Meavy, West Devon       WISIGNAL VULNERABUTY:     Other     TREND:     Unknown       WINER TYPE:     Private     CONTRACT:     Business Manager 0117 97       WISIGNAL VULNERABUTY:     Other     TREND:     Unknown       WINER TYPE:     Private     CONTRACT:     Business Manager 0117 97       WISIGNAL VULNERABUTY:     Other     TREND:     Business Manager 0117 97       WISIGNAL VULNERABUTY:     Private     CONTRACT:     Business Manager 0117 97       WISIGNAL VULNERABUTY:     Plant growth     TREND:     Declining       WINNER TYPE:     Private     CONTRACT:     Business Manager 0117 97       WISIGNAL VULNERABUTY:     Plant growth     TREND:     Declining       WINNER TYPE:     Private     CONTRACT:     Business Manager 0117 97       WISIGNAL VULNERABUTY:     Plant growth     TREND:     Declining       WINNER TYPE:     Private     CONTRACT:     Business Manager 0117 97       WISIGNAL VULNERABUTY:     Plant growth     TREND:     Declining       WINNER TYPE:     Private     CONTRACT:     Business Manager 0117 97       WISIGNALTION:     Scheduled Monument (No. 1020241)     CONTRACT:				but with significant localised problems
And Control         Greenwell Girt socket stone 600m SSW of Lovaton hamlet, Meavy, West Devon           Scheduled Monument (No. 1008929)         condition         Unknown           Scheduled Monument (No. 1008929)         condition         Unknown           Swinestring:         Private         Control         Business Manager 0117 97           Scheduled Monument (No. 1002551)         control         Generally satisfactory but with significant localise           Scheduled Monument (No. 1002551)         control         Generally satisfactory but with significant localise           Scheduled Monument (No. 1002551)         control         Business Manager 0117 97           Scheduled Monument (No. 1002551)         control         Generally satisfactory but with significant localise           Scheduled Monument (No. 1002551)         control         Generally unsatisfactory with major localised proble           Arre NAME:         Hut circles south east of Brisworthy, Meavy, West Devon         Generally unsatisfactory with major localised proble           RINCIPAL VULNERABLITY:         Plant growth         TREND:         Declining           Scheduled Monument (No. 1020241)         control         Generally unsatisfactory with major localised proble           Scheduled Monument (No. 1020241)         control         Generally unsatisfactory with major localised proble           RENORAL VULNERABLITY:         Plant growt	RINCIPAL VULNERABILITY:	-	TREND:	
Scheduled Monument (No. 1008929) CONDITION: Unknown TREND: Unknown WINRERTIPE: Other TREND: Unknown WINRERTIPE: Private CONTACT: Business Manager 0117 97 Besignaation: Scheduled Monument (No. 1002551) CONDITION: Generally satisfactory but with significant localise RINCIPAL VULNERABULTY: Plant growth TREND: Declining WINRERTIPE: Private CONTACT: Business Manager 0117 97 TRE NAME: Hut circles south east of Brisworthy, Meavy, West Devon TRE NAME: Hut circles south east of Brisworthy, Meavy, West Devon TRE NAME: Hut circles south east of Brisworthy, Meavy, West Devon TRE NAME: Private CONTACT: Business Manager 0117 97 WINRERTIPE: Private CONTACT: Business Manager 0117 97 TRE NAME: Plant growth TREND: Declining WINRERTIPE: Private CONTACT: Business Manager 0117 97 TREND: Declining WINRERTIPE: Plant growth TREND: Declining WINRERTIPE: Private CONTACT: Business Manager 0117 97 TREND: Declining WINRERTIPE: Private CONTACT: Business Manager 0117 97 TREND: Declining WINRERTIPE: Plant growth TREND: Declining WINRERTIPE: Plant growth Of Cadworthy Wood, Meavy, West Devon TREND: Declining WINRERTIPE: Private CONTACT: Business Manager 0117 97 WITH Major localised proble TREND: Declining WINRERTIPE: Private CONTACT: Business Manager 0117 97 WITH Major localised proble Business Manager 0117 97 WITH MAJOR CONTACT: Business Manager 0117 97 WITH MAJOR CONT	WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
RINCIPAL VULNERABULTY: Other TREND: Unknown WINERTYPE: Private contract: Business Manager 0117 97 WINERTYPE: Private contract: Business Manager 0117 97 Besignation: Scheduled Monument (No. 1002551) condition: Generally satisfactory but with significant localise RINCIPAL VULNERABULTY: Plant growth TREND: Devoin TREND: Hut circles south east of Brisworthy, Meavy, West Devoin TREND: Scheduled Monument (No. 1004585) condition: Generally unsatisfactory with major localised proble RINCIPAL VULNERABULTY: Plant growth TREND: Declining WINERTYPE: Private contract: Business Manager 0117 97 TREND: Declining WINERTYPE: Plant growth TREND: Declining WINERTYPE: Private contract: Business Manager 0117 97 TREND: Declining WINERTYPE: Plant growth TREND: Declining WINERTYPE: Private contract: Business Manager 0117 97 TREND: Declining WINERTYPE: Plant growth Gradworthy Wood, Meavy, West Devon WINE WINE MINERTYPE: Devon WINE MINE MINERTYPE: Devon WINE MINE MINERTYPE: Devon WINE MINE MINERTYPE: Devon WINE MINE MINERTYPE: Devon WINE MINERTYPE: Devon WINE MINERTYPE: Devon WINE MINERTYPE: Devon WINE MINERTYPE: D	ITE NAME:	Greenwell Girt socket stone 600m SSW of	Lovaton hamlet, I	Meavy, West Devon
WAREN TYPE:       Private       CONTACT:       Business Manager 0117 97         ITTE NAME:       Hut circle on Wigford Down, Meavy, West Devon       CONDITION:       Generally satisfactory but with significant localise         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WARENTYPE:       Private       CONTACT:       Business Manager 0117 97         WINCENTYPE:       Private       CONTACT:       Declining         WINCENTYPE:       Private       CONTACT:       Business Manager 0117 97         WINCENTYPE:       Hut circles south east of Brisworthy, Meavy, West Devon       CONDITION:       Generally unsatisfactory with major localised proble         WINCENTYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble         WINCENTYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble         WINCENTYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble         WINCENTYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble         WINCENTYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble         WINCENTYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble </td <td>)ESIGNATION:</td> <td>Scheduled Monument (No. 1008929)</td> <td>CONDITION:</td> <td>Unknown</td>	)ESIGNATION:	Scheduled Monument (No. 1008929)	CONDITION:	Unknown
TE NAME:       Hut circle on Wigford Down, Meavy, West Devon         ESIGNATION:       Scheduled Monument (No. 1002551)       CONDITION:       Generally satisfactory but with significant localise         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINNERTYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble         ESIGNATION:       Scheduled Monument (No. 1004585)       CONDITION:       Generally unsatisfactory with major localised proble         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINNERTYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINNERTYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble         ESIGNATION:       Scheduled Monument (No. 1020241)       CONDITION:       Generally unsatisfactory with major localised proble         WINNERTYPE:       Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Me       ESIGNATION:       Generally unsatisfactory with major localised proble         WINNERTYPE:       Private       CONTROL:       Declining       ESIGNATION:       Declining         WINNERTYPE:       Private <t< td=""><td>RINCIPAL VULNERABILITY:</td><td>Other</td><td>TREND:</td><td>Unknown</td></t<>	RINCIPAL VULNERABILITY:	Other	TREND:	Unknown
ESIGNATION: Scheduled Monument (No. 1002551) CONDITION: Generally satisfactory but with significant localise winker type: Private CONTACT: Business Manager 0117 97 TE NAME: Hut circles south east of Brisworthy, Meavy, West Devon ESIGNATION: Scheduled Monument (No. 1004585) CONDITION: Generally unsatisfactory with major localised proble sincipal vulnerABBLITY: Plant growth TREND: Declining winker type: Private CONTACT: Business Manager 0117 97 TE NAME: Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Me ESIGNATION: Scheduled Monument (No. 1020241) CONDITION: Generally unsatisfactory with major localised proble sincipal vulnerABBLITY: Plant growth TREND: Declining scheduled Monument (No. 1020241) CONDITION: Generally unsatisfactory with major localised proble sincipal vulnerABBLITY: Plant growth TREND: Declining scheduled Monument (No. 1020241) CONDITION: Generally unsatisfactory with major localised proble sincipal vulnerABBLITY: Plant growth TREND: Declining scheduled Monument (No. 1020241) CONDITION: Generally unsatisfactory with major localised proble te NAME: Private CONTACT: Business Manager 0117 97 TE NAME: Round barrow north of Cadworthy Wood, Meavy, West Devon ESIGNATION: Scheduled Monument (No. 1002552) CONDITION: Generally satisfactory but with significant localise	WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
RINCIPAL VULNERABILITY: Plant growth TREND: Declining WINER TYPE: Private CONTACT: Business Manager 0117 97 Hut circles south east of Brisworthy, Meavy, West Devon Hut circles south east of Brisworthy, Meavy, West Devon FINCIPAL VULNERABILITY: Plant growth TREND: CONDITION: Generally unsatisfactory with major localised proble RINCIPAL VULNERABILITY: Plant growth TREND: Declining WINER TYPE: Private CONTACT: Business Manager 0117 97 HTE NAME: Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Me Designation: Scheduled Monument (No. 1020241) CONDITION: Generally unsatisfactory with major localised proble RINCIPAL VULNERABILITY: Plant growth TREND: Declining Business Manager 0117 97 HTE NAME: Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Me Designation: Scheduled Monument (No. 1020241) CONDITION: Generally unsatisfactory with major localised proble RINCIPAL VULNERABILITY: Plant growth TREND: Declining WINER TYPE: Private CONTACT: Business Manager 0117 97 HTE NAME: Round barrow north of Cadworthy Wood, Meavy, West Devon HTE NAME: Scheduled Monument (No. 1002552) CONDITION: Generally satisfactory but with significant localised	ITE NAME:	Hut circle on Wigford Down, Meavy, West I	Devon	
DWNERTYPE:       Private       CONTACT:       Business Manager 0117 97         ARTE NAME:       Hut circles south east of Brisworthy, Meavy, West Devon       Scheduled Monument (No. 1004585)       CONDITION:       Generally unsatisfactory with major localised proble         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         DWNERTYPE:       Private       CONTACT:       Business Manager 0117 97         WITE NAME:       Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Me         DESIGNATION:       Scheduled Monument (No. 1020241)       CONDITION:       Generally unsatisfactory with major localised proble         WITE NAME:       Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Me       Designation:       Scheduled Monument (No. 1020241)       CONDITION:       Generally unsatisfactory with major localised proble         WITE NAME:       Plant growth       TREND:       Declining       Declining         DWNERTYPE:       Private       CONTACT:       Business Manager 0117 97         WITE NAME:       Round barrow north of Cadworthy Wood, Meavy, West Devon       Declining         DESIGNATION:       Scheduled Monument (No. 1002552)       CONDITION:       Generally satisfactory but with significant localise	DESIGNATION:	Scheduled Monument (No. 1002551)	CONDITION:	Generally satisfactory but with significant localised problems
Intername:       Hut circles south east of Brisworthy, Meavy, West Devon         Designation:       Scheduled Monument (No. 1004585)       CONDITION:       Generally unsatisfactory with major localised proble         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         ITTE NAME:       Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Me         VESIGNATION:       Scheduled Monument (No. 1020241)       CONDITION:       Generally unsatisfactory with major localised proble         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         NUMER TYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble         WINER TYPE:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         WITE NAME:       Round barrow north of Cadworthy Wood, Meavy, West Devon       Egnerally satisfactory but with significant localised         VESIGNATION:       Scheduled Monument (No. 1002552)       CONDITION:       Generally satisfactory but with significant localised	RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
ESIGNATION:       Scheduled Monument (No. 1004585)       CONDITION:       Generally unsatisfactory with major localised proble minorpative private         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble majo	WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         THE NAME:       Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Me         Designation:       Scheduled Monument (No. 1020241)       CONDITION:       Generally unsatisfactory with major localised proble         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONDITION:       Generally unsatisfactory with major localised proble         WINER TYPE:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         THE NAME:       Round barrow north of Cadworthy Wood, Meavy. West Devon       TREND:       Declining         RESIGNATION:       Scheduled Monument (No. 1002552)       CONDITION:       Generally satisfactory but with significant localised	TE NAME:	Hut circles south east of Brisworthy, Meavy	West Devon	
RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         ITTE NAME:       Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Me         VESIGNATION:       Scheduled Monument (No. 1020241)       CONDITION:       Generally unsatisfactory with major localised proble         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         ITTE NAME:       Round barrow north of Cadworthy Wood, Meavy. West Devon       UNITION:       Generally satisfactory but with significant localised	DESIGNATION:	Scheduled Monument (No. 1004585)	CONDITION:	Generally unsatisfactory
RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         ITTE NAME:       Prehistoric enclosures on Dewerstone Hill, 500m       south east of Dewerstone Cottage, Me         RESIGNATION:       Scheduled Monument (No. 1020241)       CONDITION:       Generally unsatisfactory with major localised problematism major localised problematism major localised problematism.         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         TTE NAME:       Round barrow north of Cadworthy Wood, Meavy, West Devon       TREND:       Generally satisfactory but with significant localised         RESIGNATION:       Scheduled Monument (No. 1002552)       CONDITION:       Generally satisfactory but with significant localised		· · · · · · · · · · · · · · · · · · ·		with major localised problems
WWNER TYPE:       Private       CONTACT:       Business Manager 0117 97         ITE NAME:       Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Me         Designation:       Scheduled Monument (No. 1020241)       CONDITION:       Generally unsatisfactory with major localised proble         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         TTE NAME:       Round barrow north of Cadworthy Wood, Meavy, West Devon       TREND:       Generally satisfactory but with significant localised	RINCIPAL VULNERABILITY:	Plant growth	TREND:	
Designation:       Scheduled Monument (No. 1020241)       CONDITION:       Generally unsatisfactory with major localised proble         RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         TTE NAME:       Round barrow north of Cadworthy Wood, Meavy, West Devon       Esignation:       Scheduled Monument (No. 1002552)       CONDITION:       Generally satisfactory but with significant localise	WNER TYPE:	-	CONTACT:	Business Manager 0117 975 0700
RINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         WINER TYPE:       Private       CONTACT:       Business Manager 0117 97         TTE NAME:       Round barrow north of Cadworthy Wood, Meavy, West Devon         Designation:       Scheduled Monument (No. 1002552)       CONDITION:       Generally satisfactory but with significant localised	TE NAME:	Prehistoric enclosures on Dewerstone Hill,	500m south east	of Dewerstone Cottage, Meavy, West Deve
RINCIPAL VULNERABILITY: Plant growth TREND: Declining DWNER TYPE: Private CONTACT: Business Manager 0117 97 Inte NAME: Round barrow north of Cadworthy Wood, Meavy, West Devon Scheduled Monument (No. 1002552) CONDITION: Generally satisfactory but with significant localise	DESIGNATION:	Scheduled Monument (No. 1020241)	CONDITION:	Generally unsatisfactory with major localised problems
DWNER TYPE:     Private     CONTACT:     Business Manager 0117 97       ITE NAME:     Round barrow north of Cadworthy Wood, Meavy, West Devon       DESIGNATION:     Scheduled Monument (No. 1002552)     CONDITION:       Generally satisfactory but with significant localise	RINCIPAL VULNERABILITY:	Plant growth	TREND:	
ESIGNATION: Scheduled Monument (No. 1002552) CONDITION: Generally satisfactory but with significant localise		-		Business Manager 0117 975 0700
but with significant localise	TE NAME:	Round barrow north of Cadworthy Wood,	Meavy, West Deve	on
	DESIGNATION:	Scheduled Monument (No. 1002552)	CONDITION:	Generally satisfactory but with significant localised problems
rincipal vulnerability: Plant growth trend: Declining	RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
		-		Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Settlement on Wigford Down south of Dur	ance, Meavy, Wes	Devon
DESIGNATION:	Scheduled Monument (No. 1002523)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			-
SITE NAME:	Settlement on Wigford Down, Meavy, West	Devon	
DESIGNATION:	Scheduled Monument (No. 1002550)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Three hut circles north west of Cadworthy	, Meavy, West Dev	/on
DESIGNATION:	Scheduled Monument (No. 1003057)	CONDITION:	Generally unsatisfactory
		CONDITION.	with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		Contraction	
SITE NAME:	Three hut circles on south part of Wigford	Down, Meavy, We	est Devon
DESIGNATION:	Scheduled Monument (No. 1002549)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two hut circles south of Catstor Down, Me	eavy, West Devon	
DESIGNATION:	Scheduled Monument (No. 1002548)	CONDITION:	Generally satisfactory
Designation.	Scheduled Hohament (No. 1002510)	CONDITION.	but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cairnfield 460m south east of Cox Tor, Pete	er Tavy, West Devo	on
	Cairnfield 460m south east of Cox Tor, Peter Scheduled Monument (No. 1020005)	er Tavy, West Deve condition:	Generally satisfactory
		-	
DESIGNATION:		-	Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020005)	CONDITION:	Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1020005) Plant growth	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1020005) Plant growth Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 vest of Cox Tor, Peter Tavy, West Devon Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1020005) Plant growth Private Cairnfield and two stone hut circles 490m a Scheduled Monument (No. 1020004)	CONDITION: TREND: CONTACT: and 550m south v CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>vest of Cox Tor, Peter Tavy, West Devon</b> Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020005) Plant growth Private Cairnfield and two stone hut circles 490m a Scheduled Monument (No. 1020004) Plant growth	CONDITION: TREND: CONTACT: and 550m south v CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 vest of Cox Tor, Peter Tavy, West Devon Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020005) Plant growth Private Cairnfield and two stone hut circles 490m a Scheduled Monument (No. 1020004)	CONDITION: TREND: CONTACT: and 550m south v CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>vest of Cox Tor, Peter Tavy, West Devon</b> Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1020005) Plant growth Private Cairnfield and two stone hut circles 490m a Scheduled Monument (No. 1020004) Plant growth	CONDITION: TREND: CONTACT: and 550m south v CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 vest of Cox Tor, Peter Tavy, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1020005)         Plant growth         Private         Cairnfield and two stone hut circles 490m a         Scheduled Monument (No. 1020004)         Plant growth         Private	CONDITION: TREND: CONTACT: and 550m south v CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 vest of Cox Tor, Peter Tavy, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 f Cox Tor, Peter Tavy, West Devon Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No. 1020005)         Plant growth         Private         Cairnfield and two stone hut circles 490m at Scheduled Monument (No. 1020004)         Plant growth         Private         Coaxial field system and prehistoric settlem	CONDITION: TREND: CONTACT: and 550m south v CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 vest of Cox Tor, Peter Tavy, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

	Eluvial tin streamworks and prehistoric coa together with other archaeological remains		Common, Peter Tavy, West Devon
DESIGNATION:	Scheduled Monument (No. 1020089)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Enclosed settlement 420m south of Doeton	<sup>-</sup> Farm, Peter Tavy,	West Devon
DESIGNATION:	Scheduled Monument (No. 1007540)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Prehistoric settlement 610m south west of	Cox Tor, Peter Ta	vy, West Devon
DESIGNATION:	Scheduled Monument (No. 1020002)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Stone hut circle and a short length of boun settlement on the north east slope of Cox		
DESIGNATION:	Scheduled Monument (No. 1011432)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone hut circle and field-plots 100m east o	f Ger Tor, Peter Ta	avy, West Devon
SITE NAME: DESIGNATION:	Stone hut circle and field-plots 100m east o Scheduled Monument (No. 1011240)	f Ger Tor, Peter Ta	avy, West Devon Generally unsatisfactory with major localised problems
	Scheduled Monument (No. 1011240)		Generally unsatisfactory
DESIGNATION:		CONDITION:	Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1011240) Plant growth	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE:	Scheduled Monument (No. 1011240) Plant growth Government or Agency	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: 5ITE NAME:	Scheduled Monument (No. 1011240) Plant growth Government or Agency Two stone hut circles 450m SSE of Ger Tor	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1011240) Plant growth Government or Agency Two stone hut circles 450m SSE of Ger Tor Scheduled Monument (No. 1011231)	CONDITION: TREND: CONTACT: Peter Tavy, West CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1011240) Plant growth Government or Agency Two stone hut circles 450m SSE of Ger Tor Scheduled Monument (No. 1011231) Plant growth	CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DITE NAME:	Scheduled Monument (No. 1011240)         Plant growth         Government or Agency         Two stone hut circles 450m SSE of Ger Tor         Scheduled Monument (No. 1011231)         Plant growth         Government or Agency         Agglomerated enclosure with hut circles and	CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DISTE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DISTE NAME: DESIGNATION: DESIGNATION: DESIGNATION:	Scheduled Monument (No. 1011240)         Plant growth         Government or Agency         Two stone hut circles 450m SSE of Ger Tor         Scheduled Monument (No. 1011231)         Plant growth         Government or Agency         Agglomerated enclosure with hut circles an Sheepstor, West Devon	CONDITION: TREND: CONTACT: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 at Whittenknowles Rocks, Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1011240)         Plant growth         Government or Agency         Two stone hut circles 450m SSE of Ger Tor         Scheduled Monument (No. 1011231)         Plant growth         Government or Agency         Agglomerated enclosure with hut circles an         Scheduled Monument (No. 1010650)	CONDITION: TREND: CONTACT: CONTACT: CONDITION: CONTACT: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 at Whittenknowles Rocks, Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1011240)         Plant growth         Government or Agency         Two stone hut circles 450m SSE of Ger Tor         Scheduled Monument (No. 1011231)         Plant growth         Government or Agency         Agglomerated enclosure with hut circles an Sheepstor, West Devon         Scheduled Monument (No. 1010650)         Plant growth	CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONTACT: CONDITION: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 at Whittenknowles Rocks, Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: DESI	Scheduled Monument (No. 1011240)         Plant growth         Government or Agency         Two stone hut circles 450m SSE of Ger Tor         Scheduled Monument (No. 1011231)         Plant growth         Government or Agency         Agglomerated enclosure with hut circles an         Scheduled Monument (No. 1010650)         Plant growth         Government or Agency	CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONTACT: CONDITION: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 at Whittenknowles Rocks, Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: DESIGNATIO	Scheduled Monument (No. 1011240)         Plant growth         Government or Agency         Two stone hut circles 450m SSE of Ger Tor         Scheduled Monument (No. 1011231)         Plant growth         Government or Agency         Agglomerated enclosure with hut circles an Sheepstor, West Devon         Scheduled Monument (No. 1010650)         Plant growth         Plant growth         Cairn east of Scout Hut, Sheepstor, West D	CONDITION: TREND: CONTACT: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Whittenknowles Rocks, Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Cairn south west of Lower Hartor Tor, She	epstor, West Devo	on
DESIGNATION:	Scheduled Monument (No. 1012293)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cairn with a cist north of Drizzlecombe sto	one alignments, Sh	eepstor, West Devon
DESIGNATION:	Scheduled Monument (No. 1010654)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cairn with cist north of Gutter Tor, Sheeps	tor, West Devon	
DESIGNATION:	Scheduled Monument (No. 1012473)	CONDITION:	Generally unsatisfactory
	× , , , , , , , , , , , , , , , , , , ,		with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Enclosed stone hut settlement south west	of Gutter Tor, She	epstor, West Devon
DESIGNATION:	Scheduled Monument (No. 1012251)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Enclosure north west of Gutter Tor, Sheeps	tor, West Devon	
	Enclosure north west of Gutter Tor, Sheeps Scheduled Monument (No. 1012032)	tor, West Devon	Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	•		Generally satisfactory but with significant localised problems Declining
DESIGNATION:	Scheduled Monument (No. 1012032)	CONDITION:	but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012032) Plant growth	CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1012032) Plant growth Private	CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1012032) Plant growth Private Enclosure with hut circles on Eastern Tor, S	CONDITION: TREND: CONTACT: heepstor, West Do	but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1012032) Plant growth Private Enclosure with hut circles on Eastern Tor, S	CONDITION: TREND: CONTACT: heepstor, West Do	but with significant localised problems Declining Business Manager 0117 975 0700 evon Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012032) Plant growth Private Enclosure with hut circles on Eastern Tor, S Scheduled Monument (No. 1010652)	CONDITION: TREND: CONTACT: heepstor, West Do CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 evon Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1012032) Plant growth Private Enclosure with hut circles on Eastern Tor, S Scheduled Monument (No. 1010652) Plant growth	CONDITION: TREND: CONTACT: heepstor, West Do CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 evon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1012032) Plant growth Private Enclosure with hut circles on Eastern Tor, S Scheduled Monument (No. 1010652) Plant growth Private	CONDITION: TREND: CONTACT: heepstor, West Do CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 evon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 or, West Devon Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1012032)         Plant growth         Private         Enclosure with hut circles on Eastern Tor, S         Scheduled Monument (No. 1010652)         Plant growth         Private         Enclosure with hut circles south east of East         Scheduled Monument (No. 1010652)	CONDITION: TREND: CONTACT: heepstor, West Do CONDITION: TREND: CONTACT: stern Tor, Sheepsto	but with significant localised problems Declining Business Manager 0117 975 0700 evon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 or, West Devon Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No. 1012032)         Plant growth         Private         Enclosure with hut circles on Eastern Tor, S         Scheduled Monument (No. 1010652)         Plant growth         Private         Enclosure with hut circles south east of Eastern         Scheduled Monument (No. 1010652)         Plant growth         Private         Enclosure with hut circles south east of Eastern         Plant growth         Private	CONDITION: TREND: CONTACT: heepstor, West Da CONDITION: TREND: CONTACT: stern Tor, Sheepsto	but with significant localised problems Declining Business Manager 0117 975 0700 evon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 or, West Devon Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012032)         Plant growth         Private         Enclosure with hut circles on Eastern Tor, S         Scheduled Monument (No. 1010652)         Plant growth         Private         Enclosure with hut circles south east of East         Scheduled Monument (No. 1010652)	CONDITION: TREND: CONTACT: heepstor, West Da CONDITION: TREND: CONTACT: stern Tor, Sheepstor	but with significant localised problems Declining Business Manager 0117 975 0700 evon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 or, West Devon Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012032)         Plant growth         Private         Enclosure with hut circles on Eastern Tor, S         Scheduled Monument (No. 1010652)         Plant growth         Private         Enclosure with hut circles south east of Eastern         Scheduled Monument (No. 1010652)         Plant growth         Private         Enclosure with hut circles south east of Eastern         Plant growth         Private	CONDITION: TREND: CONTACT: heepstor, West Da CONDITION: TREND: CONTACT: stern Tor, Sheepstor CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 evon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 or, West Devon Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1012032)         Plant growth         Private         Enclosure with hut circles on Eastern Tor, S         Scheduled Monument (No. 1010652)         Plant growth         Private         Enclosure with hut circles south east of East         Scheduled Monument (No. 1010651)         Plant growth         Private	CONDITION: TREND: CONTACT: heepstor, West Da CONDITION: TREND: CONTACT: stern Tor, Sheepstor CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 evon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 or, West Devon Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1012032)         Plant growth         Private         Enclosure with hut circles on Eastern Tor, S         Scheduled Monument (No. 1010652)         Plant growth         Private         Enclosure with hut circles south east of Eastern         Enclosure with hut circles south east of Eastern         Plant growth         Private         Plant growth         Plant growth         Private         Private	CONDITION: TREND: CONTACT: heepstor, West Da CONDITION: TREND: CONTACT: stern Tor, Sheepstor CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 evon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 or, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS ATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Part of Eylesbarrow watershed reave, Sheep	pstor, West Devor	1
DESIGNATION:	Scheduled Monument (No. 1010669)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Pillow mound 180m west of Legis Tor form	ing part of Legisto	r Warren, Sheepstor, West Devon
DESIGNATION:	Scheduled Monument (No. 1008714)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Pillow mound 220m south west of Legis To	r forming part of	Legistor Warren, Sheepstor, West Devon
DESIGNATION:	Scheduled Monument (No. 1008713)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Pillow mound 40m east of Legis Tor formin	g part of Legistor	Warren, Sheepstor, West Devon
DESIGNATION:	Scheduled Monument (No. 1008715)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric enclosed settlement 950m nort	h east of Ditswor	thy Warren House, Sheepstor, West Devo
DESIGNATION:	Scheduled Monument (No. 1021058)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Prehistoric settlement, three round cairns a at Legis Tor, Sheepstor, West Devon	and a post-mediev	al rabbit warren
DESIGNATION:	Scheduled Monument (No. 1019876)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Round cairn east of Whittenknowles Rocks	s, 960m ENE of G	utter Tor, Sheepstor, West Devon
DESIGNATION:	Scheduled Monument (No. 1021052)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION.			
	Plant growth	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth Private	TREND: CONTACT:	Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Three stone alignments, 15 cairns, a cist, a p	CONTACT:	Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: 	Private	CONTACT:	Business Manager 0117 975 0700 stone hut circle settlement t Devon Generally satisfactory
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Three stone alignments, 15 cairns, a cist, a p and a small clapper bridge at Drizzle Comb	CONTACT: partially enclosed s pe, Sheepstor, Wes	Business Manager 0117 975 0700 stone hut circle settlement t Devon

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

But with significant localised problem metabolic settlement south west of Cutter Tor, Sheepstor, West Devon           Bits now:         Unenclosed stone hut settlement south west of Gutter Tor, Sheepstor, West Devon           Destination         Generally satisfactory but with significant localised problem metabolic settlement (No. 1012239)         Construct construct         Generally satisfactory but with significant localised problem mucha-vutationaum:           Plant growth         meso:         Declining           Wester         Vermin trap immediately south west of Legis Tor forming part of Legistor Warren, Sheepstor, West Declining         Generally satisfactory but with significant localised problem metabolic settlement (No. 1008716)           Owner:         Vermin trap immediately south west of Legis Tor forming part of Legistor Warren, Sheepstor, West Declining         Generally satisfactory but with significant localised problem metabolic settlement (No. 1008716)         Constructs           Aprehistoric settlement complex, length of reave, in streamwork and stamping mill on the western slopes of Cosdon Hill, South Tawton, West Devon         Generally satisfactory but with significant localised problem metabolic settlement (No. 1015760)         Constructs           Scheduled Monument (No. 1015760)         constructs         Generally satisfactory but with significant localised problem metabolic settlement (No. 1018925)         Constructs           Scheduled Monument (No. 1018925)         constructs         Generally satisfactory but with significant localised problem metabolic settlement (No. 1010791)		Tin mill, tinwork and post-medieval farmste 260m east of eastern boundary of Roughto		pstor, West Devon
Moderate natural erosion         Tree:         Declining           www.mme         Utility         center         Business Manager 0117 975 0700           ministrame         Two enclosures and a length of the Eyledsarrow watershed reave s00m WSW of Eyledsarrow, Sheepstor, West Devon         Generally satisfactory but with significant localised problem watersheet           with enclosed stone hut settlement south west of Gutter Tor, Sheepstor, West Devon         Declining         Declining           with enclosed stone hut settlement south west of Gutter Tor, Sheepstor, West Devon         Generally satisfactory but with significant localised problem watersheet           with enclosed stone hut settlement south west of Gutter Tor, Sheepstor, West Devon         Generally satisfactory but with significant localised problem watersheet           with enclosed stone hut settlement could west of Legis Tor forming part of Legistor Warren, Sheepstor, West answer         Declining           with trap immediately south west of Legis Tor forming part of Legistor Warren, Sheepstor, West answer         Generally satisfactory but with significant localised problem watersheet           with trap immediately south west of reave, in streamwork and stamping mill on the western slopes of Cosion Hill, South Tawton, West Devon         Generally satisfactory but with significant localised problem watersheet           with trap owth         reave         Declining         Declining           with trap owth         reave         Generally satisfactory but with significant localised problem w	DESIGNATION:	Scheduled Monument (No. 1020242)	CONDITION:	
Semistrime         Utility         control:         Business Manager 0117 975 0700           Implication         Two enclosures and a length of the Eylesbarrow watershed reave 800m WSW of Eylesbarrow. Sheepstor, West Devon         Generally satisfactory but with significant localised problem reason. Unclosed stone hut settlement south west of Gutter Tor, Sheepstor, West Devon           Senserine         Private         Control:         Generally satisfactory but with significant localised problem recens. Valuescentric           Scheduled Monument (No. 101229)         control:         Generally satisfactory but with significant localised problem recens. Valuescentric           Scheduled Monument (No. 101229)         control:         Business Manager 0117 975 0700           Masserme         Plant growth         men           Private         Control:         Generally satisfactory but with significant localised problem recens. Valuescentric           Scheduled Monument (No. 1008716)         control:         Beaching           Scheduled Monument (No. 1008716)         control:         Beaching           Business Manager 0117 975 0700         Control:         Business Manager 0117 975 0700           Implact and growth         meto.         Declining         Control:           Business Manager 0117 975 0700         Control:         Business Manager 0117 975 0700           Implact and growth         meto.         Declining		Moderate natural erosion		
Instruction         Two enclosures at a length of the Eylesbarrow watershed reave 800m WSW of Eylesbarrow. Sheepstor, West Devon         Generally satisfactory but with significant localised problem watersheet.           Scheduled Monument (No. 101 3474)         coxonox.         Generally satisfactory but with significant localised problem man.           Swharme:         Private         coxonox.         Business Manager 0117 975 0700           Are swit:         Unenclosed stone hut settlement south west of Gutter Tor, Sheepstor, West Devon         Generally satisfactory but with significant localised problem metry. vanawaure           Metric:         Unenclosed stone hut settlement south west of Legis Tor forming part of Legistor Warren, Sheepstor, West coxonox.         Generally satisfactory but with significant localised problem metry.           Scheduled Monument (No. 1008716)         coxonox.         Generally satisfactory but with significant localised problem metry.           Scheduled Monument (No. 1008716)         coxonox.         Generally satisfactory but with significant localised problem metry.           Scheduled Monument (No. 1018760)         coxonox.         Generally satisfactory but with significant localised problem metry.           A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slopes of Coson Hill, South Tawton, West Devon         Generally satisfactory but with significant localised problem metry.           A prehistoric settlement complex, length of reave.         Scheduled Monument (No. 1018925)         coron				0
BOOm WSW of Eylesbarrow, Sheepstor, West Devon           BERGWARDLE         Scheduled Monument (No. 1013474)         conome.         Generally satisfactory but with significant localised problem waraw.auxware           Plant growth         marea         Declining         Declining           waraw.auxware         Private         convort.         Business Manager 0117 975 0700           assessance:         Scheduled Monument (No. 1012239)         convort.         Generally satisfactory but with significant localised problem massessance:           assessance:         Scheduled Monument (No. 1012239)         convort.         Business Manager 0117 975 0700           massessance:         Private         Declining         Declining           www.th.me:         Private         convort.         Business Manager 0117 975 0700           meterse         Vermin trap immediately south west of Legis Tor forming part of Legistor Warren, Sheepstor, West         Declining           meterse         Scheduled Monument (No. 1008716)         convort.         Generally satisfactory but with significant localised problem           meterse         Scheduled Monument (No. 1018760)         convort.         Generally satisfactory but with significant localised problem           warea.messantre:         Private         convort.         Generally satisfactory but with significant localised problem           sessantre:			CONVICE.	
but with significant localised problem mscrew.usavaum:         Plant growth         mscr.         Declining           www.servic:         Private         covince:         Business Manager 0117 975 0700           mr.exvic:         Unenclosed stone hut settlement south west of Gutter Tor, Sheepstor, West Devon           mr.exvic:         Unenclosed stone hut settlement south west of Gutter Tor, Sheepstor, West Devon           mr.exvis:         Scheduled Monument (No. 1012239)         covemow         Generally satisfactory but with significant localised problem           www.servic:         Private         covince:         Business Manager 01 17 975 0700           www.servic:         Private         covince:         Business Manager 01 17 975 0700           www.servic:         Private         covince:         Business Manager 01 17 975 0700           www.servic:         Private         covince:         Generally satisfactory but with significant localised problem           www.servic:         Private         covince:         Business Manager 01 17 975 0700           www.servic:         Private         covince:         Business Manager 01 17 975 0700           www.servic:         Private         covince:         Business Manager 01 17 975 0700           www.servic:         Private         covince:         Business Manager 01 17 975 0700           www.s	ITE NAME:			eave
Deviate         Private         Contract:         Business Manager 01 17 975 0700           art NAME:         Unenclosed stone hut settlement south west of Gutter Tor. Sheepstor, West Devon         Scheduled Monument (No. 1012239)         Continue         Generally satisfactory but with significant localised problem           Secondaria         Scheduled Monument (No. 1012239)         Continue         Declining           Secondaria         Plant growth         Trand         Declining           Secondaria         Scheduled Monument (No. 1008716)         Continue         Generally satisfactory but with significant localised problem           Scheduled Monument (No. 1008716)         Continue         Generally satisfactory but with significant localised problem           Wermin trap immediately south west of Legis Tor forming part of Legistor Warren, Sheepstor, West         Scheduled Monument (No. 1008716)         Continue           Scheduled Monument (No. 1008716)         Continue         Generally satisfactory but with significant localised problem           Minesk Wuterweith         Plant growth         Trando         Generally satisfactory but with significant localised problem           Scheduled Monument (No. 1015760)         Continue         Generally satisfactory but with significant localised problem           Scheduled Monument (No. 1018925)         Continue         Generally satisfactory but with significant localised problem           Scheduled	DESIGNATION:	Scheduled Monument (No. 1013474)	CONDITION:	Generally satisfactory but with significant localised problems
All FLAMPE:         Unenclosed stone hut settlement south west of Gutter Tor, Sheepstor, West Devon           ScaleANTORE         Scheduled Monument (No. 1012239)         Control N         Generally satisfactory but with significant localised problem           WINCARE WARKER         Plant growth         TRENA         Declining           WINCARE WARKER         Plant growth         TRENA         Declining           WINCARE WARKER         Plant growth         TRENA         Declining           WINCARE WARKER         Scheduled Monument (No. 1008716)         Control N         Generally satisfactory but with significant localised problem           WINCARE WARKER         Plant growth         TRENA         Declining         Declining           Scheduled Monument (No. 1015760)         Control Net         Generally satisfactory but with significant localised problem           WINCARE WARKER         Plant growth         TRENA         Declining	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	8
Scheduled Monument (No. 1012239)       соколона вислика и и development part of the specificant localised problem mecrative workerwattm:       Generally satisfactory but with significant localised problem mecrative contract:         Business Manager 0117 975 0700       contract:       Business Manager 0117 975 0700         Stream       Vermin trap immediately south west of Legis Tor forming part of Legistor Warren, Sheepstor, West assistantion:       Scheduled Monument (No. 1008716)       controls         Scheduled Monument (No. 1008716)       controls       Generally satisfactory but with significant localised problem mecraw, workerwattm         Plant growth       metro       Declining         water me       Private       controls         Scheduled Monument (No. 1015760)       controls       Generally satisfactory but with significant localised problem mecraw.worker slopes of Cosdon Hill, South Tawton, West Devon         Scheduled Monument (No. 1015760)       controls       Generally satisfactory but with significant localised problem mecraw.workersme         Private       A warren, two stone hut circle settlements, cairmfelds and cairrs at Ivy Tor, ESE of Belstone, South Tawton, West Devon       Generally satisfactory but with significant localised problem mecraw.workersme         Scheduled Monument (No. 1018925)       controls       Generally satisfactory but with significant localised problem         Scheduled Monument (No. 101791)       controls       Generally satisfactory but with significant localised problem	OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
But with significant localised problem remonstructure     Declining       Private     CONVACE     Business Manager 0117 975 0700       Wernin trap immediately south west of Legis Tor forming part of Legistor Warren, Sheepstor, West     Generally satisfactory but with significant localised problem       Scheduled Monument (No. 1008716)     construct     Generally satisfactory but with significant localised problem       Sencent VLNERABUTY     Plant growth     Texto     Declining       Sencent VLNERABUTY     Plant growth     Texto     Generally satisfactory but with significant localised problem       Sencent VLNERABUTY     Plant growth     Texto     Generally satisfactory but with significant localised problem       Texto     Scheduled Monument (No. 1015760)     controls     Generally satisfactory but with significant localised problem       Texto     A warren, two stone hut circle settlements complex, length of reave, tim stammory attrone     Generally satisfactory but with significant localised problem       Texto     A warren two stone hut circle settlements commons     Generally satisfactory but with significant localised problem       Texto     A settle growth     Texto     Controls     Generally satisfacto	SITE NAME:	Unenclosed stone hut settlement south we	st of Gutter Tor, S	heepstor, West Devon
Prescrete     Plant growth     текно:     Declining       OWNERTTYPE     Private     construct:     Business Manager 0117 975 0700       Stre NAME:     Vermin trap immediately south west of Legis Tor forming part of Legistor Warren, Sheepstor, West       Descuration:     Scheduled Monument (No. 1008716)     conomox     Generally satisfactory but with significant localised problem       Rescuration:     Plant growth     TERNA:     Declining     Declining       Rescuration:     Private     construct:     Business Manager 0117 975 0700       Stre NAME:     A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slopes of Cosdon Hill, South Tawton, West Devon     Declining       Scheduled Monument (No. 1015760)     construct:     Business Manager 0117 975 0700       Stre NAME:     Private     construct:     Business Manager 0117 975 0700       Stre NAME:     Private     construct:     Business Manager 0117 975 0700       Stre NAME:     Private     construct:     Business Manager 0117 975 0700       Stre NAME:     A warren, two stone hut circle settlements, cairnfields and cairrs at ly Tor,     ESE of Belstone, South Tawton, West Devon       Scheduled Monument (No. 1018925)     construct:     Business Manager 0117 975 0700       Stable     onstruct:     Stable     Stable       OWNERTIFIE     Agglomerate enclosure and 1	DESIGNATION:	Scheduled Monument (No. 1012239)	CONDITION:	Generally satisfactory but with significant localised problems
Appendix and the set of Legis Tor forming part of Legistor Warren, Sheepstor, West           Scheduled Monument (No. 1008716)         Constance:         Generally satisfactory but with significant localised problem memory           Plant growth         THEND:         Declining           Private         A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slopes of Coston Hill, South Tavton, West Devon         Generally satisfactory but with significant localised problem           Descurrence:         Scheduled Monument (No. 1015760)         Constance:         Generally satisfactory but with significant localised problem           Private         Constance:         Declining         Declining           Ownerstring:         Plant growth         THEND:         Declining           Ownerstring:         A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slopes of Coston Hill, South Tavton, West Devon         Generally satisfactory but with significant localised problem           Ownerstring:         Plant growth         THEND:         Declining           Stresses:         A warren, two stone hut circle settlements, cairnfields and cairns at ly Tor, ESE of Belstone, South Tawton, West Devon         Generally satisfactory but with significant localised problem           Stresses:         Agglomerate enclosure and IS stone hut circles S60m west of Cawsand Beacon, South Tawton, West Devontex waren, West Devon         Declining </td <td>PRINCIPAL VULNERABILITY:</td> <td>Plant growth</td> <td>TREND:</td> <td></td>	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	
Besidewarion:       Scheduled Monument (No. 1008716)       convortion:       Generally satisfactory but with significant localised problem menocine.         Prediction.vulue.evalue.rv:       Plant growth       menocine.       Declining         Streenweit:       A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slopes of Cosdon Hill, South Tawton, West Devon       Generally satisfactory         Streenweit:       A prehistoric settlement (No. 1015760)       convorter:       Business Manager 0117 975 0700         Scheduled Monument (No. 1015760)       convorter:       Business Manager 0117 975 0700         Scheduled Monument (No. 1015760)       convorter:       Business Manager 0117 975 0700         Scheduled Monument (No. 1018760)       convorter:       Business Manager 0117 975 0700         Stresmet:       A warren, two stone hut circle settlements, cairmfields and cairns at lvy Tor,         ESE of Belstone, South Tawton, West Devon       Generally satisfactory but with significant localised problem         Scheduled Monument (No. 1018925)       convorter:       Business Manager 0117 975 0700         Scheduled Monument (No. 1010791)       convorter:       Generally satisfactory but with significant localised problem         Scheduled Monument (No. 1010791)       convorter:       Generally satisfactory but with significant localised problem         Scheduled Monument (No. 1010791)       convorter: </td <td>OWNER TYPE:</td> <td>5</td> <td>CONTACT:</td> <td>Business Manager 0117 975 0700</td>	OWNER TYPE:	5	CONTACT:	Business Manager 0117 975 0700
But with significant localised problem       RINCIPAL VULNERABLITY:     Plant growth       Private     CONTACT:       Business Manager 0117 975 0700       <	SITE NAME:	Vermin trap immediately south west of Leg	is Tor forming par	t of Legistor Warren, Sheepstor, West De
PRINCENALULARINABILITY:       Plant growth       TRIND:       Declining         OWNERTIME:       Private       contract:       Business Manager 0117 975 0700         STR NAME:       A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slopes of Cosdon Hill, South Tawton, West Devon       Generally satisfactory but with significant localised problem         DESIGNATION:       Scheduled Monument (No. 1015760)       CONDITION       Generally satisfactory but with significant localised problem         WINERTIME       Plant growth       TREND:       Declining         OWNERTIME       Plant growth       TREND:       Declining         Stre NAME:       A warren, two stone hut circle settlements, cairnfields and cairns at Ivy Tor, ESE of Belstone, South Tawton, West Devon       Generally satisfactory but with significant localised problem         TREND:       Scheduled Monument (No. 1018925)       CONDITION       Generally satisfactory but with significant localised problem         TREND:       Plant growth       TREND:       Stable         OWNERTIME:       Agglomerate enclosure and 15 stone hut circles 560m west of Cawsand Beacon, South Tawton, West         Designation:       Scheduled Monument (No. 1010791)       CONDITION:       Generally satisfactory but with significant localised problem         TREND:       Plant growth       TREND:       Declining       Declining <td>DESIGNATION:</td> <td>Scheduled Monument (No. 1008716)</td> <td>CONDITION:</td> <td></td>	DESIGNATION:	Scheduled Monument (No. 1008716)	CONDITION:	
омнектите: Private contract: Business Manager 0117 975 0700 A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slopes of Cosdon Hill, South Tawton, West Devon Descendation: Scheduled Monument (No. 1015760) contornor: Generally satisfactory but with significant localised problem Prencend vulnervalutr: Plant growth TREND: Declining owner type: Private contract: Business Manager 0117 975 0700 Scheduled Monument (No. 1018760) contract: Business Manager 0117 975 0700 Stre NAME: A warren, two stone hut circle settlements, cairmfields and cairns at Ivy Tor, ESE of Belstone, South Tawton, West Devon Descendation: Scheduled Monument (No. 1018925) contract: Business Manager 0117 975 0700 Descendation: Scheduled Monument (No. 1018925) contract: Business Manager 0117 975 0700 Scheduled Monument (No. 1018925) contract: Business Manager 0117 975 0700 Stre NAME: Agglomerate enclosure and 15 stone hut circles 560m west of Cawsand Beacon, South Tawton, West Descendation: Scheduled Monument (No. 1010791) contract: Business Manager 0117 975 0700 Stre NAME: Agglomerate enclosure and to stone hut circles 500m west of Cawsand Beacon, South Tawton, West Descendation: Scheduled Monument (No. 1010791) contract: Business Manager 0117 975 0700 Stre NAME: Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Stre NAME: Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Stre NAME: Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Scheduled Monument (No. 1010790) contract: Business Manager 0117 975 0700 Stre NAME: Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon Descendation: Scheduled Monument (No. 1010790) contract: Business Manager 0117 975 0700 Stre NAME: Agglomerate enclosure and ten stone hut circles for the stone hut circles for the stone for the significant loc	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	
A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slopes of Cosdon Hill, South Tawton, West Devon Scheduled Monument (No. 1015760) contorion: Generally satisfactory but with significant localised problem reincerve vulnerability: Plant growth TRENDRY Vulnerability: Private Contract: Business Manager 0117 975 0700 Contorion: Generally satisfactory but with significant localised problem reincerve vulnerability: Plant growth TRENDRY Vulnerability: Plant growth Contract: Business Manager 0117 975 0700 Contract: Business				0
on'the western slopes of Cosdon Hill, South Tawton, West Devon Besignation: Scheduled Monument (No. 1015760) CONDITION: Generally satisfactory but with significant localised problem Prince Private CONTACT: Business Manager 0117 975 0700	SITE NAME:	A prehistoric settlement complex, length of	reave, tin stream	work and stamping mill
PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE       Private       contract:       Business Manager 0117 975 0700         SITE NAME:       A warren, two stone hut circle settlements, cairnfields and cairns at lvy Tor, ESE of Belstone, South Tawton, West Devon       Generally satisfactory but with significant localised problem         SITE NAME:       Plant growth       TREND:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Stable         OWNER TYPE       Private       contract:       Business Manager 0117 975 0700         Stre NAME:       Agglomerate enclosure and 15 stone hut circles 560m west of Cawsand Beacon, South Tawton, West       Scheduled Monument (No. 1010791)       contract:       Business Manager 0117 975 0700         Stre NAME:       Agglomerate enclosure and 15 stone hut circles 560m west of Cawsand Beacon, South Tawton, West       Declining         OWNER TYPE       Plant growth       TREND:       Declining         Stre NAME:       Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon       Declining         Stre NAME:       Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon       Generally satisfactory but with significant localised problem         Stre NAME:       Agglomerate encl		on the western slopes of Cosdon Hill, Sout		evon
DWNER TYPE       Private       CONTACT:       Business Manager 0117 975 0700         SITE NAME:       A warren, two stone hut circle settlements, cairnfields and cairns at lvy Tor, ESE of Belstone, South Tawton, West Devon       Generally satisfactory but with significant localised problem         DESIGNATION:       Scheduled Monument (No. 1018925)       CONDITION:       Generally satisfactory but with significant localised problem         RRINCIPAL VULNERABUTY:       Plant growth       TREND:       Stable         OWNER TYPE       Private       CONTACT:       Business Manager 0117 975 0700         Stre NAME:       Agglomerate enclosure and 15 stone hut circles 560m west of Cawsand Beacon, South Tawton, West       Generally satisfactory but with significant localised problem         DESIGNATION:       Scheduled Monument (No. 1010791)       CONDITION:       Generally satisfactory but with significant localised problem         RRINCIPAL VULNERABUTY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Business Manager 0117 975 0700         Stre NAME:       Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon       Declining         Stre NAME:       Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon       Generally satisfactory but with significant localised problem         DESIGNATION: <td< td=""><td>DESIGNATION:</td><td>Scheduled Monument (No. 1015760)</td><td>CONDITION:</td><td></td></td<>	DESIGNATION:	Scheduled Monument (No. 1015760)	CONDITION:	
STEE NAME:       A warren, two stone hut circle settlements, cairnfields and cairns at lvy Tor, ESE of Belstone, South Tawton, West Devon         DESIGNATION:       Scheduled Monument (No. 1018925)       CONDITION:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABULTY:       Plant growth       TREND:       Stable         OWNER TYPE       Private       contract:       Business Manager 0117 975 0700         Stre NAME:       Agglomerate enclosure and IS stone hut circles 560m west of Cawsand Beacon, South Tawton, West         DESIGNATION:       Scheduled Monument (No. 1010791)       CONDITION:       Generally satisfactory but with significant localised problem         RRINCIPAL VULNERABULTY:       Plant growth       TREND:       Declining         OWNER TYPE       Private       contract:       Business Manager 0117 975 0700         Stre NAME:       Agglomerate enclosure and IS stone hut circles 560m west of Cawsand Beacon, South Tawton, West         DESIGNATION:       Scheduled Monument (No. 1010791)       CONDITION:       Generally satisfactory but with significant localised problem         Stre NAME:       Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon       Scheduled Monument (No. 1010790)       CONDITION:       Generally satisfactory but with significant localised problem         Stre NAME:       Agglomerate enclosure and ten stone hut circles 50				
ESE of Belstone, South Tawton, West Devon         DESIGNATION:       Scheduled Monument (No. 1018925)       CONDITION:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Stable         OWNER TYPE:       Private       CONTACT:       Business Manager 0117 975 0700         UNITION:       Agglomerate enclosure and 15 stone hut circles 560m west of Cawsand Beacon, South Tawton, West         DESIGNATION:       Scheduled Monument (No. 1010791)       CONDITION:       Generally satisfactory but with significant localised problem         RRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Business Manager 0117 975 0700         Stre NAME:       Agglomerate enclosure and 15 stone hut circles 560m west of Cawsand Beacon, South Tawton, West         DESIGNATION:       Plant growth       TREND:       Declining         OWNER TYPE:       Plant growth       TREND:       Declining         Stre NAME:       Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon       Condition:         DESIGNATION:       Scheduled Monument (No. 1010790)       Condition:       Generally satisfactory but with significant localised problem         DESIGNATION:       Scheduled Monument (No.	PRINCIPAL VULNERABILITY:		TREND:	Declining
PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Stable         OWNNERTYPE:       Private       CONTACT:       Business Manager 0117 975 0700         STRE NAME:       Agglomerate enclosure and 15 stone hut circles 560m west of Cawsand Beacon, South Tawton, Wess         DESIGNATION:       Scheduled Monument (No. 1010791)       CONDITION:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNNERTYPE:       Private       CONTACT:       Business Manager 0117 975 0700         STRE NAME:       Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West       Declining         DWNERTYPE:       Private       CONTACT:       Business Manager 0117 975 0700         Stre NAME:       Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon       Scheduled Monument (No. 1010790)         DESIGNATION:       Scheduled Monument (No. 1010790)       CONDITION:       Generally satisfactory but with significant localised problem         DESIGNATION:       Scheduled Monument (No. 1010790)       CONDITION:       Generally satisfactory but with significant localised problem         DESIGNATION:       Scheduled Monument (No. 1010790)       CONDITION:       Generally satisfactory but with significant localised problem <td></td> <td></td> <td></td> <td>Declining</td>				Declining
OWNER TYPE:       Private       CONTACT:       Business Manager 0117 975 0700         SITE NAME:       Agglomerate enclosure and IS stone hut circles 560m west of Cawsand Beacon, South Tawton, West       Generally satisfactory but with significant localised problem         DESIGNATION:       Scheduled Monument (No. 1010791)       CONDITION:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Business Manager 0117 975 0700         SITE NAME:       Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon       CONTACT:       Business Manager 0117 975 0700         DESIGNATION:       Scheduled Monument (No. 1010790)       CONTACT:       Business Manager 0117 975 0700         DESIGNATION:       Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon       CONTACT:       Business Manager 0117 975 0700         DESIGNATION:       Scheduled Monument (No. 1010790)       CONDITION:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining	OWNER TYPE:	Private A warren, two stone hut circle settlements	CONTACT:	Declining Business Manager 0117 975 0700
SITE NAME:       Agglomerate enclosure and I5 stone hut circles 560m west of Cawsand Beacon, South Tawton, West         DESIGNATION:       Scheduled Monument (No. 1010791)       CONDITION:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Business Manager 0117 975 0700         STE NAME:       Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon       CONDITION:       Generally satisfactory but with significant localised problem         DESIGNATION:       Scheduled Monument (No. 1010790)       CONDITION:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining	PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Private A warren, two stone hut circle settlements. ESE of Belstone, South Tawton, West Devor	contact: , cairnfields and ca	Declining Business Manager 0117 975 0700 irrns at Ivy Tor,
Designation:       Scheduled Monument (No. 1010791)       CONDITION:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       contact:       Business Manager 0117 975 0700         State NAME:       Agglomerate enclosure and ten stone hut circles       500m west of Cawsand Beacon, South Tawton, West Devon         Designation:       Scheduled Monument (No. 1010790)       Condition:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining	OWNER TYPE:	Private A warren, two stone hut circle settlements ESE of Belstone, South Tawton, West Devor Scheduled Monument (No. 1018925)	contact: , cairnfields and ca condition:	Declining Business Manager 0117 975 0700 irrns at Ivy Tor, Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         DOWNER TYPE:       Private       CONTACT:       Business Manager 0117 975 0700         SITE NAME:       Agglomerate enclosure and ten stone hut circles       500m west of Cawsand Beacon, South Tawton, West Devon         DESIGNATION:       Scheduled Monument (No. 1010790)       CONDITION:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining	DWNER TYPE:	Private A warren, two stone hut circle settlements, ESE of Belstone, South Tawton, West Devor Scheduled Monument (No. 1018925) Plant growth	CONTACT: cairnfields and ca CONDITION: TREND:	Declining Business Manager 0117 975 0700 wirns at Ivy Tor, Generally satisfactory but with significant localised problems Stable
PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Business Manager 0117 975 0700         SITE NAME:       Agglomerate enclosure and ten stone hut circles       500m west of Cawsand Beacon, South Tawton, West Devon         DESIGNATION:       Scheduled Monument (No. 1010790)       CONDITION:       Generally satisfactory but with significant localised problem         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining	OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private A warren, two stone hut circle settlements. ESE of Belstone, South Tawton, West Devor Scheduled Monument (No. 1018925) Plant growth Private	CONTACT: Cairnfields and ca CONDITION: TREND: CONTACT:	Declining Business Manager 0117 975 0700 irrns at Ivy Tor, Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700
OWNER TYPE:     Private     CONTACT:     Business Manager 0117 975 0700       SITE NAME:     Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon     Condition:       DESIGNATION:     Scheduled Monument (No. 1010790)     CONDITION:     Generally satisfactory but with significant localised problem       PRINCIPAL VULNERABILITY:     Plant growth     TREND:     Declining	OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private A warren, two stone hut circle settlements. ESE of Belstone, South Tawton, West Devor Scheduled Monument (No. 1018925) Plant growth Private Agglomerate enclosure and 15 stone hut circle	CONTACT: cairnfields and ca CONDITION: TREND: CONTACT: rcles 560m west c	Declining Business Manager 0117 975 0700 irrns at Ivy Tor, Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 of Cawsand Beacon, South Tawton, West I Generally satisfactory
South Tawton, West Devon       DESIGNATION:     Scheduled Monument (No. 1010790)     CONDITION:     Generally satisfactory but with significant localised problem       PRINCIPAL VULNERABILITY:     Plant growth     TREND:     Declining	DWNER TYPE:	Private A warren, two stone hut circle settlements, ESE of Belstone, South Tawton, West Devor Scheduled Monument (No. 1018925) Plant growth Private Agglomerate enclosure and 15 stone hut circle Scheduled Monument (No. 1010791)	CONTACT: cairnfields and ca CONDITION: TREND: CONTACT: rcles 560m west c CONDITION:	Declining Business Manager 0117 975 0700 irrns at Ivy Tor, Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 of Cawsand Beacon, South Tawton, West I Generally satisfactory but with significant localised problems
DESIGNATION: Scheduled Monument (No. 1010790) CONDITION: Generally satisfactory but with significant localised problem PRINCIPAL VULNERABILITY: Plant growth TREND: Declining	OWNER TYPE:	Private A warren, two stone hut circle settlements, ESE of Belstone, South Tawton, West Devor Scheduled Monument (No. 1018925) Plant growth Private Agglomerate enclosure and 15 stone hut circle Scheduled Monument (No. 1010791) Plant growth	CONTACT: Cairnfields and ca CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION:	Declining Business Manager 0117 975 0700 irrns at Ivy Tor, Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 of Cawsand Beacon, South Tawton, West I Generally satisfactory but with significant localised problems Declining
PRINCIPAL VULNERABILITY: Plant growth TREND: Declining	OWNER TYPE:	Private A warren, two stone hut circle settlements, ESE of Belstone, South Tawton, West Devor Scheduled Monument (No. 1018925) Plant growth Private Agglomerate enclosure and 15 stone hut circle Scheduled Monument (No. 1010791) Plant growth Private Agglomerate enclosure and ten stone hut circle Agglomerate enclosure and ten stone hut circle	CONTACT:	Declining Business Manager 0117 975 0700 irrns at Ivy Tor, Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 of Cawsand Beacon, South Tawton, West I Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
	OWNER TYPE:	Private         A warren, two stone hut circle settlements.         ESE of Belstone, South Tawton, West Devor         Scheduled Monument (No. 1018925)         Plant growth         Private         Agglomerate enclosure and 15 stone hut circle         Scheduled Monument (No. 1010791)         Plant growth         Private         Agglomerate enclosure and to stone hut circle         Scheduled Monument (No. 1010791)         Plant growth         Private         Agglomerate enclosure and ten stone hut circle         Scheduled Monument (No. 1010791)	CONTACT: Cairnfields and ca CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT:	Declining Business Manager 0117 975 0700 irrns at Ivy Tor, Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 of Cawsand Beacon, South Tawton, West I Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 of Cawsand Beacon, Generally satisfactory
OWNER TYPE: Private CONTACT: Business Manager 0117 975 0700	OWNER TYPE:	Private         A warren, two stone hut circle settlements.         ESE of Belstone, South Tawton, West Devor         Scheduled Monument (No. 1018925)         Plant growth         Private         Agglomerate enclosure and 15 stone hut circle         Scheduled Monument (No. 1010791)         Plant growth         Private         Agglomerate enclosure and to stone hut circle         Scheduled Monument (No. 1010791)         Plant growth         Private         Scheduled Monument (No. 1010791)         Scheduled Monument (No. 1010791)	CONTACT: Cairnfields and ca CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: TREND: CONTACT: CONTACT:	Declining Business Manager 0117 975 0700 irrns at Ivy Tor, Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 of Cawsand Beacon, South Tawton, West I Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 of Cawsand Beacon, Generally satisfactory but with significant localised problems

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	An agglomerated enclosed settlement 480n	n west of Stoneyh	urst, South Tawton, West Devon
DESIGNATION:	Scheduled Monument (No. 1017285)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cairn cemetery and earthwork bank 340m South Tawton, West Devon	south west of Bla	ckaton Brook Ford,
DESIGNATION:	Scheduled Monument (No. 1018906)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cairnfield 760m west of Stoneyhurst, South	n Tawton, West De	evon
DESIGNATION:	Scheduled Monument (No. 1017287)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cairnfield 790m north west of Stoneyhurst	, South Tawton, W	lest Devon
DESIGNATION:	Scheduled Monument (No. 1017284)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
ININGII AL VOLINLIVADILITT.			
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	-	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devon Generally satisfactory
OWNER TYPE: SITE NAME: DESIGNATION:	Private Partially enclosed stone hut circle settlement Scheduled Monument (No. 1015759)	CONTACT: nt 650m south ea:	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devon Generally satisfactory but with significant localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Partially enclosed stone hut circle settlement	CONTACT: nt 650m south ea: CONDITION:	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devor Generally satisfactory
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Partially enclosed stone hut circle settlement Scheduled Monument (No. 1015759) Plant growth	CONTACT: nt 650m south ea: CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devor Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private Partially enclosed stone hut circle settlemen Scheduled Monument (No. 1015759) Plant growth Private	CONTACT: nt 650m south ea: CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory
OWNER TYPE: SITE NAME: DESIGNATION: OWNER TYPE: SITE NAME: DESIGNATION:	Private Partially enclosed stone hut circle settlement Scheduled Monument (No. 1015759) Plant growth Private Round cairn 570m west of Stoneyhurst, Sou Scheduled Monument (No. 1017286)	CONTACT: nt 650m south ea: CONDITION: TREND: CONTACT: uth Tawton, West	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Devon
OWNER TYPE:	Private Partially enclosed stone hut circle settlemen Scheduled Monument (No. 1015759) Plant growth Private Round cairn 570m west of Stoneyhurst, Sou	CONTACT: nt 650m south ea: CONDITION: TREND: CONTACT: uth Tawton, West CONDITION:	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devor Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Partially enclosed stone hut circle settlement Scheduled Monument (No. 1015759) Plant growth Private Round cairn 570m west of Stoneyhurst, Sou Scheduled Monument (No. 1017286) Plant growth	CONTACT: Int 650m south ea: CONDITION: TREND: CONTACT: Uth Tawton, West CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:	Private Partially enclosed stone hut circle settlement Scheduled Monument (No. 1015759) Plant growth Private Round cairn 570m west of Stoneyhurst, Sou Scheduled Monument (No. 1017286) Plant growth Private	CONTACT: Int 650m south ea: CONDITION: TREND: CONTACT: Uth Tawton, West CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:	Private Partially enclosed stone hut circle settlemen Scheduled Monument (No. 1015759) Plant growth Private Round cairn 570m west of Stoneyhurst, Son Scheduled Monument (No. 1017286) Plant growth Private Two hut circles east of Foxes Holt, South Ta	CONTACT: Int 650m south ea: CONDITION: TREND: CONTACT: Uth Tawton, West CONDITION: TREND: CONTACT: awton, West Devo	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 m Generally unsatisfactory
OWNER TYPE:	Private         Partially enclosed stone hut circle settlement         Scheduled Monument (No. 1015759)         Plant growth         Private         Round cairn 570m west of Stoneyhurst, Sont         Scheduled Monument (No. 1017286)         Plant growth         Private         Two hut circles east of Foxes Holt, South Tail         Scheduled Monument (No. 1002599)	CONTACT: Int 650m south ea: CONDITION: TREND: CONTACT: Uth Tawton, West CONDITION: TREND: CONTACT: awton, West Devo	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 n Generally unsatisfactory with major localised problems
OWNER TYPE:	Private         Partially enclosed stone hut circle settlement         Scheduled Monument (No. 1015759)         Plant growth         Private         Round cairn 570m west of Stoneyhurst, South         Scheduled Monument (No. 1017286)         Plant growth         Private         Two hut circles east of Foxes Holt, South Tail         Scheduled Monument (No. 1002599)         Plant growth		Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devor Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 n Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:	Private         Partially enclosed stone hut circle settlement         Scheduled Monument (No. 1015759)         Plant growth         Private         Round cairn 570m west of Stoneyhurst, South         Scheduled Monument (No. 1017286)         Plant growth         Private         Two hut circles east of Foxes Holt, South Tail         Scheduled Monument (No. 1002599)         Plant growth         Private		Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 n Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 leigh, West Devon Generally satisfactory
OWNER TYPE:	Private         Partially enclosed stone hut circle settlement         Scheduled Monument (No. 1015759)         Plant growth         Private         Round cairn 570m west of Stoneyhurst, Some         Scheduled Monument (No. 1017286)         Plant growth         Private         Two hut circles east of Foxes Holt, South Tail         Scheduled Monument (No. 1002599)         Plant growth         Private         Scheduled Monument (No. 1002599)         Plant growth         Private         Scheduled Monument (No. 1002599)         Plant growth         Private         Stone hut circle 140m north west of Higher	CONTACT: Int 650m south ea: CONDITION: TREND: CONTACT: Uth Tawton, West CONDITION: TREND: CONTACT: Awton, West Devoc TREND: CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT: CONTACT: TREND: CONTACT: CONTA	Business Manager 0117 975 0700 st of Tawcroft, South Tawton, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 m Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Heigh, West Devon

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

	A length of the Great Western Reave, a pre three cairns and two field systems on Walkl		
DESIGNATION:	Scheduled Monument (No. 1019589)	CONDITION:	Generally satisfactory
			but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
	,		
TE NAME:	An agglomerate enclosure and seven stone Walkhampton, West Devon	hut circles 460m	WSW of Raddick Hill summit,
DESIGNATION:	Scheduled Monument (No. 1011171)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
WNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
ite name:	An enclosed stone hut circle settlement and 540m south east of Down Tor, Walkhampto		g earthworks,
DESIGNATION:	Scheduled Monument (No. 1009088)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
TENIANE	An opelocure containing and store but similar	0.460m wast of 1	Prote Cate Wallshampton Wast Davis
	An enclosure containing one stone hut circl		·
DESIGNATION:	Scheduled Monument (No. 1009091)	CONDITION:	Generally unsatisfactory
	Plant growth	TREND	with major localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining Business Manager 0117 975 0700
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
DITE NAME:	An enclosure, attached stone hut circle and Walkhampton, West Devon	length of reave l	30m NNE of Leather Tor,
	Scheduled Monument (No. 1011248)	CONDITION:	Generally satisfactory
DESIGNATION:	Scheduled Fiondment (140, 1011210)	CONDITION:	
			but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	but with significant localised problems Declining
RINCIPAL VULNERABILITY:			but with significant localised problems
PRINCIPAL VULNERABILITY: DWNER TYPE:	Plant growth	TREND: CONTACT: of reave and seve	but with significant localised problems Declining Business Manager 0117 975 0700
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Plant growth Utility An enclosure, six stone hut circles, a length	TREND: CONTACT: of reave and seve	but with significant localised problems Declining Business Manager 0117 975 0700
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Plant growth Utility An enclosure, six stone hut circles, a length 170m north east of Leather Tor, Walkhampt	TREND: CONTACT: of reave and seve on, West Devon	but with significant localised problems Declining Business Manager 0117 975 0700 ral prospecting pits
RINCIPAL VULNERABILITY: WWNER TYPE: ITE NAME: DESIGNATION:	Plant growth Utility An enclosure, six stone hut circles, a length 170m north east of Leather Tor, Walkhampt Scheduled Monument (No. 1011247)	TREND: CONTACT: of reave and seve on, West Devon	but with significant localised problems Declining Business Manager 0117 975 0700 Tral prospecting pits Generally satisfactory
RINCIPAL VULNERABILITY: WINER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Plant growth Utility An enclosure, six stone hut circles, a length 170m north east of Leather Tor, Walkhampt	TREND: CONTACT: of reave and seve on, West Devon CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 Fral prospecting pits Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Plant growth Utility An enclosure, six stone hut circles, a length 170m north east of Leather Tor, Walkhampt Scheduled Monument (No. 1011247) Plant growth	TREND: CONTACT: of reave and seve on, West Devon CONDITION: TREND: CONTACT: an irregular aggre	but with significant localised problems Declining Business Manager 0117 975 0700 aral prospecting pits Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gate field system,
PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWN	Plant growth Utility An enclosure, six stone hut circles, a length I70m north east of Leather Tor, Walkhampt Scheduled Monument (No. 1011247) Plant growth Utility An unenclosed stone hut circle settlement,	TREND: CONTACT: of reave and seve on, West Devon CONDITION: TREND: CONTACT: an irregular aggre	but with significant localised problems Declining Business Manager 0117 975 0700 rral prospecting pits Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gate field system,
RINCIPAL VULNERABILITY: WINER TYPE TE NAME: ESIGNATION: TE NAME: ESIGNATION:	Plant growth Utility An enclosure, six stone hut circles, a length 170m north east of Leather Tor, Walkhampt Scheduled Monument (No. 1011247) Plant growth Utility An unenclosed stone hut circle settlement, a length of reave and an enclosure on the set	TREND: CONTACT: of reave and seve on, West Devon CONDITION: TREND: CONTACT: an irregular aggre outh east slope o	but with significant localised problems Declining Business Manager 0117 975 0700 aral prospecting pits Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gate field system, f Leeden Tor, Walkhampton, West Devon Generally unsatisfactory
RINCIPAL VULNERABILITY: WINER TYPE: ITE NAME: PESIGNATION: WINER TYPE: ITE NAME: PESIGNATION: RINCIPAL VULNERABILITY: PESIGNATION: RINCIPAL VULNERABILITY: RINCIPAL VULNERABILITY:	Plant growth         Utility         An enclosure, six stone hut circles, a length         I70m north east of Leather Tor, Walkhampt         Scheduled Monument (No. 1011247)         Plant growth         Utility         An unenclosed stone hut circle settlement, a length of reave and an enclosure on the set         Scheduled Monument (No. 1008671)	TREND: CONTACT: of reave and seve on, West Devon CONDITION: TREND: CONTACT: an irregular aggre buth east slope o CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 Tral prospecting pits Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gate field system, f Leeden Tor, Walkhampton, West Devon Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:  WHER TYPE:  ITE NAME:  ESIGNATION:  RINCIPAL VULNERABILITY:  VWNER TYPE:  ITE NAME:  ESIGNATION:  RINCIPAL VULNERABILITY:  WHER TYPE:  SWNER TYPE:  S	Plant growth         Utility         An enclosure, six stone hut circles, a length         I70m north east of Leather Tor, Walkhampt         Scheduled Monument (No. 1011247)         Plant growth         Utility         An unenclosed stone hut circle settlement, a length of reave and an enclosure on the set         Scheduled Monument (No. 1008671)         Plant growth         Utility	TREND: CONTACT: of reave and seve on, West Devon CONDITION: TREND: CONTACT: an irregular aggre puth east slope of CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 Tral prospecting pits Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gate field system, f Leeden Tor, Walkhampton, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
RINCIPAL VULNERABILITY:          DWNER TYPE:         ITE NAME:         DESIGNATION:         RINCIPAL VULNERABILITY:         DWNER TYPE:         ITE NAME:         DESIGNATION:         RINCIPAL VULNERABILITY:         DWNER TYPE:         ITE NAME:         DESIGNATION:         RINCIPAL VULNERABILITY:         DWNER TYPE:         ITE NAME:	Plant growth         Utility         An enclosure, six stone hut circles, a length         I70m north east of Leather Tor, Walkhampt         Scheduled Monument (No. 1011247)         Plant growth         Utility         An unenclosed stone hut circle settlement, a length of reave and an enclosure on the set         Scheduled Monument (No. 1008671)         Plant growth         Utility         Cairn 550m south west of Raddick Hill sum	TREND: CONTACT: of reave and seve on, West Devon CONDITION: TREND: CONTACT: an irregular aggre outh east slope or CONDITION: TREND: CONTACT: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 aral prospecting pits Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gate field system, f Leeden Tor, Walkhampton, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 of a cairnfield, Walkhampton, West Devor
PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY: DESIGNATION: DESIGNATION	Plant growth         Utility         An enclosure, six stone hut circles, a length         I70m north east of Leather Tor, Walkhampt         Scheduled Monument (No. 1011247)         Plant growth         Utility         An unenclosed stone hut circle settlement, a length of reave and an enclosure on the set         Scheduled Monument (No. 1008671)         Plant growth         Utility	TREND: CONTACT: of reave and seve on, West Devon CONDITION: TREND: CONTACT: an irregular aggre puth east slope of CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 Tral prospecting pits Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gate field system, f Leeden Tor, Walkhampton, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 of a cairnfield, Walkhampton, West Devor Generally unsatisfactory
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Plant growth         Utility         An enclosure, six stone hut circles, a length         I70m north east of Leather Tor, Walkhampt         Scheduled Monument (No. 1011247)         Plant growth         Utility         An unenclosed stone hut circle settlement, a length of reave and an enclosure on the set         Scheduled Monument (No. 1008671)         Plant growth         Utility         Cairn 550m south west of Raddick Hill sum	TREND: CONTACT: of reave and seve on, West Devon CONDITION: TREND: CONTACT: an irregular aggre outh east slope or CONDITION: TREND: CONTACT: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 aral prospecting pits Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 gate field system, f Leeden Tor, Walkhampton, West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 of a cairnfield, Walkhampton, West Devor

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Cairn 560m south west of Raddick Hill sum	nmit forming part	of a cairnfield, Walkhampton, West Devoi
DESIGNATION:	Scheduled Monument (No. 1007415)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Eight stone hut circles and two enclosures forming part of an unenclosed settlement 5	80m south of Lee	den Tor, Walkhampton, West Devon
DESIGNATION:	Scheduled Monument (No. 1008661)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Eleven stone hut circles, a length of bounda forming part of an unenclosed settlement c		
DESIGNATION:	Scheduled Monument (No. 1007435)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Enclosed settlement 380m south west of R	addick Hill summi	t, Walkhampton, West Devon
DESIGNATION:	Scheduled Monument (No. 1011173)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Enclosed settlement 400m west of Raddick	Hill summit, Walk	shampton, West Devon
DESIGNATION:	Scheduled Monument (No. 1011172)	CONDITION:	Generally unsatisfactory
	······································	CONDITION.	with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	, , ,
			with major localised problems
OWNER TYPE:	Plant growth	TREND: CONTACT: east of Sharpitor	with major localised problems Declining Business Manager 0117 975 0700
DWNER TYPE:	Plant growth Utility Enclosure and stone hut circle 320m north	TREND: CONTACT: east of Sharpitor	with major localised problems Declining Business Manager 0117 975 0700
DWNER TYPE:	Plant growth Utility Enclosure and stone hut circle 320m north forming part of a stone hut circle settlemen	TREND: CONTACT: east of Sharpitor ht, Walkhampton, V	with major localised problems Declining Business Manager 0117 975 0700 West Devon Generally unsatisfactory
DWNER TYPE:	Plant growth Utility Enclosure and stone hut circle 320m north forming part of a stone hut circle settlemer Scheduled Monument (No. 1007434)	TREND: CONTACT: east of Sharpitor nt, Walkhampton, V CONDITION:	with major localised problems Declining Business Manager 0117 975 0700 West Devon Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Plant growth Utility Enclosure and stone hut circle 320m north forming part of a stone hut circle settlemen Scheduled Monument (No. 1007434) Plant growth	TREND: CONTACT: east of Sharpitor nt, Walkhampton, V CONDITION: TREND: CONTACT:	with major localised problems Declining Business Manager 0117 975 0700 West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Plant growth Utility Enclosure and stone hut circle 320m north forming part of a stone hut circle settlemen Scheduled Monument (No. 1007434) Plant growth Utility	TREND: CONTACT: east of Sharpitor nt, Walkhampton, V CONDITION: TREND: CONTACT:	with major localised problems Declining Business Manager 0117 975 0700 West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:	Plant growth         Utility         Enclosure and stone hut circle 320m north         forming part of a stone hut circle settlemer         Scheduled Monument (No. 1007434)         Plant growth         Utility         Enclosure and stone hut circle 700m west of	TREND: CONTACT: east of Sharpitor nt, Walkhampton, V CONDITION: TREND: CONTACT: of Sharpitor, Walkl	with major localised problems Declining Business Manager 0117 975 0700 West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 hampton, West Devon Generally satisfactory
OWNER TYPE:	Plant growth         Utility         Enclosure and stone hut circle 320m north         forming part of a stone hut circle settlemer         Scheduled Monument (No. 1007434)         Plant growth         Utility         Enclosure and stone hut circle 700m west of         Scheduled Monument (No. 1019590)	TREND: CONTACT: east of Sharpitor nt, Walkhampton, V CONDITION: TREND: CONTACT: of Sharpitor, Walk	with major localised problems Declining Business Manager 0117 975 0700 West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 hampton, West Devon Generally satisfactory but with significant localised problems
OWNER TYPE:	Plant growth         Utility         Enclosure and stone hut circle 320m north         forming part of a stone hut circle settlemer         Scheduled Monument (No. 1007434)         Plant growth         Utility         Enclosure and stone hut circle 700m west of         Scheduled Monument (No. 1019590)         Plant growth	TREND: CONTACT: east of Sharpitor nt, Walkhampton, V CONDITION: TREND: CONTACT: TREND: CONDITION:	with major localised problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Plant growth         Utility         Enclosure and stone hut circle 320m north forming part of a stone hut circle settlemer         Scheduled Monument (No. 1007434)         Plant growth         Utility         Enclosure and stone hut circle 700m west of Scheduled Monument (No. 1019590)         Plant growth         Plant growth	TREND: CONTACT: east of Sharpitor nt, Walkhampton, V CONDITION: TREND: CONTACT: TREND: CONDITION:	with major localised problems Declining Business Manager 0117 975 0700 West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 hampton, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Sharpitor summit, Walkhampton, West Dev Generally satisfactory
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: SITE NAME: SITE NAME:	Plant growth         Utility         Enclosure and stone hut circle 320m north         forming part of a stone hut circle settlemer         Scheduled Monument (No. 1007434)         Plant growth         Utility         Enclosure and stone hut circle 700m west of         Scheduled Monument (No. 1019590)         Plant growth         Plant growth         Private         Four stone hut circles and an enclosure 100	TREND: CONTACT: east of Sharpitor nt, Walkhampton, V CONDITION: TREND: CONTACT: Of Sharpitor, Walk CONDITION: TREND: CONTACT:	with major localised problems Declining Business Manager 0117 975 0700 West Devon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Mampton, West Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Sharpitor summit, Walkhampton, West Deven

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Concentration

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Medieval settlement on Peek Hill, 240m and	1 280m north east	t of Lowery Tor, Walkhampton, West De
DESIGNATION:	Scheduled Monument (No. 1020237)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric coaxial field system and cairns, a situated on and around Peek Hill, Walkham		
DESIGNATION:	Scheduled Monument (No. 1020238)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round cairn 340m ESE of Norsworthy Brid	ge, Walkhampton	West Devon
DESIGNATION:	Scheduled Monument (No. 1008651)	CONDITION:	Generally unsatisfactory
	× /		with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round cairn 650m WSW of Raddick Hill su	mmit, Walkhampt	on, West Devon
DESIGNATION:	Scheduled Monument (No. 1007424)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Routrundle Pound, Walkhampton, West De	von	
DESIGNATION:	Scheduled Monument (No. 1002494)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone alignment, two round cairns and a lei lying in a valley between Sharpitor and Lee		
DESIGNATION:	Scheduled Monument (No. 1007433)	CONDITION:	Generally satisfactory
		Contonion.	but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone hut circle 155m east of Sharpitor, Wa	lkhampton, West	Devon
designation:	Scheduled Monument (No. 1007421)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone hut circle 240m south of Down Tor,	Walkhampton, We	st Devon
DESIGNATION:	Scheduled Monument (No. 1008641)	CONDITION:	Generally satisfactory but with significant localised problems
	Plant growth	TREND:	Declining
PRINCIPAL VULNERABILITY:			8

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

ITE NAME:	Stone hut circle 315m north east of Sharpite forming part of a stone hut circle settlement		West Devon
DESIGNATION:	Scheduled Monument (No. 1007436)	CONDITION:	Generally satisfactory
	· · · · · ·		but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone hut circle 350m north east of Sharpito forming part of a stone hut circle settlement		West Devon
DESIGNATION:	Scheduled Monument (No. 1007437)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone hut circle 370m north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton, West Devon		
DESIGNATION:	Scheduled Monument (No. 1007438)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone hut circle settlement 250m east of Cu	ickoo Rock, Wall	khampton, West Devon
DESIGNATION:	Scheduled Monument (No. 1021057)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
	Utility	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Guilty	CONTACT:	Dusiness Flanager 0117 775 0700
SITE NAME:	Stone hut circle settlement, irregular aggrega and post-medieval field system 700m SSW o		
DESIGNATION:	Scheduled Monument (No. 1011170)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Tinworks and other archaeological remains Hart Tor and Cramber Tor, Walkhampton, W		ey at Stanlake, Black Tor,
DESIGNATION:	Scheduled Monument (No. 1020129)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Twelve cairns, a lynchet and a boundary banl 440m south west of Raddick Hill summit, W	01	
	, , ,	01	st Devon Generally satisfactory
DESIGNATION:	<b>440m south west of Raddick Hill summit, W</b> Scheduled Monument (No. 1007425)	alkhampton, Wes	<b>St Devon</b> Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	440m south west of Raddick Hill summit, W	alkhampton, Wes	st Devon Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY:	<b>440m south west of Raddick Hill summit, W</b> Scheduled Monument (No. 1007425) Plant growth	alkhampton, Wes condition: trend:	<b>St Devon</b> Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	<b>440m south west of Raddick Hill summit, W</b> Scheduled Monument (No. 1007425) Plant growth	alkhampton, Wes Condition: Trend: Contact: rt of a cairnfield	<b>St Devon</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	440m south west of Raddick Hill summit, W Scheduled Monument (No. 1007425) Plant growth Utility Two cairns and a boundary bank forming par	alkhampton, Wes Condition: Trend: Contact: rt of a cairnfield	t Devon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 t Devon Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	440m south west of Raddick Hill summit, W Scheduled Monument (No. 1007425) Plant growth Utility Two cairns and a boundary bank forming par 440m south west of Raddick Hill summit, W	alkhampton, Wes condition: trend: contact: rt of a cairnfield alkhampton, Wes	st Devon         Generally satisfactory         but with significant localised problems         Declining         Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / DARTMOOR (NP) / EAST DEVON

SITE NAME:	Two stone hut circles 570m south we	est of Down Tor, Walkha	ampton, West Devon
DESIGNATION:	Scheduled Monument (No. 1019572)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two stone hut circles, a reave, round	cairn and shelter south	east of Sharpitor, Walkhampton, West De
DESIGNATION:	Scheduled Monument (No. 1011167)	CONDITION:	Generally satisfactory
	``````````````````````````````````````		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Business Manager 0117 975 0700
site name:	Unenclosed stone hut circle settleme	nt 370m south west of	Routrundle, Walkhampton, West Devon
DESIGNATION:	Scheduled Monument (No. 1019565)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Enclosure and stone hut circle 770m	south of Cox Tor, White	church, West Devon
		,	
	Enclosure and stone hut circle 770m Scheduled Monument (No. 1020006)	south of Cox Tor, White condition:	Generally satisfactory
DESIGNATION:	Scheduled Monument (No. 1020006)	,	Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:		CONDITION:	Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020006) Plant growth	CONDITION: TREND:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1020006) Plant growth	CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1020006) Plant growth Private	CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1020006) Plant growth Private Horrabridge Conservation Area Medium	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020006) Plant growth Private Horrabridge Conservation Area	CONDITION: TREND: CONTACT: CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY:	Scheduled Monument (No. 1020006) Plant growth Private Horrabridge Conservation Area Medium	CONDITION: TREND: CONTACT: CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Poor Deteriorating
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Scheduled Monument (No. 1020006) Plant growth Private Horrabridge Conservation Area Medium	CONDITION: TREND: CONTACT: CONDITION: TREND: NEW ENTRY? Remains of and failure	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Poor Deteriorating
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Scheduled Monument (No. 1020006) Plant growth Private Horrabridge Conservation Area Medium Keith McKay (LPA) 01626 832093 SITE NAME Dunkeswell Abbey,	CONDITION: TREND: CONTACT: CONDITION: TREND: NEW ENTRY? Remains of and failure	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Poor Deteriorating No

OCCUPANCY: N/A A (New entry) PRIORITY Contact: Nick Russell 0117 975 0671 Trust OWNER TYPE: C16 country house with later additions. Acquired by Poltimore House. SITE NAME: a trust with funding from English Heritage and the Local Planning Authority in 1997. Urgent works carried out in 1998 to make the building wind/weathertight. Emergency roof cover erected 2006. A feasibility study was undertaken with grant from Architectural Heritage Poltimore DESIGNATION: Listed Building Grade II\* Very bad CONDITION Fund and English Heritage. The first phase of repairs Vacant OCCUPANCY: to the roof will commence in 2011. A (A) PRIORITY: Contact: Nicola Lauder 0117 975 0674 OWNER TYPE: Trust



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

. 4	SITE NAME:	Tithe barn and stable block at Bishop's Court, Clyst St Mary, Sowton	Large mid C14 barn with arch-braced base-cruck roof of seven bays, and long early C16 range of stables. Currently unused and with a temporary corrugated roof.The owners are undertaking an English Heritage
A Destruction	DESIGNATION:	Listed Building Grade I	grant-aided feasibility study into potential uses, due to
	CONDITION:	Very bad	be completed summer 2011.
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Sarah Ball 0117 975 0666

SITE NAME:	Hembury Fort, Awliscombe		
DESIGNATION:	Scheduled Monument (No. 1018850)	CONDITION:	Generally unsatisfactory
	х, , , , , , , , , , , , , , , , , , ,		with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Newenham Abbey, Axminster		
DESIGNATION:	Scheduled Monument (No. 1011671)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hawkesdown Camp and associated outwork	, Axmouth	
DESIGNATION:	Scheduled Monument (No. 1017775)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 400m north east of Common I	Farm, Aylesbeare	2
DESIGNATION:	Scheduled Monument (No. 1017770)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 130m south east of St Mary's C	Church, Bicton	
	Scheduled Monument (No. 1018056)	CONDITION	Generally satisfactory
DESIGNATION:	Scheduled Monument (No. 1018056)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	but with significant localised problems Declining
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable clipping Private Bowl barrow 210m north east of Starved Oa	trend: contact: ak Cross, Bramp	but with significant localised problems Declining Business Manager 0117 975 0700 ford Speke
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Arable clipping Private	trend: contact: ak Cross, Bramp	but with significant localised problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Arable clipping Private Bowl barrow 210m north east of Starved Oa Scheduled Monument (No. 1010633)	trend: contact: ak Cross, Bramp	but with significant localised problems Declining Business Manager 0117 975 0700 ford Speke Extensive significant problems
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Arable clipping Private Bowl barrow 210m north east of Starved Oa Scheduled Monument (No. 1010633) Arable ploughing	TREND: CONTACT: ak Cross, Bramp CONDITION: TREND:	but with significant localised problems Declining Business Manager 0117 975 0700 ford Speke Extensive significant problems i.e. under plough, collapse Declining
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Arable clipping Private Bowl barrow 210m north east of Starved Oa Scheduled Monument (No. 1010633)	TREND: CONTACT: ak Cross, Bramp CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 ford Speke Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Arable clipping Private Bowl barrow 210m north east of Starved Oa Scheduled Monument (No. 1010633) Arable ploughing	TREND: CONTACT: ak Cross, Bramp CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 ford Speke Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable clipping Private Bowl barrow 210m north east of Starved Oa Scheduled Monument (No. 1010633) Arable ploughing Private	TREND: CONTACT: ak Cross, Bramp CONDITION: TREND: CONTACT:	but with significant localised problems Declining Business Manager 0117 975 0700 ford Speke Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Arable clipping Private Bowl barrow 210m north east of Starved Oa Scheduled Monument (No. 1010633) Arable ploughing Private Bowl barrow 320m north east of Starved Oa	TREND: CONTACT: ak Cross, Bramp CONDITION: TREND: CONTACT: ak Cross, Bramp	but with significant localised problems Declining Business Manager 0117 975 0700 ford Speke Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 ford Speke
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Arable clipping Private Bowl barrow 210m north east of Starved Oa Scheduled Monument (No. 1010633) Arable ploughing Private Bowl barrow 320m north east of Starved Oa	TREND: CONTACT: ak Cross, Bramp CONDITION: TREND: CONTACT: ak Cross, Bramp	but with significant localised problems Declining Business Manager 0117 975 0700 ford Speke Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 ford Speke Extensive significant problems

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Bowl barrow in Long Plantation, 610m nort	h east of Starved	Oak Cross, Brampford Speke
DESIGNATION:	Scheduled Monument (No. 1010636)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow in Long Plantation, 680m nort	h east of Starved	Oak Cross, Brampford Speke
DESIGNATION:	Scheduled Monument (No. 1010634)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cross ridge dyke extending north and sout	h of The Three H	orse Shoes Inn, Branscombe
DESIGNATION:	Scheduled Monument (No. 1017771)	CONDITION:	Extensive significant problems
	. , , ,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric field system on the cliffs above	Littlecombe Shoo	t, Branscombe
DESIGNATION:	Scheduled Monument (No. 1020710)	CONDITION:	Generally satisfactory
			but with minor localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Dolbury hillfort, 320m north of Killerton H	louse, Broad Clyst	:
DESIGNATION:	Scheduled Monument (No. 1017192)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	
		TREND: CONTACT:	but with significant localised problems
OWNER TYPE:	Forestry	CONTACT:	but with significant localised problems Improving
OWNER TYPE:	Forestry Private Ice house 210m north west of Killerton Ho	CONTACT:	but with significant localised problems Improving Business Manager 0117 975 0700
OWNER TYPE:	Forestry Private	CONTACT:	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory
OWNER TYPE: SITE NAME: DESIGNATION:	Forestry Private Ice house 210m north west of Killerton Ho Scheduled Monument (No. 1017191)	CONTACT:	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Forestry Private Ice house 210m north west of Killerton Ho	CONTACT:	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Forestry Private Ice house 210m north west of Killerton Ho Scheduled Monument (No. 1017191) Collapse	CONTACT: DUSE, Broad Clyst CONDITION: TREND: CONTACT:	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Forestry Private Ice house 210m north west of Killerton Ho Scheduled Monument (No. 1017191) Collapse Private	CONTACT: DUSE, Broad Clyst CONDITION: TREND: CONTACT:	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Forestry Private Ice house 210m north west of Killerton Ho Scheduled Monument (No. 1017191) Collapse Private Sections of two deer park pales and a deer	CONTACT: DUSE, Broad Clyst CONDITION: TREND: CONTACT: park pond at Kill	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 erton Park, Broad Clyst
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Forestry Private Ice house 210m north west of Killerton Ho Scheduled Monument (No. 1017191) Collapse Private Sections of two deer park pales and a deer Scheduled Monument (No. 1017193) Collapse	CONTACT: DUSE, Broad Clyst CONDITION: TREND: CONTACT: park pond at Kill	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 erton Park, Broad Clyst Generally unsatisfactory with major localised problems Declining
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Forestry Private Ice house 210m north west of Killerton Ho Scheduled Monument (No. 1017191) Collapse Private Sections of two deer park pales and a deer Scheduled Monument (No. 1017193)	CONTACT: DUSE, Broad Clyst CONDITION: TREND: CONTACT: park pond at Kill CONDITION:	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 erton Park, Broad Clyst Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Forestry Private Ice house 210m north west of Killerton Ho Scheduled Monument (No. 1017191) Collapse Private Sections of two deer park pales and a deer Scheduled Monument (No. 1017193) Collapse	CONTACT: CONDITION: CONDITION: TREND: CONTACT: Park pond at Kill CONDITION: TREND: CONTACT:	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 erton Park, Broad Clyst Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:	Forestry Private Ice house 210m north west of Killerton Ho Scheduled Monument (No. 1017191) Collapse Private Sections of two deer park pales and a deer Scheduled Monument (No. 1017193) Collapse Private Two bowl barrows at Big Wood, 580m sout	CONTACT: DUSE, Broad Clyst CONDITION: TREND: CONTACT: Park pond at Kill CONDITION: TREND: CONTACT: th west and 470m	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 erton Park, Broad Clyst Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 south of Moorland Cottage, Exmouth
OWNER TYPE:	Forestry Private Ice house 210m north west of Killerton Ho Scheduled Monument (No. 1017191) Collapse Private Sections of two deer park pales and a deer Scheduled Monument (No. 1017193) Collapse Private	CONTACT: CONDITION: CONDITION: TREND: CONTACT: Park pond at Kill CONDITION: TREND: CONTACT:	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 erton Park, Broad Clyst Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 south of Moorland Cottage, Exmouth Generally satisfactory
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Forestry Private Ice house 210m north west of Killerton Ho Scheduled Monument (No. 1017191) Collapse Private Sections of two deer park pales and a deer Scheduled Monument (No. 1017193) Collapse Private Two bowl barrows at Big Wood, 580m sout	CONTACT: DUSE, Broad Clyst CONDITION: TREND: CONTACT: Park pond at Kill CONDITION: TREND: CONTACT: th west and 470m	but with significant localised problems Improving Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 erton Park, Broad Clyst Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 south of Moorland Cottage, Exmouth

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

	Bowl barrow 160m north west of the Farwa forming part of a dispersed barrow group o	,		
DESIGNATION:	Scheduled Monument (No. 1010270)	CONDITION:	Generally satisfactory	
			but with significant localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Bowl barrow 20m north east of the B3174, forming part of a round barrow cemetery c		rway	
DESIGNATION:	Scheduled Monument (No. 1010278)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Bowl barrow 210m north west of the Farway Common Road, forming part of a dispersed barrow group on Farway Hill, Farway			
DESIGNATION:	Scheduled Monument (No. 1010269)	CONDITION:	Unknown	
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Unknown	
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Bowl barrow 30m west of the Farway Com forming part of a round barrow cemetery c		-way	
DESIGNATION:	Scheduled Monument (No. 1010279)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
	Bowl barrow 320m north west of Farway C			
SITE INAME:				
	forming part of a dispersed barrow group o	on Farway Hill, Far	-	
			Extensive significant problems	
designation:	forming part of a dispersed barrow group o Scheduled Monument (No. 1010267)	on Farway Hill, Far condition:	Extensive significant problems i.e. under plough, collapse	
DESIGNATION: PRINCIPAL VULNERABILITY:	forming part of a dispersed barrow group o	on Farway Hill, Far	Extensive significant problems i.e. under plough, collapse Declining	
DESIGNATION: PRINCIPAL VULNERABILITY:	forming part of a dispersed barrow group o Scheduled Monument (No. 1010267) Scrub / tree growth	on Farway Hill, Far condition: trend:	Extensive significant problems i.e. under plough, collapse	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	forming part of a dispersed barrow group o Scheduled Monument (No. 1010267) Scrub / tree growth	n Farway Hill, Far condition: trend: contact: Castle,	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	forming part of a dispersed barrow group of Scheduled Monument (No. 1010267) Scrub / tree growth Private Bowl barrow 340m north west of Farway C	n Farway Hill, Far condition: trend: contact: Castle,	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	forming part of a dispersed barrow group of Scheduled Monument (No. 1010267) Scrub / tree growth Private Bowl barrow 340m north west of Farway C forming part of a dispersed barrow group of	TREND: CONTACT: CONTACT: Castle, on Farway Hill, Far	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	forming part of a dispersed barrow group of Scheduled Monument (No. 1010267) Scrub / tree growth Private Bowl barrow 340m north west of Farway C forming part of a dispersed barrow group of	TREND: CONTACT: CONTACT: Castle, on Farway Hill, Far	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	forming part of a dispersed barrow group of Scheduled Monument (No. 1010267) Scrub / tree growth Private Bowl barrow 340m north west of Farway C forming part of a dispersed barrow group of Scheduled Monument (No. 1010268)	TREND: CONDITION: TREND: CONTACT: Castle, on Farway Hill, Far CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>way</b> Generally unsatisfactory with major localised problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	forming part of a dispersed barrow group of Scheduled Monument (No. 1010267) Scrub / tree growth Private Bowl barrow 340m north west of Farway C forming part of a dispersed barrow group of Scheduled Monument (No. 1010268) Arable ploughing	n Farway Hill, Far CONDITION: TREND: CONTACT: Castle, on Farway Hill, Far CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>rway</b> Generally unsatisfactory with major localised problems Declining	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	forming part of a dispersed barrow group of Scheduled Monument (No. 1010267) Scrub / tree growth Private Bowl barrow 340m north west of Farway C forming part of a dispersed barrow group of Scheduled Monument (No. 1010268) Arable ploughing Private	n Farway Hill, Far CONDITION: TREND: CONTACT: Castle, on Farway Hill, Far CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>rway</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: SITE NAME: DESIGNATION:	forming part of a dispersed barrow group of Scheduled Monument (No. 1010267) Scrub / tree growth Private Bowl barrow 340m north west of Farway C forming part of a dispersed barrow group of Scheduled Monument (No. 1010268) Arable ploughing Private Round barrow cemetery on Broad Down, F Scheduled Monument (No. 1017642)	In Farway Hill, Far CONDITION: TREND: CONTACT: Castle, on Farway Hill, Far CONDITION: TREND: CONDITION: TREND: CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>rway</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY:	forming part of a dispersed barrow group of         Scheduled Monument (No. 1010267)         Scrub / tree growth         Private         Bowl barrow 340m north west of Farway C         forming part of a dispersed barrow group of         Scheduled Monument (No. 1010268)         Arable ploughing         Private         Round barrow cemetery on Broad Down, F         Scheduled Monument (No. 1017642)         Deterioration – in need of management	n Farway Hill, Far CONDITION: TREND: CONTACT: Castle, on Farway Hill, Far CONDITION: TREND: CONDITION: TREND: CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 way Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY:	forming part of a dispersed barrow group of Scheduled Monument (No. 1010267) Scrub / tree growth Private Bowl barrow 340m north west of Farway C forming part of a dispersed barrow group of Scheduled Monument (No. 1010268) Arable ploughing Private Round barrow cemetery on Broad Down, F Scheduled Monument (No. 1017642)	In Farway Hill, Far CONDITION: TREND: CONTACT: Castle, on Farway Hill, Far CONDITION: TREND: CONDITION: TREND: CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>rway</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	forming part of a dispersed barrow group of         Scheduled Monument (No. 1010267)         Scrub / tree growth         Private         Bowl barrow 340m north west of Farway C         forming part of a dispersed barrow group of         Scheduled Monument (No. 1010268)         Arable ploughing         Private         Round barrow cemetery on Broad Down, F         Scheduled Monument (No. 1017642)         Deterioration – in need of management	n Farway Hill, Far CONDITION: TREND: CONTACT: Castle, on Farway Hill, Far CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: Mire,	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>rway</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION:	forming part of a dispersed barrow group of Scheduled Monument (No. 1010267) Scrub / tree growth Private Bowl barrow 340m north west of Farway C forming part of a dispersed barrow group of Scheduled Monument (No. 1010268) Arable ploughing Private Round barrow cemetery on Broad Down, F Scheduled Monument (No. 1017642) Deterioration – in need of management Private A bowl barrow 370m WNW of Ring-in-the-	n Farway Hill, Far CONDITION: TREND: CONTACT: Castle, on Farway Hill, Far CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: Mire,	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 way Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Gittisham Generally unsatisfactory	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: OWNER TYPE:	forming part of a dispersed barrow group of Scheduled Monument (No. 1010267) Scrub / tree growth Private Bowl barrow 340m north west of Farway C forming part of a dispersed barrow group of Scheduled Monument (No. 1010268) Arable ploughing Private Round barrow cemetery on Broad Down, F Scheduled Monument (No. 1017642) Deterioration – in need of management Private A bowl barrow 370m WNW of Ring-in-the- forming part of a round barrow cemetery of	In Farway Hill, Far CONDITION: TREND: CONTACT: Castle, IN Farway Hill, Far CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDI	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 way Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Gittisham	

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

	A bowl barrow 420m NNW of Ring-in-the-I forming part of a round barrow cemetery o		Gittisham	
DESIGNATION:	Scheduled Monument (No. 1014247)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	A bowl barrow 460m NNW of Ring-in-the-I forming part of a round barrow cemetery o	,	Gittisham	
DESIGNATION:	Scheduled Monument (No. 1014248)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	A bowl barrow 500m WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham			
DESIGNATION:	Scheduled Monument (No. 1014250)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
DITE NAME:	A bowl barrow 570m NNE of Putts Corner, forming part of a round barrow cemetery on Gittisham Hill, Gittisham			
DESIGNATION:	Scheduled Monument (No. 1014254)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	A cairn 450m WNW of Putts Corner, forming part of a round barrow cemetery o	n Gittisham Hill,	Gittisham	
DESIGNATION:	forming part of a round barrow cemetery o Scheduled Monument (No. 1014255)	CONDITION:	Gittisham Generally unsatisfactory with major localised problems	
DESIGNATION: RINCIPAL VULNERABILITY:	forming part of a round barrow cemetery o Scheduled Monument (No. 1014255) Scrub / tree growth	CONDITION: TREND:	Gittisham Generally unsatisfactory with major localised problems Declining	
DESIGNATION: RINCIPAL VULNERABILITY:	forming part of a round barrow cemetery o Scheduled Monument (No. 1014255)	CONDITION:	Gittisham Generally unsatisfactory with major localised problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	forming part of a round barrow cemetery of Scheduled Monument (No. 1014255) Scrub / tree growth Private A ring cairn and bowl barrow 540m NNE of forming part of a round barrow cemetery of	CONDITION: TREND: CONTACT: f Putts Corner,	Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	forming part of a round barrow cemetery o Scheduled Monument (No. 1014255) Scrub / tree growth Private A ring cairn and bowl barrow 540m NNE o	CONDITION: TREND: CONTACT: f Putts Corner,	Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700	
DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE: SITE NAME: DESIGNATION:	forming part of a round barrow cemetery of Scheduled Monument (No. 1014255) Scrub / tree growth Private A ring cairn and bowl barrow 540m NNE of forming part of a round barrow cemetery of	CONDITION: TREND: CONTACT: f Putts Corner, n Gittisham Hill,	Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Gittisham Generally satisfactory but with significant localised problems Declining	
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	forming part of a round barrow cemetery o Scheduled Monument (No. 1014255) Scrub / tree growth Private A ring cairn and bowl barrow 540m NNE o forming part of a round barrow cemetery o Scheduled Monument (No. 1014253)	CONDITION: TREND: CONTACT: f Putts Corner, n Gittisham Hill, CONDITION:	Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Gittisham Generally satisfactory but with significant localised problems	
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE:	forming part of a round barrow cemetery of Scheduled Monument (No. 1014255) Scrub / tree growth Private A ring cairn and bowl barrow 540m NNE of forming part of a round barrow cemetery of Scheduled Monument (No. 1014253) Scrub / tree growth	CONDITION: TREND: CONTACT: f Putts Corner, n Gittisham Hill, CONDITION: TREND: CONTACT: east of Putts Cor	Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Gittisham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700	
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DISTE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DISTE NAME: DISTE NAME:	forming part of a round barrow cemetery of Scheduled Monument (No. 1014255) Scrub / tree growth Private A ring cairn and bowl barrow 540m NNE of forming part of a round barrow cemetery of Scheduled Monument (No. 1014253) Scrub / tree growth Private An enclosure and two bowl barrows 180m et	CONDITION: TREND: CONTACT: f Putts Corner, n Gittisham Hill, CONDITION: TREND: CONTACT: east of Putts Cor	Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Gittisham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700	
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: ITE NAME: DESIGNATION: DWNER TYPE: ITE NAME: DESIGNATION:	forming part of a round barrow cemetery of Scheduled Monument (No. 1014255) Scrub / tree growth Private A ring cairn and bowl barrow 540m NNE of forming part of a round barrow cemetery of Scheduled Monument (No. 1014253) Scrub / tree growth Private An enclosure and two bowl barrows 180m e forming part of a round barrow cemetery of	CONDITION: TREND: CONTACT: f Putts Corner, n Gittisham Hill, CONDITION: TREND: CONTACT: east of Putts Corn n Gittisham Hill,	Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Gittisham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 ner, Gittisham Generally unsatisfactory	
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: DESIGNATION: RINCIPAL VULNERABILITY:	forming part of a round barrow cemetery of Scheduled Monument (No. 1014255) Scrub / tree growth Private A ring cairn and bowl barrow 540m NNE of forming part of a round barrow cemetery of Scheduled Monument (No. 1014253) Scrub / tree growth Private An enclosure and two bowl barrows 180m of forming part of a round barrow cemetery of Scheduled Monument (No. 1014252)	CONDITION: TREND: CONTACT: f Putts Corner, n Gittisham Hill, CONDITION: TREND: CONTACT: east of Putts Cor n Gittisham Hill, CONDITION:	Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Gittisham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 ner, Gittisham Generally unsatisfactory with major localised problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	forming part of a round barrow cemetery of Scheduled Monument (No. 1014255) Scrub / tree growth Private A ring cairn and bowl barrow 540m NNE of forming part of a round barrow cemetery of Scheduled Monument (No. 1014253) Scrub / tree growth Private An enclosure and two bowl barrows 180m of forming part of a round barrow cemetery of Scheduled Monument (No. 1014252) Plant growth	CONDITION: TREND: CONTACT: f Putts Corner, n Gittisham Hill, CONDITION: TREND: CONTACT: east of Putts Cor n Gittisham Hill, CONDITION: TREND: CONDITION:	Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Gittisham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 ner, Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	forming part of a round barrow cemetery o Scheduled Monument (No. 1014255) Scrub / tree growth Private A ring cairn and bowl barrow 540m NNE or forming part of a round barrow cemetery o Scheduled Monument (No. 1014253) Scrub / tree growth Private An enclosure and two bowl barrows 180m e forming part of a round barrow cemetery o Scheduled Monument (No. 1014252) Plant growth Private Two bowl barrows, 220m ESE of Putts Corm	CONDITION: TREND: CONTACT: f Putts Corner, n Gittisham Hill, CONDITION: TREND: CONTACT: east of Putts Cor n Gittisham Hill, CONDITION: TREND: CONDITION:	Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Gittisham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 ner, Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Gittisham	
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DUNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TY	forming part of a round barrow cemetery of         Scheduled Monument (No. 1014255)         Scrub / tree growth         Private         A ring cairn and bowl barrow 540m NNE of         forming part of a round barrow cemetery of         Scheduled Monument (No. 1014253)         Scrub / tree growth         Private         An enclosure and two bowl barrows 180m efforming part of a round barrow cemetery of         Scheduled Monument (No. 1014253)         Scheduled Monument (No. 1014252)         Plant growth         Private         Two bowl barrows, 220m ESE of Putts Corm         forming part of a round barrow cemetery of	CONDITION: TREND: CONTACT: f Putts Corner, n Gittisham Hill, CONDITION: TREND: CONTACT: east of Putts Corn n Gittisham Hill, CONDITION: TREND: CONDITION:	Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Gittisham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 ner, Gittisham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Gittisham	

### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ITE NAME:	Two ring cairns 410m south east of Higher forming part of a round barrow cemetery of		pniton		
DESIGNATION:	Scheduled Monument (No. 1014245)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining		
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700		
ITE NAME:	Dumpdon Camp, Luppitt				
DESIGNATION:	Scheduled Monument (No. 1018851)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
ITE NAME:	Three bowl barrows on Lympstone Common, 500m west of Fryingpans, Lympstone				
DESIGNATION:	Scheduled Monument (No. 1020014)	CONDITION:	Generally satisfactory		
			but with minor localised problems		
RINCIPAL VULNERABILITY:	Localised/limited animal burrowing	TREND:	Declining		
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
DITE NAME:	Membury Castle, Membury				
DESIGNATION:	Scheduled Monument (No. 1017951)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Musbury Castle, Musbury				
DESIGNATION:	Scheduled Monument (No. 1016793)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
ITE NAME:	Cursus, long mortuary enclosure, ring ditch 700m east of Netherexe Barton, Nether Ex		ated cropmarks		
DESIGNATION:	Scheduled Monument (No. 1014144)	CONDITION:	Extensive significant problems		
Designation.		CONDITION.	i.e. under plough, collapse		
	Arable ploughing	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Private	TREND: CONTACT:	Business Manager 0117 975 0700		
2441NEIN FIFE:	/ Trade	CONTACT:			
ITE NAME:	Two bowl barrows north of Green Lane, 43	30m and 330m we	est of Rewe Cross, Nether Exe		
DESIGNATION:	Scheduled Monument (No. 1016565)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Round barrow cemetery on Venn Ottery H 660m south east of Happy Valley, Newton P		rpford		
	Scheduled Monument (No. 1017476)		Extensive significant problems		
		CONDITION:	Extensive significant problems		
DESIGNATION:			i e under plough collapso		
		TOPNIC	i.e. under plough, collapse		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Plant growth Private	TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700		

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	High Peak camp, Sidmouth, Otterton		
DESIGNATION:	Scheduled Monument (No. 1003887)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Belbury Castle, Ottery St Mary		
DESIGNATION:	Scheduled Monument (No. 1017774)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow in Lee's Plantation, East Hill, 56	0m east of Highe	er Rill Farm, Ottery St Mary
DESIGNATION:	Scheduled Monument (No. 1017773)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Promontory fort on Seaton Down, Seaton		
DESIGNATION:	Scheduled Monument (No. 1017776)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			Ŭ
SITE NAME:	The Beacon on Shute Hill, 200m north east	of Rowlands, Shu	te
DESIGNATION:	Scheduled Monument (No. 1020312)	CONDITION:	Generally satisfactory
	Deterioretion in read of more constant		but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management Private	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	A bowl barrow I20m south west of Ring-in- forming part of a round barrow cemetery o		Sidmouth
DESIGNATION:	Scheduled Monument (No. 1014246)		
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two bowl barrows to the north west of Ron forming part of a dispersed barrow group of		
	Scheduled Monument (No. 1010271)	-	
DESIGNATION:	Scheduled Fionament (NO. 1010271)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stockland Great Castle, Stockland		
DESIGNATION:	Scheduled Monument (No. 1017952)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
ININGIAL VOLINERADILITT:		I NEIND:	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Bowl barrow 470m east of Fortescue, Stok	e Canon	
DESIGNATION:	Scheduled Monument (No. 1016564)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Roman villa 300yds (270m) SSW of Holcom	ıbe Farm, Uplyme	
DESIGNATION:	Scheduled Monument (No. 1002558)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Trinity Beacon, Uplyme		
DESIGNATION:	Scheduled Monument (No. 1017950)	CONDITION:	Generally satisfactory
	× , , , , , , , , , , , , , , , , , , ,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 280m NNE of Starved Oak C	Cross, Upton Pyne	
DESIGNATION:	Scheduled Monument (No. 1010638)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 300m SSE of Stevenstone Far	m, Upton Pyne	
DESIGNATION:	Scheduled Monument (No. 1015973)	CONDITION:	Extensive significant problems
	· · · · · · · · · · · · · · · · · · ·		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 350m NNE of Starved Oak C	Cross, Upton Pyne	
designation:	Scheduled Monument (No. 1010639)	CONDITION:	Extensive significant problems
		CONDITION.	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 450m SSE of Stevenstone Far	m, Upton Pyne	
DESIGNATION:	Scheduled Monument (No. 1015974)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		west of Three Ho	orse Shoes Inn, Upton Pyne
SITE NAME:	Earthwork enclosure 330yds (300m) south		
			Extensive significant problems
	Earthwork enclosure 330yds (300m) south Scheduled Monument (No. 1002645)	CONDITION:	Extensive significant problems
DESIGNATION:	Scheduled Monument (No. 1002645)	CONDITION:	i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:			

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS ATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

	Two bowl barrows, 350m south of Stevenston	e Farm, Upton	Pyne
DESIGNATION:	Scheduled Monument (No. 1010631)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 310m south of Widworthy Barte	on, Widworthy	
DESIGNATION:	Scheduled Monument (No. 1017475)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
JITE NAME:	Castle Hill, Widworthy		
DESIGNATION:	Scheduled Monument (No. 1017477)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			, , , , , , , , , , , , , , , , , , ,
SITE NAME:	Two bowl barrows on Colaton Raleigh Comm 500m north and 780m north east of Woodbu		dbury
DESIGNATION:	Scheduled Monument (No. 1018053)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two bowl barrows on Woodbury Common, b	oth 330m east	of Four Firs, Woodbury
DESIGNATION:	Scheduled Monument (No. 1018050)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
EXETER			
EXELER			
	Danes Castle, Exeter		
ITE NAME:	Danes Castle, Exeter Scheduled Monument (No. 1011673)	CONDITION:	Unknown
DESIGNATION:	,	CONDITION: TREND:	Unknown Unknown
DITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1011673)		
DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE:	Scheduled Monument (No. 1011673) Scrub / tree growth	TREND:	Unknown
SITE NAME:	Scheduled Monument (No. 1011673) Scrub / tree growth Utility	TREND:	Unknown
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1011673) Scrub / tree growth Utility Alphin Brook, Exeter	TREND: CONTACT:	Unknown Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY:	Scheduled Monument (No. 1011673) Scrub / tree growth Utility Alphin Brook, Exeter Conservation Area	TREND: CONTACT: CONDITION:	Unknown Business Manager 0117 975 0700 Optimal
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Scheduled Monument (No. 1011673) Scrub / tree growth Utility Alphin Brook, Exeter Conservation Area Low	TREND: CONTACT: CONDITION: TREND:	Unknown Business Manager 0117 975 0700 Optimal Deteriorating significantly
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: VULNERABILITY: CONTACT: ITE NAME:	Scheduled Monument (No. 1011673)         Scrub / tree growth         Utility         Alphin Brook, Exeter         Conservation Area         Low         Ms Katharine Metcalfe (LPA) 01392 265227	TREND: CONTACT: CONDITION: TREND:	Unknown Business Manager 0117 975 0700 Optimal Deteriorating significantly No
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1011673) Scrub / tree growth Utility Alphin Brook, Exeter Conservation Area Low Ms Katharine Metcalfe (LPA) 01392 265227 St David's, Exeter	TREND: CONTACT: CONDITION: TREND: NEW ENTRY?:	Unknown Business Manager 0117 975 0700 Optimal Deteriorating significantly
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: SITE NAME: DESIGNATION: VULNERABILITY:	Scheduled Monument (No. 1011673) Scrub / tree growth Utility Alphin Brook, Exeter Conservation Area Low Ms Katharine Metcalfe (LPA) 01392 265227 St David's, Exeter Conservation Area	TREND: CONTACT: CONDITION: TREND: NEW ENTRY?: CONDITION:	Unknown Business Manager 0117 975 0700 Optimal Deteriorating significantly No
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: CONTACT:	Scheduled Monument (No. 1011673) Scrub / tree growth Utility Alphin Brook, Exeter Conservation Area Low Ms Katharine Metcalfe (LPA) 01392 265227 St David's, Exeter Conservation Area Low	TREND: CONTACT: CONDITION: TREND: NEW ENTRY?: CONDITION: TREND:	Unknown Business Manager 0117 975 0700 Optimal Deteriorating significantly No Very bad Deteriorating
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: SITE NAME:	Scheduled Monument (No. 1011673)         Scrub / tree growth         Utility         Alphin Brook, Exeter         Conservation Area         Low         Ms Katharine Metcalfe (LPA) 01392 265227         St David's, Exeter         Conservation Area         Low         Ms Katharine Metcalfe (LPA) 01392 265227	TREND: CONTACT: CONDITION: TREND: NEW ENTRY?: CONDITION: TREND:	Unknown Business Manager 0117 975 0700 Optimal Deteriorating significantly No Very bad Deteriorating No
EXELLER SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: SITE NAME: DESIGNATION: VULNERABILITY:	Scheduled Monument (No. 1011673) Scrub / tree growth Utility Alphin Brook, Exeter Conservation Area Low Ms Katharine Metcalfe (LPA) 01392 265227 St David's, Exeter Conservation Area Low Ms Katharine Metcalfe (LPA) 01392 265227 St Sidwells, Exeter	TREND: CONTACT: CONDITION: TREND: NEW ENTRY? CONDITION: TREND: NEW ENTRY?	Unknown Business Manager 0117 975 0700 Optimal Deteriorating significantly No Very bad Deteriorating

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Doone's Houses, Brendon, North Devon		
DESIGNATION:	Scheduled Monument (No. 1003886)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			5
SITE NAME:	Two round barrows on Cheriton Ridge, Bre	endon, North Dev	<i>i</i> on
DESIGNATION:	Scheduled Monument (No. 1002583)	d Monument (No. 1002583) соматтом: Extensive signif i.e. under ploug	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Five barrows and an enclosure on Challaco	mbe Common, C	hallacombe, North Devon
DESIGNATION:	Scheduled Monument (No. 1002634)	CONDITION:	Extensive significant problems
	· · · /		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow on East Anstey Common, Ea	ast Anstey, North	Devon
DESIGNATION:	Scheduled Monument (No. 1002569)	CONDITION:	Extensive significant problems
	·····,		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Earthwork defences of Countisbury Castle	promontory fort	, Lynton and Lynmouth, North Devon
	÷	· ·	
SITE NAME: DESIGNATION:	Earthwork defences of Countisbury Castle Scheduled Monument (No. 1020807)		Generally satisfactory
	Scheduled Monument (No. 1020807)	· ·	Generally satisfactory
DESIGNATION:	÷	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020807) Plant growth	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No. 1020807) Plant growth Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No. 1020807) Plant growth Private Roborough Castle, Lynton and Lynmouth, N Scheduled Monument (No. 1003281)	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION:	Scheduled Monument (No. 1020807) Plant growth Private Roborough Castle, Lynton and Lynmouth, N	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: DOWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020807) Plant growth Private Roborough Castle, Lynton and Lynmouth, N Scheduled Monument (No. 1003281)	CONDITION: TREND: CONTACT: North Devon CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No. 1020807) Plant growth Private Roborough Castle, Lynton and Lynmouth, N Scheduled Monument (No. 1003281) Localised/limited natural erosion	CONDITION: TREND: CONTACT: North Devon CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE:	Scheduled Monument (No. 1020807)         Plant growth         Private         Roborough Castle, Lynton and Lynmouth, N         Scheduled Monument (No. 1003281)         Localised/limited natural erosion         Private	CONDITION: TREND: CONTACT: North Devon CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: DESIGNATION: DESIGNATION:	Scheduled Monument (No. 1020807)         Plant growth         Private         Roborough Castle, Lynton and Lynmouth, N         Scheduled Monument (No. 1003281)         Localised/limited natural erosion         Private         Round barrow south east of Down Linhay,	CONDITION: TREND: CONTACT: Vorth Devon CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DW	Scheduled Monument (No. 1020807)         Plant growth         Private         Roborough Castle, Lynton and Lynmouth, N         Scheduled Monument (No. 1003281)         Localised/limited natural erosion         Private         Round barrow south east of Down Linhay,         Scheduled Monument (No. 1002545)	CONDITION: TREND: CONTACT: North Devon CONDITION: TREND: CONTACT: Lynton and Lynmo	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>Duth, North Devon</b> Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DISTE NAME:	Scheduled Monument (No. 1020807)         Plant growth         Private         Roborough Castle, Lynton and Lynmouth, N         Scheduled Monument (No. 1003281)         Localised/limited natural erosion         Private         Round barrow south east of Down Linhay,         Scheduled Monument (No. 1002545)         Other	CONDITION: TREND: CONTACT: North Devon CONDITION: TREND: CONTACT: Lynton and Lynmo CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Douth, North Devon Extensive significant problems i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DISTE NAME:	Scheduled Monument (No. 1020807)         Plant growth         Private         Roborough Castle, Lynton and Lynmouth, N         Scheduled Monument (No. 1003281)         Localised/limited natural erosion         Private         Round barrow south east of Down Linhay,         Scheduled Monument (No. 1002545)         Other         Private         Two round barrows and cairn cemetery, Ikk	CONDITION: TREND: CONTACT: North Devon CONDITION: TREND: CONTACT: Lynton and Lynmo CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive Significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DOWNER TYPE: DWNER TYPE:	Scheduled Monument (No. 1020807)         Plant growth         Private         Roborough Castle, Lynton and Lynmouth, N         Scheduled Monument (No. 1003281)         Localised/limited natural erosion         Private         Round barrow south east of Down Linhay,         Scheduled Monument (No. 1002545)         Other         Private	CONDITION: TREND: CONTACT: North Devon CONDITION: TREND: CONTACT: Lynton and Lynmo CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>Duth, North Devon</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE	Scheduled Monument (No. 1020807)         Plant growth         Private         Roborough Castle, Lynton and Lynmouth, N         Scheduled Monument (No. 1003281)         Localised/limited natural erosion         Private         Round barrow south east of Down Linhay,         Scheduled Monument (No. 1002545)         Other         Private         Two round barrows and cairn cemetery, Ikk	CONDITION: TREND: CONTACT: North Devon CONDITION: TREND: CONTACT: Lynton and Lynmo CONDITION: TREND: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

#### HERITAGE AT RISK 2011 / SOUTH WEST / EXMOOR (NP) / MID DEVON

SITE NAME:	Two round barrows near Warcombe Water	, Lynton and Lynn	nouth, North Devon
DESIGNATION:	Scheduled Monument (No. 1003299)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Beacon Castle, South Down, Martinhoe, No	orth Devon	
DESIGNATION:	Scheduled Monument (No. 1002540)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Voley Castle, Parracombe, North Devon		
DESIGNATION:	Scheduled Monument (No. 1003885)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Trentishoe barrows, round cairns, Trentisho	e, North Devon	
DESIGNATION:	Scheduled Monument (No. 1002556)	CONDITION:	Generally satisfactory
	· · · · · · · · · · · · · · · · · · ·		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two round barrows on West Anstey Comm	non, West Anstey,	North Devon
DESIGNATION:	Scheduled Monument (No. 1002570)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700

MID DEVON



SITE NAME:	The Walronds, 6 Fore Street, Cullompton	A large early C17 mansion in the centre of Cullompton. The owner, Cullompton Walronds Preservation Trust, has obtained Stage I Heritage Lottery Fund funding and grant aid for project development has been provided by English
DESIGNATION:	Listed Building Grade I, CA	Heritage and the Local Authority. Emergency repairs have
CONDITION:	Poor	been undertaken. Heritage Lottery Fund and English Heritage grant-aided project development ongoing
OCCUPANCY:	Vacant	with repairs due to start 2012.
PRIORITY:	F (B)	
OWNER TYPE:	Trust	Contact: Nicola Lauder 0117 975 0674
SITE NAME:	Prescott Baptist Chapel, Culmstock	This simple, unspoilt C18 church is in an isolated rural location with two other Baptist Churches within a five mile radius and



PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the solution of the solution

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs

Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site UA WHS

SITE NAME:	Roman fort 300m NE of Cudmore Farm, B	ampton	
DESIGNATION:	Scheduled Monument (No. 1011251)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 140m south east of Burston (	Cross, Bow	
DESIGNATION:	Scheduled Monument (No. 1015471)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 220m south west of Hampso	n Cottage, Bow	
DESIGNATION:	Scheduled Monument (No. 1015474)	CONDITION:	Extensive significant problems
	Analala - Laurahia -		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 80m south west of Hampson	Cottage, Bow	
DESIGNATION:	Scheduled Monument (No. 1016189)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Ring ditch I50m north of Natson Farm, Bo	w	
DESIGNATION:	Scheduled Monument (No. 1015477)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two bowl barrows 180m south west of Ha	mpson Cottage, Be	ow
DESIGNATION:	Scheduled Monument (No. 1015475)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two bowl barrows 250m north of Natson	Farm, Bow	
DESIGNATION:	Scheduled Monument (No. 1015476)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Canonsleigh Abbey, Burlescombe		
DESIGNATION:	Scheduled Monument (No. 1003830)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:			
OWNER TYPE:			
SITE NAME:	Copplestone Cross, Crediton Hamlets		
SITE NAME:	Copplestone Cross, Crediton Hamlets Scheduled Monument (No. 1013728)	CONDITION:	Generally satisfactory but with significant localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:		CONDITION: TREND:	, ,

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Posbury camp, Castle Down, Crediton Hamlet	ts	
DESIGNATION:	Scheduled Monument (No. 1003826)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	Romano British villa Downes poor Craditon	Craditon Haml	
	Romano-British villa, Downes, near Crediton, 4 Scheduled Monument (No. 1002668)		
DESIGNATION:	Scheduled Hohument (NO. 1002000)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two Roman forts and two Roman camps at St	t Andrew's Hill,	Cullompton
DESIGNATION:	Scheduled Monument (No. 1019543)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Raddon Hill: a Neolithic causewayed enclosure	e and later hillfo	ort, Shobrooke
DESIGNATION:	Scheduled Monument (No. 1016259)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Three bowl barrows 250m south east of Gibb	et Moor Cross	, Templeton
DESIGNATION:	Scheduled Monument (No. 1017134)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
site name:	Bowl barrow 260m north west of Putson Cro	oss, Tiverton	
DESIGNATION:	Scheduled Monument (No. 1017132)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Eggesford Castle, 640m north east of Eggesfor	d House Wem	hworthy
	Scheduled Monument (No. 1016208)		Extensive significant problems
DESIGNATION:	Scheduled Fiohament (140, 1016206)	CONDITION:	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow I30m north east of Burston Cro	oss, Zeal Monacl	horum
DESIGNATION:	Scheduled Monument (No. 1015152)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	Thate	convict.	
DITE NAME:	Bickleigh, Tiverton		
DESIGNATION:	Conservation Area	CONDITION:	Poor
/ULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Sue Warren (LPA) 01884 234264	NEW ENTRY?:	No
RIORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; no solution agreed.	<ul> <li>D Slow decay; solution agreed but not yet implemented.</li> <li>F Repair scheme in pr and (where applicab end use or user ider functionally redundar with no obvious new user (applicable only to buildings capable of beneficial use).</li> </ul>	le) If the ntified; has ch nt buildings registe	E ABBREVIATIONS priority category LB/LBs Listed Building/s anged since the 2010 LPA Local Planning Author pri he previous category n in brackets. MP National Park RPG Registered Park and SM/SMs Scheduled Monumen UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2011 / SOUTH WEST / MID DEVON / NORTH DEVON

SITE NAME:	Bow		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Sue Warren (LPA) 01884 234264	NEW ENTRY?:	Yes
SITE NAME:	Bradninch, Cullompton		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Sue Warren (LPA) 01884 234264	NEW ENTRY?:	No
SITE NAME:	Cullompton		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Sue Warren (LPA) 01884 234264	NEW ENTRY?:	No
SITE NAME:	Sandford, Crediton		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Sue Warren (LPA) 01884 234264	NEW ENTRY?:	Yes
SITE NAME:	Tiverton		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Sue Warren (LPA) 01884 234264	NEW ENTRY?:	No
NORTH DEVON			

#### Hall House, Built circa 1846-50 by Philip Hardwick, with a rear range SITE NAME: by RD Gould. The house lies within an estate containing **Bishops Tawton** several other listed structures within the vicinity. The main range is generally fair, but the rear range is in very poor DESIGNATION: Listed Building Grade II\* condition, though roof is now weathertight. CONDITION: Poor OCCUPANCY: Vacant C (C) PRIORITY: Contact: Francis Kelly 0117 975 0725 OWNER TYPE: Trust Broomham Farmhouse, Early CI6 Longhouse with later additions. The roof SITE NAME: has been re-thatched with English Heritage grant aid. Kings Nympton Further structural work still required. DESIGNATION: Listed Building Grade II\* Poor CONDITION: Vacant OCCUPANCY: PRIORITY: C (C) Contact: Francis Kelly 0117 975 0725 OWNER TYPE: Private Church of St Thomas, CI5 / CI6 church with major CI9 interventions. SITE NAME: Kentisbury, Delabole slates to north nave, north aisle, chancel / vestry and south porch have joining fixings and all need to be reroofed. A Repair Grant for Places of North Devon Worship has been offered for repairs.

Contact: Francis Kelly 0117 975 0725

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

CONDITION:

PRIORITY:

 E Under renair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Very bad

OWNER TYPE: Religious organisation

B (New entry)

DESIGNATION: Listed Place of Worship Grade II\*

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets. 
 ABBREVIATIONS

 CA
 Conservation Area

 LB/LBs
 Listed Building's

 LPA
 Local Planning Authority

 NP
 National Park

 RPG
 Registered Park and Garden

 SM/SMS
 Scheduled Monument/s

 UA
 Unitary Authority

 WHS
 World Heritage Site

	SITE NAME:	Christ Church, Parracombe, North Devon	but areas o beginning t The tower	It 1878 by W Oliver. Roofs are well maintained of weakness are developing and the roof is o need some major work to address these. is also in need of repair, particularly the south aces which are exposed to prevailing weather,
	DESIGNATION:	Listed Place of Worship Grade II, CA	strong wind	ds and high rainfall. A Repair Grant for Places of
~ ~	CONDITION:	Poor		as been offered for roof repairs to north aisle,
	PRIORITY:	B (New entry)	vestry and	nave, as well as emergency works to tower.
	OWNER TYPE:	Religious organisation	Contact: Sa	rah Ball 0117 975 0666
SITE NAME:		barrows 170m west and 200m south v art of a round barrow cemetery on Be		
DESIGNATION:	Scheduled	Monument (No. 1019261)	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round bar	row cemetery 210m south west of Hi	llcrest, Cent	ery Lane, Bittadon
DESIGNATION:	Scheduled	Monument (No. 1019252)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
site name:	Three bov	vl barrows 170m and 270m east of Frie	endship Farm	n, Bratton Fleming
DESIGNATION:	Scheduled	Monument (No. 1017130)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Plant grow	th	TREND:	Unknown
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
site name:		ow 280m north east of Beacon Moor art of a round barrow cemetery, Chuln	,	
DESIGNATION:	÷.	Monument (No. 1015153)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barro	ow 330m east of Beacon Moor Cross,	forming part	t of a round barrow cemetery, Chulmleigh
DESIGNATION:	Scheduled	Monument (No. 1015154)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	i.e. under plough, collapse Declining
OWNER TYPE:	Private	ugning	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Camp in E	ast Kidland Wood, Knowstone		
DESIGNATION:	Scheduled	Monument (No. 1004588)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Plant grow	,	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Four bowl	barrows 560m south east of New Mc	oor Cross, Ki	nowstone
DESIGNATION:	Scheduled	Monument (No. 1017135)	CONDITION:	Generally unsatisfactory
				with major localised problems
PRINCIPAL VULNERABILITY:	Arable plo Private	ughing	TREND:	Declining
			CONTACT:	Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

SITE NAME:	Castle Roborough, Loxhore				
DESIGNATION:	Scheduled Monument (No. 1002543)	CONDITION:	Extensive significant problems		
			i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Bowl barrow 320m east of New Moor Cross, Molland				
DESIGNATION:	Scheduled Monument (No. 1017136)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Hillfort 400m north west of Woodhouse, C	Queen's Nympton			
DESIGNATION:	Scheduled Monument (No. 1015463)	CONDITION:	Extensive significant problems		
	Arable ploughing	TOPIC	i.e. under plough, collapse Declining		
PRINCIPAL VULNERABILITY:	Private	TREND: CONTACT:	Business Manager 0117 975 0700		
		CONIACI.			
SITE NAME:	Two bowl barrows 100m east of Catkill Cro	oss, Rose Ash			
DESIGNATION:	Scheduled Monument (No. 1015145)	CONDITION:	Generally satisfactory		
	Moderate animal burrowing	TREND	but with significant localised problems Declining		
PRINCIPAL VULNERABILITY:	Private	TREND: CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Camp south of Birch Ham Wood, Stoke Riv	rers			
DESIGNATION:	Scheduled Monument (No. 1002533)	CONDITION:	Generally satisfactory but with minor localised problems		
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Bowl barrow 300m north west of Witherid	lge Moor Cross (v	west), Witheridge		
	<b>Bowl barrow 300m north west of Witherid</b> Scheduled Monument (No. 1016652)	lge Moor Cross (v	Extensive significant problems		
DESIGNATION:					
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1016652)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1016652) Plant growth	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1016652) Plant growth Private	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1016652) Plant growth Private Bowl barrow 610m south east of Elworthy Scheduled Monument (No. 1016651)	CONDITION: TREND: CONTACT: Cross, Witheridge CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1016652) Plant growth Private Bowl barrow 610m south east of Elworthy	CONDITION: TREND: CONTACT: Cross, Witheridge	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1016652) Plant growth Private Bowl barrow 610m south east of Elworthy Scheduled Monument (No. 1016651) Plant growth	CONDITION: TREND: CONTACT: Cross, Witheridge CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1016652) Plant growth Private Bowl barrow 610m south east of Elworthy Scheduled Monument (No. 1016651) Plant growth Private	CONDITION: TREND: CONTACT: Cross, Witheridge CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1016652) Plant growth Private Bowl barrow 610m south east of Elworthy Scheduled Monument (No. 1016651) Plant growth Private Ilfracombe	CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700		

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SOUTH HAMS				
-	SITE NAME:	Deer Park wall at	Mediaeval deer park wall, extended in the C16.	
	SITE INAME:	Berry Pomeroy Castle,	Neglected, heavily overgrown with ivy and partially	
		Berry Pomeroy	collapsed in places, particularly in the woods where	
the stand		Listed Building Grade II*	it has no use as a boundary. English Heritage working with the Estate to prepare a condition survey in order	
	CONDITION:	Poor	to understand and monitor mechanisms of decay	
	OCCUPANCY:		and to prioritise repairs.	
17698	PRIORITY:	C (New entry)		
	OWNER TYPE:		Contact: Francis Kelly 0117 975 0725	
	SITE NAME:	Warleigh House,	Medieval site. The present CI6 house incorporates late	
	JILLINALIE.	Tamerton Foliot,	medieval roof structures and was remodelled in the mid	
VITI		Bickleigh	CI8 and again, importantly, by John Foulston of Plymou	
	DESIGNATION:	Listed Building Grade II*	from 1825-31. For sale May 2011. Urgent Works Notice outstanding and conditional listed building consent agreed	
	CONDITION:	Poor	for reinstatement of significant features.	
	OCCUPANCY:	Vacant		
	PRIORITY:	B (B)		
	OWNER TYPE:	Company	Contact: Francis Kelly 0117 975 0725	
	SITE NAME:	Yarde Farmhouse,	Late CI6 evolved manor house.The early CI8 chamber	
		Malborough	block is now wind and weathertight externally. The greatest	
			area of uncertainty remains the important painted hangings whose conservation and future display are not resolved.	
	DESIGNATION:	Listed Building Grade I	whose conservation and rature display are not resolved.	
	CONDITION:	Fair		
	OCCUPANCY:	Part occupied		
	PRIORITY:	F (F)		
A CLOCK DISABASE SALARS	OWNER TYPE:	Private	Contact: Francis Kelly 0117 975 0725	
-	SITE NAME:	Pridhamsleigh Farmhouse,	C16 and C17 Farmhouse. Subdivided into Pridhamsleigh	
200		Ashburton,	Manor and Pridhamsleigh Farmhouse. Farmhouse only is	
		Staverton	at risk. Part of the Farmhouse has suffered collapse. At risk from exposure and neglect. Listed building consent granted	
	DESIGNATION:	Listed Building Grade II*	for repairs which are due to start 2011-12.	
			IOI TEPAILS WHICH ALE QUE LO SLALL ZUTTETZ.	
	CONDITION:	Very bad	for repairs which are due to start 2011-12.	
		Vacant	for repairs which are due to start 2011-12.	
	CONDITION: OCCUPANCY: PRIORITY:	Vacant B (A)		
	CONDITION: OCCUPANCY:	Vacant B (A)	Contact: Francis Kelly 0117 975 0725	
	CONDITION: OCCUPANCY: PRIORITY:	Vacant B (A) Private	Contact: Francis Kelly 0117 975 0725	
	CONDITION: OCCUPANCY: PRIORITY:	Vacant B (A) Private 39 The High Street,	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor	
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Vacant B (A) Private	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors	
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Vacant B (A) Private 39 The High Street, Totnes	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration	
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Vacant B (A) Private 39 The High Street, Totnes Listed Building Grade II*, CA	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services.	
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Vacant B (A) Private 39 The High Street, Totnes Listed Building Grade II*, CA Poor	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration	
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Vacant B (A) Private 39 The High Street, Totnes Listed Building Grade II*, CA Poor Part occupied	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration	
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Vacant B (A) Private 39 The High Street, Totnes Listed Building Grade II*, CA Poor Part occupied C (C)	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration with the Local Planning Authority and English Heritage.	
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Vacant B (A) Private 39 The High Street, Totnes Listed Building Grade II*, CA Poor Part occupied	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration	
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Vacant B (A) Private 39 The High Street, Totnes Listed Building Grade II*, CA Poor Part occupied C (C) Private	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration with the Local Planning Authority and English Heritage. Contact: Francis Kelly 0117 975 0725	
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Vacant B (A) Private 39 The High Street, Totnes Listed Building Grade II*, CA Poor Part occupied C (C) Private Garden wall, steps and gatepiers south of Langdon Court Hotel,	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration with the Local Planning Authority and English Heritage. Contact: Francis Kelly 0117 975 0725 Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south	
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Vacant B (A) Private 39 The High Street, Totnes Listed Building Grade II*, CA Poor Part occupied C (C) Private Garden wall, steps and gatepiers	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration with the Local Planning Authority and English Heritage. Contact: Francis Kelly 0117 975 0725 Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central axial path	
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Vacant B (A) Private 39 The High Street, Totnes Listed Building Grade II*, CA Poor Part occupied C (C) Private Garden wall, steps and gatepiers south of Langdon Court Hotel,	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration with the Local Planning Authority and English Heritage. Contact: Francis Kelly 0117 975 0725 Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central axial path and connecting steps. Enclosed by walls to the east, south	
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION:	Vacant B (A) Private 39 The High Street, Totnes Listed Building Grade II*, CA Poor Part occupied C (C) Private Garden wall, steps and gatepiers south of Langdon Court Hotel, Langdon, Wembury Listed Building Grade II*, RPG II Very bad	<ul> <li>Contact: Francis Kelly 0117 975 0725</li> <li>Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration with the Local Planning Authority and English Heritage.</li> <li>Contact: Francis Kelly 0117 975 0725</li> <li>Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central axial path and connecting steps. Enclosed by walls to the east, south and west. The northern (larger) terrace has C17 gate piers and gates in the east and west walls and a central pool.</li> </ul>	
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Vacant B (A) Private 39 The High Street, Totnes JSH High Street, Totnes Listed Building Grade II*, CA Poor Part occupied C (C) Private Garden wall, steps and gatepiers south of Langdon Court Hotel, Langdon, Wembury Listed Building Grade II*, RPG II Very bad N/A	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration with the Local Planning Authority and English Heritage. Contact: Francis Kelly 0117 975 0725 Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central axial path and connecting steps. Enclosed by walls to the east, south and west. The northerm (larger) terrace has C17 gate piers	
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION:	Vacant B (A) Private 39 The High Street, Totnes Listed Building Grade II*, CA Poor Part occupied C (C) Private Garden wall, steps and gatepiers south of Langdon Court Hotel, Langdon, Wembury Listed Building Grade II*, RPG II Very bad	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration with the Local Planning Authority and English Heritage. Contact: Francis Kelly 0117 975 0725 Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central axial path and connecting steps. Enclosed by walls to the east, south and west. The northerm (larger) terrace has C17 gate piers and gates in the east and west walls and a central pool.	
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION:	Vacant B (A) Private 39 The High Street, Totnes JSH High Street, Totnes Listed Building Grade II*, CA Poor Part occupied C (C) Private Garden wall, steps and gatepiers south of Langdon Court Hotel, Langdon, Wembury Listed Building Grade II*, RPG II Very bad N/A	Contact: Francis Kelly 0117 975 0725 Fine C17 plasterwork and interior threatened by poor condition of roof. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration with the Local Planning Authority and English Heritage. Contact: Francis Kelly 0117 975 0725 Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central axial path and connecting steps. Enclosed by walls to the east, south and west. The northerm (larger) terrace has C17 gate piers and gates in the east and west walls and a central pool.	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

	SITE NAME:	Pair of garden houses south of Langdon Court Hotel, Langdon, Wembury	Early C18 gazebos standing at the junction of the northern and southern terraces in the late C17 to early C18 formal terraced garden to the south of the house. The walls, steps and gate piers of the terraced garden are also at risk.
	DESIGNATION:	Listed Building Grade II*, RPG II	Roofless. Negotiations are underway to restore them
Martin Martin Col	CONDITION:	Very bad	as annexes of the hotel. Owner has begun clearance
And the first of the	OCCUPANCY:	N/A	and re-pointing.
A SALE AND A SALE	PRIORITY: C (C)	C (C)	
	OWNER TYPE:	Private	Contact: Francis Kelly 0117 975 0725

SITE NAME:	Hilltop enclosure known as Maristow Camp, 240m east of Middle Park House, Bickleigh				
DESIGNATION:	Scheduled Monument (No. 1019784)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Long barrow and two bowl barrows, 200m	south east of Cha	pelcombe, Bigbury		
DESIGNATION:	Scheduled Monument (No. 1019239)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Iron Age hillfort known as Wasteberry Can 800m north west of Lyneham House, Brixto		park and post-medieval warren,		
DESIGNATION:	Scheduled Monument (No. 1020160)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Two bowl barrows 440m south east of Dur forming part of a round barrow cemetery, (				
DESIGNATION:	Scheduled Monument (No. 1019791)	CONDITION:	Extensive significant problems		
	Ample playshing		i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing Private	TREND:	Declining Business Manager 0117 975 0700		
OWNER TYPE:	TIVALE	CONTACT:			
SITE NAME:	Two round barrows on Ridding Down, Cor	nwood			
DESIGNATION:	Scheduled Monument (No. 1002586)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
	Deer park north and north west of Dartington Hall, Dartington				
SITE NAME:	Deer park north and north west of Darting	gton Hall, Dartingt	on		
	Deer park north and north west of Darting Scheduled Monument (No. 1020870)	gton Hall, Dartingt	con Generally satisfactory		
DESIGNATION:			Generally satisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020870)	CONDITION:	Generally satisfactory but with significant localised problems		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1020870) Other Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1020870) Other Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 n north west of Dartington Hall, Dartington Generally satisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1020870) Other Private Hilltop enclosure and woodbanks in Chace	CONDITION: TREND: CONTACT: grove Wood, 540n	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700		

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Hilltop enclosures in North Wood, 780m N	NW of Old Parso	onage Farm, Dartington		
DESIGNATION:	Scheduled Monument (No. 1020381)	CONDITION:	Extensive significant problems		
			i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Hillfort and two bowl barrows at Halwell C	amp, Halwell and	Moreleigh		
DESIGNATION:	Scheduled Monument (No. 1019237)	CONDITION:	Generally unsatisfactory		
	· · · · · · · · · · · · · · · · · · ·		with major localised problems		
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Improving		
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
DITE NAME:	Medieval churchyard cross, 6m south east o	f the porch of St	Andrew's Church, Harberton		
DESIGNATION:	Scheduled Monument (No. 1019234)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Bowl barrow 470m south of Borough Farm,	Holbeton			
DESIGNATION:	Scheduled Monument (No. 1019316)	CONDITION:	Extensive significant problems		
	scheduled Hondment (No. 1017510)	Condition.	i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
	Three houd barrows 140m west of Borough	Earm Holbston			
SITE NAME:	Three bowl barrows 140m west of Borough		Eutonai va aizaificant avablana		
DESIGNATION:	Scheduled Monument (No. 1019317)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
		contract.			
SITE NAME:	D-Day landing craft maintenance site on the immediately to the south of Lower Noss Pc				
DESIGNATION:	Scheduled Monument (No. 1021076)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
· · · · · · · · · · · · · · · · · · ·					
SITE NAME:	Gomerock Tower, Kingswear				
DESIGNATION:	Scheduled Monument (No. 1003852)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
	Coaxial field system, hut circles and medieval farm buildings at Starehole Bottom, Malborough				
SITE NAME:	Coaxial field system, hut circles and medieva	a larin buildings a			
SITE NAME: DESIGNATION:	Coaxial field system, hut circles and medievand Scheduled Monument (No. 1020577)		Generally satisfactory		
		-	-		

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Field systems, hut circles and four beacons,	510m south of M	iddle Soar, Malborough
DESIGNATION:	Scheduled Monument (No. 1020574)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hilltop enclosure 380m east of Middle Soar	r, Malborough	
designation:	Scheduled Monument (No. 1019533)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Medieval farmstead, boundary work and ea	rthwork enclosure	es 350m south east of Middle Soar, Malbor
DESIGNATION:	Scheduled Monument (No. 1020575)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two hut circles and associated field system:	s and enclosure at	: Mousehill Brake, Malborough
DESIGNATION:	Scheduled Monument (No. 1020573)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
	0		8
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Private Two bowl barrows at Beacon Hill,120m sou		
SITE NAME:			
SITE NAME: DESIGNATION:	Two bowl barrows at Beacon Hill,120m sou	uth of The Beacor	n, Marldon Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	<b>Two bowl barrows at Beacon Hill,120m sou</b> Scheduled Monument (No. 1020164)	uth of The Beacor	n, Marldon Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Two bowl barrows at Beacon Hill, 120m sou Scheduled Monument (No. 1020164) Digging Private Two prehistoric hilltop enclosures, a ditch s	Uth of The Beacor CONDITION: TREND: CONTACT:	n, Marldon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME:	<b>Two bowl barrows at Beacon Hill,120m sou</b> Scheduled Monument (No. 1020164) Digging Private	Uth of The Beacor CONDITION: TREND: CONTACT:	n, Marldon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: DESIGNATION:	Two bowl barrows at Beacon Hill,120m sou Scheduled Monument (No. 1020164) Digging Private Two prehistoric hilltop enclosures, a ditch s 300m north of Barton Pines Inn, Marldon	uth of The Beacor CONDITION: TREND: CONTACT:	n, Marldon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 owl barrows, Extensive significant problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Two bowl barrows at Beacon Hill, 120m sou         Scheduled Monument (No. 1020164)         Digging         Private         Two prehistoric hilltop enclosures, a ditch s         300m north of Barton Pines Inn, Marldon         Scheduled Monument (No. 1020162)	uth of The Beacor CONDITION: TREND: CONTACT: system and four be CONDITION:	n, Marldon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 owl barrows, Extensive significant problems i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE:	Two bowl barrows at Beacon Hill, 120m sou         Scheduled Monument (No. 1020164)         Digging         Private         Two prehistoric hilltop enclosures, a ditch s         300m north of Barton Pines Inn, Marldon         Scheduled Monument (No. 1020162)         Arable ploughing	Uth of The Beacor CONDITION: TREND: CONTACT: System and four be CONDITION: TREND: CONTACT:	A, Marldon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devel barrows, Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Two bowl barrows at Beacon Hill, 120m sou         Scheduled Monument (No. 1020164)         Digging         Private         Two prehistoric hilltop enclosures, a ditch s         300m north of Barton Pines Inn, Marldon         Scheduled Monument (No. 1020162)         Arable ploughing         Private	Uth of The Beacor CONDITION: TREND: CONTACT: System and four be CONDITION: TREND: CONTACT:	A, Marldon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devel barrows, Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: DESIGNATION: DESIGNATION:	Two bowl barrows at Beacon Hill, 120m sou         Scheduled Monument (No. 1020164)         Digging         Private         Two prehistoric hilltop enclosures, a ditch s         300m north of Barton Pines Inn, Marldon         Scheduled Monument (No. 1020162)         Arable ploughing         Private         Iron Age promontory fort known as Oldap	uth of The Beacor CONDITION: TREND: CONTACT: System and four be CONDITION: TREND: CONTACT: TREND: CONTACT:	A, Marldon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Devl barrows, Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Ty Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Two bowl barrows at Beacon Hill, 120m sou         Scheduled Monument (No. 1020164)         Digging         Private         Two prehistoric hilltop enclosures, a ditch s         300m north of Barton Pines Inn, Marldon         Scheduled Monument (No. 1020162)         Arable ploughing         Private         Iron Age promontory fort known as Oldape         Scheduled Monument (No. 1020234)	uth of The Beacor CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT: Ort Camp, Modbu	A, Marldon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Development Development Declining Business Manager 0117 975 0700 Fry Generally satisfactory but with significant localised problems
	Two bowl barrows at Beacon Hill, 120m sou         Scheduled Monument (No. 1020164)         Digging         Private         Two prehistoric hilltop enclosures, a ditch s         300m north of Barton Pines Inn, Marldon         Scheduled Monument (No. 1020162)         Arable ploughing         Private         Iron Age promontory fort known as Oldap         Scheduled Monument (No. 1020234)         Localised/limited stock erosion	uth of The Beacor CONDITION: TREND: CONTACT: system and four bo CONDITION: TREND: CONDITION: ort Camp, Modbu CONDITION:	A, Marldon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 burrows, Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 ry Generally satisfactory but with significant localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION:	Two bowl barrows at Beacon Hill, 120m sou         Scheduled Monument (No. 1020164)         Digging         Private         Two prehistoric hilltop enclosures, a ditch s         300m north of Barton Pines Inn, Marldon         Scheduled Monument (No. 1020162)         Arable ploughing         Private         Iron Age promontory fort known as Oldap         Scheduled Monument (No. 1020234)         Localised/limited stock erosion         Private	uth of The Beacor CONDITION: TREND: CONTACT: system and four bo CONDITION: TREND: CONDITION: ort Camp, Modbu CONDITION:	A, Marldon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 burrows, Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 ry Generally satisfactory but with significant localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Two bowl barrows at Beacon Hill, 120m source         Scheduled Monument (No. 1020164)         Digging         Private         Two prehistoric hilltop enclosures, a ditch state         300m north of Barton Pines Inn, Marldon         Scheduled Monument (No. 1020162)         Arable ploughing         Private         Iron Age promontory fort known as Oldap         Scheduled Monument (No. 1020234)         Localised/limited stock erosion         Private         Fort Charles, Salcombe	uth of The Beacor CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION:	A Marldon Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 business Manager 0117 975 0700 Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Barrow cemetery on western slope of Crow	wnhill Down, Shau	ugh Prior
DESIGNATION:	Scheduled Monument (No. 1003201)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		convict.	
SITE NAME:	Hentor Warren boundary stone standing 20	00m south east of	Hen Tor, Shaugh Prior
DESIGNATION:	Scheduled Monument (No. 1015744)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Iron Age cliff castle known as Bolt Tail Cam	o, South Huish	
designation:	Scheduled Monument (No. 1019323)	CONDITION:	Generally unsatisfactory
		constrict.	with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Deer park and rabbit warren at Newnham	Park, Sparkwell	
DESIGNATION:	Scheduled Monument (No. 1020169)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hut circle 1000yds (915m) east of Coleland	Bridge, Sparkwel	
DESIGNATION:	Scheduled Monument (No. 1002596)	CONDITION:	Generally satisfactory
Designation.		CONDITION.	but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
FRINCIPAL VOLINERABILITT.	-	TREND.	6
	Private	CONITACT	Business Manager 0117 975 0700
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	Post-medieval deer park, medieval fishpond,	18th century triu	mphal arch
SITE NAME:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works an	18th century triu	mphal arch ringdon Park, Sparkwell
SITE NAME:	Post-medieval deer park, medieval fishpond,	18th century triu d smelt mill at Bc	mphal arch ringdon Park, Sparkwell Extensive significant problems
SITE NAME: DESIGNATION:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works an	18th century triu d smelt mill at Bc	mphal arch ringdon Park, Sparkwell Extensive significant problems i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works an Scheduled Monument (No. 1020565)	18th century triu d smelt mill at Bc condition:	mphal arch ringdon Park, Sparkwell Extensive significant problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works an Scheduled Monument (No. 1020565) Collapse Government or Agency	18th century triu d smelt mill at Bc condition: trend:	mphal arch ringdon Park, Sparkwell Extensive significant problems i.e. under plough, collapse Improving
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works and Scheduled Monument (No. 1020565) Collapse Government or Agency Woodbury Camp, Stoke Fleming	18th century triu d smelt mill at Bo condition: TREND: CONTACT:	mphal arch ringdon Park, Sparkwell Extensive significant problems i.e. under plough, collapse Improving Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works an Scheduled Monument (No. 1020565) Collapse Government or Agency	18th century triu d smelt mill at Bc condition: trend:	mphal arch ringdon Park, Sparkwell Extensive significant problems i.e. under plough, collapse Improving
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works and Scheduled Monument (No. 1020565) Collapse Government or Agency Woodbury Camp, Stoke Fleming	18th century triu d smelt mill at Bo condition: TREND: CONTACT:	mphal arch ringdon Park, Sparkwell Extensive significant problems i.e. under plough, collapse Improving Business Manager 0117 975 0700 Extensive significant problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works and Scheduled Monument (No. 1020565)         Collapse         Government or Agency         Woodbury Camp, Stoke Fleming         Scheduled Monument (No. 1019783)	I8th century triu d smelt mill at Bc CONDITION: TREND: CONTACT:	mphal arch ringdon Park, Sparkwell Extensive significant problems i.e. under plough, collapse Improving Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works and Scheduled Monument (No. 1020565)         Collapse         Government or Agency         Woodbury Camp, Stoke Fleming         Scheduled Monument (No. 1019783)         Arable ploughing	I8th century triu d smelt mill at Bc CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	mphal arch ringdon Park, Sparkwell Extensive significant problems i.e. under plough, collapse Improving Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Stable
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works and Scheduled Monument (No. 1020565)         Collapse         Government or Agency         Woodbury Camp, Stoke Fleming         Scheduled Monument (No. 1019783)         Arable ploughing         Private         Hillfort known as Slapton Castle, Stokenham	I8th century triu d smelt mill at Bo condition: TREND: CONTACT: CONDITION: TREND: CONTACT:	mphal arch ringdon Park, Sparkwell Extensive significant problems i.e. under plough, collapse Improving Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Stable Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works and Scheduled Monument (No. 1020565)         Collapse         Government or Agency         Woodbury Camp, Stoke Fleming         Scheduled Monument (No. 1019783)         Arable ploughing         Private	I8th century triu d smelt mill at Bc CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	mphal arch ringdon Park, Sparkwell Extensive significant problems i.e. under plough, collapse Improving Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Stable Business Manager 0117 975 0700 Extensive significant problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works and Scheduled Monument (No. 1020565)         Collapse         Government or Agency         Woodbury Camp, Stoke Fleming         Scheduled Monument (No. 1019783)         Arable ploughing         Private         Hillfort known as Slapton Castle, Stokenham         Scheduled Monument (No. 1019236)	I8th century triu d smelt mill at Bo CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	mphal arch         ringdon Park, Sparkwell         Extensive significant problems         i.e. under plough, collapse         Improving         Business Manager 0117 975 0700         Extensive significant problems         i.e. under plough, collapse         Stable         Business Manager 0117 975 0700         Extensive significant problems         i.e. under plough, collapse         Stable         Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Post-medieval deer park, medieval fishpond, and a 19th century lead mine, ore works and Scheduled Monument (No. 1020565)         Collapse         Government or Agency         Woodbury Camp, Stoke Fleming         Scheduled Monument (No. 1019783)         Arable ploughing         Private         Hillfort known as Slapton Castle, Stokenham	I8th century triu d smelt mill at Bo condition: TREND: CONTACT: CONDITION: TREND: CONTACT:	mphal arch ringdon Park, Sparkwell Extensive significant problems i.e. under plough, collapse Improving Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Stable Business Manager 0117 975 0700 Extensive significant problems

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / SOUTH HAMS / TEIGNBRIDGE

SITE NAME:	Roman settlement site at Bantham Ham, Thurlestone		
DESIGNATION:	Scheduled Monument (No. 1019322)	CONDITION:	Generally satisfactory
	`````		but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hilltop enclosure at Yellowberries Copse, 430	m west of High	er Turtlev Lisboroush
SITE INAME:			
DESIGNATION:	Scheduled Monument (No. 1019325)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Fort Bovisand, Wembury		
DESIGNATION:	Scheduled Monument (No. 1002584)	CONDITION:	Generally satisfactory
	`````		but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Watch House battery and ditch, Wembury		
DESIGNATION:	Scheduled Monument (No. 1002585)	CONDITION:	Generally satisfactory
	`````		but with significant localised problems
PRINCIPAL VULNERABILITY:	Subsidence	TREND:	Improving
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	World War II Heavy Anti-aircraft gunsite, 100n	n west of Princ	es Cottages, Wembury
DESIGNATION:	Scheduled Monument (No. 1021147)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		001101011	

### TEIGNBRIDGE



OWNER TYPE:	Private	Contact: Francis Kelly 0117 975 0725	
PRIORITY:	C (C)		
OCCUPANCY:	N/A	future, the building remains at risk.	
CONDITION:	Poor	and a first phase of repairs has been completed. With no prospect of a further phase being funded in the immediate	
DESIGNATION:	Listed Building Grade II*, RPG II*	English Heritage grant has been offered towards repairs	
SITE NAME:	The Belvedere, Powderham	Gothick Belvedere, 1771-1774, situated 600m north west of Powderham Castle on the north east fringe of Powderham Old Plantation within the C18 park. Damaged by fire after the war and now a roofless shell.	



	SITE NAME:	St Michael the Archangel, Den Promenade, Teignmouth	Multi–phase Norman style church. Current Repair Grant for Places of Worship for repairs to valley gutters which have been leaking for several years. Roof covering replaced in recent past with concrete tiles and there is concern as to increased load this has applied to the roof structure. This will be assessed as part of the
	DESIGNATION:	Listed Place of Worship Grade II, CA	grant. Stonework tracery of windows is deteriorating. Cracking ceilings internally is extensive and may indicate expansion of structural timbers as a result of water ingress and decay.
	CONDITION:	Poor	
	PRIORITY:	B (New entry)	su uctural unibers as a result of water ingress and decay.
- Colore	OWNER TYPE:	Religious organisation	Contact: Nicola Lauder 0117 975 0674

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Earthwork (possibly civil war) on Bovey He	ath, Bovey Tracey	
designation:	Scheduled Monument (No. 1002657)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bishop's Palace, Chudleigh		
DESIGNATION:	Scheduled Monument (No. 1008679)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cow Cave, Chudleigh Rocks, Chudleigh		
DESIGNATION:	Scheduled Monument (No. 1010726)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Milber Down camp, Coffinswell		
designation:	Scheduled Monument (No. 1003178)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Cotley Castle, Dunsford		
DESIGNATION:	Scheduled Monument (No. 1003180)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Earthwork enclosure south of Blackall's Cop	pse, Exminster	
SITE NAME: DESIGNATION:	Earthwork enclosure south of Blackall's Cop Scheduled Monument (No. 1004579)	pse, Exminster	Generally unsatisfactory with major localised problems
DESIGNATION:	Scheduled Monument (No. 1004579)		Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:		CONDITION:	with major localised problems
	Scheduled Monument (No. 1004579) Arable clipping	CONDITION: TREND: CONTACT:	with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1004579) Arable clipping Private	CONDITION: TREND: CONTACT:	with major localised problems Declining Business Manager 0117 975 0700 cminster Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1004579) Arable clipping Private Linear round barrow cemetery at Castle Pa Scheduled Monument (No. 1012347)	CONDITION: TREND: CONTACT: rk, Alphington, Ex	with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004579) Arable clipping Private Linear round barrow cemetery at Castle Pa	CONDITION: TREND: CONTACT: rk, Alphington, Ex	with major localised problems Declining Business Manager 0117 975 0700 cminster Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004579) Arable clipping Private Linear round barrow cemetery at Castle Pa Scheduled Monument (No. 1012347) Arable ploughing	CONDITION: TREND: CONTACT: rk, Alphington, Ex CONDITION: TREND:	with major localised problems Declining Business Manager 0117 975 0700 minster Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1004579) Arable clipping Private Linear round barrow cemetery at Castle Pa Scheduled Monument (No. 1012347) Arable ploughing	CONDITION: TREND: CONTACT: rk, Alphington, Ex CONDITION: TREND:	with major localised problems Declining Business Manager 0117 975 0700 minster Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1004579) Arable clipping Private Linear round barrow cemetery at Castle Pa Scheduled Monument (No. 1012347) Arable ploughing Private	CONDITION: TREND: CONTACT: rk, Alphington, Ex CONDITION: TREND:	with major localised problems Declining Business Manager 0117 975 0700 minster Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1004579)         Arable clipping         Private         Linear round barrow cemetery at Castle Pa         Scheduled Monument (No. 1012347)         Arable ploughing         Private         Kingskerswell Manor House, Kingskerswell	CONDITION: TREND: CONTACT: rk, Alphington, Ex CONDITION: TREND: CONTACT:	with major localised problems Declining Business Manager 0117 975 0700 minster Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

### HERITAGE AT RISK 2011 / SOUTH WEST / TEIGNBRIDGE / TORRIDGE

	SITE NAME:       Oxton House, Kenton         DESIGNATION:       Registered Park and Garden Grade also 7 LBs         CONDITION:       Generally satisfactory but with significant localised problem         VULNERABILITY:       Medium         TREND:       Declining         OWNERTYPE:       Private, multiple owners         SITE NAME:       Mamhead Park, Mamhead         DESIGNATION:       Registered Park and Garden Grade II also 16 LBs         CONDITION:       Generally unsatisfactory with major localised problems         VULNERABILITY:       Medium	C20, the property was firstly a school and then divided into apartments. The pleasure grounds are neglected and much of the park is ploughed up, with considerable loss of parkland planting. Contact: Kim Auston 0117 975 0696 Mamhead contains the remnants of a 'Capability' Brown park overlooking the Eve estuary Extensive loss of parkland
	owner in the industrie owners	
	SITE NAME: Stover Park, Teigngrace DESIGNATION: Registered Park and Garden Grade also 7 LBs CONDITION: Generally satisfactory but with significant localised problem	Council as country park, the remainder a school with ongoing expansion of school facilities. Much altered setting with pressure for hotel, retail, residential and industrial
	vulnerability: High       TREND:     Stable       OWNERTYPE:     Mixed, multiple owners	<ul> <li><sup>15</sup> development associated with A38 trunk road.</li> <li>Contact: Kim Auston 0117 975 0696</li> </ul>
	Pavau Traanu Pattamu Paad	
SITE NAME:	Bovey Tracey, Pottery Road	
DESIGNATION:	Conservation Area Low	CONDITION: Very bad TREND: No significant change
VULNERABILITY: CONTACT:	Maureen Pearce LPA) 01626 215705	TREND: INO SIGNIFICANT Change NEW ENTRY?: Yes
SITE NAME:	Chudleigh	
DESIGNATION:	Conservation Area	CONDITION: Very bad
VULNERABILITY:	Medium	TREND: Deteriorating
CONTACT:	Maureen Pearce LPA) 01626 215705	NEW ENTRY?: Yes
SITE NAME:	Dawlish	
	Conservation Area	condition: Very bad
DESIGNATION: VULNERABILITY:	Low	condition: Very bad trend: Improving
CONTACT:	Maureen Pearce LPA) 01626 215705	NEW ENTRY: Yes
TORRIDGE		
	site NAME: Richmond Dock, Appledore	Dry dock, 1856. It is said to be the largest dry dock in the Bristol Channel at the time it was built. Now vacant and in fair to poor condition, the dock has not seen significant maintenance in recent years. Appeal into refusal
The Party of the P	DESIGNATION: Listed Building Grade II*	for damaging development adjacent to site June 2011.
	CONDITION: Fair	
Philippine and	occupancy: Vacant	
And the second s	priority: C (C)	
	OWNER TYPE: Company	Contact: Francis Kelly 0117 975 0725

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

	SITE NAME:	Winsford Hospital, Halwill Junction, Halwill	Winsford centre built as a cottage hospital in 1899, designed by Charles Voysey and founded by a local landowner. The NHS closed the hospital in 1998 when it was bought by the Winsford Trust. Since then, it has been
	DESIGNATION:	Listed Building Grade II*	run as a day centre and community resource. The future
	CONDITION:	Fair	of the building is threatened by the urgent need for major
	OCCUPANCY:	Part occupied	repairs. English Heritage grant has been given towards a
	PRIORITY:	C (C)	condition survey.
	OWNER TYPE:	Trust	Contact: Francis Kelly 0117 975 0725
SITE NAME	Cairn 20m	east of Tibbett's Lookout, Lundy	

SITE NAME:	Cairn 20m east of Tibbett's Lookout, Lundy	/	
DESIGNATION:	Scheduled Monument (No. 1016015)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Chapel remains, cemetery and prehistoric s	settlement on Bea	con Hill, Lundy
DESIGNATION:	Scheduled Monument (No. 1016040)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
site name:	Granite quarry on East Sidelands, Lundy		
DESIGNATION:	Scheduled Monument (No. 1016041)	CONDITION:	Generally unsatisfactory
	· · · · · ·		with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hut circle and small enclosure 270m north	west of The Old	Lighthouse, Lundy
DESIGNIATION	Scheduled Monument (No. 1016014)		Extensive significant problems

DESIGNATION:	Scheduled Monument (No. 1016014)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700

SITE NAME:	Long house and enclosure 160m north of Widow's Tenement, Lundy				
DESIGNATION:	Scheduled Monument (No. 1018547)	CONDITION:	Extensive significant problems		
			i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		

 
 SITE NAME:
 Quarry infirmary and surgery, 220m north west of Quarter wall Cottages, Lundy

 DESIGNATION:
 Scheduled Monument (No. 1016026)
 CONDITION:
 Generally satisfactory but with significant localised problems

 PRINCIPAL VULNERABILITY:
 Collapse
 TREND:
 Declining

 OWNER TYPE:
 Private
 CONTACT:
 Business Manager 0117 975 0700

 SITE NAME:
 Ruined cottages and well 190m north west of Quarterwall Cottages, Lundy

 DESIGNATION:
 Scheduled Monument (No. 1016027)
 CONDITION:
 Generally unsatisfactory with major localised problems

 PRINCIPAL VULNERABILITY:
 Plant growth
 TREND:
 Declining

 OWNERTYPE:
 Private
 CONTACT:
 Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

 D Slow decay: solution agreed but not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA Conservation Area LB/LBs Listed Building/s LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM/SMS Scheduled Monument/s UA Unitary Authority WHS World Heritage Site

SITE NAME:	Standing stone 100m north east of The Old	l Lighthouse, Lund	у
DESIGNATION:	Scheduled Monument (No. 1015928)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	The Widow's Tenement medieval settlemen	t and prehistoric s	settlement sites, Lundy
DESIGNATION:	Scheduled Monument (No. 1017646)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Iron Age enclosure and Roman marching ca	ımp, Alverdiscott	
DESIGNATION:	Scheduled Monument (No. 1004558)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 250m north east of Oak Cott	tage, forming part	of a round barrow cemetery, Ashwater
DESIGNATION:	Scheduled Monument (No. 1020079)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
	Arable ploughing Private	TREND: CONTACT:	Declining Business Manager 0117 975 0700
OWNER TYPE:		CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION:	Private Bowl barrow 540m south east of Sandymoo	contact: or Cross, forming	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Bowl barrow 540m south east of Sandymoo Scheduled Monument (No. 1020080)	CONTACT: or Cross, forming CONDITION:	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Bowl barrow 540m south east of Sandymoo Scheduled Monument (No. 1020080) Other	CONTACT: or Cross, forming CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private Bowl barrow 540m south east of Sandymoo Scheduled Monument (No. 1020080) Other Private	CONTACT: or Cross, forming CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems
OWNER TYPE:	Private Bowl barrow 540m south east of Sandymod Scheduled Monument (No. 1020080) Other Private Bowl barrow 770m south east of Sandymod	CONTACT: or Cross, forming CONDITION: TREND: CONTACT: or Cross, forming	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Bowl barrow 540m south east of Sandymod Scheduled Monument (No. 1020080) Other Private Bowl barrow 770m south east of Sandymod Scheduled Monument (No. 1020081)	CONTACT: or Cross, forming CONDITION: TREND: CONTACT: or Cross, forming CONDITION:	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Bowl barrow 540m south east of Sandymod Scheduled Monument (No. 1020080) Other Private Bowl barrow 770m south east of Sandymod Scheduled Monument (No. 1020081) Other	CONTACT: or Cross, forming CONDITION: TREND: CONDITION: CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
OWNER TYPE:	Private Bowl barrow 540m south east of Sandymod Scheduled Monument (No. 1020080) Other Private Bowl barrow 770m south east of Sandymod Scheduled Monument (No. 1020081) Other Private Hillfort known as Castle Hill Settlement, 35	CONTACT: or Cross, forming CONDITION: TREND: CONTACT: or Cross, forming CONDITION: TREND: CONTACT: TREND: CONTACT:	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 parter of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
OWNER TYPE:	Private Bowl barrow 540m south east of Sandymod Scheduled Monument (No. 1020080) Other Private Bowl barrow 770m south east of Sandymod Scheduled Monument (No. 1020081) Other Private Hillfort known as Castle Hill Settlement, 35 Scheduled Monument (No. 1021417)	CONTACT: or Cross, forming CONDITION: TREND: CONDITION: CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONDITION:	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 pleigh Bridge, Beaford Unknown
OWNER TYPE:	Private Bowl barrow 540m south east of Sandymod Scheduled Monument (No. 1020080) Other Private Bowl barrow 770m south east of Sandymod Scheduled Monument (No. 1020081) Other Private Hillfort known as Castle Hill Settlement, 35		Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 pleigh Bridge, Beaford Unknown Unknown
OWNER TYPE:	Private Bowl barrow 540m south east of Sandymod Scheduled Monument (No. 1020080) Other Private Bowl barrow 770m south east of Sandymod Scheduled Monument (No. 1020081) Other Private Hillfort known as Castle Hill Settlement, 35 Scheduled Monument (No. 1021417) Other	CONTACT: or Cross, forming CONDITION: TREND: CONDITION: CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONDITION:	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 pleigh Bridge, Beaford Unknown
OWNER TYPE:	Private Bowl barrow 540m south east of Sandymod Scheduled Monument (No. 1020080) Other Private Bowl barrow 770m south east of Sandymod Scheduled Monument (No. 1020081) Other Private Hillfort known as Castle Hill Settlement, 35 Scheduled Monument (No. 1021417) Other	CONTACT: OF CFOSS, forming CONDITION: TREND: CONTACT: OF CFOSS, forming CONDITION: TREND: CONTACT: OF CONDITION: TREND: CONDITION: CONDITION:	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 pleigh Bridge, Beaford Unknown Unknown
OWNER TYPE:	Private Bowl barrow 540m south east of Sandymod Scheduled Monument (No. 1020080) Other Private Bowl barrow 770m south east of Sandymod Scheduled Monument (No. 1020081) Other Private Hillfort known as Castle Hill Settlement, 35 Scheduled Monument (No. 1021417) Other Private	CONTACT: OF CFOSS, forming CONDITION: TREND: CONTACT: OF CFOSS, forming CONDITION: TREND: CONTACT: OF CONDITION: TREND: CONDITION: CONDITION:	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 plleigh Bridge, Beaford Unknown Unknown Business Manager 0117 975 0700 Extensive significant problems
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Bowl barrow 540m south east of Sandymod Scheduled Monument (No. 1020080) Other Private Bowl barrow 770m south east of Sandymod Scheduled Monument (No. 1020081) Other Private Hillfort known as Castle Hill Settlement, 35 Scheduled Monument (No. 1021417) Other Private Bowl barrow 420m north west of Dural Cr	CONTACT: or Cross, forming CONDITION: TREND: CONTACT: or Cross, forming CONDITION: TREND: CONTACT: 00m south of Wood CONDITION: TREND: CONTACT: 00m south of Wood	Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 part of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 parter of a round barrow cemetery, Ashwate Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 parter of a round barrow cemetery, Ashwate Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Thorn Barrow 520m south east of Coop, ir	n Highermoor Plar	ntations, Broadwoodwidger
ESIGNATION:	Scheduled Monument (No. 1017144)	CONDITION:	Generally satisfactory
			but with significant localised problems
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	
WNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow I 30m north of Wrangworthy forming part of a round barrow cemetery, I		
DESIGNATION:	Scheduled Monument (No. 1018527)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Three bowl barrows 250m west of Bower,	Bulkworthy	
DESIGNATION:	Scheduled Monument (No. 1020340)	CONDITION:	Extensive significant problems
	Ample plaushing		i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing Private	TREND:	Declining Business Manager 0117 975 0700
DWNER TYPE:	rnvate	CONTACT:	Dusifiess Flandger 0117 975 0700
ITE NAME:	Two bowl barrows 690m and 760m south v	west of Leworthy,	Clawton
DESIGNATION:	Scheduled Monument (No. 1017974)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
WWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Clovelly Dykes hillfort, Clovelly		
DESIGNATION:	Scheduled Monument (No. 1018522)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
DITE NAME:	Four bowl barrows I I 0m and 360m west o		iross
	forming part of a round barrow cemetery, I		Conorally unceticfactory
DESIGNATION:	Scheduled Monument (No. 1018526)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Other	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Three bowl barrows I 60m north west of W forming part of a round barrow cemetery, I		
DESIGNATION:	Scheduled Monument (No. 1018514)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Other	TREND:	Declining
WWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
DITE NAME:	Three fishponds at Winslade, East Putford		
DESIGNATION:	Scheduled Monument (No. 1017979)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
	Private		Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME: Two bowl barrows 600m and 750m west of Wrangworthy cross forming part of a round barrow cemetery, East Putford				
DESIGNATION:	Scheduled Monument (No. 1018515)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Two bowl barrows one immediately north a forming part of a round barrow cemetery.		th of Commonmoor Cottage	
DESIGNATION:	Scheduled Monument (No. 1018516)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Round barrow on south east of Darracott	Moor, Great Torri	ngton	
DESIGNATION:	Scheduled Monument (No. 1012444)	eduled Monument (No. 1012444) CONDITION: Generally satisfactor but with significant l		
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Bowl barrow 300m south east of Gorvin, H	artland		
DESIGNATION:	Scheduled Monument (No. 1016645)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Bowl barrow 520m west of Higher Welsfor	d, Hartland		
DESIGNATION:	Scheduled Monument (No. 1017138)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Bowl barrow 580m north west of Gorvin, H	Hartland		
DESIGNATION:	Scheduled Monument (No. 1016648)	CONDITION:	Extensive significant problems i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining	
	Private	CONTACT:	Business Manager 0117 975 0700	
OWNER TYPE:			0	
OWNER TYPE:	Embury Beacon camp, Hartland			
SITE NAME:	<b>Embury Beacon camp, Hartland</b> Scheduled Monument (No. 1003845)	CONDITION:	Generally satisfactory but with minor localised problems	
ITE NAME: DESIGNATION:			Generally satisfactory	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1003845)	CONDITION:	Generally satisfactory but with minor localised problems	
	Scheduled Monument (No. 1003845) Coastal erosion	CONDITION: TREND: CONTACT: n Bursdon Moor	Generally satisfactory but with minor localised problems Declining	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1003845) Coastal erosion Private Three bowl barrows and one bell barrow o	CONDITION: TREND: CONTACT: n Bursdon Moor	Generally satisfactory but with minor localised problems Declining	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1003845) Coastal erosion Private Three bowl barrows and one bell barrow of situated 670m north east of Lutsford Cross	CONDITION: TREND: CONTACT: n Bursdon Moor s, Hartland	Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Generally satisfactory	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Two bowl barrows 400m north w	vest of Gorvin, Hart	tland		
DESIGNATION:	Scheduled Monument (No. 10166	47) co	NDITION:	Extensive signification i.e. under plough	
RINCIPAL VULNERABILITY:	Other	TRE	ND:	Declining	
DWNER TYPE:	Private	CO	NTACT:	Business Manage	r 0117 975 0700
ITE NAME:	Bowl barrow on Ugworthy Moor	510m south of We	est Ugwo	rthy House, Holsw	orthy Hamlets
ESIGNATION:	Scheduled Monument (No. 10179)		NDITION:	, Extensive signific	-
	(			i.e. under plough	
PRINCIPAL VULNERABILITY:	Other	TRE	ND:	Declining	
DWNER TYPE:	Private	CO	NTACT:	Business Manage	r 0117 975 0700
ITE NAME:	Bowl barrow 60m west of St Jame	es's Church, Luffince	ott		
DESIGNATION:	Scheduled Monument (No. 10204)	76) co	NDITION:	Extensive signification i.e. under plough	
PRINCIPAL VULNERABILITY:	Arable ploughing	TRE	ND:	Declining	
OWNER TYPE:	Private	CO	NTACT:	Business Manage	r 0117 975 0700
SITE NAME:	Moated site at Grange Farm, Mer	ton			
DESIGNATION:	Scheduled Monument (No. 10178	67) со	NDITION:	Extensive signific	ant problems
				i.e. under plough	collapse
PRINCIPAL VULNERABILITY:	Other	TRE	ND:	Declining	
OWNER TYPE:	Private	CO	NTACT:	Business Manage	r 0117 975 0700
SITE NAME:	Cross ridge dyke on Godborough	n Castle earthwork	north w	est of Turner's Wo	od, Northam
DESIGNATION:	Scheduled Monument (No. 100264	40) co	NDITION:	Unknown	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TRE	ND:	Stable	
OWNER TYPE:	Other	CO	NTACT:	Business Manage	r 0117 975 0700
SITE NAME:	Hallsannery limekiln, Northam				
DESIGNATION:	Scheduled Monument (No. 10045	78) co	NDITION:	Unknown	
PRINCIPAL VULNERABILITY:	Deterioration – in need of manage	ement TRE	ND:	Unknown	
OWNER TYPE:	Private	CO	NTACT:	Business Manage	r 0117 975 0700
SITE NAME:	Northcott Wood camp, Northcot	t			
DESIGNATION:	Scheduled Monument (No. 10038	63) co	NDITION:	Generally unsatis	factory
				with major locali	sed problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TRE	ND:	Declining	0117 075 0700
OWNER TYPE:	Private	CO	NTACT:	Business Manage	r 0117 975 0700
SITE NAME:	Bowl barrow 685m NNE of Moo	rfield, Peters Marlar	nd		
DESIGNATION:	Scheduled Monument (No. 101796	63) co	NDITION:	Extensive signific	
	Other			i.e. under plough,	collapse
PRINCIPAL VULNERABILITY:	Other Private	TRE		Declining Business Manage	r 0117 975 0700
OWNER TYPE:	I I IVALE	CO	NTACT:	DUSITIESS I*Tanage	
DITE NAME:	Bowl barrow in Heathermoor Pla	ntation, 50m north	east of I	Petrockstow Statio	n, Petrockstow
DESIGNATION:	Scheduled Monument (No. 10162	10) co	NDITION:	Generally unsatis with major localis	,
PRINCIPAL VULNERABILITY:	Forestry	TRE	ND:	Declining	
OWNER TYPE:	Private	CO	NTACT:	Business Manage	r 0117 975 0700
RIORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.	but not yet implemented.	Repair scheme in progress and (where applicable) and use or user identified; functionally redundant buildings with new use agreed but not yet implemented.	has ch regist	: priority category anged since the 2010 ar, the previous category n in brackets.	ABBREVIATIONS CA Conservation Area LB/LBs Listed Building/s LPA Local Planning Authori NP National Park RPG Registered Park and G SM/SMs Scheduled Monument/

agreed but not yet implemented. C Slow decay; no solution agreed.

under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

 RPG
 Registered Park and Gar

 SM/SMs
 Scheduled Monument/s

 UA
 Unitary Authority

 WHS
 World Heritage Site

### HERITAGE AT RISK 2011 / SOUTH WEST / TORRIDGE / WEST DEVON

SITE NAME:	Beacon or	n Belland Moor 770m north east of Be	elland, Tetcott	
DESIGNATION:	Scheduled	Monument (No. 1020609)	CONDITION:	Generally unsatisfactory
				with major localised problems
PRINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bideford			
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Low		TREND:	Improving
CONTACT:	Sarah Cha	ppell (LPA) 01237 428742	NEW ENTRY?:	Yes
SITE NAME:	Northam			
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor
VULNERABILITY:	Low		TREND:	Deteriorating
CONTACT:	Sarah Cha	ppell (LPA) 01237 428742	NEW ENTRY?:	Yes
WEST DEVON				
	SITE NAME:	Gawton Mine complex, Gulworthy	complex con cooperage t	per and arsenic mine and processing mprising a full range of buildings from to engine houses. Structures are at risk of maintenance.
-	DESIGNATION:	Scheduled Monument, WHS	IFOITI & IACK	or maintenance.
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY:	A (New entry)		
	OWNER TYPE:		Contact: Nic	ck Russell 0117 975 0671
	0,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Contacti i in	
-	SITE NAME:	Kelly House, Kelly	C18 house. Serious maintenance issues. Roof in need or renewal, rear medieval wing partly propped. Main hous weathertight and maintenance gradually being address	
THE LEFT	DESIGNATION:	Listed Building Grade I		
	CONDITION:	Poor		
	OCCUPANCY:	Part occupied		
	PRIORITY:	C (C)		
	OWNER TYPE:	Private	Contact: Fra	ncis Kelly 0117 975 0725
1	SITE NAME:	Stable block north of Kelly House, Kelly	Stables, 1740	). Partly used, part collapsed.
Aliz	DESIGNATION:	Listed Building Grade II*		
	CONDITION:	Very bad		
Print Print		Part occupied		
	PRIORITY:	A (A)		
and the second second second	OWNER TYPE:		Contact: Fra	ncis Kelly 0117 975 0725
	SITE NAME:	Lower Sessland Farm including cob walls adjoining to north west and south west, Sessland Lane, South Tawton	including CI addition to and is now water penet	val thatched farmhouse with later additions 7 hall bay and parlour wing. Further C17 north west has been used as a separate cottage vacant and in very poor condition with severe rration and decay of thatch and roof timbers.
	DESIGNATION:	Listed Building Grade II*	Temporary	protection was erected in 2006 following an
A REAL AND A REAL AND A REAL AND	CONDITION	Very bad	Orgent Wor	ks Notice. Owner negotiating over repairs.
	CONDITION:			
		Part occupied		
				ncis Kelly 0117 975 0725

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

	SITE NAME:	Church of Our Lady and St Mary Magdalene, Callington Road, Tavistock	Built 1825-67 by Henry Clutton for Duke of Norfolk. The church has previously been at risk of being made redundant, though has recently increased its congregation. The church has had English Heritage funding to investigate
1, AC	DESIGNATION:	Listed Place of Worship Grade II*, CA.WHS	the structural cracking and cause. A scheme for repair has been agreed and the church successfully applied for grant
1 AM	CONDITION:	Poor	aid in 2010 to complete the works.
	PRIORITY:	B (B)	
	OWNER TYPE:	Religious organisation	Contact: Nicola Lauder 0117 975 0674

SITE NAME:	Round barrow cemetery and beacon at He	athfield, 650m we	st of Moorlands, Brentor
DESIGNATION:	Scheduled Monument (No. 1020075)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Motte with two baileys and a multivallate hi	illfort at Burley W	'ood, Bridestowe
DESIGNATION:	Scheduled Monument (No. 1018519)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Coaxial fields, prehistoric settlement, two c 900m south east of Stannon Tor, Dartmoor		alignment in Little Stannon Newtake,
DESIGNATION:	Scheduled Monument (No. 1021339)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric enclosed settlement 740m nort	h west of Hartland	d Tor, Dartmoor Forest
DESIGNATION:	Scheduled Monument (No. 1021335)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Iron Age defended settlement in Dunterue	Wood, 570m sout	h of Castle Head, Dunterton
DESIGNATION:	Scheduled Monument (No. 1020273)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 620m north of Higher Eworth	ny, Germansweek	
	<b>Bowl barrow 620m north of Higher Eworth</b> Scheduled Monument (No. 1017971)	ny, Germansweek	Generally unsatisfactory with major localised problems
designation:	-		Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1017971)	CONDITION:	with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1017971) Extensive animal burrowing	CONDITION: TREND:	with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No. 1017971) Extensive animal burrowing Private Gawton arsenic mine and flue, Gulworthy	CONDITION: TREND: CONTACT:	with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1017971) Extensive animal burrowing Private	CONDITION: TREND:	with major localised problems Declining

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Roman forts, marching camps and associate	ed monuments, No	orth Tawton
DESIGNATION:	Scheduled Monument (No. 1021151)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Guide post at Place Cross, Okehampton Ha	amlets	
DESIGNATION:	Scheduled Monument (No. 1020069)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Warren at Sheeps Tor, 520m north of Chub	ostone Cottage, Sh	eepstor
DESIGNATION:	Scheduled Monument (No. 1021391)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bere Alston		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Laura Batham (LPA) 01822 813549	NEW ENTRY?:	No
SITE NAME:	Exbourne		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Laura Batham (LPA) 01822 813549	NEW ENTRY?:	No
SITE NAME:	Hatherleigh		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Laura Batham (LPA) 01822 813549	NEW ENTRY?:	No
SITE NAME:	North Tawton		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Laura Batham (LPA) 01822 813549	NEW ENTRY?:	No
SITE NAME:	Okehampton		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Laura Batham (LPA) 01822 813549	NEW ENTRY?:	No
SITE NAME:	Tavistock		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Unknown
CONTACT:	Laura Batham (LPA) 01822 813549	NEW ENTRY?:	No

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

HERITAGE AT RISK 2011 / SOUTH WEST / CHRISTCHURCH / EAST DORSET

DORSET CHRISTCHURCH				
	Devid have	ann an East Barlan Camman (10m a		in Course France Library
ITE NAME:	BOWI Darr	row on East Parley Common 610m s	outh west of r	
esignation:	Scheduled	I Monument (No. 1016092)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Extensive	animal burrowing	TREND:	Declining
WNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two bowl	barrows at Gibbet Firs, 950m south	west and 1080	m south west of Palmers Ford Works, Hurn
DESIGNATION:	Scheduled	Monument (No. 1016091)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Arable clip	ping	TREND:	Declining
DWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
AST DORSET				
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Grotto 250 metres south west of St Giles House, Wimborne St Giles Listed Building Grade II*, RPG II* Very bad N/A	of the hous water runn extremity c of the hous the CI7 an a priority ir	751-53, located 250 metres to the south-east se, at the east end of a winding channel of ing westwards for 300 metres to the norther of the lake (which lies 150 metres to the south se). One of several garden buildings situated ir id C18 landscape. The Grotto is identified as in the Parkland Plan produced as part of el Stewardship.
	PRIORITY:	С (С)	0	1
	OWNER TYPE:	Private	Contact: Isl	a Macneal 0117 975 0742
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	St Giles House, Wimborne St Giles Listed Building Grade I, RPG II* Very bad Part occupied C (C)	CI8 park. ( since the So requisitione now largely estate office are current	buse. C17, C18 and C19, situated in a C17 an Owner's family have lived in the Dower Hous econd World War when the main house was ed and subsequently used as a school. House v unoccupied apart from one wing used as e. Following inheritance by new owner, works dy underway to repair and reuse the south of the house.
	OWNER TYPE:		Contact: Isla	a Macneal 0117 975 0742
	CONDITION:	Remains of medieval buildings, Witchampton Scheduled Monument Poor	the ruins o used as an into a state	uthern side of the village of Witchampton lie f a substantial domestic medieval building. It w agricultural building in C19 but has since falle of disrepair. Scrub/vegetation clearance work place in the past, but is now regenerating.
	OCCUPANCY:			
	PRIORITY:	C (C)		
	OWNER TYPE:	Private	Contact: Sh	nane Gould 0117 975 0671
TE NAME:	Length of	deer park bank and ditch at Alderho	olt, Alderholt	
esignation:	Scheduled	l Monument (No. 1002394)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Extensive	animal burrowing	TREND:	Declining
	Private		CONTACT:	Business Manager 0117 975 0700
WVNER TYPE:			arm Cottages, (	Colehill
DWNER TYPE:	Section of	f Roman Road I 50m south of Park F	0	
		f Roman Road I50m south of Park Fi I Monument (No. 1018028)	CONDITION:	Extensive significant problems i.e. under plough, collapse
ITE NAME:		Monument (No. 1018028)	-	Extensive significant problems

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Barrows in and near St Giles Park, Edmonds	ham	
DESIGNATION:	Scheduled Monument (No. 1002782)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bell barrow 500m north east of Beacon Farr	n, Ferndown Tov	
DESIGNATION:	Scheduled Monument (No. 1015995)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bell barrow known as Belle Vue Barrow, and a bowl barrow 250m north east of Hilla	msland, Ferndow	rn Town
DESIGNATION:	Scheduled Monument (No. 1015994)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 250m west of Ferndown Uppe	r School, Ferndo	wn Town
DESIGNATION:	Scheduled Monument (No. 1015791)	CONDITION:	Generally unsatisfactory
	Deterior is used of more sense		with major localised problems
RINCIPAL VULNERABILITY:	Deterioration – in need of management Utility	TREND:	Declining Business Manager 0117 975 0700
OWNER TYPE:	Gunty	CONTACT:	
SITE NAME:	Barrow near Burtts Harley, Gussage All Saint	S	
DESIGNATION:	Scheduled Monument (No. 1002787)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Barrows in and near The Drive Plantation, G	ussage All Saints	
		ussage All Saints	Extensive significant problems
	<b>Barrows in and near The Drive Plantation, G</b> Scheduled Monument (No. 1002788)	-	Extensive significant problems i.e. under plough, collapse
DESIGNATION:	Scheduled Monument (No. 1002788)	-	Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY:		CONDITION:	i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE: SITE NAME:	Scheduled Monument (No. 1002788) Arable ploughing	CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No. 1002788) Arable ploughing Other	CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1002788) Arable ploughing Other Part of Ackling Dyke (Roman road), including Scheduled Monument (No. 1003309)	CONDITION: TREND: CONTACT: g Roman road or CONDITION:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>Oakley Down, Gussage All Saints</b> Extensive significant problems i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: 5ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1002788) Arable ploughing Other Part of Ackling Dyke (Roman road), including Scheduled Monument (No. 1003309) Arable ploughing	CONDITION: TREND: CONTACT: g Roman road or CONDITION: TREND:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 • Oakley Down, Gussage All Saints Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: 5ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1002788) Arable ploughing Other Part of Ackling Dyke (Roman road), including Scheduled Monument (No. 1003309)	CONDITION: TREND: CONTACT: g Roman road or CONDITION:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>Oakley Down, Gussage All Saints</b> Extensive significant problems i.e. under plough, collapse
designation: Principal vulnerability: Owner type:	Scheduled Monument (No. 1002788) Arable ploughing Other Part of Ackling Dyke (Roman road), including Scheduled Monument (No. 1003309) Arable ploughing	CONDITION: TREND: CONTACT: g Roman road or CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 • Oakley Down, Gussage All Saints Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1002788)         Arable ploughing         Other         Part of Ackling Dyke (Roman road), including         Scheduled Monument (No. 1003309)         Arable ploughing         Other	CONDITION: TREND: CONTACT: g Roman road or CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>Oakley Down, Gussage All Saints</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME:	Scheduled Monument (No. 1002788)         Arable ploughing         Other         Part of Ackling Dyke (Roman road), including         Scheduled Monument (No. 1003309)         Arable ploughing         Other         Barrow on Parsonage Hill, Gussage St Michae         Scheduled Monument (No. 1002783)	CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>Oakley Down, Gussage All Saints</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1002788)         Arable ploughing         Other         Part of Ackling Dyke (Roman road), including         Scheduled Monument (No. 1003309)         Arable ploughing         Other         Barrow on Parsonage Hill, Gussage St Michaelee	CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>Oakley Down, Gussage All Saints</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Earthworks on Gussage Down, Gussage St	Michael	
DESIGNATION:	Scheduled Monument (No. 1002740)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Long mound 1500yds (1370m) east of High	er Farm, Gussage	St Michael
DESIGNATION:	Scheduled Monument (No. 1002784)	CONDITION:	Generally satisfactory
	``````````````````````````````````````		but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrows near Thickthorn Farm, Gus	sage St Michael	
DESIGNATION:	Scheduled Monument (No. 1002816)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two barrows near Ackling Dyke, Gussage S	t Michael	
			Extensive significant problems
DESIGNATION:	Scheduled Monument (No. 1002786)	CONDITION:	Extensive significant problems
	Ample playshing	70010	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing Other	TREND:	Declining Business Manager 0117 975 0700
OWNER TIPE	Ourci	CONTACT:	
SITE NAME:	Two long barrows on Gussage Hill, Gussage	e St Michael	
designation:	Scheduled Monument (No. 1002707)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two round barrows on Gussage Down, Gu	ssage St Michael	
DESIGNATION:	Scheduled Monument (No. 1002741)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow north west of High Lea Farr	n, Hinton Martell	
DESIGNATION:	Scheduled Monument (No. 1004552)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
			~
SITE NAME:	Bowl barrow on Summerlug Hill 250m sour	th of Mannington	
	Scheduled Monument (No. 1018199)	CONDITION:	Generally unsatisfactory
DESIGNATION:	Scheduled Hohament (140. 1010177)		with major localized problems
			with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scrub / tree growth Private	TREND: CONTACT:	with major localised problems Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Bull Barrow on Holt Heath, Holt		
DESIGNATION:	Scheduled Monument (No. 1018198)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow cemetery and a cross dyke or	n Horton Commo	on 800m south of Bridge Farm, Horton
DESIGNATION:	Scheduled Monument (No. 1018411)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 250m north west of Veiny Ch	eese Pond, Long (	Crichel
DESIGNATION:	Scheduled Monument (No. 1015191)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Disc barrow and a bowl barrow 640m sout	th west of Veiny C	-
DESIGNATION:	Scheduled Monument (No. 1020444)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two bowl barrows 165m west of Veiny Che	eese Pond, Long C	richel
SITE NAME: DESIGNATION:	Two bowl barrows 165m west of Veiny Che Scheduled Monument (No. 1015785)	condition:	richel Extensive significant problems i.e. under plough, collapse
DESIGNATION:	•	-	Extensive significant problems
	Scheduled Monument (No. 1015785)	CONDITION:	Extensive significant problems i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1015785) Arable ploughing	CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE:	Scheduled Monument (No. 1015785) Arable ploughing Other	CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1015785) Arable ploughing Other Bradford Barrow, Pamphill Scheduled Monument (No. 1002713)	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No. 1015785) Arable ploughing Other Bradford Barrow, Pamphill	CONDITION: TREND: CONTACT: CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1015785) Arable ploughing Other Bradford Barrow, Pamphill Scheduled Monument (No. 1002713) Extensive animal burrowing	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE:	Scheduled Monument (No. 1015785) Arable ploughing Other Bradford Barrow, Pamphill Scheduled Monument (No. 1002713) Extensive animal burrowing Private	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 art of the 'Bokerley Line', Pentridge Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DSITE NAME: DESIGNATION: DESIGNATION:	Scheduled Monument (No. 1015785)         Arable ploughing         Other         Bradford Barrow, Pamphill         Scheduled Monument (No. 1002713)         Extensive animal burrowing         Private         A linear earthwork north east of West Wo         Scheduled Monument (No. 1012138)	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: Odyates Manor: pa	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Art of the 'Bokerley Line', Pentridge Extensive significant problems i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1015785)         Arable ploughing         Other         Bradford Barrow, Pamphill         Scheduled Monument (No. 1002713)         Extensive animal burrowing         Private         A linear earthwork north east of West Wo	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: Odyates Manor: pa CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Art of the 'Bokerley Line', Pentridge Extensive significant problems i.e. under plough, collapse Unknown
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DSITE NAME: DESIGNATION: DESIGNATION:	Scheduled Monument (No. 1015785)         Arable ploughing         Other         Bradford Barrow, Pamphill         Scheduled Monument (No. 1002713)         Extensive animal burrowing         Private         A linear earthwork north east of West Wo         Scheduled Monument (No. 1012138)         Arable ploughing	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: Odyates Manor: pa	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Art of the 'Bokerley Line', Pentridge Extensive significant problems i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1015785)         Arable ploughing         Other         Bradford Barrow, Pamphill         Scheduled Monument (No. 1002713)         Extensive animal burrowing         Private         A linear earthwork north east of West Wo         Scheduled Monument (No. 1012138)         Arable ploughing	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: Odyates Manor: pa CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Art of the 'Bokerley Line', Pentridge Extensive significant problems i.e. under plough, collapse Unknown
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE	Scheduled Monument (No. 1015785)         Arable ploughing         Other         Bradford Barrow, Pamphill         Scheduled Monument (No. 1002713)         Extensive animal burrowing         Private         A linear earthwork north east of West Wo         Scheduled Monument (No. 1012138)         Arable ploughing         Private	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: Odyates Manor: pa CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Art of the 'Bokerley Line', Pentridge Extensive significant problems i.e. under plough, collapse Unknown
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION:	Scheduled Monument (No. 1015785)         Arable ploughing         Other         Bradford Barrow, Pamphill         Scheduled Monument (No. 1002713)         Extensive animal burrowing         Private         A linear earthwork north east of West Wo         Scheduled Monument (No. 1012138)         A linear earthwork north east of West Wo         Scheduled Monument (No. 1012138)         Arable ploughing         Private         Barrow west of village, Pentridge	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Art of the 'Bokerley Line', Pentridge Extensive significant problems i.e. under plough, collapse Unknown Business Manager 0117 975 0700 Extensive significant problems

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Barrows in Salisbury Plantation, Pentridge		
ESIGNATION:	Scheduled Monument (No. 1002817)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
WNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Celtic fields on Pentridge Down, Pentridge		
DESIGNATION:	Scheduled Monument (No. 1002796)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
WNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Long barrows and group of round barrows	on Bokerly Dowr	n, Pentridge
DESIGNATION:	Scheduled Monument (No. 1002722)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Part of Dorset Cursus, Pentridge		
DESIGNATION:	Scheduled Monument (No. 1003222)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Roman fort at Crab Farm, Shapwick		
DESIGNATION:	Scheduled Monument (No. 1002372)	CONDITION:	Extensive significant problems
	· · · · · · · · · · · · · · · · · · ·		i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Camp in Mistlebury Wood, Sixpenny Handle	ÿ	
DESIGNATION:	Scheduled Monument (No. 1002455)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Enclosure south of Humby's Stock Coppice	Sixpenny Handle	у
			Extensive significant problems
	Scheduled Monument (No. 1005575)	CONDITION:	- · ·
esignation:	Scheduled Monument (No. 1005575) Arable ploughing	CONDITION: TREND:	i.e. under plough, collapse Declining
ESIGNATION: RINCIPAL VULNERABILITY:			i.e. under plough, collapse
DESIGNATION: RINCIPAL VULNERABILITY: WWNER TYPE:	Arable ploughing Other	TREND: CONTACT:	i.e. under plough, collapse Declining
DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Arable ploughing	trend: contact: <b>y Park,</b>	i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Arable ploughing Other Three bowl barrows in Avon Heath Countr	trend: contact: <b>y Park,</b>	i.e. under plough, collapse Declining Business Manager 0117 975 0700 : Leonards and St Ives Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME:	Arable ploughing Other Three bowl barrows in Avon Heath Countr two 620m and one 700m north west of Ma	trend: contact: y Park, tcham's House, St	i.e. under plough, collapse Declining Business Manager 0117 975 0700

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Stephen's Castle, a bowl barrow 720m east	of Eastworth Far	m, Verwood
DESIGNATION:	Scheduled Monument (No. 1021148)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Parley Barrow, a bowl barrow on the corne	r of Ellesfield Dri	ve and Druid's Close, West Parley
DESIGNATION:	Scheduled Monument (No. 1015792)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Barrow 30yds (27m) east of Dorset Cursus	s, Wimborne St G	iles
DESIGNATION:	Scheduled Monument (No. 1002793)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Parts of Dorset Cursus on Bottlebush Dow	vn, Wimborne St	Giles
DESIGNATION:	Scheduled Monument (No. 1002799)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Improving
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two round barrows south of Cranborne Fa	rm. Wimborne St	Giles
		,	
DESIGNATION:	Scheduled Monument (No. 1002459)	CONDITION:	Generally unsatisfactory with major localised problems
			Generally unsatisfactory
PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1002459)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1002459) Arable clipping	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1002459) Arable clipping Other	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1002459) Arable clipping Other Bowl barrow 250m north east of Monmout	CONDITION: TREND: CONTACT: th's Ash Farm, Wo	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 odlands Generally unsatisfactory
PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1002459) Arable clipping Other Bowl barrow 250m north east of Monmout Scheduled Monument (No. 1016093)	CONDITION: TREND: CONTACT: th's Ash Farm, Wo CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 odlands Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1002459) Arable clipping Other Bowl barrow 250m north east of Monmout Scheduled Monument (No. 1016093) Mineral extraction / related subsidence	CONDITION: TREND: CONTACT: th's Ash Farm, Wo CONDITION: TREND: CONTACT: group of round b	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 odlands Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:	Scheduled Monument (No. 1002459) Arable clipping Other Bowl barrow 250m north east of Monmout Scheduled Monument (No. 1016093) Mineral extraction / related subsidence Private Group of henge monuments, an associated	CONDITION: TREND: CONTACT: th's Ash Farm, Wo CONDITION: TREND: CONTACT: group of round b	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 odlands Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1002459)         Arable clipping         Other         Bowl barrow 250m north east of Monmout         Scheduled Monument (No. 1016093)         Mineral extraction / related subsidence         Private         Group of henge monuments, an associated a Saxon cemetery, and a Norman church at	CONDITION: TREND: CONTACT: th's Ash Farm, Wo CONDITION: TREND: CONTACT: group of round ba Knowlton, Wood	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 odlands Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 arrows, Ilands Extensive significant problems i.e. under plough, collapse Declining
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: WINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1002459)         Arable clipping         Other         Bowl barrow 250m north east of Monmout         Scheduled Monument (No. 1016093)         Mineral extraction / related subsidence         Private         Group of henge monuments, an associated a Saxon cemetery, and a Norman church at Scheduled Monument (No. 1020580)	CONDITION: TREND: CONTACT: contact: condition: TREND: CONTACT: group of round bi Knowlton, Wood	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 odlands Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 arrows, llands Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: OWNER TYPE:	Scheduled Monument (No. 1002459)         Arable clipping         Other         Bowl barrow 250m north east of Monmout         Scheduled Monument (No. 1016093)         Mineral extraction / related subsidence         Private         Group of henge monuments, an associated a Saxon cemetery, and a Norman church at Scheduled Monument (No. 1020580)         Arable ploughing	CONDITION: TREND: CONTACT: contact: condition: TREND: CONTACT: group of round bi Knowlton, Wood CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 odlands Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 arrows, Ilands Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1002459)         Arable clipping         Other         Bowl barrow 250m north east of Monmout         Scheduled Monument (No. 1016093)         Mineral extraction / related subsidence         Private         Group of henge monuments, an associated a Saxon cemetery, and a Norman church at Scheduled Monument (No. 1020580)         Arable ploughing         Private	CONDITION: TREND: CONTACT: contact: condition: TREND: CONTACT: group of round bi Knowlton, Wood CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 odlands Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 arrows, Ilands Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1002459)         Arable clipping         Other         Bowl barrow 250m north east of Monmout         Scheduled Monument (No. 1016093)         Mineral extraction / related subsidence         Private         Group of henge monuments, an associated a Saxon cemetery, and a Norman church at Scheduled Monument (No. 1020580)         Arable ploughing         Private         Round barrow cemetery south of New Bar	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONTACT: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 odlands Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 d with the Knowlton Circles, Woodlands Extensive significant problems

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

### HERITAGE AT RISK 2011 / SOUTH WEST / EAST DORSET / NORTH DORSET

SITE NAME: St Giles' House, Wimborne St. Giles Wimborne St. Giles Wimborne St. Giles St Giles St Giles Wimborne St. Giles St Gile	risk.
DESIGNATION: Registered Park and Garden Grade II*, The structural elements of the park design survive in	n
also part in CA, 7 LBs, 12 SMs moderate condition but the majority of the park is in arable cultivation. In 2010, Natural England grant-aide	in Iod
CONDITION: Extensive significant problems a plan for the park and it is hoped that a programm	eu 1e
CONDITION: Extensive significant problems VULNERABILITY: Medium of restoration will commence in 2011.	
TREND: Stable	
OWNERTYPE Private, single owner Contact: Kim Auston 0117 975 0696	

### Ν

NORTH DORSET				
	SITE NAME:	Sturminster Newton Castle, Sturminster Newton	within Sturn Age promo Upstanding	f C14 stone built manor house stand ninster Newton Castle, a probable Iron ntory fort overlooking the River Stour. remains in very precarious position trable amount of consolidation work
1. 网络小松		Scheduled Monument	is urgently n	equired to avoid significant areas of
	CONDITION:	Very bad	collapse. Eng	glish Heritage architectural survey team
and and changes and the second	OCCUPANCY:		has recorde	d the structure.
and the second s	PRIORITY:	C (C)		
and a state of the	OWNER TYPE:	Private	Contact: Sha	ane Gould 0117 975 0671
	SITE NAME:	Barn and outbuilding range, Tarrant Abbey Farm, Tarrant Crawford	No longer i	ith CI8 outbuildings and alterations. n agricultural use. Works have recently taken to support the structure.
Notes and a second	DESIGNATION:	Listed Building Grade II*, SM		
ALL DE L	CONDITION:	Very bad		
	OCCUPANCY:	N/A		
	PRIORITY:	С (С)		
	OWNER TYPE:	Private	Contact: Sha	ane Gould 0117 975 0671
	SITE NAME:	Manor Farm barn, Winterborne Clenston	The hamme a monastic l	I 6 tithe barn part used for storage. Ir beam roof may have been reused from building at Milton Abbey. Partial roof collapse
	DESIGNATION:	Listed Building Grade I, SM		I in English Heritage funding the erection
	CONDITION:	Very bad	OF SCATIOIUIT	g as a temporary roof support.
	OCCUPANCY:			
	PRIORITY:	С (С)		
	OWNER TYPE:		Contact: Sha	ane Gould 0117 975 0671
	SITE NAME:	St Mary Magdalen, Fifehead Magdelen	with C17 or restored in chancel roo	4 parish church on the edge of the village, r C18 north chapel. The church was extensively 1904. Repairs have been undertaken to south f, but the fixings to the stone tiles on the pofs appear to be progressively failing.
	DESIGNATION:	Listed Place of Worship Grade II, CA	A Repair Gr	rant for Places of Worship has been offered
	CONDITION:	Poor	for roof rep	airs.
	PRIORITY:	B (New entry)		
and the second	OWNER TYPE:	Religious organisation	Contact: Sar	rah Ball 0117 975 0666
SITE NAME:	Linear bo	undary 870m south west of Spring Farr	n. Ashmore	
DESIGNATION:	Scheduled	Monument (No. 1020729)	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	bughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Linear bou	undary and section of Roman road, 550	)m south east	t of Ashmore Farm, Ashmore
DESIGNATION:	Scheduled	Monument (No. 1020728)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable plo Private	ughing	TREND: CONTACT:	Declining Business Manager 0117 975 0700

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Concentration

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ITE NAME:	St Leonard's Chapel, Blandford Forum		
DESIGNATION:	Scheduled Monument (No. 1002726)	CONDITION:	Generally satisfactory
			but with significant localised problems
RINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Field system in Old Park, Bryanston		
DESIGNATION:	Scheduled Monument (No. 1002427)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 1020m south east of Chariswo	rth Cottages, Ch	arlton Marshall
DESIGNATION:	Scheduled Monument (No. 1014846)	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 350m south of Gorcombe Farr	n. Charlton Mars	shall
DESIGNATION:	Scheduled Monument (No. 1014848)	CONDITION:	Extensive significant problems
	Arable ploughing		i.e. under plough, collapse Decliping
RINCIPAL VULNERABILITY:	Arable ploughing Other	TREND:	Declining
OWNER TYPE:		CONTACT:	Business Manager UTT / 773 U/UU
DWNER TYPE:	Othe	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 500m south west of Gorcomb	e Farm, Charlton	Marshall
	<b>Bowl barrow 500m south west of Gorcomb</b> Scheduled Monument (No. 1014847)		Marshall Extensive significant problems i.e. under plough, collapse
ITE NAME: DESIGNATION:	<b>Bowl barrow 500m south west of Gorcomb</b> Scheduled Monument (No. 1014847) Arable ploughing	e Farm, Charlton	Marshall Extensive significant problems i.e. under plough, collapse Declining
ITE NAME:	<b>Bowl barrow 500m south west of Gorcomb</b> Scheduled Monument (No. 1014847)	e Farm, Charlton	Marshall Extensive significant problems i.e. under plough, collapse
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	<b>Bowl barrow 500m south west of Gorcomb</b> Scheduled Monument (No. 1014847) Arable ploughing	e Farm, Charlton Condition: Trend: Contact:	Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Bowl barrow 500m south west of Gorcomb Scheduled Monument (No. 1014847) Arable ploughing Other	e Farm, Charlton Condition: Trend: Contact:	Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Marshall Extensive significant problems
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Bowl barrow 500m south west of Gorcombe         Scheduled Monument (No. 1014847)         Arable ploughing         Other         Bowl barrow 650m south west of Gorcombe         Scheduled Monument (No. 1014849)	e Farm, Charlton Condition: Trend: Contact: e Farm, Charlton	Marshall         Extensive significant problems         i.e. under plough, collapse         Declining         Business Manager 0117 975 0700    Marshall Extensive significant problems i.e. under plough, collapse
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION:	Bowl barrow 500m south west of Gorcomb Scheduled Monument (No. 1014847) Arable ploughing Other Bowl barrow 650m south west of Gorcomb	E Farm, Charlton CONDITION: TREND: CONTACT: E Farm, Charlton CONDITION:	Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Marshall Extensive significant problems
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Bowl barrow 500m south west of Gorcombe         Scheduled Monument (No. 1014847)         Arable ploughing         Other         Bowl barrow 650m south west of Gorcombe         Scheduled Monument (No. 1014849)         Arable ploughing	E Farm, Charlton CONDITION: TREND: CONTACT: E Farm, Charlton CONDITION: TREND: CONTACT:	Marshall         Extensive significant problems         i.e. under plough, collapse         Declining         Business Manager 0117 975 0700         Marshall         Extensive significant problems         i.e. under plough, collapse         Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Bowl barrow 500m south west of Gorcombe         Scheduled Monument (No. 1014847)         Arable ploughing         Other         Bowl barrow 650m south west of Gorcombe         Scheduled Monument (No. 1014849)         Arable ploughing         Other	E Farm, Charlton CONDITION: TREND: CONTACT: E Farm, Charlton CONDITION: TREND: CONTACT:	Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  Generally unsatisfactory
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Bowl barrow 500m south west of Gorcombe         Scheduled Monument (No. 1014847)         Arable ploughing         Other         Bowl barrow 650m south west of Gorcombe         Scheduled Monument (No. 1014849)         Arable ploughing         Other         Long barrow 360m SSW of Chettle House, O         Scheduled Monument (No. 1013792)	e Farm, Charlton CONDITION: TREND: CONTACT: e Farm, Charlton CONDITION: TREND: CONTACT: CONTACT:	Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: WINER TYPE: ITE NAME: DESIGNATION:	Bowl barrow 500m south west of Gorcomb         Scheduled Monument (No. 1014847)         Arable ploughing         Other         Bowl barrow 650m south west of Gorcomb         Scheduled Monument (No. 1014849)         Arable ploughing         Other         Long barrow 360m SSW of Chettle House, Comb	E Farm, Charlton CONDITION: TREND: CONTACT: E Farm, Charlton CONDITION: TREND: CONTACT: CONTACT:	Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY:	Bowl barrow 500m south west of Gorcomb         Scheduled Monument (No. 1014847)         Arable ploughing         Other         Bowl barrow 650m south west of Gorcomb         Scheduled Monument (No. 1014849)         Arable ploughing         Other         Long barrow 360m SSW of Chettle House, O         Scheduled Monument (No. 1013792)         Arable clipping	E Farm, Charlton CONDITION: TREND: CONTACT: E Farm, Charlton CONDITION: TREND: CONTACT: CONTACT: TREND: CONDITION:	Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY:	Bowl barrow 500m south west of Gorcombil         Scheduled Monument (No. 1014847)         Arable ploughing         Other         Bowl barrow 650m south west of Gorcombil         Scheduled Monument (No. 1014849)         Arable ploughing         Other         Long barrow 360m SSW of Chettle House, O         Scheduled Monument (No. 1013792)         Arable clipping         Other         Causewayed camp on Hambledon Hill, Child	E Farm, Charlton CONDITION: TREND: CONTACT: E Farm, Charlton CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION:	Marshall         Extensive significant problems         i.e. under plough, collapse         Declining         Business Manager 0117 975 0700         Marshall         Extensive significant problems         i.e. under plough, collapse         Declining         Business Manager 0117 975 0700         Generally unsatisfactory         with major localised problems         Declining         Business Manager 0117 975 0700
ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE:	Bowl barrow 500m south west of Gorcomb         Scheduled Monument (No. 1014847)         Arable ploughing         Other         Bowl barrow 650m south west of Gorcomb         Scheduled Monument (No. 1014849)         Arable ploughing         Other         Long barrow 360m SSW of Chettle House, C         Scheduled Monument (No. 1013792)         Arable clipping         Other	E Farm, Charlton CONDITION: TREND: CONTACT: E Farm, Charlton CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION:	Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Bowl barrow 500m south west of Gorcombil         Scheduled Monument (No. 1014847)         Arable ploughing         Other         Bowl barrow 650m south west of Gorcombil         Scheduled Monument (No. 1014849)         Arable ploughing         Other         Long barrow 360m SSW of Chettle House, O         Scheduled Monument (No. 1013792)         Arable clipping         Other         Causewayed camp on Hambledon Hill, Child	E Farm, Charlton CONDITION: TREND: CONTACT: E Farm, Charlton CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION: CONDITION:	Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  Marshall Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

ITE NAME:	Longbury long barrow 600m north west of S	Slaughtergate Far	m, Gillingham
DESIGNATION:	Scheduled Monument (No. 1013680)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Bowl barrow known as Folly Barrow, Iwerne	Minster	
DESIGNATION:	Scheduled Monument (No. 1020030)		Generally unsatisfactory
ESIGNATION:	Scheduled Hohument (140, 1020050)	CONDITION:	with major localised problems
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Bowl barrow 480m south east of West End	Barn, Milborne S	t Andrew
DESIGNATION:	Scheduled Monument (No. 1014855)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Bowl barrow 70m south east of West End B	arn, Milborne St	Andrew
DESIGNATION:	Scheduled Monument (No. 1014854)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNER TYPE:	Other Stable Barrow 230m NNE of Frogmore Farm	contact: n, Milborne St Ar	Business Manager 0117 975 0700
DWNER TYPE: ITE NAME:			ndrew Generally unsatisfactory
WNER TYPE: TE NAME: ESIGNATION:	Stable Barrow 230m NNE of Frogmore Farr	n, Milborne St Ar	ndrew
WINER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Stable Barrow 230m NNE of Frogmore Farm Scheduled Monument (No. 1014761)	n, Milborne St Ar	ndrew Generally unsatisfactory with major localised problems
DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	<b>Stable Barrow 230m NNE of Frogmore Farm</b> Scheduled Monument (No. 1014761) Arable ploughing	n, Milborne St Ar condition: trend: contact:	ndrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
WINER TYPE: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WINER TYPE: TE NAME:	Stable Barrow 230m NNE of Frogmore Farm Scheduled Monument (No. 1014761) Arable ploughing Other	n, Milborne St Ar condition: trend: contact:	ndrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 St Andrew Extensive significant problems
WINER TYPE: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WINER TYPE: TE NAME: ESIGNATION:	Stable Barrow 230m NNE of Frogmore Farm         Scheduled Monument (No. 1014761)         Arable ploughing         Other         Three bowl barrows 380m west of West En         Scheduled Monument (No. 1015031)	n, Milborne St Ar condition: trend: contact: d Barn, Milborne condition:	ndrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 St Andrew Extensive significant problems i.e. under plough, collapse
WINER TYPE: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WINER TYPE: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY:	Stable Barrow 230m NNE of Frogmore Farm         Scheduled Monument (No. 1014761)         Arable ploughing         Other         Three bowl barrows 380m west of West En         Scheduled Monument (No. 1015031)         Arable ploughing	n, Milborne St Ar CONDITION: TREND: CONTACT: d Barn, Milborne CONDITION: TREND:	Adrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 St Andrew Extensive significant problems i.e. under plough, collapse Declining
DWNER TYPE:	Stable Barrow 230m NNE of Frogmore Farm         Scheduled Monument (No. 1014761)         Arable ploughing         Other         Three bowl barrows 380m west of West En         Scheduled Monument (No. 1015031)	n, Milborne St Ar condition: trend: contact: d Barn, Milborne condition:	ndrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 St Andrew Extensive significant problems i.e. under plough, collapse
DWNER TYPE:	Stable Barrow 230m NNE of Frogmore Farm         Scheduled Monument (No. 1014761)         Arable ploughing         Other         Three bowl barrows 380m west of West En         Scheduled Monument (No. 1015031)         Arable ploughing	n, Milborne St Ar CONDITION: TREND: CONTACT: d Barn, Milborne CONDITION: TREND: CONTACT: Dm and 585m	Adrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 St Andrew Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DWNER TYPE:         ITE NAME:         DESIGNATION:         RINCIPAL VULNERABILITY:         DWNER TYPE:         ITE NAME:         DESIGNATION:         RINCIPAL VULNERABILITY:         DWNER TYPE:         ITE NAME:         DESIGNATION:         DWNER TYPE:         ITE NAME:         DWNER TYPE:	Stable Barrow 230m NNE of Frogmore Farm         Scheduled Monument (No. 1014761)         Arable ploughing         Other         Three bowl barrows 380m west of West En         Scheduled Monument (No. 1015031)         Arable ploughing         Other	n, Milborne St Ar CONDITION: TREND: CONTACT: d Barn, Milborne CONDITION: TREND: CONTACT: Dm and 585m	Adrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 St Andrew Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
WINER TYPE:	Stable Barrow 230m NNE of Frogmore Farm         Scheduled Monument (No. 1014761)         Arable ploughing         Other         Three bowl barrows 380m west of West En         Scheduled Monument (No. 1015031)         Arable ploughing         Other         Three bowl barrows on Milborne Down 520 north east of obelisk on Weatherby Castle her	n, Milborne St Ar CONDITION: TREND: CONTACT: d Barn, Milborne CONDITION: TREND: CONTACT: Om and 585m illfort, Milborne	Adrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 St Andrew Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 St Andrew Extensive significant problems
DWNER TYPE:	Stable Barrow 230m NNE of Frogmore Farm         Scheduled Monument (No. 1014761)         Arable ploughing         Other         Three bowl barrows 380m west of West En         Scheduled Monument (No. 1015031)         Arable ploughing         Other         Three bowl barrows on Milborne Down 520 north east of obelisk on Weatherby Castle for Scheduled Monument (No. 1019364)	n, Milborne St Ar CONDITION: TREND: CONTACT: d Barn, Milborne CONDITION: TREND: CONTACT: Dm and 585m illfort, Milborne CONDITION:	Adrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  St Andrew Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  St Andrew Extensive significant problems i.e. under plough, collapse
DWNER TYPE:	Stable Barrow 230m NNE of Frogmore Farm         Scheduled Monument (No. 1014761)         Arable ploughing         Other         Three bowl barrows 380m west of West En         Scheduled Monument (No. 1015031)         Arable ploughing         Other         Three bowl barrows on Milborne Down 520         Other         Scheduled Monument (No. 1019364)         Arable ploughing         Other	n, Milborne St Ar CONDITION: TREND: CONTACT: d Barn, Milborne CONDITION: TREND: CONTACT: 0m and 585m illfort, Milborne CONDITION: TREND: CONDITION:	Adrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 St Andrew Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 St Andrew Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DWNER TYPE:	Stable Barrow 230m NNE of Frogmore Farm         Scheduled Monument (No. 1014761)         Arable ploughing         Other         Three bowl barrows 380m west of West En         Scheduled Monument (No. 1015031)         Arable ploughing         Other         Three bowl barrows on Milborne Down 520         Arable ploughing         Other         Arable ploughing         Other         Arable ploughing         Arable ploughing         Other         Arable ploughing         Private	n, Milborne St Ar CONDITION: TREND: CONTACT: d Barn, Milborne CONDITION: TREND: CONTACT: 0m and 585m illfort, Milborne CONDITION: TREND: CONDITION:	Adrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  St Andrew Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  St Andrew Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  THaywards Farm, Milborne St Andrew Extensive significant problems
DWNER TYPE:	Stable Barrow 230m NNE of Frogmore Farm         Scheduled Monument (No. 1014761)         Arable ploughing         Other         Three bowl barrows 380m west of West En         Scheduled Monument (No. 1015031)         Arable ploughing         Other         Three bowl barrows on Milborne Down 520         north east of obelisk on Weatherby Castle h         Scheduled Monument (No. 1019364)         Arable ploughing         Private         Two bowl barrows and two ring ditches 450	n, Milborne St Ar CONDITION: TREND: CONTACT: d Barn, Milborne CONDITION: TREND: CONTACT: 0m and 585m illfort, Milborne CONDITION: TREND: CONDITION: TREND: CONTACT: m north west of	Adrew Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  St Andrew Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  St Andrew  Thaywards Farm, Milborne St Andrew

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ITE NAME:	Weatherby Castle, an Iron Age hillfort 1020n	n north west of A	Ashley Barn Farm, Milborne St Andrew
DESIGNATION:	Scheduled Monument (No. 1019360)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Enclosure south of Pimperne Down, Pimpern	ne	
DESIGNATION:	Scheduled Monument (No. 1002860)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Site of St John's Church, Shaftesbury		
DESIGNATION:	Scheduled Monument (No. 1005580)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Crawford Castle (or Spetisbury Rings), Speti	sbury	
DESIGNATION:	Scheduled Monument (No. 1004563)	CONDITION:	Generally satisfactory
			but with significant localised problems
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Chapel west of Manor Farm, Stourton Caun	dle	
DESIGNATION:	Scheduled Monument (No. 1002857)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Slight univallate hillfort 850m north east of E	Busseys Stool Far	m,Tarrant Gunville
DESIGNATION:	Scheduled Monument (No. 1020611)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 200m south east of Pimperne	Long Barrow, Tar	rant Hinton
DESIGNATION:	Scheduled Monument (No. 1013794)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric habitation site between north an	d south Hinton [	Downs, Tarrant Hinton
DESIGNATION:	Scheduled Monument (No. 1003235)	CONDITION:	Extensive significant problems
			i.e. under plougn, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	i.e. under plough, collapse Declining

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ITE NAME:	Roman villa on Little Barton Hill,Tarrant Hi	inton	
DESIGNATION:	Scheduled Monument (No. 1002424)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 350m south west of Buzbury	Rings, Tarrant Key	rneston
DESIGNATION:	Scheduled Monument (No. 1013789)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Buzbury Rings, Tarrant Keyneston		
DESIGNATION:	Scheduled Monument (No. 1002718)	CONDITION:	Extensive significant problems
	`````		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Roman enclosure on Keyneston Down,Tari	rant Kevneston	
DESIGNATION:	Scheduled Monument (No. 1002373)	•	Extensive significant problems
JESIGNATION:	Scheduled Monument (No. 1002375)	CONDITION:	i.e. under plough, collapse
	Arable plaughing		
	Arable ploughing Other	TREND:	Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: DWNER TYPE:	Arable ploughing Other	TREND: CONTACT:	Business Manager 0117 975 0700
	Other Bowl barrow 600m south of Plantation Farm	CONTACT:	Business Manager 0117 975 0700
DWNER TYPE:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190)	CONTACT:	Business Manager 0117 975 0700
DWNER TYPE: ITE NAME: DESIGNATION:	Other Bowl barrow 600m south of Plantation Farm	CONTACT: m, Tarrant Launces	Business Manager 0117 975 0700 ston Generally unsatisfactory with major localised problems Declining
DWNER TYPE:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190)	CONTACT: m, Tarrant Launce: CONDITION:	Business Manager 0117 975 0700 ston Generally unsatisfactory with major localised problems
DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190) Arable clipping	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 ston Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DWNER TYPE:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190) Arable clipping Other	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 ston Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 n Generally unsatisfactory
DWNER TYPE:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190) Arable clipping Other Bowl barrow 700m south of Old Turnpike, Scheduled Monument (No. 1015192)	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto	Business Manager 0117 975 0700  ston Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  n Generally unsatisfactory with major localised problems
DWNER TYPE:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190) Arable clipping Other Bowl barrow 700m south of Old Turnpike, Scheduled Monument (No. 1015192) Arable clipping	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto	Business Manager 0117 975 0700 ston Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 n Generally unsatisfactory with major localised problems Declining
DWNER TYPE:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190) Arable clipping Other Bowl barrow 700m south of Old Turnpike, Scheduled Monument (No. 1015192)	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto CONDITION:	Business Manager 0117 975 0700  ston Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  n Generally unsatisfactory with major localised problems
DWNER TYPE: SITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190) Arable clipping Other Bowl barrow 700m south of Old Turnpike, Scheduled Monument (No. 1015192) Arable clipping	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 ston Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 n Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DWNER TYPE:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190) Arable clipping Other Bowl barrow 700m south of Old Turnpike, Scheduled Monument (No. 1015192) Arable clipping Other	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700  ston Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  n Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Rawston Extensive significant problems
DWNER TYPE:	Other         Bowl barrow 600m south of Plantation Farm         Scheduled Monument (No. 1015190)         Arable clipping         Other         Bowl barrow 700m south of Old Turnpike,         Scheduled Monument (No. 1015192)         Arable clipping         Other         Bowl barrow 700m south of Old Turnpike,         Scheduled Monument (No. 1015192)         Arable clipping         Other         Bowl barrow on The Cliff 680m east of Lut         Scheduled Monument (No. 1015187)	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto CONDITION: TREND: CONTACT: TREND: CONTACT:	Business Manager 0117 975 0700 Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Kawston
DWNER TYPE:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190) Arable clipping Other Bowl barrow 700m south of Old Turnpike, Scheduled Monument (No. 1015192) Arable clipping Other Bowl barrow on The Cliff 680m east of Lut	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto CONDITION: TREND: CONTACT: ON Farm, Tarrant P	Business Manager 0117 975 0700  Ston Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Carrow Ca
DWNER TYPE:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190) Arable clipping Other Bowl barrow 700m south of Old Turnpike, Scheduled Monument (No. 1015192) Arable clipping Other Bowl barrow on The Cliff 680m east of Lut Scheduled Monument (No. 1015187) Arable ploughing	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto CONDITION: TREND: CONTACT: TREND: CONDITION: TREND: CONDITION:	Business Manager 0117 975 0700  Ston Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Kawston Extensive significant problems i.e. under plough, collapse
DWNER TYPE:	Other         Bowl barrow 600m south of Plantation Farm         Scheduled Monument (No. 1015190)         Arable clipping         Other         Bowl barrow 700m south of Old Turnpike,         Scheduled Monument (No. 1015192)         Arable clipping         Other         Bowl barrow 700m south of Old Turnpike,         Scheduled Monument (No. 1015192)         Arable clipping         Other         Bowl barrow on The Cliff 680m east of Lut         Scheduled Monument (No. 1015187)         Arable ploughing         Other         Bowl barrow on The Cliff 680m NNVV of S	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto CONDITION: TREND: CONTACT: ON Farm, Tarrant I CONDITION: TREND: CONDITION:	Business Manager 0117 975 0700 Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DWNER TYPE:	Other Bowl barrow 600m south of Plantation Farm Scheduled Monument (No. 1015190) Arable clipping Other Bowl barrow 700m south of Old Turnpike, Scheduled Monument (No. 1015192) Arable clipping Other Bowl barrow on The Cliff 680m east of Lutt Scheduled Monument (No. 1015187) Arable ploughing Other	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto CONDITION: TREND: CONTACT: ON Farm, Tarrant I CONDITION: TREND: CONDITION:	Business Manager 0117 975 0700  Ston  Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  Extensive significant problems Declining Business Manager 0117 975 0700 Extensive significant problems Extensive significant problems Extensive significant problems Extensive significant problems
DWNER TYPE:	Other         Bowl barrow 600m south of Plantation Farm         Scheduled Monument (No. 1015190)         Arable clipping         Other         Bowl barrow 700m south of Old Turnpike,         Scheduled Monument (No. 1015192)         Arable clipping         Other         Bowl barrow on The Cliff 680m east of Lut         Scheduled Monument (No. 1015187)         Arable ploughing         Other         Bowl barrow on The Cliff 680m NNVV of S         Scheduled Monument (No. 1015187)	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: CONDITION:	Business Manager 0117 975 0700  Ston Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  Extensive significant problems i.e. under plough, collapse Extensive significant problems Extensive significant problems Business Manager 0117 975 0700
DWNER TYPE:	Other         Bowl barrow 600m south of Plantation Farm         Scheduled Monument (No. 1015190)         Arable clipping         Other         Bowl barrow 700m south of Old Turnpike,         Scheduled Monument (No. 1015192)         Arable clipping         Other         Bowl barrow 700m south of Old Turnpike,         Scheduled Monument (No. 1015192)         Arable clipping         Other         Bowl barrow on The Cliff 680m east of Lut         Scheduled Monument (No. 1015187)         Arable ploughing         Other         Bowl barrow on The Cliff 680m NNVV of S	CONTACT: m, Tarrant Launces CONDITION: TREND: CONTACT: Tarrant Launcesto CONDITION: TREND: CONTACT: ON Farm, Tarrant I CONDITION: TREND: CONDITION: TREND: CONTACT: TREND: CONTACT:	Business Manager 0117 975 0700  Ston  Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  Extensive significant problems Declining Business Manager 0117 975 0700 Extensive significant problems Extensive significant problems Extensive significant problems Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bowl barrow 850m ESE of Hill Farm, Tarran	nt Rushton	
DESIGNATION:	Scheduled Monument (No. 1015182)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow I50m north east of Dunbury,	Winterborne Hou	ighton
DESIGNATION:	Scheduled Monument (No. 1014758)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 800m north west of North B	arn Farm on Hou	ghton North Down, Winterborne Houghto
DESIGNATION:	Scheduled Monument (No. 1013748)	CONDITION:	Generally unsatisfactory
	· /		with major localised problems
RINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
DITE NAME:	Bowl barrow 500m south of West Down B	arn, Winterborne	Kingston
DESIGNATION:	Scheduled Monument (No. 1020986)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:		CONTACT.	Dusiness Franager OFF7 775 0700
JWNEK I YPE:	Bowl barrow 900m north west of Pond Do		
SITE NAME:			
ITE NAME: DESIGNATION:	Bowl barrow 900m north west of Pond Do	own Buildings, Wir	terborne Stickland Generally unsatisfactory
	<b>Bowl barrow 900m north west of Pond Do</b> Scheduled Monument (No. 1013749)	own Buildings, Wir	Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE:	<b>Bowl barrow 900m north west of Pond Do</b> Scheduled Monument (No. 1013749) Arable clipping	own Buildings, Wir condition: trend: contact:	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME:	Bowl barrow 900m north west of Pond Do Scheduled Monument (No. 1013749) Arable clipping Other Rowbarrow, 500m north west of Hedge En	DWN Buildings, Wir CONDITION: TREND: CONTACT: d Farm, Winterbo	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME:	<b>Bowl barrow 900m north west of Pond Do</b> Scheduled Monument (No. 1013749) Arable clipping Other	own Buildings, Wir condition: trend: contact:	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland Generally unsatisfactory
ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION:	Bowl barrow 900m north west of Pond Do         Scheduled Monument (No. 1013749)         Arable clipping         Other         Rowbarrow, 500m north west of Hedge En         Scheduled Monument (No. 1013747)	DWN Buildings, Wir CONDITION: TREND: CONTACT: d Farm, Winterbo	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland Generally unsatisfactory with major localised problems
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Bowl barrow 900m north west of Pond Do Scheduled Monument (No. 1013749) Arable clipping Other Rowbarrow, 500m north west of Hedge En	DWN Buildings, Wir CONDITION: TREND: CONTACT: d Farm, Winterbo CONDITION:	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Bowl barrow 900m north west of Pond Do         Scheduled Monument (No. 1013749)         Arable clipping         Other         Rowbarrow, 500m north west of Hedge En         Scheduled Monument (No. 1013747)         Arable clipping	DWN Buildings, Wir CONDITION: TREND: CONTACT: d Farm, Winterboo CONDITION: TREND: CONTACT:	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Bowl barrow 900m north west of Pond Do         Scheduled Monument (No. 1013749)         Arable clipping         Other         Rowbarrow, 500m north west of Hedge En         Scheduled Monument (No. 1013747)         Arable clipping         Other	DWN Buildings, Wir CONDITION: TREND: CONTACT: d Farm, Winterboo CONDITION: TREND: CONTACT:	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Iose Plantation, Winterborne Whitechurch Generally unsatisfactory
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: ITE NAME: DWNER TYPE: ITE NAME: DWNER TYPE: ITE NAME: DESIGNATION:	Bowl barrow 900m north west of Pond Do         Scheduled Monument (No. 1013749)         Arable clipping         Other         Rowbarrow, 500m north west of Hedge En         Scheduled Monument (No. 1013747)         Arable clipping         Other         Bowl barrow 120m south of the southern en         Scheduled Monument (No. 1015387)	own Buildings, Wir CONDITION: TREND: CONTACT: d Farm, Winterboo CONDITION: TREND: CONTACT: extent of Horse C CONDITION:	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Iose Plantation, Winterborne Whitechurch Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY:	Bowl barrow 900m north west of Pond Do         Scheduled Monument (No. 1013749)         Arable clipping         Other         Rowbarrow, 500m north west of Hedge En         Scheduled Monument (No. 1013747)         Arable clipping         Other         Bowl barrow 120m south of the southern en         Scheduled Monument (No. 1015387)         Arable clipping	Aven Buildings, Wir CONDITION: TREND: CONTACT: d Farm, Winterboo CONDITION: TREND: CONTACT: extent of Horse C CONDITION: TREND:	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Iose Plantation, Winterborne Whitechurch Generally unsatisfactory with major localised problems Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY:	Bowl barrow 900m north west of Pond Do         Scheduled Monument (No. 1013749)         Arable clipping         Other         Rowbarrow, 500m north west of Hedge En         Scheduled Monument (No. 1013747)         Arable clipping         Other         Bowl barrow 120m south of the southern en         Scheduled Monument (No. 1015387)	own Buildings, Wir CONDITION: TREND: CONTACT: d Farm, Winterboo CONDITION: TREND: CONTACT: extent of Horse C CONDITION:	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Iose Plantation, Winterborne Whitechurch Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Bowl barrow 900m north west of Pond Do         Scheduled Monument (No. 1013749)         Arable clipping         Other         Rowbarrow, 500m north west of Hedge En         Scheduled Monument (No. 1013747)         Arable clipping         Other         Bowl barrow 120m south of the southern en         Scheduled Monument (No. 1015387)         Arable clipping	Aven Buildings, Wir CONDITION: TREND: CONTACT: d Farm, Winterboo CONDITION: TREND: CONTACT: extent of Horse C CONDITION: TREND: CONTACT:	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Iose Plantation, Winterborne Whitechurch Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Bowl barrow 900m north west of Pond Do         Scheduled Monument (No. 1013749)         Arable clipping         Other         Rowbarrow, 500m north west of Hedge En         Scheduled Monument (No. 1013747)         Arable clipping         Other         Bowl barrow 120m south of the southern end         Scheduled Monument (No. 1015387)         Arable clipping         Private	Aven Buildings, Wir CONDITION: TREND: CONTACT: d Farm, Winterboo CONDITION: TREND: CONTACT: extent of Horse C CONDITION: TREND: CONTACT:	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Iose Plantation, Winterborne Whitechurch Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Bowl barrow 900m north west of Pond Do         Scheduled Monument (No. 1013749)         Arable clipping         Other         Rowbarrow, 500m north west of Hedge En         Scheduled Monument (No. 1013747)         Arable clipping         Other         Bowl barrow 120m south of the southern end         Scheduled Monument (No. 1015387)         Arable clipping         Other         Bowl barrow 120m south of the southern end         Scheduled Monument (No. 1015387)         Arable clipping         Private         Bowl barrow 25m south of Whitechurch H	Aven Buildings, Wir CONDITION: TREND: CONTACT: d Farm, Winterboo CONDITION: TREND: CONTACT: extent of Horse C CONDITION: TREND: CONTACT:	terborne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 rne Stickland Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 lose Plantation, Winterborne Whitechurch Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 mre Whitechurch Extensive significant problems

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Milling House, West Farm, Winterborne \	Whitechurch	
DESIGNATION:	Scheduled Monument (No. 1002396)		Generally unsatisfactory
DESIGNATION:	Scheduled Fiohament (140, 1002570)		with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management		Declining
OWNER TYPE:	Private		Business Manager 0117 975 0700
OWNERTH L.	The	CONTACT.	
SITE NAME:	Bowl barrow 550m north west of Bulbar	row Farm, Woolland	
DESIGNATION:	Scheduled Monument (No. 1013786)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bul Barrow, 750m east of Rawlsbury Can	1p, Woolland	
DESIGNATION:	Scheduled Monument (No. 1013787)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth		Declining
OWNER TYPE:	Other		Business Manager 0117 975 0700
		contraction of the second seco	
SITE NAME:	Blandford Forum		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium		Deteriorating
CONTACT:	Kevin Morris (LPA) 01258 484276		Yes
SITE NAME:	Gillingham		
DESIGNATION:	Conservation Area		Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Kevin Morris (LPA) 01258 484276	NEW ENTRY?:	Yes
SITE NAME:	Milton Abbas		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low		Deteriorating
CONTACT:	Kevin Morris (LPA) 01258 484276	NEW ENTRY?:	Yes
PURBECK			
	SITE NAME: North Lodges,		nd gateway to Lulworth Castle, 1785.
	Lulworth Castle,		been undertaken by the estate, but a longer
A DECEMBER OF THE OWNER OWNER OF THE OWNER	Coombe Keynes	term plan for	the buildings needs to be conceived.
	DESIGNATION: Listed Building Grade II*, SM		
	CONDITION: Poor		
and the second second	occupancy: Vacant		
	PRIORITY: C (E)		
	OWNERTYPE: Private	Contact: Isla N	1acneal 0117 975 0742
SITE NAME:	Bowl barrow in Throop Clump, 450m we	st of Heatherdown. Af	fpuddle
DESIGNATION:	Scheduled Monument (No. 1020734)		Extensive significant problems
DEJIONATION:			i.e. under plough, collapse
	Forestry		Declining
PRINCIPAL VULNERABILITY:	Government or Agency		Business Manager 0117 975 0700
OWNER TYPE:	Government of Agency	CONTACT:	Dusiness Franager 0117 775 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Concentration
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

ITE NAME:	The Double Barrow, a bowl barrow in Kite 250m south east of Roger's Hill Cottages, A		
DESIGNATION:	Scheduled Monument (No. 1015900)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow on Worgret Heath, 320m nor	th west of High To	or, Arne
DESIGNATION:	Scheduled Monument (No. 1018190)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bell barrow on Blackhill Clump 470m north	n of Mintern's Feri	ry, Bere Regis
DESIGNATION:	Scheduled Monument (No. 1015899)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 190m north west of Bere Dov	wn Farm Bare Pa	aic
			-
DESIGNATION:	Scheduled Monument (No. 1015376)	CONDITION:	Extensive significant problems
		TRENES	i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing Private	TREND: CONTACT:	Declining Business Manager 0117 975 0700
te name: Esignation:	Bowl barrow 515m south of the southern of	extent of Horse C	-
	Scheduled Monument (INO. 1015386)	CONDITION:	Extensive significant problems
	Scheduled Monument (No. 1015386)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	CONDITION: TREND:	
RINCIPAL VULNERABILITY: DWNER TYPE:			i.e. under plough, collapse
	Arable ploughing	TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700
OWNER TYPE:	Arable ploughing Private	TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700
DWNER TYPE: ITE NAME: DESIGNATION:	Arable ploughing Private Bowl barrow 590m north east of Bere Dov	trend: contact: wn Farm, Bere Reg	i.e. under plough, collapse Declining Business Manager 0117 975 0700 gis Extensive significant problems i.e. under plough, collapse Declining
DWNER TYPE:	Arable ploughing Private Bowl barrow 590m north east of Bere Dow Scheduled Monument (No. 1015378)	trend: Contact: wn Farm, Bere Reg Condition:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 gis Extensive significant problems i.e. under plough, collapse
DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Arable ploughing Private Bowl barrow 590m north east of Bere Dow Scheduled Monument (No. 1015378) Arable ploughing	TREND: CONTACT: wn Farm, Bere Reg CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 gis Extensive significant problems i.e. under plough, collapse Declining
DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Arable ploughing Private Bowl barrow 590m north east of Bere Dow Scheduled Monument (No. 1015378) Arable ploughing Private	TREND: CONTACT: wn Farm, Bere Reg CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 gis Extensive significant problems i.e. under plough, collapse Declining
DWNER TYPE: ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Arable ploughing Private Bowl barrow 590m north east of Bere Dow Scheduled Monument (No. 1015378) Arable ploughing Private Bowl barrow 610m east of Bere Heath Far	TREND: CONTACT: wn Farm, Bere Reg CONDITION: TREND: CONTACT: m, Bere Regis	i.e. under plough, collapse Declining Business Manager 0117 975 0700 gis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory
DWNER TYPE:	Arable ploughing Private Bowl barrow 590m north east of Bere Dow Scheduled Monument (No. 1015378) Arable ploughing Private Bowl barrow 610m east of Bere Heath Fart Scheduled Monument (No. 1015365)	TREND: CONTACT: wn Farm, Bere Reg CONDITION: TREND: CONTACT: m, Bere Regis	i.e. under plough, collapse Declining Business Manager 0117 975 0700
DWNER TYPE:	Arable ploughing Private Bowl barrow 590m north east of Bere Dow Scheduled Monument (No. 1015378) Arable ploughing Private Bowl barrow 610m east of Bere Heath Far Scheduled Monument (No. 1015365) Extensive animal burrowing Government or Agency	TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 gis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DWNER TYPE:	Arable ploughing         Private         Bowl barrow 590m north east of Bere Down         Scheduled Monument (No. 1015378)         Arable ploughing         Private         Bowl barrow 610m east of Bere Heath Fare         Scheduled Monument (No. 1015365)         Extensive animal burrowing         Government or Agency         Bowl barrow 790m north east of Haywards	TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 gis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DWNER TYPE:	Arable ploughing Private Bowl barrow 590m north east of Bere Dow Scheduled Monument (No. 1015378) Arable ploughing Private Bowl barrow 610m east of Bere Heath Far Scheduled Monument (No. 1015365) Extensive animal burrowing Government or Agency Bowl barrow 790m north east of Haywards Scheduled Monument (No. 1015330)	TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 jis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse
DWNER TYPE:	Arable ploughing Private Bowl barrow 590m north east of Bere Dow Scheduled Monument (No. 1015378) Arable ploughing Private Bowl barrow 610m east of Bere Heath Far Scheduled Monument (No. 1015365) Extensive animal burrowing Government or Agency Bowl barrow 790m north east of Haywards	TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 jis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bowl barrow on Warren Heath, 350m sout	h west of Warren	House, bere Regis
DESIGNATION:	Scheduled Monument (No. 1019367)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Four bowl barrows 240m east of Oak Cott	tage, Bere Regis	
DESIGNATION:	Scheduled Monument (No. 1015369)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ite name:	Four bowl barrows 600m east and 650m n	orth east of Hayw	rards Farm, Bere Regis
DESIGNATION:	Scheduled Monument (No. 1015331)	CONDITION:	Extensive significant problems
		CONDITION.	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of six bowl barrows, forming a roun	d barrow cemete	ry on Black Hill, Bere Regis
DESIGNATION:	Scheduled Monument (No. 1015897)	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Plant growth Private Long barrow on Bere Down, 1100m north	CONTACT:	
PRINCIPAL VULNERABILITY:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329)	CONTACT:	Business Manager 0117 975 0700 <b>n, Bere Regis</b> Extensive significant problems i.e. under plough, collapse
DWNER TYPE: ITE NAME: DESIGNATION:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329) Arable ploughing	CONTACT: east of Roke Barr	Business Manager 0117 975 0700 <b>n, Bere Regis</b> Extensive significant problems i.e. under plough, collapse Declining
DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329)	CONTACT: east of Roke Barr CONDITION:	Business Manager 0117 975 0700 <b>n, Bere Regis</b> Extensive significant problems i.e. under plough, collapse Declining
DWNER TYPE:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329) Arable ploughing	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 <b>A, Bere Regis</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329) Arable ploughing Private	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 <b>A, Bere Regis</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DWNER TYPE:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329) Arable ploughing Private The End Barrow, a bowl barrow 320m sout	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT: th west of White	Business Manager 0117 975 0700 <b>n, Bere Regis</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>House, Bere Regis</b> Generally unsatisfactory
DWNER TYPE:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329) Arable ploughing Private The End Barrow, a bowl barrow 320m sout Scheduled Monument (No. 1017462)	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT: th west of White CONDITION:	Business Manager 0117 975 0700 <b>n, Bere Regis</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>House, Bere Regis</b> Generally unsatisfactory with major localised problems Declining
DWNER TYPE:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329) Arable ploughing Private The End Barrow, a bowl barrow 320m sout Scheduled Monument (No. 1017462) Arable clipping	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT:	Business Manager 0117 975 0700 h, Bere Regis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 House, Bere Regis Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DWNER TYPE:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329) Arable ploughing Private The End Barrow, a bowl barrow 320m sourd Scheduled Monument (No. 1017462) Arable clipping Private	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT:	Business Manager 0117 975 0700 h, Bere Regis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 House, Bere Regis Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DWNER TYPE:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329) Arable ploughing Private The End Barrow, a bowl barrow 320m south Scheduled Monument (No. 1017462) Arable clipping Private Three bowl barrows 230m south west of H	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT: th west of White CONDITION: TREND: CONTACT: Haywards Farm, Be	Business Manager 0117 975 0700 <b>A, Bere Regis</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>House, Bere Regis</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 <b>Extensive significant problems</b>
DWNER TYPE:	Private         Long barrow on Bere Down, 1100m north         Scheduled Monument (No. 1015329)         Arable ploughing         Private         The End Barrow, a bowl barrow 320m south         Scheduled Monument (No. 1017462)         Arable clipping         Private         Three bowl barrows 230m south west of H         Scheduled Monument (No. 1015333)	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT: th west of White CONDITION: TREND: CONTACT: Haywards Farm, Be	Business Manager 0117 975 0700 h, Bere Regis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 House, Bere Regis Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ere Regis Extensive significant problems i.e. under plough, collapse Declining
DWNER TYPE:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329) Arable ploughing Private The End Barrow, a bowl barrow 320m south Scheduled Monument (No. 1017462) Arable clipping Private Three bowl barrows 230m south west of H Scheduled Monument (No. 1015333) Arable ploughing Private	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONDITION: CONDITION: TREND: CONDITION:	Business Manager 0117 975 0700 h, Bere Regis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 House, Bere Regis Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ere Regis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DWNER TYPE:	Private         Long barrow on Bere Down, 1100m north         Scheduled Monument (No. 1015329)         Arable ploughing         Private         The End Barrow, a bowl barrow 320m south         Scheduled Monument (No. 1017462)         Arable clipping         Private         Three bowl barrows 230m south west of H         Scheduled Monument (No. 1015333)         Arable ploughing         Private         Three bowl barrows 650m south west of B	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONDITION: TREND: CONDITION: CONTACT: CON	Business Manager 0117 975 0700 h, Bere Regis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 House, Bere Regis Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ere Regis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Bere Regis
DWNER TYPE:	Private Long barrow on Bere Down, 1100m north Scheduled Monument (No. 1015329) Arable ploughing Private The End Barrow, a bowl barrow 320m south Scheduled Monument (No. 1017462) Arable clipping Private Three bowl barrows 230m south west of H Scheduled Monument (No. 1015333) Arable ploughing Private	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONDITION: CONDITION: TREND: CONDITION:	Business Manager 0117 975 0700 h, Bere Regis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 House, Bere Regis Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ere Regis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Bere Regis Extensive significant problems
DWNER TYPE:	Private         Long barrow on Bere Down, 1100m north         Scheduled Monument (No. 1015329)         Arable ploughing         Private         The End Barrow, a bowl barrow 320m south         Scheduled Monument (No. 1017462)         Arable clipping         Private         Three bowl barrows 230m south west of H         Scheduled Monument (No. 1015333)         Arable ploughing         Private         Three bowl barrows 650m south west of E         Scheduled Monument (No. 1018193)	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT: th west of White CONDITION: TREND: CONDITION: Haywards Farm, Be CONDITION: TREND: CONDITION: CONDITION:	Business Manager 0117 975 0700  A, Bere Regis  Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  House, Bere Regis  Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700  ere Regis  Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700  Bere Regis  Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DWNER TYPE:	Private         Long barrow on Bere Down, 1100m north         Scheduled Monument (No. 1015329)         Arable ploughing         Private         The End Barrow, a bowl barrow 320m south         Scheduled Monument (No. 1017462)         Arable clipping         Private         Three bowl barrows 230m south west of H         Scheduled Monument (No. 1015333)         Arable ploughing         Private         Three bowl barrows 650m south west of B	CONTACT: east of Roke Barr CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONDITION: TREND: CONDITION: CONTACT: CON	Business Manager 0117 975 0700 h, Bere Regis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 House, Bere Regis Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ere Regis Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Bere Regis Extensive significant problems

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ITE NAME:	Two bell barrows and a bowl barrow, 200m	north east of Ha	ywards Farm, Bere Regis
esignation:	Scheduled Monument (No. 1015332)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Two bowl barrows both 350m north east c	of Spring Garden I	Barn, Bere Regis
DESIGNATION:	Scheduled Monument (No. 1015898)	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two bowl barrows on South Heath, 900m S	SSE of The Bungal	ow, Bere Regis
DESIGNATION:	Scheduled Monument (No. 1017694)	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 800m NNW of West Morden	Farm, Bloxworth	
DESIGNATION:	Scheduled Monument (No. 1015367)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		contraction	
ITE NAME:	Bowl barrow on Bloxworth Down, 740m s		
	<b>Bowl barrow on Bloxworth Down, 740m s</b> Scheduled Monument (No. 1017626)		
ITE NAME:	Scheduled Monument (No. 1017626)	outh of Marsh Far	m, Bloxworth
te name: Esignation:		outh of Marsh Far	<b>m, Bloxworth</b> Extensive significant problems i.e. under plough, collapse Declining
ITE NAME:	Scheduled Monument (No. 1017626)	outh of Marsh Far	<b>m, Bloxworth</b> Extensive significant problems i.e. under plough, collapse Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1017626) Arable ploughing	outh of Marsh Far Condition: Trend: Contact:	<b>m, Bloxworth</b> Extensive significant problems i.e. under plough, collapse Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No. 1017626) Arable ploughing Private	outh of Marsh Far Condition: Trend: Contact:	<b>m, Bloxworth</b> Extensive significant problems i.e. under plough, collapse Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Scheduled Monument (No. 1017626) Arable ploughing Private Round barrow cemetery on Bloxworth Do	outh of Marsh Far Condition: TREND: CONTACT: wn, Bloxworth	<b>m, Bloxworth</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNER TYPE: TE NAME: ESIGNATION:	Scheduled Monument (No. 1017626) Arable ploughing Private Round barrow cemetery on Bloxworth Do	outh of Marsh Far Condition: TREND: CONTACT: wn, Bloxworth	m, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining
	Scheduled Monument (No. 1017626) Arable ploughing Private Round barrow cemetery on Bloxworth Do Scheduled Monument (No. 1017624)	outh of Marsh Far CONDITION: TREND: CONTACT: wn, Bloxworth CONDITION:	m, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Scheduled Monument (No. 1017626) Arable ploughing Private Round barrow cemetery on Bloxworth Do Scheduled Monument (No. 1017624) Arable ploughing	outh of Marsh Far CONDITION: TREND: CONTACT: wn, Bloxworth CONDITION: TREND: CONTACT:	m, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE:	Scheduled Monument (No. 1017626) Arable ploughing Private Round barrow cemetery on Bloxworth Do Scheduled Monument (No. 1017624) Arable ploughing Other	outh of Marsh Far CONDITION: TREND: CONTACT: wn, Bloxworth CONDITION: TREND: CONTACT:	m, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWINER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWINER TYPE: ITE NAME:	Scheduled Monument (No. 1017626)         Arable ploughing         Private         Round barrow cemetery on Bloxworth Do         Scheduled Monument (No. 1017624)         Arable ploughing         Other         Three bowl barrows on Bloxworth Down,         Scheduled Monument (No. 1017625)	outh of Marsh Far CONDITION: TREND: CONTACT: wn, Bloxworth CONDITION: TREND: CONTACT: 800m west of Bot	m, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Cany Bay Barn, Bloxworth Extensive significant problems i.e. under plough, collapse
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: DESIGNATION:	Scheduled Monument (No. 1017626)         Arable ploughing         Private         Round barrow cemetery on Bloxworth Do         Scheduled Monument (No. 1017624)         Arable ploughing         Other         Three bowl barrows on Bloxworth Down,	outh of Marsh Far CONDITION: TREND: CONTACT: wn, Bloxworth CONDITION: TREND: CONTACT: 800m west of Bot CONDITION:	m, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Cany Bay Barn, Bloxworth Extensive significant problems i.e. under plough, collapse Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DESIGNATION: RINCIPAL VULNERABILITY: DESIGNATION	Scheduled Monument (No. 1017626)         Arable ploughing         Private         Round barrow cemetery on Bloxworth Do         Scheduled Monument (No. 1017624)         Arable ploughing         Other         Three bowl barrows on Bloxworth Down,         Scheduled Monument (No. 1017625)         Arable ploughing	outh of Marsh Far CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONDITION: 8000m west of Boo CONDITION:	m, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Extensive significant problems i.e. under plough, collapse Declining
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DESIGNATION: RINCIPAL VULNERABILITY: DESIGNATION	Scheduled Monument (No. 1017626)         Arable ploughing         Private         Round barrow cemetery on Bloxworth Do         Scheduled Monument (No. 1017624)         Arable ploughing         Other         Three bowl barrows on Bloxworth Down,         Scheduled Monument (No. 1017625)         Arable ploughing	outh of Marsh Far CONDITION: TREND: CONTACT: WIN, BIOXWORTH CONDITION: TREND: CONTACT: 800m West of Bor CONDITION: TREND: CONDITION:	m, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Cany Bay Barn, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DESIGNATION: RINCIPAL VULNERABILITY: DESIGNATION: DESIGNATION: RINCIPAL VULNERABILITY: DESIGNATION: RINCIPAL VULNERABILITY: RINCIPAL VULNE	Scheduled Monument (No. 1017626)         Arable ploughing         Private         Round barrow cemetery on Bloxworth Do         Scheduled Monument (No. 1017624)         Arable ploughing         Other         Three bowl barrows on Bloxworth Down,         Scheduled Monument (No. 1017625)         Arable ploughing         Other	outh of Marsh Far CONDITION: TREND: CONTACT: WIN, BIOXWORTH CONDITION: TREND: CONTACT: 800m West of Bor CONDITION: TREND: CONDITION:	m, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Cany Bay Barn, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DWNER TYPE: DWNER TYPE:	Scheduled Monument (No. 1017626)         Arable ploughing         Private         Round barrow cemetery on Bloxworth Do         Scheduled Monument (No. 1017624)         Arable ploughing         Other         Three bowl barrows on Bloxworth Down,         Scheduled Monument (No. 1017625)         Arable ploughing         Other         Bowl barrow 200m south east of Hill Barn:	outh of Marsh Far CONDITION: TREND: CONTACT: WIN, BIOXWORTH CONDITION: TREND: CONTACT: 800m West of Bor CONDITION: TREND: CONDITION: 000 of a group o	m, Bloxworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 f three barrows, Chaldon Herring Extensive significant problems

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Bowl barrow 470m south east of Down Ba an outlier of the Chaldon Down barrow gro		ring
DESIGNATION:	Scheduled Monument (No. 1008146)		Extensive significant problems
SESIGI VITION.		CONDITION.	i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 550m south of Chaldon Dow part of the Chaldon Down round barrow c	U U	Herring
DESIGNATION:	Scheduled Monument (No. 1008520)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 650m south of Chaldon Dow part of the Chaldon Down round barrow c	0	Herring
DESIGNATION:	Scheduled Monument (No. 1008523)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
JITE NAME: DESIGNATION:	Bowl barrow 660m south of Chaldon Dow part of the Chaldon Down round barrow c Scheduled Monument (No. 1008521)		Herring Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow to the west of Five Marys:		
	an outlier to the Five Marys round barrow		•
	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683)	CONDITION:	Generally satisfactory but with significant localised problems
	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other		Generally satisfactory but with significant localised problems Stable
PRINCIPAL VULNERABILITY:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: OWNER TYPE:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other Private The Round Pound, an enclosure on Chaldon	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Herring Generally unsatisfactory
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other Private The Round Pound, an enclosure on Chaldon Scheduled Monument (No. 1018436)	CONDITION: TREND: CONTACT: n Down, Chaldon CONDITION:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Herring Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other Private The Round Pound, an enclosure on Chaldon Scheduled Monument (No. 1018436) Arable clipping	CONDITION: TREND: CONTACT: n Down, Chaldon CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Herring Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other Private The Round Pound, an enclosure on Chaldon Scheduled Monument (No. 1018436) Arable clipping Private	CONDITION: TREND: CONTACT: n Down, Chaldon CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Herring Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
RINCIPAL VULNERABILITY:  WHER TYPE:  ITE NAME:  DESIGNATION:  ITE NAME:  DESIGNATION:  DESIGNATION:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other Private The Round Pound, an enclosure on Chaldon Scheduled Monument (No. 1018436) Arable clipping Private Two bowl barrows 200m south east of Hill	CONDITION: TREND: CONTACT: n Down, Chaldon CONDITION: TREND: CONTACT: Barn: two of a gro	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Herring Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Oup of three barrows, Chaldon Herring Extensive significant problems
RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:  RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:  RINCIPAL VULNERABILITY:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other Private The Round Pound, an enclosure on Chaldon Scheduled Monument (No. 1018436) Arable clipping Private Two bowl barrows 200m south east of Hill Scheduled Monument (No. 1008162)	CONDITION: TREND: CONTACT: n Down, Chaldon CONDITION: TREND: CONTACT: Barn: two of a gro CONDITION:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Herring Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 oup of three barrows, Chaldon Herring Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other Private The Round Pound, an enclosure on Chaldo Scheduled Monument (No. 1018436) Arable clipping Private Two bowl barrows 200m south east of Hill Scheduled Monument (No. 1008162) Arable ploughing	CONDITION: TREND: CONTACT: TREND: CONDITION: TREND: CONTACT: Barn: two of a gro CONDITION: TREND: TREND:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Herring Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 oup of three barrows, Chaldon Herring Extensive significant problems i.e. under plough, collapse Declining
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other Private The Round Pound, an enclosure on Chaldo Scheduled Monument (No. 1018436) Arable clipping Private Two bowl barrows 200m south east of Hill Scheduled Monument (No. 1008162) Arable ploughing	CONDITION: TREND: CONTACT: n Down, Chaldon CONDITION: TREND: CONTACT: Barn: two of a gro CONDITION: TREND: CONDITION: TREND: CONTACT: Dorset coastal ric	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Herring Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 oup of three barrows, Chaldon Herring Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME: SITE NAME:	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other Private The Round Pound, an enclosure on Chaldon Scheduled Monument (No. 1018436) Arable clipping Private Two bowl barrows 200m south east of Hill Scheduled Monument (No. 1008162) Arable ploughing Private Wardstone Barrow: a bowl barrow on the 300m south of Chideock Farm, Chaldon He Scheduled Monument (No. 1008676)	CONDITION: TREND: CONTACT: n Down, Chaldon CONDITION: TREND: CONTACT: Barn: two of a gro CONDITION: TREND: CONDITION: TREND: CONTACT: Dorset coastal ric	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Herring Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 dge Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABI	an outlier to the Five Marys round barrow Scheduled Monument (No. 1008683) Other Private The Round Pound, an enclosure on Chaldor Scheduled Monument (No. 1018436) Arable clipping Private Two bowl barrows 200m south east of Hill Scheduled Monument (No. 1008162) Arable ploughing Private Wardstone Barrow: a bowl barrow on the B 300m south of Chideock Farm, Chaldon He	CONDITION: TREND: CONTACT: TREND: CONDITION: TREND: CONTACT: Barn: two of a gro CONDITION: TREND: CONTACT: Dorset coastal rice	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Herring Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 ge Generally unsatisfactory

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Bowl barrow on Creech Barrow hill, Churc	h Knowle	
DESIGNATION:	Scheduled Monument (No. 1014830)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 760m south west of Afflingtor	n Barn, Corfe Cas	tle
DESIGNATION:	Scheduled Monument (No. 1016935)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow on Swyre Head, Corfe Castle		
DESIGNATION:	Scheduled Monument (No. 1017271)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	The Rings: a ringwork and bailey and a Civi	War battery 400	m south west of Corfe Castle, Corfe Castl
DESIGNATION:	Scheduled Monument (No. 1011479)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	TTVate	CONTACT:	
SITE NAME:	Three bowl barrows in Holme Lane Plantat		
SITE NAME:			
ITE NAME: DESIGNATION:	Three bowl barrows in Holme Lane Plantat	ion, 200m south v	west of Squirrel's Cottages, East Holme Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Three bowl barrows in Holme Lane Plantat Scheduled Monument (No. 1016728)	condition:	west of Squirrel's Cottages, East Holme Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE:	<b>Three bowl barrows in Holme Lane Plantat</b> Scheduled Monument (No. 1016728) Plant growth	condition; condition: trend: contact:	west of Squirrel's Cottages, East Holme Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME:	<b>Three bowl barrows in Holme Lane Plantat</b> Scheduled Monument (No. 1016728) Plant growth Private	condition; condition: trend: contact:	west of Squirrel's Cottages, East Holme Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Three bowl barrows in Holme Lane Plantat Scheduled Monument (No. 1016728) Plant growth Private Flower's Barrow: a small multivallate hillfort	CONDITION: TREND: CONTACT:	west of Squirrel's Cottages, East Holme Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 utwork on Rings Hill, East Lulworth Extensive significant problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Three bowl barrows in Holme Lane Plantat Scheduled Monument (No. 1016728) Plant growth Private Flower's Barrow: a small multivallate hillfort Scheduled Monument (No. 1008141)	CONDITION: CONDITION: TREND: CONTACT: and associated o CONDITION:	west of Squirrel's Cottages, East Holme Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 utwork on Rings Hill, East Lulworth Extensive significant problems i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Three bowl barrows in Holme Lane Plantat         Scheduled Monument (No. 1016728)         Plant growth         Private         Flower's Barrow: a small multivallate hillfort         Scheduled Monument (No. 1008141)         Coastal erosion	CONDITION: CONDITION: TREND: CONTACT: and associated of CONDITION: TREND: CONTACT: CONTACT: CONTACT:	west of Squirrel's Cottages, East Holme Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 utwork on Rings Hill, East Lulworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 iteway Farm:
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE: DWNER TYPE:	Three bowl barrows in Holme Lane Plantat         Scheduled Monument (No. 1016728)         Plant growth         Private         Flower's Barrow: a small multivallate hillfort         Scheduled Monument (No. 1008141)         Coastal erosion         Other         Two barrows known as 'Water Barrows' 65	CONDITION: CONDITION: TREND: CONTACT: and associated of CONDITION: TREND: CONTACT: CONTACT: CONTACT:	west of Squirrel's Cottages, East Holme Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 utwork on Rings Hill, East Lulworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 iteway Farm:
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION:	Three bowl barrows in Holme Lane Plantat         Scheduled Monument (No. 1016728)         Plant growth         Private         Flower's Barrow: a small multivallate hillfort         Scheduled Monument (No. 1008141)         Coastal erosion         Other         Two barrows known as 'Water Barrows' 65 part of a round barrow cemetery to the so	tion, 200m south v CONDITION: TREND: CONTACT: and associated o CONDITION: TREND: CONTACT: 50m WNW of Wh	west of Squirrel's Cottages, East Holme Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 utwork on Rings Hill, East Lulworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 iteway Farm: ulworth, East Lulworth Extensive significant problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Three bowl barrows in Holme Lane Plantat         Scheduled Monument (No. 1016728)         Plant growth         Private         Flower's Barrow: a small multivallate hillfort         Scheduled Monument (No. 1008141)         Coastal erosion         Other         Two barrows known as 'Water Barrows' 65 part of a round barrow cemetery to the so         Scheduled Monument (No. 1008144)	tion, 200m south v CONDITION: TREND: CONTACT: and associated of CONDITION: TREND: CONTACT: i0m WNW of Wh outh east of East L CONDITION:	west of Squirrel's Cottages, East Holme         Generally unsatisfactory         with major localised problems         Declining         Business Manager 0117 975 0700         utwork on Rings Hill, East Lulworth         Extensive significant problems         Declining         Business Manager 0117 975 0700         utwork on Rings Hill, East Lulworth         Extensive significant problems         i.e. under plough, collapse         Declining         Business Manager 0117 975 0700         iteway Farm:         ulworth, East Lulworth         Extensive significant problems         i.e. under plough, collapse
	Three bowl barrows in Holme Lane Plantat         Scheduled Monument (No. 1016728)         Plant growth         Private         Flower's Barrow: a small multivallate hillfort         Scheduled Monument (No. 1008141)         Coastal erosion         Other         Two barrows known as 'Water Barrows' 65 part of a round barrow cemetery to the so         Scheduled Monument (No. 1008144)         Extensive animal burrowing	CONDITION: CONDITION: CONTACT: CONTACT: CONDITION: CONDITION: CONTACT: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	west of Squirrel's Cottages, East Holme Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 utwork on Rings Hill, East Lulworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 iteway Farm: ulworth, East Lulworth Extensive significant problems i.e. under plough, collapse Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Three bowl barrows in Holme Lane Plantat         Scheduled Monument (No. 1016728)         Plant growth         Private         Flower's Barrow: a small multivallate hillfort         Scheduled Monument (No. 1008141)         Coastal erosion         Other         Two barrows known as 'Water Barrows' 65 part of a round barrow cemetery to the so Scheduled Monument (No. 1008144)         Extensive animal burrowing         Government or Agency	CONDITION: CONDITION: CONTACT: CONTACT: CONDITION: CONDITION: CONTACT: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	west of Squirrel's Cottages, East Holme Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 utwork on Rings Hill, East Lulworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 iteway Farm: ulworth, East Lulworth Extensive significant problems i.e. under plough, collapse Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Three bowl barrows in Holme Lane Plantat         Scheduled Monument (No. 1016728)         Plant growth         Private         Flower's Barrow: a small multivallate hillfort         Scheduled Monument (No. 1008141)         Coastal erosion         Other         Two barrows known as 'Water Barrows' 65 part of a round barrow cemetery to the so         Scheduled Monument (No. 1008141)         Extensive animal burrowing         Government or Agency         Bowl barrow 60m north east of Hethfelton	tion, 200m south v CONDITION: TREND: CONTACT: and associated of CONDITION: TREND: CONTACT: 00m WNW of Wh outh east of East L CONDITION: TREND: CONDITION:	west of Squirrel's Cottages, East Holme         Generally unsatisfactory         with major localised problems         Declining         Business Manager 0117 975 0700         utwork on Rings Hill, East Lulworth         Extensive significant problems         Declining         Business Manager 0117 975 0700         utwork on Rings Hill, East Lulworth         Extensive significant problems         i.e. under plough, collapse         Declining         Business Manager 0117 975 0700         iteway Farm:         ulworth, East Lulworth         Extensive significant problems         i.e. under plough, collapse         Declining         Business Manager 0117 975 0700         Generally unsatisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bowl barrow on Farm Heath, 470m south e	east of Hill Cottag	ges, East Stoke
DESIGNATION:	Scheduled Monument (No. 1016272)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
GITE NAME:	Bowl barrow on Farm Heath, 480m south 6	east of Hill Cottag	yes, East Stoke
designation:	Scheduled Monument (No. 1016271)	CONDITION:	Generally unsatisfactory
		Condition	with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow cemetery on West Holme H	leath, 850m north	west of Hurst Mill, East Stoke
	Scheduled Monument (No. 1007691)		Ceperally unsatisfactory
DESIGNATION:		CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Government or Agency		Business Manager 0117 975 0700
DWINER LIFE:		CONTACT:	Dushiness Frankger 0117 773 0700
SITE NAME:	Section of Battery Bank on Binnegar Plain, 8	830m north east o	of Stokeford Farm, East Stoke
DESIGNATION:	Scheduled Monument (No. 1018189)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Section of Battery Bank on South Heath, Ea	ast Stoke	
DESIGNATION:	Scheduled Monument (No. 1016273)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two bowl barrows on South Heath, 290m a	and 370m east of	Binnegar Hall, East Stoke
DESIGNATION:	Scheduled Monument (No. 1016276)	CONDITION:	Generally unsatisfactory
	· · · · · · · · · · · · · · · · · · ·		with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Alum works, other multi-period industrial r Kimmeridge Bay, Kimmeridge	remains and an ass	sociated group of jetties and breakwaters,
DESIGNATION:	Scheduled Monument (No. 1017307)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	Bowl barrow in Morden Park 350m south v	west of Hunting B	ridge, Morden
SITE NAME:			Consumily uncertisfactory
	Scheduled Monument (No. 1016281)		
	Scheduled Monument (No. 1016281)	CONDITION:	Generally unsatisfactory with major localised problems
Designation:			with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1016281) Scrub / tree growth Private	CONDITION: TREND: CONTACT:	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Two bowl barrows 760m north east of Mille	r's Farm, Morder	1
DESIGNATION:	Scheduled Monument (No. 1016283)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Obelisk on Fir Hill, Moreton		
DESIGNATION:	Scheduled Monument (No. 1002425)	CONDITION:	Generally unsatisfactory
	``````		with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of three bell barrows and a bowl bar	row on Godlings	ton Heath, Studland
DESIGNATION:	Scheduled Monument (No. 1014291)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow in Piddle Wood, 530m north ea	ast of Gate Barn,	Turners Puddle
DESIGNATION:	Scheduled Monument (No. 1015901)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
			Dusing an Margary 0117 075 0700
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Round barrow cemetery on Povington Heat		
SITE NAME:	Round barrow cemetery on Povington Heat	h 550m north ea	ist of Whiteway Farm, Tyneham
SITE NAME:			ist of Whiteway Farm, Tyneham Generally unsatisfactory
ITE NAME: DESIGNATION:	Round barrow cemetery on Povington Heat Scheduled Monument (No. 1008026)	h 550m north ea	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Round barrow cemetery on Povington Heat	h 550m north ea	ist of Whiteway Farm, Tyneham Generally unsatisfactory
	<b>Round barrow cemetery on Povington Heat</b> Scheduled Monument (No. 1008026) Digging	h 550m north ea Condition: Trend: Contact:	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Round barrow cemetery on Povington Heat Scheduled Monument (No. 1008026) Digging Government or Agency Thorn Barrow: a bowl barrow on East Holm	h 550m north ea condition: trend: contact: e Range, 650m n	ast of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME:	Round barrow cemetery on Povington Heat Scheduled Monument (No. 1008026) Digging Government or Agency	h 550m north ea Condition: Trend: Contact:	Ast of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Corth east of Whiteway Farm, Tyneham Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Round barrow cemetery on Povington Heat         Scheduled Monument (No. 1008026)         Digging         Government or Agency         Thorn Barrow: a bowl barrow on East Holm         Scheduled Monument (No. 1009610)	h 550m north ea CONDITION: TREND: CONTACT: e Range, 650m n CONDITION:	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Forth east of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Round barrow cemetery on Povington Heat Scheduled Monument (No. 1008026) Digging Government or Agency Thorn Barrow: a bowl barrow on East Holm	h 550m north ea condition: trend: contact: e Range, 650m n	Ast of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Corth east of Whiteway Farm, Tyneham Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Round barrow cemetery on Povington Heat         Scheduled Monument (No. 1008026)         Digging         Government or Agency         Thorn Barrow: a bowl barrow on East Holm         Scheduled Monument (No. 1009610)         Plant growth	h 550m north ea CONDITION: TREND: CONTACT: e Range, 650m n CONDITION: TREND: CONTACT:	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Forth east of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Round barrow cemetery on Povington Heat         Scheduled Monument (No. 1008026)         Digging         Government or Agency         Thorn Barrow: a bowl barrow on East Holm         Scheduled Monument (No. 1009610)         Plant growth         Government or Agency         Light Anti-aircraft battery on Holton Heath,	h 550m north ea CONDITION: TREND: CONTACT: e Range, 650m m CONDITION: TREND: CONTACT: 210m west of Sa	Ast of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Corth east of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Martin
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Round barrow cemetery on Povington Heat         Scheduled Monument (No. 1008026)         Digging         Government or Agency         Thorn Barrow: a bowl barrow on East Holm         Scheduled Monument (No. 1009610)         Plant growth         Government or Agency	h 550m north ea CONDITION: TREND: CONTACT: e Range, 650m n CONDITION: TREND: CONTACT:	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Forth east of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Indford House, Wareham St Martin Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: OWNER TYPE: SITE NAME: DESIGNATION:	Round barrow cemetery on Povington Heat         Scheduled Monument (No. 1008026)         Digging         Government or Agency         Thorn Barrow: a bowl barrow on East Holm         Scheduled Monument (No. 1009610)         Plant growth         Government or Agency         Light Anti-aircraft battery on Holton Heath,         Scheduled Monument (No. 1019153)	h 550m north ea CONDITION: TREND: CONTACT: e Range, 650m n CONDITION: TREND: CONTACT: 210m west of Sa CONDITION:	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Forth east of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Indford House, Wareham St Martin Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION:	Round barrow cemetery on Povington Heat         Scheduled Monument (No. 1008026)         Digging         Government or Agency         Thorn Barrow: a bowl barrow on East Holm         Scheduled Monument (No. 1009610)         Plant growth         Government or Agency         Light Anti-aircraft battery on Holton Heath,         Scheduled Monument (No. 1019153)         Deterioration – in need of management	h 550m north ea CONDITION: TREND: CONTACT: e Range, 650m n CONDITION: TREND: 210m west of Sa CONDITION: TREND:	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Forth east of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Indford House, Wareham St Martin Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION:	Round barrow cemetery on Povington Heat         Scheduled Monument (No. 1008026)         Digging         Government or Agency         Thorn Barrow: a bowl barrow on East Holm         Scheduled Monument (No. 1009610)         Plant growth         Government or Agency         Light Anti-aircraft battery on Holton Heath,         Scheduled Monument (No. 1019153)	h 550m north ea CONDITION: TREND: CONTACT: e Range, 650m n CONDITION: TREND: CONTACT: 210m west of Sa CONDITION:	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Forth east of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Indford House, Wareham St Martin Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: OWNER TYPE: SITE NAME: DESIGNATION:	Round barrow cemetery on Povington Heat         Scheduled Monument (No. 1008026)         Digging         Government or Agency         Thorn Barrow: a bowl barrow on East Holm         Scheduled Monument (No. 1009610)         Plant growth         Government or Agency         Light Anti-aircraft battery on Holton Heath,         Scheduled Monument (No. 1019153)         Deterioration – in need of management	h 550m north ea CONDITION: TREND: CONTACT: e Range, 650m m CONDITION: TREND: CONTACT: 210m west of Sa CONDITION: TREND: CONDITION:	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Forth east of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Indford House, Wareham St Martin Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Round barrow cemetery on Povington Heat         Scheduled Monument (No. 1008026)         Digging         Government or Agency         Thorn Barrow: a bowl barrow on East Holm         Scheduled Monument (No. 1009610)         Plant growth         Government or Agency         Light Anti-aircraft battery on Holton Heath,         Scheduled Monument (No. 1019153)         Deterioration – in need of management         Private	h 550m north ea CONDITION: TREND: CONTACT: e Range, 650m m CONDITION: TREND: CONTACT: 210m west of Sa CONDITION: TREND: CONDITION:	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Forth east of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Indford House, Wareham St Martin Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Round barrow cemetery on Povington Heat         Scheduled Monument (No. 1008026)         Digging         Government or Agency         Thorn Barrow: a bowl barrow on East Holm         Scheduled Monument (No. 1009610)         Plant growth         Government or Agency         Light Anti-aircraft battery on Holton Heath,         Scheduled Monument (No. 1019153)         Deterioration – in need of management         Private         Royal Naval Cordite Factory at Holton Heat	h 550m north ea CONDITION: TREND: CONTACT: e Range, 650m m CONDITION: TREND: CONTACT: 210m west of Sa CONDITION: TREND: CONTACT: treend: CONTACT:	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Forth east of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Indford House, Wareham St Martin Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Idartin
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Round barrow cemetery on Povington Heat         Scheduled Monument (No. 1008026)         Digging         Government or Agency         Thorn Barrow: a bowl barrow on East Holm         Scheduled Monument (No. 1009610)         Plant growth         Government or Agency         Light Anti-aircraft battery on Holton Heath,         Scheduled Monument (No. 1019153)         Deterioration – in need of management         Private         Royal Naval Cordite Factory at Holton Heat	h 550m north ea CONDITION: TREND: CONTACT: e Range, 650m m CONDITION: TREND: CONTACT: 210m west of Sa CONDITION: TREND: CONTACT: treend: CONTACT:	st of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 orth east of Whiteway Farm, Tyneham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ndford House, Wareham St Martin Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 fartin Generally unsatisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Bindon Hill camp, West Lulworth		
DESIGNATION:	Scheduled Monument (No. 1002705)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 370m east of Belhuish Farm:		
	one of a group of barrows to the west of B	urngate Wood, W	est Lulworth
DESIGNATION:	Scheduled Monument (No. 1008220)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 400m ENE of Belhuish Farm: one of a group of barrows to the west of B	urngate Wood, W	/est Lulworth
DESIGNATION:	Scheduled Monument (No. 1012050)		Extensive significant problems
		condition.	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 650m south east of Belhuish F one of a group of barrows to the west of Be		est Lulworth
DESIGNATION:	Scheduled Monument (No. 1008455)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
DWNER TYPE:	Private Drove Hill round barrows, Winfrith Newbur		Business Manager 0117 975 0700
			Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
SITE NAME:	Drove Hill round barrows, Winfrith Newbu	rgh	Generally unsatisfactory
SITE NAME: DESIGNATION:	Drove Hill round barrows, Winfrith Newbur Scheduled Monument (No. 1002765)	rgh CONDITION:	Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Drove Hill round barrows, Winfrith Newbur Scheduled Monument (No. 1002765) Extensive animal burrowing	r <b>gh</b> CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE:	Drove Hill round barrows, Winfrith Newbur Scheduled Monument (No. 1002765) Extensive animal burrowing Government or Agency	r <b>gh</b> CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Drove Hill round barrows, Winfrith Newbur Scheduled Monument (No. 1002765) Extensive animal burrowing Government or Agency Bindon Abbey (site), Wool Scheduled Monument (No. 1002703)	rgh CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Drove Hill round barrows, Winfrith Newbur Scheduled Monument (No. 1002765) Extensive animal burrowing Government or Agency Bindon Abbey (site), Wool	rgh CONDITION: TREND: CONTACT: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Drove Hill round barrows, Winfrith Newbur         Scheduled Monument (No. 1002765)         Extensive animal burrowing         Government or Agency         Bindon Abbey (site), Wool         Scheduled Monument (No. 1002703)         Deterioration – in need of management         Private	rgh CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Drove Hill round barrows, Winfrith Newbur         Scheduled Monument (No. 1002765)         Extensive animal burrowing         Government or Agency         Bindon Abbey (site), Wool         Scheduled Monument (No. 1002703)         Deterioration – in need of management         Private         Bowl barrow 300m south east of Hyford Comparison	rgh CONDITION: TREND: CONTACT: CONTACT: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION:	Drove Hill round barrows, Winfrith Newbur         Scheduled Monument (No. 1002765)         Extensive animal burrowing         Government or Agency         Bindon Abbey (site), Wool         Scheduled Monument (No. 1002703)         Deterioration – in need of management         Private         Bowl barrow 300m south east of Hyford Construction         Scheduled Monument (No. 1015894)	rgh CONDITION: TREND: CONTACT: CONTACT: TREND: CONTACT: TREND: CONTACT: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Drove Hill round barrows, Winfrith Newbur         Scheduled Monument (No. 1002765)         Extensive animal burrowing         Government or Agency         Bindon Abbey (site), Wool         Scheduled Monument (No. 1002703)         Deterioration – in need of management         Private         Bowl barrow 300m south east of Hyford Construction         Scheduled Monument (No. 1015894)         Extensive animal burrowing	rgh CONDITION: TREND: CONTACT: CONTACT: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Improving
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION:	Drove Hill round barrows, Winfrith Newbur         Scheduled Monument (No. 1002765)         Extensive animal burrowing         Government or Agency         Bindon Abbey (site), Wool         Scheduled Monument (No. 1002703)         Deterioration – in need of management         Private         Bowl barrow 300m south east of Hyford Construction         Scheduled Monument (No. 1015894)	rgh CONDITION: TREND: CONTACT: CONTACT: TREND: CONTACT: TREND: CONTACT: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY:	Drove Hill round barrows, Winfrith Newbur         Scheduled Monument (No. 1002765)         Extensive animal burrowing         Government or Agency         Bindon Abbey (site), Wool         Scheduled Monument (No. 1002703)         Deterioration – in need of management         Private         Bowl barrow 300m south east of Hyford Construction         Scheduled Monument (No. 1015894)         Extensive animal burrowing	rgh CONDITION: TREND: CONTACT: CONTACT: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Improving
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Drove Hill round barrows, Winfrith Newbur         Scheduled Monument (No. 1002765)         Extensive animal burrowing         Government or Agency         Bindon Abbey (site), Wool         Scheduled Monument (No. 1002703)         Deterioration – in need of management         Private         Bowl barrow 300m south east of Hyford Co         Scheduled Monument (No. 1015894)         Extensive animal burrowing         Private	rgh CONDITION: TREND: CONTACT: CONTACT: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Improving
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Drove Hill round barrows, Winfrith Newbur         Scheduled Monument (No. 1002765)         Extensive animal burrowing         Government or Agency         Bindon Abbey (site), Wool         Scheduled Monument (No. 1002703)         Deterioration – in need of management         Private         Bowl barrow 300m south east of Hyford Comparison         Scheduled Monument (No. 1015894)         Extensive animal burrowing         Private         Bowl barrow 380m north west of Hyford Comparison	rgh CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CO	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Improving Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Two bowl barrows 85m and 130m south we	est of Cambrai Ho	ouse, Wool
DESIGNATION:	Scheduled Monument (No. 1020738)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow on Emmett's Hill, Worth Matr	ravers	
DESIGNATION:	Scheduled Monument (No. 1017268)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow on St Aldhelm's Head, 470m r	orth east of St Al	dhelm's Chapel, Worth Matravers
DESIGNATION:	Scheduled Monument (No. 1017267)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Early Christian enclosure on St Aldhelm's H	lead, Worth Matra	vers
DESIGNATION:	Scheduled Monument (No. 1017308)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Acton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Benjamin Webb (LPA) 01929 556561	NEW ENTRY?:	No
SITE NAME:	Chaldon Herring		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Benjamin Webb (LPA) 01929 556561	NEW ENTRY?:	No
SITE NAME:	East Lulworth		
DESIGNATION:	Conservation Area	CONDITION:	At risk
/ULNERABILITY:	Unknown	TREND:	Improving
CONTACT:	Benjamin Webb (LPA) 01929 556561	NEW ENTRY?:	No
SITE NAME:	Kimmeridge		
DESIGNATION:	Conservation Area	CONDITION:	At risk
/ULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Benjamin Webb (LPA) 01929 556561	NEW ENTRY?:	No
SITE NAME:	Wareham and Stoborough		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Improving

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### HERITAGE AT RISK 2011 / SOUTH WEST / PURBECK / WEST DORSET

SITE NAME:	West Lulworth		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Benjamin Webb (LPA) 01929 556561	NEW ENTRY?:	No

East Street, Bridport       B55 as Liteary and Scientific Institute Logan Counces         Procession       Listed Building Grade II*, CA         counces       Poor         counces       C(C)         counces       C(C)         counces       Stream         more train       Local authority         counces       Fair         counces       Fair      <	WEST DORSET						
Image: Second		SITE NAME:	East Street,	has a long lease on the building but has instituted legal			
Occurrence       Viscant       on for community purposes, and discussions are underway with the LPA and EH.         Occurrence       C (C)       contact: Jenny Chesher 0117 975 0686         Sile NAME       Messrs Norman goods warehouse, Station Road, West Bay, Bridgort       C18, possibly older. Former bonded stores. Vacant with no user identified.         Discourse       Exteed Building Grade II*       Contact: Jenny Chesher 0117 975 0686         Sile NAME       Nate       Contact: Jenny Chesher 0117 975 0686         Sile NAME       Nate       Contact: Jenny Chesher 0117 975 0686         Sile NAME       The Riding School, Wolfeton Manor, Wolfeton, Charminster       One of the oldest surviving riding schools in England, late C16. Currently used as a bain In Trust ownership awaiting major repairs. Temporary In Trust show be undertaken with English Heritage grant ald. Specification repair and some alteration has been prepares have be undertaken with English Heritage. Phasing of works anticipated begining 2011/12.         Site NAME       Marshwood       Contact: Sarah Bail 0117 975 0666         Site NAME       Marshwood       The site comprises a rectangular earthwork enclosure a moal fampts and the motter. These masonry struct require consolidation and careful ongoing management Contact: Shane Gould 0117 975 0671         Site NAME       Remains of Old Parish Church of St Mary Magdalene, Nich Woottow       Vest tower of former parish church. Early C15. The na d chance! were demolished circa 1883 when the C1 contact: Shane Gould 0117 975 0671         Si		DESIGNATION:	Listed Building Grade II*, CA	disposed of A court hearing has been adjourned to			
Image: Second		CONDITION:	Poor	establish the feasibility of a local trust taking the building			
PRORITY:       C (C)         ownextme:       Local authority         STEINER:       Messrs Norman goods warehouse, Station Road, West Bay, Bridport       Cl 8, possibly older. Former bonded stores. Vacant with no user identified.         STEINER:       Isted Building Grade II*       Contact: Jenny Chesher 0117 975 0686         COLUMNEX:       Vacant       Contact: Jenny Chesher 0117 975 0686         STEINER:       The Riding School, Wolfecon Manor, Wolfecon, Contartise Private       Contact: Jenny Chesher 0117 975 0686         STEINER:       The Riding School, Wolfecon Manor, Wolfecon, Contartise Private       One of the oldest surviving riding schools in England, late C16, Currenty used as a barn. In Trust ownership awaiting major repairs Fave bounder taken with English Heritage grant ad. Specificatio repair and some alteration has been prepared with grant aud from English Heritage. Phasing of works anticipated beginning 2011/12.         STEINER:       Marshwood       Contact: Sarah Ball 0117 975 0666         STEINER:       Marshwood       The site comprises a rectangular earthwork enclosure a most (party prilled). There are substantial remains of a internal ramparts and the motte. These masonry struct require consolidation and careful ongoing management consumers:         OCOLUMNEX:       N/A median:       Contact: Shane Gould 0117 975 0671         STEINER:       Remains of Old Parish Church of St Mary Magdaleen, North Wootney       West tower of former parish church. Early C15. The na and chancel were demolished cira 1833 whenth the C1 worth was		OCCUPANCY:	Vacant	underway with the LPA and EH.			
STE NAME       Messrs Norman goods warehouse, Bridport       CI8, possibly older. Former bonded stores. Vacant with no user identified.         Descentroe:       Listed Building Grade II* CONDITION: Fair OCCUMANCY: Vacant HORITY: E (E)       Contact: Jenny Chesher 0117 975 0666         STE NAME:       The Riding School, Wolfeton Manor, Wolfeton, Charminster       One of the oldest surviving riding schools in England, Nederation Mass part of the oldest surviving riding schools in England, Wolfeton Manor, Wolfeton, Charminster         STE NAME:       The Riding School, Wolfeton Manor, Wolfeton, Charminster       One of the oldest surviving riding schools in England, Molfeton Manor, Wolfeton, Charminster         STE NAME:       The Riding Grade II*, CA contacts: Rart Occupied moleculation with English Heritage Part add Specification contantow. Very bad doccumence:       One of the oldest surviving riding schools in England, Molfeton Highsh Heritage Part of the part of the oldest surviving riding schools in England, the one after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after and some after		PRIORITY:	C (C)				
Station Road, West Bay, Bridport       Vacant with no user identified.         Descrution:       Fair         OCCUPANCE:       Vacant         PHORETY:       E [G]         OWNERTYME       The Riding School, Wolfeton Manor, Wolfeton, Charminster       One of the oldest surviving riding schools in England, Later C16. Currently used as a barn. In Trust ownership awaiting major repairs. Temporary roof repairs have be repair and some atteration has been prepared with gra aid from English Heritage prant aid. Specificatio repair and some atteration has been prepared with gra aid from English Heritage. Phasing of works anticipated becommen:         Discontine:       D (D)         Ownerstrie:       The Arshwood Castle, Marshwood         Streme:       Marshwood Castle, Marshwood         Streme:       Numeric C (C)         Ownerstrie:       Contact: Sanah Ball 0117 975 0666         Streme:       Marshwood Castle, Marshwood       The site comprises a rectangular earthwork enclosure a moat (parthy filled). There are substantial remains of the major ramparts and the motte. These masonry struct require consolidation and careful ongoing management         ORDERTY:       D (C)       Contact: Shane Gould 0117 975 0671         Streme:       Remains of Old Parish Church of & thary Magdalene, North Wootton       West tower of former parish church. Early C15. The parish and chancel were demolshed circa 1883 when the C14 church was built. The tower is completely encased with and in a nuinous condition. In need of repairs, particula to the roof. Rem		OWNER TYPE:	Local authority	Contact: Jenny Chesher 0117 975 0686			
control Fair         occurrence:       Vacant         montry:       E (E)         owner:       File         owner:       E (E)         owner:       Private         owner:       File         owner:       Private		SITE NAME:	Station Road, West Bay,				
OCCUPANCE:       Vacant PRORTY:       E (E) OWNERTIME       Contact: Jenny Chesher 0117 975 0686         STE NAME:       The Riding School, Wolfeton Manor, Wolfeton, Charminster       One of the oldest surviving riding schools in England, late C16. Currently used as a barn. In Trust ownership awaiting major repairs. Tarepoints have be under taken with English Heritage grant aid. Specificatio repair and some alteration has been prepared with gra aid from English Heritage. Phasing of works anticipated beginning 2011/12.         OCUPANCE:       Part occupied PRORTY:       D (D)         OWNERTIME:       Trust       Contact: Sarah Ball 0117 975 0666         STE NAME:       Marshwood Castle, Marshwood       The site comprises a rectangular earthwork enclosure a most further larger and the moster. These masonry struct require consolidation and careful ongoing management         OUDITION:       Poor       Contact: Shane Gould 0117 975 0671         STE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton       West tower of former parish church. Early C15. The na and chancel were demolished circa 1883 when the C1' church was built. The tower is completely encased with and na narinous condition. In eed of repairs, particular to the roof. Removal of ivy and consolidation works started March 2011.		DESIGNATION:	Listed Building Grade II*				
IFFLORETTY:       E (E)         OWNERTTYPE       Private         Contact: Jenny Chesher 0117 975 0686         Image: Stremark St		CONDITION:	Fair				
OWNERTING       Private       Contact: Jenny Chesher 0117 975 0686         STE NAME       The Riding School, Wolfeton Manor, Wolfeton, Charminster       One of the oldest surviving riding schools in England, late C16. Currently used as a barn. In Trust ownership pavaiting major repairs. Temporary roof repairs have be undertaken with English Heritage grant aid. Specification repair and some alteration has been prepared with Specification repair and the motte. These masony struct require consolidation and careful ongoing management condition and careful ongoing management condition with Stated Building Grade I, SM controne         STE NAME       Remains of Old Parish Church of St Mary Magdalene, North Wootton       West tower of former parish church. Early C15. The na and chancel were demolished circa 1893 when the C14 church was built. The tower is completely encased with and chancel were demolished circa 1893 when the C14 church was built. The tower is completely encased with and chancel were demolished circa 1893 when the C14 church was built. The tower is com		OCCUPANCY:	Vacant				
STE NAME       The Riding School, Wolfston Manor, Wolfston, Charminster       One of the oldest surviving riding schools in England, late C16. Currently used as a barn. In Trust ownership awaiting major repairs. Elemporary roof repairs have be undertaken with English Heintage grant aid. Specificatio conditione: Very bad         CONDITION:       Procent:         D (D)       Ownerstrie:         Ownerstrie:       D (D)         Contact:       Sarah Ball 0117 975 0666         STE NAME:       Marshwood         STE NAME:       Marshwood         Descentation:       Listed Building Grade I, SM         CONDITION:       Poor         OCCUPANCE:       N/A         PROVET:       C (C)         Owner three:       Private         Construct:       Shane Gould 0117 975 0671         STE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton       West tower of former parish church, Early C15. The n		PRIORITY:	E (E)				
Wolfeton Manor, Wolfeton, Charminster       late C16. Currently used as a barn. In Trust ownership awaiting major repairs. Temporary roof repairs have be undertaken with English Heritage. Pranary roof repairs have be undertaken with English Heritage. Phasing of works anticipated beginning 2011/12.         Image: Steen Namor, Wolfeton, CONDITION:       Very bad occurrent.       isted Building Grade II*, CA PRORITY:       D (D)         Image: Steen Namor, Wolfeton, CONDITION:       Very bad occurrent.       Contact: Sarah Ball 0117 975 0666         Image: Steen Namor, Wolfeton, With Trust       Marshwood Castle, Marshwood       The site comprises a rectangular earthwork enclosure a moat (partly filled). There are substantial remains of the internal ramparts and the motte. These masonry struct require consolidation and careful ongoing management CONDITION:         Image: Stee NAME:       N/A PRORITY:       C (C) Contact: Shane Gould 0117 975 0671         Image: Stee NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton       West tower of former parish church. Early C15. The na and chancel were demolished circa 1883 when the C14 and in a ruinous condition. In need of repairs, particular to the roof. Removal of ity and consolidation works started March 2011.		OWNER TYPE:	Private	Contact: Jenny Chesher 0117 975 0686			
Desided and the listed building Grade II*, CA       repair and some alteration has been prepared with gra aid from English Heritage. Phasing of works anticipated beginning 2011/12.         PRORTY:       D (D)         OWNER TYPE       Trust         CONDITION:       Listed Building Grade II*, CA         PRORTY:       D (D)         OWNER TYPE       Trust         CONDITION:       Listed Building Grade I, SM         CONDITION:       Listed Building Grade I, SM         CONDITION:       Listed Building Grade I, SM         CONDITION:       C (C)         OCCUPANCE:       N/A         PRORTY:       C (C)         OWNER TYPE       Private         CONDITION:       STE NAME:         Remains of Old Parish Church of St Mary Magdalene, North Wootton       Contact: Shane Gould 0117 975 0671         STE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton       West tower of former parish church. Early CI5. The na and chancel were demolished circa 1883 when the CI's tourch was built. The tower is completely encased with and in a ruinous condition. In need of repairs, particular to the roof. Removal of ivy and consolidation works started March 2011.         DESIGNATION:       Listed Building Grade II*, SM       Contact: All March 2011.	mineral all a start in the		Wolfeton Manor, Wolfeton, Charminster	late C16. Currently used as a barn. In Trust ownership awaiting major repairs. Temporary roof repairs have been			
OCCUPANCY:       Part occupied       beginning 2011/12.       beginning 2011/12.         PRORITY:       D (D)       Contact: Sarah Ball 0117 975 0666         SITE NAME:       Marshwood Castle, Marshwood       The site comprises a rectangular earthwork enclosure a moat (partly filled). There are substantial remains of t internal ramparts and the motte. These masonry struct require consolidation and careful ongoing management         ONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY:       C (C)         OWNERTYPE:       Private         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY:       C (C)         OWNERTYPE:       Private         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY:       C (C)         OWNERTYPE:       Private         SITE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton         DESIGNATION:       Listed Building Grade II*, SM         CONDITION:       Poor         OCCUPANCY:       N/A         PRORITY:       D (D)		DESIGNATION:	Listed Building Grade II*, CA	repair and some alteration has been prepared with grant			
PRIORITY:       D (D) OWNERTYPE       Contact: Sarah Ball 0117 975 0666         SITE NAME       Marshwood       Contact: Sarah Ball 0117 975 0666         SITE NAME       Marshwood       The site comprises a rectangular earthwork enclosure a moat (partly filled). There are substantial remains of t internal ramparts and the motte. These masonry struct require consolidation and careful ongoing management         DESIGNATION:       Listed Building Grade I, SM       Contact: Shane Gould 0117 975 0671         CONDITION:       Poor       Contact: Shane Gould 0117 975 0671         SITE NAME       Remains of Old Parish Church of St Mary Magdalene, North Wootton       Contact: Shane Gould 0117 975 0671         SITE NAME       Remains of Old Parish Church of St Mary Magdalene, North Wootton       West tower of former parish church. Early C15. The na and chancel were demolished circa 1883 when the C14 church was built. The tower is completely encased with and in a ruinous condition. In need of repairs, particular to the roof. Removal of ivy and consolidation works started March 2011.         CONDITION:       Poor         OCCUPANCY:       N/A         PRORITY:       D (D)			1				
OWNERTYPE       Trust       Contact: Sarah Ball 0117 975 0666         SITE NAME       Marshwood Castle, Marshwood       The site comprises a rectangular earthwork enclosure a moat (partly filled). There are substantial remains of the internal ramparts and the motte. These masonry struct require consolidation and careful ongoing management         DESIGNATION:       Eisted Building Grade I, SM CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY:       C (C)         OWNERTYPE       Private         SITE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton         DESIGNATION:       Listed Building Grade II*, SM         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY:       D (D)		OCCUPANCY:	Part occupied	beginning 2011/12.			
SITE NAME       Marshwood Castle, Marshwood       The site comprises a rectangular earthwork enclosure a moat (partly filled). There are substantial remains of tinternal ramparts and the motte. These masonry struct require consolidation and careful ongoing management         DESIGNATION:       Listed Building Grade I, SM         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY:       C (C)         OWNER TYPE       Private         SITE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton         DESIGNATION:       Listed Building Grade II*, SM         CONDITION:       Designation:         DESIGNATION:       Listed Building Grade II*, SM         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY:       D (D)		PRIORITY:	D (D)				
Marshwood       a moat (partly filled). There are substantial remains of t internal ramparts and the motte. These masonry struct require consolidation and careful ongoing management         DESIGNATION:       Listed Building Grade I, SM         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY:       C (C)         OWNER TYPE       Private         STE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton         DESIGNATION:       Listed Building Grade II*, SM         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY:       D (D)		OWNER TYPE:	Trust	Contact: Sarah Ball 0117 975 0666			
DESIGNATION:       Listed Building Grade I, SM         CONDITION:       Poor         OCCUPANCY:       N/A         PRORITY:       C (C)         OWNERTYPE       Private         SITE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton       Contact: Shane Gould 0117 975 0671         West tower of former parish church. Early C15. The na and chancel were demolished circa 1883 when the C10 church was built. The tower is completely encased with and in a ruinous condition. In need of repairs, particular to the roof. Removal of ivy and consolidation works started March 2011.         DESIGNATION:       D (D)		SITE NAME:	Marshwood Castle,	The site comprises a rectangular earthwork enclosure with			
DESIGNATION:       Listed Building Grade I, SM         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY:       C (C)         OWNER TYPE       Private         SITE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton       Contact: Shane Gould 0117 975 0671         West tower of former parish church. Early C15. The na and chancel were demolished circa 1883 when the C14 church was built. The tower is completely encased with and in a ruinous condition. In need of repairs, particular to the roof. Removal of ivy and consolidation works started March 2011.         OCCUPANCY:       N/A         PRIORITY:       D (D)				internal ramparts and the motte. These masonry structures			
OCCUPANCY:       N/A         PRIORITY:       C (C)         OWNER TYPE       Private         STEE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton       Contact: Shane Gould 0117 975 0671         STEE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton       West tower of former parish church. Early C15. The na and chancel were demolished circa 1883 when the C19 church was built. The tower is completely encased with and in a ruinous condition. In need of repairs, particular to the roof. Removal of ivy and consolidation works started March 2011.         OCCUPANCY:       N/A         PRIORITY:       D (D)		DESIGNATION:	-	rodan o consonadaon and caronar ongoing management			
PRIORITY:       C (C)         OWNER TYPE       Private         SITE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton       Contact: Shane Gould 0117 975 0671         DESIGNATION:       Listed Building Grade II*, SM       West tower of former parish church. Early C15. The na and chancel were demolished circa 1883 when the C14 church was built. The tower is completely encased with and in a ruinous condition. In need of repairs, particular to the roof. Removal of ivy and consolidation works started March 2011.         OCCUPANCY:       N/A PRIORITY:       D (D)							
OWNER TYPE       Private       Contact: Shane Gould 0117 975 0671         SITE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton       West tower of former parish church. Early C15. The na and chancel were demolished circa 1883 when the C19 church was built. The tower is completely encased with and in a ruinous condition. In need of repairs, particular to the roof. Removal of ivy and consolidation works started March 2011.         OCUPANCY:       N/A PRIORITY:       D (D)		OCCUPANCY:					
SITE NAME:       Remains of Old Parish Church of St Mary Magdalene, North Wootton       West tower of former parish church. Early C15. The na and chancel were demolished circa 1883 when the C19 church was built. The tower is completely encased with and in a ruinous condition. In need of repairs, particular to the roof. Removal of ivy and consolidation works started March 2011.         Vest tower of former parish church. Early C15. The na and chancel were demolished circa 1883 when the C19 church was built. The tower is completely encased with and in a ruinous condition. In need of repairs, particular to the roof. Removal of ivy and consolidation works started March 2011.							
of St Mary Magdalene, North Wootton       and chancel were demolished circa I 883 when the CIM         DESIGNATION:       Listed Building Grade II*, SM       condition:         condition:       Poor       other roof. Removal of ivy and consolidation works started March 2011.         PRIORITY:       D (D)		OWNER TYPE:	Private	Contact: Shane Gould 0117 975 0671			
DESIGNATION:       Listed Building Grade II*, SI*I       to the roof. Removal of ivy and consolidation works started March 2011.         CONDITION:       POOR       V/A         PRIORITY:       D (D)	17A	SITE NAME:	of St Mary Magdalene,	West tower of former parish church. Early C15. The nave and chancel were demolished circa 1883 when the C19 church was built. The tower is completely encased with iv			
CONDITION: Poor started March 2011. OCCUPANCY: N/A PRIORITY: D (D)		DESIGNATION:	Listed Building Grade II*, SM				
PRIORITY: D (D)	Alley - The						
		OCCUPANCY:	N/A				
OWNER TYPE         Private         Contact: Shane Gould 0117 975 0671		PRIORITY:	D (D)				
	- Har and and a second	OWNER TYPE:	Private	Contact: Shane Gould 0117 975 0671			
SITE NAME: Cart shed and stables 10 metres south of Waddon House, Portesham Former stables and cart shed, dated 1702. Currently disused with roof temporarily protected. Application for repair and conversion to holiday let		site name:	south of Waddon House,	Currently disused with roof temporarily protected. Application for repair and conversion to holiday let			
DESIGNATION: Listed Building Grade II* use has been approved.		DESIGNATION:	Listed Building Grade II*	use has been approved.			
CONDITION: Poor	the second second		÷				
occupancy: Vacant		OCCUPANCY:	Vacant				
PRIORITY: D (C)		PRIORITY:	D (C)				
OWNER TYPE Private Contact: Jenny Chesher 0117 975 0686	All and a second	OWNER TYPE:		Contact: Jenny Chesher 0117 975 0686			
B Immediate risk of further rapid deterioration or loss of fabric solution repair but no user identified; or with new use agreed but not is given in brackets.	<ul> <li>A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.</li> <li>B Immediate risk of further rapid deterioration or loss of fabric; solution</li> </ul>	but not ye E Under rep repair, but	et implemented. and (where applicable) pair or in fair to good no user identified; or with new use agreed but the supervisit functionally redundant to the supervisit functional	ress NOTE: CA Conservation Area If the priority category LB/LBs Listed Building/s ied; has changed since the 2010 LPA Local Planning Authority buildings register, the previous category ut not is given in brackets. RPG Registered Park and Garden			

agreed but not yet implemented. C Slow decay; no solution agreed.

obvious new user (applicable only to buildings capable of beneficial use).

	SITE NAME:	Sherborne House, Newland, Sherborne	for plannir considerat	ca 1720. Former girls' school. An application ng permission for gallery/office use is under tion, and proposed new development at the
	DESIGNATION:	Listed Building Grade I, CA	securing n	d be subject to a section I06 agreement, epairs to Sherborne House.The building
	CONDITION:	Fair	has been	scaffolded and provided with a temporary
IT TO THE AND OF	OCCUPANCY:	Part occupied	roof struc	ture whilst full repairs are awaited.
	PRIORITY:	D (E)		
		Local authority	Contact: Je	enny Chesher 0117 975 0686
-	SITE NAME:	Stable Block immediately south east of Little Toller Farm, Toller Fratrum	but currer state with	stable building, forming part of a working farm htly disused. Thatched roof is in a very degraded large holes at the rear, through which water
State LAND	DESIGNATION:	Listed Building Grade II*	and interr	on has caused a partial collapse of the rear wall nal floor structure. The local authority has met
	CONDITION:	Very bad		r to discuss the need for urgent repairs.
	OCCUPANCY:	Vacant		- ·
1	PRIORITY:	A (New entry)		
	OWNER TYPE:		Contact: Je	enny Chesher 0117 975 0686
A	SITE NAME:	Former Methodist Chapel, Dorchester Road, Tolpuddle	the Tolpuc West Dor	: church, circa 1818, and the meeting place of ddle Martyrs. Discussions are ongoing between rset District Council and the owner, who has a willingness to sell the site, to find an appropriat
Canada I	DESIGNATION:	Listed Building Grade II*, CA		e building. The possibility of re-instating a
	CONDITION:	Poor	religious/c	ommunity use is being investigated.
	OCCUPANCY:	N/A		
	PRIORITY:	С (С)		
Carlos Maria	OWNER TYPE:	Private	Contact: Je	enny Chesher 0117 975 0686
	SITE NAME:	Parish Church of St Lawrence, Folke	with stone interior. St	uilt 1628, restored 1875. High castellated parapets e tile and Welsh slate roofs.Very good Jacobean cone tile nave roofs failing and all four abutments sle roofs have temporary sheeting in place as
	also failing A Repair Grant for Places of Worshi			
	DESIGNATION:	Listed Place of Worship Grade I	been offered for roof repairs.	
Constant - All - All	CONDITION:	Very bad		
	PRIORITY:	B (New entry)		
	OWNER TYPE:	Religious organisation	Contact: S	Garah Ball 0117 975 0666
SITE NAME:	Barrow ea	ast of Burnt House Bottom, Alton Pan	cras	
DESIGNATION:	Scheduled	Monument (No. 1002862)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clip	pping	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Dyke on I	Haydon Down, Askerswell		
designation:		Monument (No. 1002735)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable plc	( ,	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
Owiner TIFE.	Thvate		CONTACT.	
SITE NAME:	Earthworl	< 80yds (70m) long north west of Coc	mbe Bottor	m, Askerswell
DESIGNATION:	Scheduled	Monument (No. 1002734)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable plc	× ,	TREND:	Declining
OWNER TYPE:	Private	· o · o	CONTACT:	Business Manager 0117 975 0700
	····		contract.	
SITE NAME:	Group of	three round barrows west of Two Ga	tes, Askersw	vell
DESIGNATION:	Scheduled	Monument (No. 1002736)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable plc	× ,	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
RIORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; no solution agreed.	E Under rep repair, but under thre obvious ne	y; solution agreed F Repair scheme in progr at implemented. and (where applicable) end use or user identified; or at of vacancy with no wu ser (applicable only s capable of beneficial use).	ed; has buildings regi	TE: CA Conservation Area LB/LBs Listed Building/s LPA Local Planning Authority NP National Park RPG Registered Park and Gard SM/SMs Scheduled Monument/s UA Unitary Authority WHS World Heritage Site

SITE NAME:	Round barrow north west of Coombe Both	tom, Askerswell	
DESIGNATION:	Scheduled Monument (No. 1003061)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow on Beaminster Down 530m s	outh east of East	Axnoller Farm, Beaminster
DESIGNATION:	Scheduled Monument (No. 1015049)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow on Beaminster Down 770m n	orth east of High	er Meerhay Farm, Beaminster
DESIGNATION:	Scheduled Monument (No. 1015050)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Barrow east of Red Barn, Bradford Peverell		
DESIGNATION:	Scheduled Monument (No. 1002815)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
GITE NAME:	Barrow near Higher Skippet Farm, Bradford	Peverell	
DESIGNATION:	Scheduled Monument (No. 1002819)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bell barrow in Highfield Plantation and two		
	immediately north west of Forty Acre Plant		
DESIGNATION:	Scheduled Monument (No. 1019415)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			5
SITE NAME:	Bowl barrow 380m west of Whitfield Farm	, Bradford Peverel	
DESIGNATION:	Scheduled Monument (No. 1019639)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Discontinuous surviving sections of Roman	aqueduct, Bradfor	rd Peverell
DESIGNATION:	Scheduled Monument (No. 1002730)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of barrows in Seven Barrow Plantati	on, Bradford Peve	rell
DESIGNATION:	Scheduled Monument (No. 1002812)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
IORITY (FOR BUILDINGS)			ABBREVIATIONS

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Long barrow and four bowl barrows 500m	n north west of W	hitfield Farm, Bradford Peverell	
DESIGNATION:	Scheduled Monument (No. 1019416)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Culliford Tree long barrow and group of re	ound barrows, Broa	admayne	
DESIGNATION:	Scheduled Monument (No. 1003304)	CONDITION:	Generally unsatisfactory	
DESIGNATION:	Scheduled Fiondment (140, 1005501)	CONDITION:	with major localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Oval barrow and three bowl barrows 250	m and 330m south	of Whitcombe Barn, Broadmayne	
DESIGNATION:	Scheduled Monument (No. 1019414)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
JITE NAME:	Two bowl barrows on Lord's Down 580m	south east of Cray	wthorne Farm Burleston	
DESIGNATION:	Scheduled Monument (No. 1017277)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining Business Managan 0117 975 0700	
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Bowl barrow on Wood Hill 310m north east of Cowden, Charminster			
DESIGNATION:	Scheduled Monument (No. 1019395)	CONDITION:	Extensive significant problems	
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Round barrow east of Forston Farm. Char	minster		
			Extensive significant problems	
DESIGNATION:	Scheduled Monument (No. 1002851)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing Other	TREND:	Declining Business Manager 0117 975 0700	
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Earthwork and ancient fields south east of	Lyscombe Bottom	n, Cheselbourne	
DESIGNATION:	Scheduled Monument (No. 1002456)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining	
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Group of round barrows north east of Hc	g Leaze, Cheselbo	urne	
DESIGNATION:	Scheduled Monument (No. 1002877)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
		-contact.		
SITE NAME:	Round barrow on Cheselbourne West Do	wn, Cheselbourne		
DESIGNATION:	Scheduled Monument (No. 1002878)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
	Other		Business Manager 0117 975 0700	

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bowl barrow 360m south of Compton Bar	n, Compton Valeno	e	
DESIGNATION:	Scheduled Monument (No. 1019741)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Settlement south east of Soaper's Hill Plant	ation, Compton Va	lence	
DESIGNATION:	Scheduled Monument (No. 1003234)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Bowl barrow 450m east of Dennet's Bottom Barn, Dewlish			
DESIGNATION:	Scheduled Monument (No. 1015427)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
			Jan	
TE NAME:	Bowl barrow 550m WNW of West End Ba	rn, Dewlish		
DESIGNATION:	Scheduled Monument (No. 1015032)	CONDITION:	Extensive significant problems	
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Earthwork east of Stake Farm, East Chelbo	rough		
		-		
DESIGNATION:	Scheduled Monument (No. 1002845)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
RINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:		
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
ITE NAME:	Bell barrow and five bowl barrows 1000m s part of the Black Down round barrow cem			
DESIGNATION:	Scheduled Monument (No. 1011693)	CONDITION:	Extensive significant problems	
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Bowl barrow 550m north east of Pitcombe round barrow cemetery, Kingston Russell	Farm, part of the	Black Down	
DESIGNATION:	Scheduled Monument (No. 1011694)			
	Scheduled Flohument (140, 1011074)	CONDITION:	Generally unsatisfactory	
	Scheduled Hondment (No. 1011074)	CONDITION:	Generally unsatisfactory with major localised problems	
	Arable clipping	CONDITION: TREND:	, , ,	
RINCIPAL VULNERABILITY:			with major localised problems	
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Arable clipping	TREND: CONTACT: Iouse, forming par	with major localised problems Declining Business Manager 0117 975 0700	
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Arable clipping Other Bowl barrow 810m NNE of Whatcombe H	TREND: CONTACT: Iouse, forming par	with major localised problems Declining Business Manager 0117 975 0700	
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION:	Arable clipping Other Bowl barrow 810m NNE of Whatcombe H on the south western part of Black Down,	TREND: CONTACT: Iouse, forming par Kingston Russell	with major localised problems Declining Business Manager 0117 975 0700 t of the round barrow cemetery Generally unsatisfactory	
PRINCIPAL VULNERABILITY: DWNER TYPE:	Arable clipping Other Bowl barrow 810m NNE of Whatcombe H on the south western part of Black Down, Scheduled Monument (No. 1013845)	TREND: CONTACT: louse, forming par Kingston Russell CONDITION:	with major localised problems Declining Business Manager 0117 975 0700 t of the round barrow cemetery Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Arable clipping Other Bowl barrow 810m NNE of Whatcombe H on the south western part of Black Down, Scheduled Monument (No. 1013845) Extensive animal burrowing	TREND: CONTACT: louse, forming par Kingston Russell CONDITION: TREND:	with major localised problems Declining Business Manager 0117 975 0700 to f the round barrow cemetery Generally unsatisfactory with major localised problems Declining	
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Arable clipping Other Bowl barrow 810m NNE of Whatcombe Hon the south western part of Black Down, Scheduled Monument (No. 1013845) Extensive animal burrowing Other Lime kiln 800ft (245m) north west of Lange	TREND: CONTACT: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	with major localised problems Declining Business Manager 0117 975 0700 tof the round barrow cemetery Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700	
PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Arable clipping Other Bowl barrow 810m NNE of Whatcombe H on the south western part of Black Down, Scheduled Monument (No. 1013845) Extensive animal burrowing Other	TREND: CONTACT: CONTACT: CONDITION: CONDITION: TREND: CONTACT:	with major localised problems Declining Business Manager 0117 975 0700 <b>t of the round barrow cemetery</b> Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700	
PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: DITE NAME:	Arable clipping Other Bowl barrow 810m NNE of Whatcombe Hon the south western part of Black Down, Scheduled Monument (No. 1013845) Extensive animal burrowing Other Lime kiln 800ft (245m) north west of Lange	TREND: CONTACT: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONTACT:	with major localised problems Declining Business Manager 0117 975 0700 tof the round barrow cemetery Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Herring Generally satisfactory	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bowl barrow 165m NNW of White Hill Bai forming part of the White Hill round barro	,	bredy
DESIGNATION:	Scheduled Monument (No. 1013260)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 200m south of Winterbourne forming part of the Winterbourne Poor Lo		emetery, l ittlebredy
DESIGNATION:	Scheduled Monument (No. 1013254)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 265m north west of White H forming part of the White Hill round barro	,	bredy
DESIGNATION:	Scheduled Monument (No. 1013261)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 300m WNW of White Hill Ba forming part of the White Hill round barro	,	bredy
DESIGNATION:	Scheduled Monument (No. 1013262)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 340m north west of White H forming part of the White Hill round barro	w cemetery, Little	•
DESIGNATION:	Scheduled Monument (No. 1013264)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 355m north west of White H forming part of the White Hill round barro	,	bredy
		CONDITION:	Extensive significant problems
DESIGNATION:	Scheduled Monument (No. 1013263)		
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	× ,		Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: CONTACT: Vood,	Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable ploughing Other Bowl barrow 500m west of Well Bottom W	TREND: CONTACT: Vood,	Declining Business Manager 0117 975 0700 , Littlebredy Generally unsatisfactory
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Arable ploughing Other Bowl barrow 500m west of Well Bottom W forming part of the Pitcombe Down round	TREND: CONTACT: Vood, barrow cemetery	Declining Business Manager 0117 975 0700 , Littlebredy
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Arable ploughing Other Bowl barrow 500m west of Well Bottom W forming part of the Pitcombe Down round	TREND: CONTACT: Vood, barrow cemetery	Declining Business Manager 0117 975 0700 , Littlebredy Generally unsatisfactory with major localised problems Declining
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Arable ploughing Other Bowl barrow 500m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013250)	TREND: CONTACT: Vood, barrow cemetery CONDITION:	Declining Business Manager 0117 975 0700 , Littlebredy Generally unsatisfactory with major localised problems Declining
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing Other Bowl barrow 500m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013250) Arable clipping	TREND: CONTACT: Vood, barrow cemetery CONDITION: TREND: CONTACT: Vood,	Declining Business Manager 0117 975 0700 , Littlebredy Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Arable ploughing Other Bowl barrow 500m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013250) Arable clipping Other Bowl barrow 600m west of Well Bottom W	TREND: CONTACT: Vood, barrow cemetery CONDITION: TREND: CONTACT: Vood,	Declining Business Manager 0117 975 0700 , Littlebredy Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Arable ploughing Other Bowl barrow 500m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013250) Arable clipping Other Bowl barrow 600m west of Well Bottom W forming part of the Pitcombe Down round	TREND: CONTACT: Vood, barrow cemetery CONDITION: TREND: CONTACT: Vood, barrow cemetery	Declining Business Manager 0117 975 0700 , Littlebredy Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable ploughing Other Bowl barrow 500m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013250) Arable clipping Other Bowl barrow 600m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013249)	TREND: CONTACT: Vood, barrow cemetery CONDITION: TREND: CONTACT: Vood, barrow cemetery CONDITION:	Declining Business Manager 0117 975 0700 , Littlebredy Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 , Littlebredy Extensive significant problems Declining
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing Other Bowl barrow 500m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013250) Arable clipping Other Bowl barrow 600m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013249) Arable ploughing	TREND: CONTACT: Vood, barrow cemetery CONDITION: TREND: CONDITION: barrow cemetery CONDITION: TREND: CONDITION: TREND:	Declining Business Manager 0117 975 0700 , Littlebredy Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 , Littlebredy Extensive significant problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable ploughing Other Bowl barrow 500m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013250) Arable clipping Other Bowl barrow 600m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013249) Arable ploughing Other Bowl barrow 600m west of Well Bottom W	TREND: CONTACT: Vood, barrow cemetery CONDITION: TREND: CONDITION: barrow cemetery CONDITION: TREND: CONDITION: TREND:	Declining Business Manager 0117 975 0700 , Littlebredy Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 , Littlebredy Extensive significant problems Declining Business Manager 0117 975 0700
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Arable ploughing Other Bowl barrow 500m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013250) Arable clipping Other Bowl barrow 600m west of Well Bottom W forming part of the Pitcombe Down round Scheduled Monument (No. 1013249) Arable ploughing Other Bowl barrow 600m west of Well Bottom W forming part of the Pitcombe Down round	TREND: CONTACT: Vood, barrow cemetery CONDITION: TREND: CONTACT: Vood, CONDITION: TREND: CONTACT: Vood, barrow cemetery	Declining Business Manager 0117 975 0700 , Littlebredy Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 , Littlebredy Extensive significant problems Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bowl barrow on Black Down, 870m north	west of the Hardy	Monument, Littlebredy		
DESIGNATION:	Scheduled Monument (No. 1019030)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700		
DITE NAME:	Four bowl barrows 500m west of Well Bot forming part of the Pitcombe Down round	,	, Littlebredy		
DESIGNATION:	Scheduled Monument (No. 1013252)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Three bowl barrows 300m south west of Well Bottom Wood, forming part of the Pitcombe Down round barrow cemetery, Littlebredy				
DESIGNATION:	Scheduled Monument (No. 1013251)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Barrow 650yds (600m) north of North Bar	n Farm, Long Bre	dy		
DESIGNATION:	Scheduled Monument (No. 1002798)	CONDITION:	Generally unsatisfactory		
	````		with major localised problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Barrow 700yds (640m) south west of Nort	h Barn Farm, Long	g Bredy		
DESIGNATION:	Scheduled Monument (No. 1002800)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Bowl barrow on Farm Hill 620m west of M	interne Parva Far	m, Minterne Magna		
DESIGNATION:	Scheduled Monument (No. 1015046)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Bowl barrow 230m north east of Great Str	ode House, Neth	erbury		
DESIGNATION:	Scheduled Monument (No. 1016372)	CONDITION:	Generally unsatisfactory		
			with major localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable clipping Private	TREND: CONTACT:			
		CONTACT:	Declining		
OWNER TYPE:	Private George III, chalk-cut hill side figure, Osming	contact:	Declining Business Manager 0117 975 0700		
OWNER TYPE:	Private	CONTACT:	Declining		
OWNER TYPE:	Private George III, chalk-cut hill side figure, Osming	contact:	Declining Business Manager 0117 975 0700 Generally unsatisfactory		
OWNER TYPE: SITE NAME: DESIGNATION:	Private George III, chalk-cut hill side figure, Osming Scheduled Monument (No. 1005574)	contact:	Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems		
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private George III, chalk-cut hill side figure, Osming Scheduled Monument (No. 1005574) Extensive natural erosion	CONTACT: ton CONDITION: TREND: CONTACT:	Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining		
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private George III, chalk-cut hill side figure, Osming Scheduled Monument (No. 1005574) Extensive natural erosion Private	CONTACT: ton CONDITION: TREND: CONTACT:	Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining		
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private George III, chalk-cut hill side figure, Osming Scheduled Monument (No. 1005574) Extensive natural erosion Private Medieval settlement at West Ringstead, Osr	ton CONDITION: CONDITION: TREND: CONTACT: mington	Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700		

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Four barrows on Moigns Down, Owermoig	gne	
DESIGNATION:	Scheduled Monument (No. 1002774)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow south west of Bourne Farm,	, Piddlehinton	
DESIGNATION:	Scheduled Monument (No. 1004550)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two barrows on Little Puddle Hill, Piddlehir	nton	
DESIGNATION:	Scheduled Monument (No. 1003224)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two barrows west of Little Piddle Down, P	iddlehinton	
DESIGNATION:	Scheduled Monument (No. 1002805)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Barrow on College Down, Piddletrenthide		
DESIGNATION:	Scheduled Monument (No. 1002842)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow on Plush Hill 600m ESE of Lo	wer Farm, Plush, F	Piddletrenthide
DESIGNATION:	Scheduled Monument (No. 1015037)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow on Plush Hill 740m ESE of Lo	wer Farm, Plush, F	Piddletrenthide
DESIGNATION:	Scheduled Monument (No. 1015038)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow on Pond Eweleaze 500m nort	th east of Dole's A	sh Farm, Piddletrenthide
DESIGNATION:	Scheduled Monument (No. 1015035)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow on Hog Leaze, Piddletrenthi	de	
DESIGNATION:	Scheduled Monument (No. 1003238)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ITE NAME:	Bowl barrow on Black Down, 80m south ea	ast of the mardy i	ionument, i or tesnam
DESIGNATION:	Scheduled Monument (No. 1017374)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Group of round barrows on Shorn Hill and	Bronkham Hill, P	ortesham
DESIGNATION:	Scheduled Monument (No. 1002699)	CONDITION:	Generally satisfactory
	, , , , , , , , , , , , , , , , , , , ,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Round barrow north east of Friar Waddon,	Portesham	
DESIGNATION:	Scheduled Monument (No. 1002488)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two bowl barrows on Black Down immedia	ately east of the H	lardy Monument, Portesham
DESIGNATION:	Scheduled Monument (No. 1016729)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two round barrows on Ridgeway, Porteshar	m	
DESIGNATION:	Scheduled Monument (No. 1002758)	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Barrow near east boundary of parish, Powe	rstock	
DESIGNATION:	Scheduled Monument (No. 1002809)	CONDITION:	Generally unsatisfactory
	× /		with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Group of barrows east of Northdown Barr	n, Poxwell	
DESIGNATION:	Scheduled Monument (No. 1002770)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Round barrow west of Druce Higher Barn,	Puddletown	
DESIGNATION:	Scheduled Monument (No. 1002874)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Three round barrows on Puddletown Dow	n, Puddletown	
DESIGNATION:	Scheduled Monument (No. 1002450)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
RIORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	D Slow decay: solution agreed but not yet implemented. F Repair scheme i and (where append use or user Under repair or in fair to good	licable) If the	E: CA Conservation Area priority category LB/LBs Listed Building/s hanged since the 2010 LPA Local Planning Aut er the previous category NP National Park

no solution agreed. **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. **C** Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

has changed since the 2010 register, the previous category is given in brackets.

Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site LPA NP RPG SM/SMs UA WHS

SITE NAME:	Two round barrows south west of Well Ho	use Cottage, Pude	dletown
DESIGNATION:	Scheduled Monument (No. 1002875)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 400m north east of Look Farr	n, Puncknowle	
DESIGNATION:	Scheduled Monument (No. 1016370)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bell barrow 70m west of Fidler's Green, Stir	nsford	
DESIGNATION:	Scheduled Monument (No. 1017262)	CONDITION:	Generally unsatisfactory with major localised problems
	Extensive animal humawing	775115	
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining Rusiness Manager 0117 975 0700
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Round barrow north east of Hog Hill Barn,	Stratton	
DESIGNATION:	Scheduled Monument (No. 1003237)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow north west of Jackman's Cro	oss. Stratton	
	Scheduled Monument (No. 1002470)	CONDITION:	Extensive significant problems
DESIGNATION:			Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	0
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow on Stratton Down, Stratton		
DESIGNATION:	Scheduled Monument (No. 1002871)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Tithe barn at Court Farm, Sydling St Nichol	as	
DESIGNATION:	Scheduled Monument (No. 1003209)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow on Eype Down 275m east of I	Frogmore Farm, S	wmondsbury
DESIGNATION:	Scheduled Monument (No. 1016100)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Holditch Court Tower, Thorncombe		
DESIGNATION:	Scheduled Monument (No. 1002835)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
RIORITY (FOR BUILDINGS)			ABBREVIATIONS
Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution	D Slow decay solution agreed but not yet implemented.         F         Repair scheme ir and (where applied end use or user)           E         Under repair or in fair to good repair but no user identified; or with new use agr         functionally reduing with new use agr	icable) If the identified; has cl ndant buildings regist	

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

with new use agreed but not yet implemented.

register, the previous is given in brackets. egory 
 NP
 National Park

 RPG
 Registered Park and Garden

 SM/SMs
 Scheduled Monument/s

 UA
 Unitary Authority

 WHS
 World Heritage Site

SITE NAME:	Four bowl barrows 710m north, 750m north	i west and 950m	nor th west of Ciy	nie House, loipuddie
DESIGNATION:	Scheduled Monument (No. 1016378)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
WNER TYPE:	Private	CONTACT:	Business Manage	er 0117 975 0700
TE NAME:	Barrow near Eggardon, West Compton			
esignation:	Scheduled Monument (No. 1004567)	CONDITION:	Generally unsatis with major locali	,
RINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
WNER TYPE:	Private	CONTACT:	0	er 0117 975 0700
ITE NAME:	Dyke south east of Eggardon Hill camp, Wes	t Compton		
DESIGNATION:	Scheduled Monument (No. 1002404)	CONDITION:	Extensive signific	ant problems
	Arable ploughing	TREND:	Declining	ant problems
RINCIPAL VULNERABILITY:	Private	CONTACT:	•	er 0117 975 0700
WVINER I TPE:	TTVale	CONTACT:	Dusiness i lanage	
ITE NAME:	Bowl barrow on Whitcombe Hill 500m nort	h of Whitcombe	Farm, West Staffo	rd
esignation:	Scheduled Monument (No. 1017282)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Other	CONTACT:	Business Manage	er 0117 975 0700
ITE NAME:	Enclosure on Mount Pleasant Hill, West Staff	ord		
DESIGNATION:	Scheduled Monument (No. 1002463)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	•	er 0117 975 0700
			0	
ITE NAME:	Two bowl barrows on Frome Hill 520m wes	t of Frome Farm	,	
DESIGNATION:	Scheduled Monument (No. 1019875)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manage	er 0117 975 0700
SITE NAME:	Three bowl barrows 530m and 350m north	east of Whitcom	ıbe Barn, Whitcom	ıbe
DESIGNATION:	Scheduled Monument (No. 1019413)	CONDITION:	Extensive signific	ant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Business Manage	er 0117 975 0700
ITE NAME:	Two round barrows north of Came Farm, W	/interborne Cam	e	
DESIGNATION:	Scheduled Monument (No. 1002828)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Other	CONTACT:	0	er 0117 975 0700
ITE NAME:	Long barrow immediately north west of Mai	den Castle. Wint	erborne Monkton	
	- ,			ant pupple
DESIGNATION:	Scheduled Monument (No. 1015779)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing Other	TREND:	Declining Business Manage	er 0117 975 0700
DWNER TYPE:		CONTACT:	Dusiness Fidhage	
ITE NAME:	Long barrow, three bell barrows, fancy barro 800m north of Maiden Castle, Winterborne		arthwork	
DESIGNATION:	Scheduled Monument (No. 1015783)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	0	er 0117 975 0700
RIORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	D Slow decay; solution agreed but not yet implemented. F Repair scheme in and (where applic end use or user ic	able) If the	E: priority category nanged since the 2010	ABBREVIATIONS CA Conservation Area LB/LBs Listed Building/s LPA Local Planning Authorit
Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; no solution agreed.	E Under repair or in fair to good functionally redunt repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).	dant buildings regist	er, the previous category en in brackets.	NP National Park RPG Registered Park and Gz SM/SMs Scheduled Monument/s UA Unitary Authority WHS World Heritage Site

SITE NAME:	Round barrow cemetery immediately south	n east of Maiden C	Castle, Winterborne Monkton
DESIGNATION:	Scheduled Monument (No. 1015778)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Settlement remains north of Maiden Castle	, Winterborne Mo	onkton
DESIGNATION:	Scheduled Monument (No. 1002409) with major localised problems	CONDITION:	Generally unsatisfactory
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of barrows south of Goldsmith's Pla	ntation, Winterbo	rne St Martin
DESIGNATION:	Scheduled Monument (No. 1002810)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Group of round barrows near Eweleaze Ba	rn, Winterborne S	St Martin
DESIGNATION:	Scheduled Monument (No. 1002756)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of round barrows on and to east of	Great Hill, Winte	rborne St Martin
DESIGNATION:	Scheduled Monument (No. 1004564)	CONDITION:	Generally unsatisfactory
	``````````````````````````````````````		with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow north of Ballarat House, Wi	nterborne St Mar	tin
DESIGNATION:	Scheduled Monument (No. 1003236)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow north of Ridgeway, Winterb	orne St Martin	
DESIGNATION:	Scheduled Monument (No. 1002759)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrows on Four Barrow Hill, Winte	erborne St Martin	
DESIGNATION:	Scheduled Monument (No. 1002755)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
	Round barrows on Grove Hill, Winterborne St Martin		
SITE NAME:	Round barrows on Grove Hill, Winterborn	e St Martin	
SITE NAME: DESIGNATION:	Round barrows on Grove Hill, Winterborn Scheduled Monument (No. 1002757)		Extensive significant problems
			Extensive significant problems Declining

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

	Three barrows south of Hart Hill Plantatio	n, Winterborne St	: Martin
DESIGNATION:	Scheduled Monument (No. 1002814)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two barrows at Rew, Winterborne St Mart	in	
DESIGNATION:	Scheduled Monument (No. 1002811)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bell barrow 100m south of Winterbourne I part of the Winterbourne Poor Lot round	,	Winterbourne Abbas
DESIGNATION:	Scheduled Monument (No. 1012027)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 400m north east of Manor Fa part of the Pound Hill round barrow ceme		e Abbas
DESIGNATION:	Scheduled Monument (No. 1011692)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 450m north east of Manor Fa part of the Pound Hill round barrow ceme		e Abbas
			e Abbas Generally unsatisfactory with major localised problems
DESIGNATION:	part of the Pound Hill round barrow ceme	tery, Winterbourn	Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY:	part of the Pound Hill round barrow cemer Scheduled Monument (No. 1011691)	tery, Winterbourn condition:	Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	part of the Pound Hill round barrow cemer Scheduled Monument (No. 1011691) Arable clipping	tery, Winterbourn Condition: Trend:	Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	part of the Pound Hill round barrow cemer Scheduled Monument (No. 1011691) Arable clipping Other	tery, Winterbourn Condition: Trend:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	part of the Pound Hill round barrow cemer         Scheduled Monument (No. 1011691)         Arable clipping         Other         Broad Stone, Winterbourne Abbas         Scheduled Monument (No. 1002686)	CONDITION: TREND: CONTACT: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	part of the Pound Hill round barrow cemer         Scheduled Monument (No. 1011691)         Arable clipping         Other         Broad Stone, Winterbourne Abbas	tery, Winterbourn Condition: Trend: Contact:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	part of the Pound Hill round barrow cemer         Scheduled Monument (No. 1011691)         Arable clipping         Other         Broad Stone, Winterbourne Abbas         Scheduled Monument (No. 1002686)         Plant growth	tery, Winterbourn CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: SITE NAME:	part of the Pound Hill round barrow cemer         Scheduled Monument (No. 1011691)         Arable clipping         Other         Broad Stone, Winterbourne Abbas         Scheduled Monument (No. 1002686)         Plant growth         Local Authority	tery, Winterbourn CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	part of the Pound Hill round barrow cemer         Scheduled Monument (No. 1011691)         Arable clipping         Other         Broad Stone, Winterbourne Abbas         Scheduled Monument (No. 1002686)         Plant growth         Local Authority         Group of barrows near Big Wood, Winterbourne	CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	part of the Pound Hill round barrow cemer         Scheduled Monument (No. 1011691)         Arable clipping         Other         Broad Stone, Winterbourne Abbas         Scheduled Monument (No. 1002686)         Plant growth         Local Authority         Group of barrows near Big Wood, Winterb         Scheduled Monument (No. 1002696)	CONDITION: CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: CONTACT: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	part of the Pound Hill round barrow cemer         Scheduled Monument (No. 1011691)         Arable clipping         Other         Broad Stone, Winterbourne Abbas         Scheduled Monument (No. 1002686)         Plant growth         Local Authority         Group of barrows near Big Wood, Winterbourne         Scheduled Monument (No. 1002696)         Arable ploughing	tery, Winterbourn CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: TREND: TR	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	part of the Pound Hill round barrow cemer         Scheduled Monument (No. 1011691)         Arable clipping         Other         Broad Stone, Winterbourne Abbas         Scheduled Monument (No. 1002686)         Plant growth         Local Authority         Group of barrows near Big Wood, Winterb         Scheduled Monument (No. 1002696)         Arable ploughing         Private	tery, Winterbourn CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: TREND: TR	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 metery (interbourne Poor Lot, Winterbourne Abb Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME:	part of the Pound Hill round barrow cemer         Scheduled Monument (No. 1011691)         Arable clipping         Other         Broad Stone, Winterbourne Abbas         Scheduled Monument (No. 1002686)         Plant growth         Local Authority         Group of barrows near Big Wood, Winterbourne         Scheduled Monument (No. 1002696)         Arable ploughing         Private         Triple barrow and bowl barrow forming pa and part of an associated field system 250m	CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1002750) Arable ploughing Other Long barrow on Pound Hill, Winterbourne	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Other		0
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY;		CONTACT:	Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY:	Long barrow on Pound Hill, Winterbourne		
PRINCIPAL VULNERABILITY:		Steepleton	
PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1002687)	CONDITION:	Extensive significant problems
OWNER TYPE:	Arable ploughing	TREND:	Declining
	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Round barrow on Pound Hill, Winterbourn	e Steepleton	
DESIGNATION:	Scheduled Monument (No. 1002870)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
	Pound barrow south wast of village Winter	shourno Stooplata	n
SITE NAME:	Round barrow south west of village, Winter	•	
DESIGNATION:	Scheduled Monument (No. 1002751)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
		convict.	
SITE NAME:	Round barrows on Sheep Down, Winterbo	urne Steepleton	
DESIGNATION:	Scheduled Monument (No. 1003306)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrows west of Blagdon Barn, Wint	erbourne Steeple	ton
DESIGNATION:	Scheduled Monument (No. 1003307)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Three round barrows east of Smitten Corn	er, Winterbourne	Steepleton
DESIGNATION:	Scheduled Monument (No. 1003308)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two round barrows on North Hill, Wintert	ourne Steepletor	
designation:	Scheduled Monument (No. 1002865)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow Ikm south west of Manor Far	m, Wraxall	
DESIGNATION:	Scheduled Monument (No. 1015051)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

C. Bush	SITE NAME: Kingston Maurward, Stinsford DESIGNATION: Registered Park and Garden Grade II*,	Designed landscape surrounding early C18 house. Later landscape phases include formal Edwardian gardens, now open to the public. House forms nucleus		
	also part in CA, 8 LBs, 1 SM	of expanding college. Many post-war and more recent		
1. Firman	CONDITION: Generally satisfactory	buildings, with impacts on view lines and appreciation of designed landscape. Natural England has grant aided		
	but with minor localised problems	a plan for the park (completed 2011) which may help to guide future restoration and management.		
avoid .	TREND: Improving			
	OWNERTYPE Corporate, single owner	Contact: Kim Auston 0117 975 0696		
SITE NAME:	Bothenhampton			
DESIGNATION:	Conservation Area	CONDITION: At risk		
VULNERABILITY:	Unknown	TREND: Deteriorating		
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?: NO		
site name:	Bradford Abbas			
DESIGNATION:	Conservation Area	CONDITION: At risk		
VULNERABILITY:	Unknown	TREND: Deteriorating		
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?: NO		
SITE NAME:	Bradpole			
DESIGNATION:	Conservation Area	CONDITION: At risk		
VULNERABILITY:	Unknown	TREND: No significant change		
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?: NO		
SITE NAME:	Broadwindsor			
DESIGNATION:	Conservation Area	CONDITION: At risk		
VULNERABILITY:	Unknown	TREND: No significant change		
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?: NO		
SITE NAME:	Cattistock			
DESIGNATION:	Conservation Area	CONDITION: At risk		
VULNERABILITY:	Unknown	TREND: No significant change		
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?: NO		
SITE NAME:	Charminster			
DESIGNATION:	Conservation Area	CONDITION: At risk		
VULNERABILITY:	Unknown	TREND: No significant change		
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?: NO		
SITE NAME:	Charmouth			
DESIGNATION:	Conservation Area	CONDITION: At risk		
VULNERABILITY:	Unknown	TREND: No significant change		
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?: NO		
SITE NAME:	Chickerell			
DESIGNATION:	Conservation Area	CONDITION: At risk		
VULNERABILITY:	Unknown	TREND: No significant change		
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?: NO		

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the solution of the solution

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Chideock and Seatown		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	Dorchester		
designation:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	Frampton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	Herrison		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	Litton Cheney		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	Maiden Newton and Higher Frome Vauch	urch	
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	Owermoigne		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	Piddletrenthide		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	Portesham		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Improving
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
	Puddletown		
SITE NAME:			A +
	Conservation Area	CONDITION:	At risk
DESIGNATION:	Conservation Area Unknown	CONDITION: TREND:	No significant change
SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:			

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2011 / SOUTH WEST / WEST DORSET / WEYMOUTH AND PORTLAND

SITE NAME:	Shipton Gorge		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	Symondsbury		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	West Knighton		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	Whitchurch Canonicorum		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No
SITE NAME:	Winterbourne Abbas		
DESIGNATION	Conservation Area		At risk
DESIGNATION:	Unknown	CONDITION:	No significant change
VULNERABILITY:	Kim Sankey (LPA) 01305 251010	TREND: NEW ENTRY?:	No
CONTACT.		INEVV EINTRES	

#### WEYMOUTH AND PORTLAND

	SITE NAME:	Rufus Castle, Church Ope Road, Easton, Portland	Present structure probably late C15, on site of earlier building captured in 1142 by Earl Robert of Gloucester. Ruinous and in need of conservative repair and consolidation. Scheme of repair and urgent works
	DESIGNATION:	Listed Building Grade I, SM	carried out in 2010 with English Heritage grant.
	CONDITION:	Very bad	
1000	OCCUPANCY:	N/A	
	PRIORITY:	D (B)	
	OWNER TYPE:	Private	Contact: Sarah Ball 0117 975 0666
	SITE NAME:	Church of St Peter, Grove Road, Grove, Postland	Redundant robust Romanesque church, 1872. Built by convict labour from Portland's prison and later transferred to the parish. Now redundant



	SITE NAME:	Grove Road, Grove, Portland	Built by convict labour from Portland's prison and later transferred to the parish. Now redundant
T	DESIGNATION:	Listed Building Grade II*	and in poor condition.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
-	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Jenny Chesher 0117 975 0686
	SITE NAME:	Sandsfoot Castle, Weymouth	The castle is one of a pair built by Henry VIII to protect the Portland Anchorage, the other being Portland Castle. It is a scheduled monument and grade I listed. The castle
			the Portland Anchorage, the other being Portland Castle. It is a scheduled monument and grade I listed. The castle is built on soft clays that even with the protection of the
		Weymouth	the Portland Anchorage, the other being Portland Castle. It is a scheduled monument and grade I listed. The castle is built on soft clays that even with the protection of the Portland Breakwaters suffer from ongoing erosion and instability. Consent granted for repair works which are
	DESIGNATION:	Weymouth Listed Building Grade I, SM Poor	the Portland Anchorage, the other being Portland Castle. It is a scheduled monument and grade I listed. The castle is built on soft clays that even with the protection of the Portland Breakwaters suffer from ongoing erosion and instability. Consent granted for repair works which are now underway as part of HLF funded project. Due for
	DESIGNATION: CONDITION:	Weymouth Listed Building Grade I, SM Poor	the Portland Anchorage, the other being Portland Castle. It is a scheduled monument and grade I listed. The castle is built on soft clays that even with the protection of the Portland Breakwaters suffer from ongoing erosion and instability. Consent granted for repair works which are

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

#### HERITAGE AT RISK 2011 / SOUTH WEST / WEYMOUTH AND PORTLAND / COTSWOLD



# SITE NAME:Maiden Street, Methodist Church,<br/>Maiden Street,<br/>WeymouthDESIGNATION:Listed Building Grade II\*, CACONDITION:Very badOCCUPANCY:VacantPRIORITY:D (C)OWNERTYPE:Religious organisation

Redundant church. Fire in January 2002 left the church a gutted, roofless ruin. Subsequent health and safety works completely cleared the interior. Consent has been granted for conversion/reconstruction to a mixed residential and commercial use but works have not yet started.

Contact: Jenny Chesher 0117 975 0686

SITE NAME:	The Verne Citadel, Portland		
DESIGNATION:	Scheduled Monument (No. 1002411)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of round barrows on Ridgeway, Weyr	mouth and Portla	nd
DESIGNATION:	Scheduled Monument (No. 1002760)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Lodmoor Hill		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Colin Ellis (LPA) 01305 838334	NEW ENTRY?:	Yes
GLOUCESTERSHIRE			
COTSWOLD			

	SITE NAME:	Barrington Park, Barrington	Country house built circa 1736-38, extended late C19. Full repair of the house is underway.
2	DESIGNATION:	Listed Building Grade I, CA, RPG II	
	CONDITION:	Poor	
1	OCCUPANCY:	Part occupied	
	PRIORITY:	F (F)	
Sec. 1	OWNER TYPE:	Private	Contact: Justin Ayton 0117 975 0687



WA	SITE NAME:	Dovecote, Barrington Park, Barrington	C18 domed dovecote with lonic portico on east side, located approximately 500 metres north west of the house in open parkland. Emergency works to arrest
- Article	DESIGNATION:	Listed Building Grade II*, CA, RPG II	further decay have been undertaken and full repairs will start when the house repairs are completed.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
8 8 F	PRIORITY:	F (F)	
	OWNER TYPE:	Private	Contact: Justin Ayton 0117 975 0687
	SITE NAME:	Gothick Seat (Temple), Barrington Park, Barrington	Mid C18 garden temple, situated 100 metres to south west of the house in the gardens. Emergency works to arrest further decay have been undertaken and full repairs will
	DESIGNATION:	Listed Building Grade II*, CA, RPG II	start when the house repairs are completed.
12	CONDITION:	Very bad	
	OCCUPANCY:	N/A	

Contact: Justin Ayton 0117 975 0687

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

F (F)

OWNER TYPE: Private

PRIORITY:

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets. 
 ABBREVIATIONS

 CA
 Conservation Area

 LB/LBs
 Listed Building/s

 LPA
 Local Planning Authority

 NP
 National Park

 RPG
 Registered Park and Garden

 SM/SMS
 Scheduled Monument/s

 UA
 Unitary Authority

 WHS
 World Heritage Site

	TION: ANCY:	F (F) Private Elizabeth Pengree Memorial, The Square, Blockley Listed Building Grade II*, CA Poor N/A C (C) Unknown Alfreds Hall, Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad	Contact: Jus Commemo and the rail has been ur Contact: Jus Folly, begun Alexander H earliest C18 banqueting Wood, with Contact: Jus A small Cor village. The having long has been of roof coverin	stin Ayton 0117 975 0687 prative monument (1770s) decaying on one side ings are in poor condition. Basic maintenance ndertaken, but no significant repairs. stin Ayton 0117 975 0687 1721, designed by Lord Bathurst with Pope's advice, completed 1732. Probably the B mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley n rides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
Image: Street in the street	ANCY:   RTYPE   AME:	N/A F (F) Private Elizabeth Pengree Memorial, The Square, Blockley Listed Building Grade II*, CA Poor N/A C (C) Unknown Alfreds Hall, Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	Commemo and the rail has been ur Contact: Jus Folly, begun Alexander f earliest C18 banqueting Wood, with Contact: Jus A small Cor village. The having long has been of roof coverin	erative monument (1770s) decaying on one sid ings are in poor condition. Basic maintenance indertaken, but no significant repairs. stin Ayton 0117 975 0687 1721, designed by Lord Bathurst with Pope's advice, completed 1732. Probably the 8 mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley in rides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
PRIORIT CWN EF	TY: RTYPE: AME: AME: ANCY: RTYPE: AME: AMCY: RTYPE: AME: AME: AME:	F (F) Private Elizabeth Pengree Memorial, The Square, Blockley Listed Building Grade II*, CA Poor N/A C (C) Unknown Alfreds Hall, Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	Commemo and the rail has been ur Contact: Jus Folly, begun Alexander f earliest C18 banqueting Wood, with Contact: Jus A small Cor village. The having long has been of roof coverin	erative monument (1770s) decaying on one sid ings are in poor condition. Basic maintenance indertaken, but no significant repairs. stin Ayton 0117 975 0687 1721, designed by Lord Bathurst with Pope's advice, completed 1732. Probably the 8 mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley in rides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
OWNER         SITE INA         DESIGN         CONDITION         CONDITION         DESIGN         CONDITION         CONDITION         CONDITION         CONDITION         CONDITION         CONDITION         CONDITION         CONDITION         CONDITION         DESIGN         CONDITION         CONDI	R TYPE: AME: AME: ANCY: ANCY: ANCY: R TYPE: AME: AME: AME: AME:	Private Elizabeth Pengree Memorial, The Square, Blockley Listed Building Grade II*, CA Poor N/A C (C) Unknown Alfreds Hall, Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	Commemo and the rail has been ur Contact: Jus Folly, begun Alexander f earliest C18 banqueting Wood, with Contact: Jus A small Cor village. The having long has been of roof coverin	erative monument (1770s) decaying on one sid- ings are in poor condition. Basic maintenance indertaken, but no significant repairs. stin Ayton 0117 975 0687 1721, designed by Lord Bathurst with Pope's advice, completed 1732. Probably the 8 mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley in rides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
SITE NA DESIGN CONDI PRIORIT CWNER SITE NA DESIGN CONDI DESIGN CONDI PRIORIT CWNER SITE NA	AME: IATION: TION: ANCY: TY: RTYPE: AME: AME: AME: AME: AME:	Elizabeth Pengree Memorial, The Square, Blockley Listed Building Grade II*, CA Poor N/A C (C) Unknown Alfreds Hall, Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	Commemo and the rail has been ur Contact: Jus Folly, begun Alexander f earliest C18 banqueting Wood, with Contact: Jus A small Cor village. The having long has been of roof coverin	erative monument (1770s) decaying on one sid- ings are in poor condition. Basic maintenance indertaken, but no significant repairs. stin Ayton 0117 975 0687 1721, designed by Lord Bathurst with Pope's advice, completed 1732. Probably the 8 mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley in rides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
	IATION: TION: ANCY: TY: R TYPE: AME: IATION: R TYPE: AME: AME: AME:	The Square, Blockley Listed Building Grade II*, CA Poor N/A C (C) Unknown Alfreds Hall, Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	Alexander f earliest CI & banqueting Wood, with Contact: Just Contact: Just A small Corvillage. The having long has been of roof covering	ings are in poor condition. Basic maintenance ndertaken, but no significant repairs. stin Ayton 0117 975 0687 1721, designed by Lord Bathurst with Pope's advice, completed 1732. Probably the 8 mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley in rides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
	TION: ANCY: 0 ANCY: 0 TY: 0 AME: 0 AME: 0 ANCY: 0 TION: 0 ANCY: 0 AME: 0 AME	Poor N/A C (C) Unknown Alfreds Hall, Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	Folly, begun Alexander I earliest CI & banqueting Wood, with Contact: Jus A small Cot village. The having long has been of roof coverin	1721, designed by Lord Bathurst with Pope's advice, completed 1732. Probably the 8 mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley nides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
	ANCY: TY: R TYPE: AME: AME: AME: AME: AME: AME:	N/A C (C) Unknown Alfreds Hall, Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	Folly, begun Alexander I earliest CI & banqueting Wood, with Contact: Jus A small Cot village. The having long has been of roof coverin	1721, designed by Lord Bathurst with Pope's advice, completed 1732. Probably the 8 mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley nides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
PRIORIT CWN EF	TY: R TYPE: AME: AME: R TYPE: AME: AME:	C (C) Unknown Alfreds Hall, Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	Folly, begun Alexander I earliest CI & banqueting Wood, with Contact: Jus A small Cot village. The having long has been of roof coverin	1721, designed by Lord Bathurst with Pope's advice, completed 1732. Probably the 8 mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley nides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
OWNER	R TYPE: ME: JATION: TION: YANCY: R TYPE: ME:	Unknown Alfreds Hall, Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	Folly, begun Alexander I earliest CI & banqueting Wood, with Contact: Jus A small Cot village. The having long has been of roof coverin	1721, designed by Lord Bathurst with Pope's advice, completed 1732. Probably the 8 mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley nides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
SITE NA	AME: IATION: TION: ANCY: RTYPE: AME:	Alfreds Hall, Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	Folly, begun Alexander I earliest CI & banqueting Wood, with Contact: Jus A small Cot village. The having long has been of roof coverin	1721, designed by Lord Bathurst with Pope's advice, completed 1732. Probably the 8 mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley nides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
	IATION: TION: ANCY: TY: RTYPE: AME:	Cirencester Park, Cirencester Listed Building Grade II*, CA, RPG I Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	Alexander f earliest C18 banqueting Wood, with Contact: Jus A small Cor village. The having long has been of roof coverin	Pope's advice, completed 1732. Probably the 8 mock Gothic castle; part former house, part house and part mock ruin. Located in Oakley n rides radiating from it through the wood. stin Ayton 0117 975 0687 tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
CONDI OCCUP PRORT OWNER SITE NA SITE NA DESIGN CONDI PRIORT OWNER	TION: ANCY: ANCY: ANCY: ANCY: ANTE:	Very bad N/A C (C) Private Church of St Mary the Virgin, Cowley	A small Corvillage. The having long has been of roof covering the second	tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
COCCUP PRIORIT OWNER SITE NA SITE NA DESIGN CONDI PRIORIT OWNER	YANCY: TY: R TYPE: AME: IATION:	N/A C (C) Private Church of St Mary the Virgin, Cowley	A small Corvillage. The having long has been of roof covering	tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
PRIORIT OWNER STE NA STE NA DESIGN CONDI PRIORIT OWNER	TY: R TYPE: AME: IATION:	C (C) Private Church of St Mary the Virgin, Cowley	A small Corvillage. The having long has been of roof coverir	tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
OWNER	AME:	Private Church of St Mary the Virgin, Cowley	A small Corvillage. The having long has been of roof coverir	tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
SITE NA	AME: IATION:	Church of St Mary the Virgin, Cowley	A small Corvillage. The having long has been of roof coverir	tswold stone church in a pretty Cotswold Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
DESIGN CONDI PRIORIT OWNER	IATION:	Cowley	village. The having long has been of roof coverir	Cotswold stone slates are decaying badly reached the end of their life. A repair grant ffered for the replacement of the stone slate
CONDI PRIORIT OWNER		Listed Place of Worship Grade II*, CA	root coverir	
CONDIT PRIORIT OWNER		· · · · · · · · · · · · · · · · · · ·	<b>\</b>	ngs.
OWNER	HON:	Very bad		
		B (New entry)		
SITE NA	R TYPE:	Religious organisation	Contact: Ch	nris Miners 0117 975 0700
		Church of St Edward, Hawling	The stone t leaking. A R offered for	tswold Stone church in a small Cotswold villag tile roofs are falling apart and the gutters are lepair Grant for Places of Worship has been the renewal of the stone tile roofs and the argumenta goods.
DESIGN	IATION:	Listed Place of Worship Grade II*	repair of the	e rainwater goods.
CONDE		Very bad		
PRIORIT	FY:	B (New entry)		
OWNER	R TYPE:	Religious organisation	Contact: Ch	nris Miners 0117 975 0700
	bowl t	barrows 690m and 790m north of Th	e Manor Farr	n, Avening
designation: Sched	duled I	Monument (No. 1017337)	CONDITION:	Extensive significant problems
A 1	0 -	undering		i.e. under plough, collapse
	le plou to	אַ ווו ואָר איז איז אר	TREND:	Declining Rusiness Manager 0117 975 0700
OWNER TYPE: Privat	te		CONTACT:	Business Manager 0117 975 0700
SITE NAME: Perro	ott's Bi	rook dykes, Bagendon		
designation: Schee	duled I	Monument (No. 1003436)	CONDITION:	Generally unsatisfactory with major localised problems
principal vulnerability: Exter	nsive a	nimal burrowing	TREND:	
owner type: Privat			CONTACT:	

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bowl barrow 800m north east of Beverston	Castle Farm, Bev	verstone
DESIGNATION:	Scheduled Monument (No. 1008197)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Long barrow 800m north east of Oldwalls F	arm, Bibury	
DESIGNATION:	Scheduled Monument (No. 1018163)	CONDITION:	Extensive significant problems
BESIGNATION.		CONDITION.	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Wayside cross socket stone I25m NNW of	Kilkenny Cottage	es, Bibury
		, -	•
DESIGNATION:	Scheduled Monument (No. 1014414)	CONDITION:	Generally unsatisfactory
	Deterioration in need of management		with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining Business Manager 0117 975 0700
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	West Barrow: a long barrow 200m west of l	Leighterton Scho	ol, Boxwell with Leighterton
DESIGNATION:	Scheduled Monument (No. 1013590)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Localised/limited animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow north of Chedworth Roman	villa, Chedworth	
DESIGNATION:	Scheduled Monument (No. 1003346)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Settlement south east of Chesterton Farm,	Cirencester	
DESIGNATION:	Scheduled Monument (No. 1003444)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two bowl barrows, known as Crippet's Woo 560m and 590m north east of Dryhill Farm,		S,
DESIGNATION:	Scheduled Monument (No. 1017041)	CONDITION:	Extensive significant problems i.e. under plough, collapse
		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		
	Arable ploughing Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:		CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Private	CONTACT:	Extensive significant problems
OWNER TYPE: SITE NAME: DESIGNATION:	Private Norbury Camp hillfort, Colesbourne Scheduled Monument (No. 1018167)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Norbury Camp hillfort, Colesbourne		Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Condicote bowl barrow, Condicote		
DESIGNATION:	Scheduled Monument (No. 1016080)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Tump Barn bowl barrow, Didmarton		
DESIGNATION:	Scheduled Monument (No. 1016077)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow known as St Paul's Epistle Mo	und, Dowdeswell	
DESIGNATION:	Scheduled Monument (No. 1016842)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			5
SITE NAME:	Camp at Upper Dowdeswell, Dowdeswell		
DESIGNATION:	Scheduled Monument (No. 1003321)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Hillfort 320m north east of Castle Barn Far	rm, Dowdeswell	
	Hillfort 320m north east of Castle Barn Far Scheduled Monument (No. 1018170)	rm, Dowdeswell	Extensive significant problems
DESIGNATION:	Scheduled Monument (No. 1018170)	CONDITION:	i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018170) Arable ploughing	CONDITION: TREND:	i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018170)	CONDITION:	i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018170) Arable ploughing	CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1018170) Arable ploughing Private	CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1018170) Arable ploughing Private Lineover long barrow, 530m south west of	CONDITION: TREND: CONTACT: Castle Barn Farm	i.e. under plough, collapse Declining Business Manager 0117 975 0700 , Dowdeswell
DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1018170) Arable ploughing Private Lineover long barrow, 530m south west of	CONDITION: TREND: CONTACT: Castle Barn Farm	i.e. under plough, collapse Declining Business Manager 0117 975 0700 , Dowdeswell Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018170) Arable ploughing Private Lineover long barrow, 530m south west of Scheduled Monument (No. 1018166)	CONDITION: TREND: CONTACT: Castle Barn Farm CONDITION:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 , Dowdeswell Extensive significant problems i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1018170) Arable ploughing Private Lineover long barrow, 530m south west of Scheduled Monument (No. 1018166) Arable ploughing	CONDITION: TREND: CONTACT: Castle Barn Farm CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 , Dowdeswell Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No. 1018170)         Arable ploughing         Private         Lineover long barrow, 530m south west of a         Scheduled Monument (No. 1018166)         Arable ploughing         Private         Round barrow 750m north east of Eastleace	CONDITION: TREND: CONTACT: Castle Barn Farm CONDITION: TREND: CONTACT: hdowns Farm, Eas	i.e. under plough, collapse Declining Business Manager 0117 975 0700 , Dowdeswell Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 stleach
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1018170)         Arable ploughing         Private         Lineover long barrow, 530m south west of         Scheduled Monument (No. 1018166)         Arable ploughing         Private	CONDITION: TREND: CONTACT: Castle Barn Farm CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 , Dowdeswell Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 stleach Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1018170)         Arable ploughing         Private         Lineover long barrow, 530m south west of scheduled Monument (No. 1018166)         Arable ploughing         Private         Round barrow 750m north east of Eastleac         Scheduled Monument (No. 1016506)	CONDITION: TREND: CONTACT: Castle Barn Farm CONDITION: TREND: CONTACT: hdowns Farm, Eas CONDITION:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Dowdeswell Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 stleach Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018170)         Arable ploughing         Private         Lineover long barrow, 530m south west of the source of the sour	CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: Hdowns Farm, Ease CONDITION: TREND:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>Dowdeswell</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>Stleach</b> Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018170)         Arable ploughing         Private         Lineover long barrow, 530m south west of scheduled Monument (No. 1018166)         Arable ploughing         Private         Round barrow 750m north east of Eastleac         Scheduled Monument (No. 1016506)	CONDITION: TREND: CONTACT: Castle Barn Farm CONDITION: TREND: CONTACT: hdowns Farm, Eas CONDITION:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Dowdeswell Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 stleach Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018170)         Arable ploughing         Private         Lineover long barrow, 530m south west of the source of the sour	CONDITION: TREND: CONTACT: Castle Barn Farm CONDITION: TREND: CONTACT: hdowns Farm, Eas CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Dowdeswell Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Stleach Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1018170)         Arable ploughing         Private         Lineover long barrow, 530m south west of a         Scheduled Monument (No. 1018166)         Arable ploughing         Private         Round barrow 750m north east of Eastleac         Scheduled Monument (No. 1016506)         Arable ploughing         Private         Bowl barrow in Three Ash Belt, 460m north	CONDITION: TREND: CONTACT: Castle Barn Farm CONDITION: TREND: CONTACT: hdowns Farm, Eas CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Dowdeswell Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Stleach Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1018170)         Arable ploughing         Private         Lineover long barrow, 530m south west of the source of the sour	CONDITION: TREND: CONTACT: Castle Barn Farm CONDITION: TREND: CONTACT: hdowns Farm, Ease CONDITION: TREND: CONTACT: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Dowdeswell Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Stleach Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 od Farm, Edgeworth Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: OWNER TYPE:	Scheduled Monument (No. 1018170)         Arable ploughing         Private         Lineover long barrow, 530m south west of a         Scheduled Monument (No. 1018166)         Arable ploughing         Private         Round barrow 750m north east of Eastleac         Scheduled Monument (No. 1016506)         Arable ploughing         Private         Bowl barrow in Three Ash Belt, 460m north	CONDITION: TREND: CONTACT: Castle Barn Farm CONDITION: TREND: CONTACT: hdowns Farm, Ease CONDITION: TREND: CONTACT: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Dowdeswell Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Stleach Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Settlement site south of Claydon Cottages,	Fairford	
DESIGNATION:	Scheduled Monument (No. 1003443)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Mineral extraction / related subsidence	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Settlement site, Great Rissington		
DESIGNATION:	Scheduled Monument (No. 1003440)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow 300m west of Church Farm,	Guiting Power	
DESIGNATION:	Scheduled Monument (No. 1017338)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	loomh camp loomh		
SITE NAME:	Icomb camp, Icomb		
DESIGNATION:	Scheduled Monument (No. 1003342)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 450m west of Lasborough, Kir	igscote	
DESIGNATION:	Scheduled Monument (No. 1009159)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Arable ploughing Private	TREND: CONTACT:	
OWNER TYPE:			Declining
OWNER TYPE:	Private		Declining Business Manager 0117 975 0700 Extensive significant problems
OWNER TYPE: SITE NAME: DESIGNATION:	Private The Chessalls Roman town, Kingscote Scheduled Monument (No. 1018607)	CONTACT: CONDITION:	Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private The Chessalls Roman town, Kingscote Scheduled Monument (No. 1018607) Metal detecting	CONTACT: CONDITION: TREND:	Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private The Chessalls Roman town, Kingscote Scheduled Monument (No. 1018607)	CONTACT: CONDITION:	Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private The Chessalls Roman town, Kingscote Scheduled Monument (No. 1018607) Metal detecting	CONTACT: CONDITION: TREND: CONTACT:	Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
OWNER TYPE:	Private The Chessalls Roman town, Kingscote Scheduled Monument (No. 1018607) Metal detecting Private	CONTACT: CONDITION: TREND: CONTACT:	Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: OWNER TYPE: SITE NAME: DESIGNATION:	Private The Chessalls Roman town, Kingscote Scheduled Monument (No. 1018607) Metal detecting Private Roman villa 600yds (550m) north east of G	CONTACT: CONDITION: TREND: CONTACT: reat Lemhill Farm	Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>, Lechlade</b> Extensive significant problems i.e. under plough, collapse Declining
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private The Chessalls Roman town, Kingscote Scheduled Monument (No. 1018607) Metal detecting Private Roman villa 600yds (550m) north east of Ga Scheduled Monument (No. 1003420)	CONTACT: CONDITION: TREND: CONTACT: reat Lemhill Farm CONDITION:	Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b></b> <b>Lechlade</b> Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private The Chessalls Roman town, Kingscote Scheduled Monument (No. 1018607) Metal detecting Private Roman villa 600yds (550m) north east of G Scheduled Monument (No. 1003420) Extensive animal burrowing	CONTACT: CONDITION: TREND: CONTACT: reat Lemhill Farm CONDITION: TREND:	Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>, Lechlade</b> Extensive significant problems i.e. under plough, collapse Declining
OWNER TYPE:	Private The Chessalls Roman town, Kingscote Scheduled Monument (No. 1018607) Metal detecting Private Roman villa 600yds (550m) north east of G Scheduled Monument (No. 1003420) Extensive animal burrowing Private Chessels Roman site, Lower Slaughter	CONTACT: CONDITION: TREND: CONTACT: reat Lemhill Farm CONDITION: TREND:	Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>.</b> <b>Lechlade</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
OWNER TYPE:	Private The Chessalls Roman town, Kingscote Scheduled Monument (No. 1018607) Metal detecting Private Roman villa 600yds (550m) north east of G Scheduled Monument (No. 1003420) Extensive animal burrowing Private	CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION:	Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>, Lechlade</b> Extensive significant problems i.e. under plough, collapse Declining
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private The Chessalls Roman town, Kingscote Scheduled Monument (No. 1018607) Metal detecting Private Roman villa 600yds (550m) north east of G Scheduled Monument (No. 1003420) Extensive animal burrowing Private Chessels Roman site, Lower Slaughter	CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION:	Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b></b> <b>Lechlade</b> Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	New Court Ground Roman villa (south of a	new buildings), Na	unton
DESIGNATION:	Scheduled Monument (No. 1003340)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Summerhill prehistoric site, Naunton		
DESIGNATION:	Scheduled Monument (No. 1003339)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Bowl barrow in Inlands Plantation, 650m so	uth of Hazleton N	1anor Farm, Rodmarton
DESIGNATION:	Scheduled Monument (No. 1008788)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two bowl barrows 180m south east of Hare	esdown Barn, Rod	marton
DESIGNATION:	Scheduled Monument (No. 1008796)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow I 20m north of Home Farm, SI	herborne	
DESIGNATION:	Scheduled Monument (No. 1017082)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
TE NAME:	South Cerney castle, South Cerney		
DESIGNATION:	Scheduled Monument (No. 1003422)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Private Two bowl barrows 260m north of Chalk Hi part of the Cow Common round barrow co	ill Cottage;	Business Manager 0117 975 0700
DWNER TYPE:	Two bowl barrows 260m north of Chalk Hi	ill Cottage;	Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse
WNER TYPE: TE NAME: ESIGNATION:	Two bowl barrows 260m north of Chalk Hi part of the Cow Common round barrow co	ill Cottage; emetery, Swell	Extensive significant problems
WWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Two bowl barrows 260m north of Chalk Hi part of the Cow Common round barrow co Scheduled Monument (No. 1008194)	ill Cottage; emetery, Swell condition:	Extensive significant problems i.e. under plough, collapse
DWNER TYPE: ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Two bowl barrows 260m north of Chalk Hi part of the Cow Common round barrow co Scheduled Monument (No. 1008194) Arable ploughing	ill Cottage; emetery, Swell condition: trend: contact:	Extensive significant problems i.e. under plough, collapse Declining
DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Two bowl barrows 260m north of Chalk Hi part of the Cow Common round barrow co Scheduled Monument (No. 1008194) Arable ploughing Private	ill Cottage; emetery, Swell condition: trend: contact:	Extensive significant problems i.e. under plough, collapse Declining
DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DESIGNATION: RINCIPAL VULNERABILITY:	Two bowl barrows 260m north of Chalk Hi part of the Cow Common round barrow co Scheduled Monument (No. 1008194) Arable ploughing Private Two bowl barrows 80m north of Arch Holl	ill Cottage; emetery, Swell Condition: Trend: Contact: ow, Swell	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally satisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

HERITAGE AT RISK 2011 / SOUTH WEST / COTSWOLD / FOREST OF DEAN

SITE NAME:		ow 990m south east of Bemborough F e Bemborough Farm round barrow cer		le Guiting
DESIGNATION:	Scheduled	Monument (No. 1020654)	CONDITION:	Extensive significant problems
	Aughte ale	weble e		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plc	bugning	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Earthworl	< north of Lyne's Barn, Temple Guiting		
DESIGNATION:	Scheduled	Monument (No. 1003328)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	No knowr	n threat	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barr	ow 335m south east of Broadfield Farr	n,Tetbury Uj	pton
DESIGNATION:	Scheduled	Monument (No. 1016838)	CONDITION:	Generally unsatisfactory
				with major localised problems
PRINCIPAL VULNERABILITY:	Extensive	animal burrowing	TREND:	Declining
OWNER TYPE:	Other		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Four bow and a long	l barrows forming part of a round barr g barrow 550m NNE of Eyford Hill Far	ow cemetery m, Upper Sla	y, ughter
DESIGNATION:	Scheduled	Monument (No. 1020987)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
ite name: Designation:		Farm bowl barrow, <b>450</b> m south west of Monument (No. 1018155)		Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clip	ning	TREND:	Declining
OWNER TYPE:	Private	,P., .8	CONTACT:	Business Manager 0117 975 0700
	Thrate		convice.	
N A	contemporary Richard Woods and rework		vas possibly landscaped by 'Capability' Brown's ary Richard Woods, and reworked extensively	
	DESIGNATION:	Registered Park and Garden Grade II,	in the C19.	The main house is occupied by a school with
2 22 42		also part in CA, 2 LBs, I SM		ea of new build. The wider parkland, in separa
	CONDITION:	Generally unsatisfactory	clumps and	is neglected: many parkland trees have gone, ornamental woodland are over-mature and
Maria maria		with major localised problems	decaying, ar	nd sections of park wall and estate railings are
and the second s	VULNERABILITY		in very poo	or condition.
Surger and the	TREND:	Stable		
- A Carlos	OWNER TYPE:	Mixed, multiple owners	Contact: Kir	m Auston 0117 975 0696
FOREST OF DEAN				
	SITE NAME:	Blakeney United Reformed Church, Cinderford Road, Blakeney, Awre	Remarkably example of	non-conformist chapel, dated 1849. complete and architecturally distinctive its type. Stonework repairs required. undertaken some repairs.
The second	DESIGNATION:	Listed Building Grade II*, CA		
	CONDITION:	Fair		
	OCCUPANCY:	N/A		
	PRIORITY:	F (F)		
				stin Ayton 0117 975 0687
1	OWNER TYPE:	Private	Contact: jus	SUIT AYLOIT 0117 973 0667
The second	OWNER TYPE:	Private	Contact: jus	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

#### HERITAGE AT RISK 2011 / SOUTH WEST / FOREST OF DEAN

	SITE NAME:	Guns Mill Barn, Littledean	Formerly a blast furnace and later a paper mill, built 1682. Now unused and in perilous condition, despite some emergency holding repairs. There have been recent	
A Providence of the second sec	DESIGNATION:	Listed Building Grade II*, SM	discussions with the owner about the site's future.	
	CONDITION:	Very bad		
	OCCUPANCY:	Vacant		
And I AN LOW	PRIORITY:	A (A)		
	OWNERTYPE: Private		Contact: Mel Barge 0117 975 1300	
	SITE NAME: Lydney Docks and Harbour, Naas Lane, Lydney		The docks and harbour date from about 1810 to 1821 and were once the main commercial port serving industr in the district. Outer basin now repaired with surrounding	
	DESIGNATION:	Scheduled Monument	area used for recreation, however the Inner Basin is still in poor condition.	
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY:	C (F)		
	OWNER TYPE:	Government	Contact: Mel Barge 0117 975 1300	
	SITE NAME:	Tithe Barn, Highleadon Court, Rudford and Highleadon	C15 or early C16 Tithe barn built for the Abbey of St Peter, Gloucester. The roof is sound, but the framing and infill panels are deteriorating. Used for agricultural	
	DESIGNATION:	Listed Building Grade II*	storage. Some maintenance undertaken.	
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY:	С (С)		
	OWNER TYPE:	Private	Contact: Justin Ayton 0117 975 0687	
	SITE NAME: DESIGNATION:	St James Church, Lancaut, Tidenham Listed Building Grade II, SM	Small C12 chapel with later medieval extension to west. Unroofed rubble-built structure with slow deterioration of stonework and internal plasterwork. A condition survey funded by English Heritage highlighted the works needed to halt further deterioration and with a recommendation	
	CONDITION:	Fair	for the wall heads to be soft-capped.	
	OCCUPANCY:			
	priority: F (F)			
	PRIORITY:	F (F)		
	PRIORITY: OWNER TYPE:	_	Contact: Mel Barge 0117 975 1300	
		_	A grand late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was not completed until 1907.The roof has been partly repaired bu the remainder is leaking badly which has damaged its	
	OWNER TYPE:	Trust Church of St John the Evangelist, Coleford	A grand late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was not completed until 1907. The roof has been partly repaired bu the remainder is leaking badly which has damaged its interior. A grant was offered 2010 towards the repair	
	OWNER TYPE: SITE NAME: DESIGNATION:	Trust Church of St John the Evangelist, Coleford Listed Place of Worship Grade II	A grand late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was not completed until 1907.The roof has been partly repaired bu the remainder is leaking badly which has damaged its	
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Trust Church of St John the Evangelist, Coleford Listed Place of Worship Grade II Poor	A grand late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was not completed until 1907. The roof has been partly repaired bu the remainder is leaking badly which has damaged its interior. A grant was offered 2010 towards the repair	
	OWNER TYPE: SITE NAME: DESIGNATION:	Trust Church of St John the Evangelist, Coleford Listed Place of Worship Grade II	A grand late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was not completed until 1907. The roof has been partly repaired bu the remainder is leaking badly which has damaged its interior. A grant was offered 2010 towards the repair	
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY:	Trust Church of St John the Evangelist, Coleford Listed Place of Worship Grade II Poor B (New entry)	A grand late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was not completed until 1907. The roof has been partly repaired but the remainder is leaking badly which has damaged its interior. A grant was offered 2010 towards the repair of the roof. Contact: Chris Miners 0117 975 0700 A large church in the centre of Newent. The stonework of the tower is heavily eroded, increasingly badly the higher it gets. The stone parapets are in the worst condition and feel unsecure. Past deathwatch beetle attack in the tower	
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	Trust Church of St John the Evangelist, Coleford Listed Place of Worship Grade II Poor B (New entry) Religious organisation Church of St Mary, Church Street, Newent	A grand late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was not completed until 1907. The roof has been partly repaired but the remainder is leaking badly which has damaged its interior. A grant was offered 2010 towards the repair of the roof. Contact: Chris Miners 0117 975 0700 A large church in the centre of Newent. The stonework of the tower is heavily eroded, increasingly badly the higher it gets. The stone parapets are in the worst condition and feel unsecure. Past deathwatch beetle attack in the tower and the nave lintels needs to be independently investigated	
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Trust Church of St John the Evangelist, Coleford Listed Place of Worship Grade II Poor B (New entry) Religious organisation Church of St Mary, Church Street, Newent Listed Place of Worship Grade I, CA	A grand late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was not completed until 1907. The roof has been partly repaired but the remainder is leaking badly which has damaged its interior. A grant was offered 2010 towards the repair of the roof. Contact: Chris Miners 0117 975 0700 A large church in the centre of Newent. The stonework of the tower is heavily eroded, increasingly badly the higher it gets. The stone parapets are in the worst condition and feel unsecure. Past deathwatch beetle attack in the tower and the nave lintels needs to be independently investigated and a control strategy established. The church recently applied for a repair grant to undertake repair work but	
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Trust Church of St John the Evangelist, Coleford Listed Place of Worship Grade II Poor B (New entry) Religious organisation Church of St Mary, Church Street, Newent Listed Place of Worship Grade I, CA Poor	A grand late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was not completed until 1907. The roof has been partly repaired but the remainder is leaking badly which has damaged its interior. A grant was offered 2010 towards the repair of the roof. Contact: Chris Miners 0117 975 0700 A large church in the centre of Newent. The stonework of the tower is heavily eroded, increasingly badly the higher it gets. The stone parapets are in the worst condition and feel unsecure. Past deathwatch beetle attack in the tower and the nave lintels needs to be independently investigated and a control strategy established. The church recently	
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Trust Trust Church of St John the Evangelist, Coleford Listed Place of Worship Grade II Poor B (New entry) Religious organisation Church of St Mary, Church Street, Newent Listed Place of Worship Grade I, CA Poor A (New entry) D the definition	A grand late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was not completed until 1907. The roof has been partly repaired but the remainder is leaking badly which has damaged its interior. A grant was offered 2010 towards the repair of the roof. Contact: Chris Miners 0117 975 0700 A large church in the centre of Newent. The stonework of the tower is heavily eroded, increasingly badly the higher it gets. The stone parapets are in the worst condition and feel unsecure. Past deathwatch beetle attack in the tower and the nave lintels needs to be independently investigated and a control strategy established. The church recently applied for a repair grant to undertake repair work but	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

#### HERITAGE AT RISK 2011 / SOUTH WEST / FOREST OF DEAN

SITE NAME:	Whitecliff Iron Works, Coleford		
DESIGNATION:	Scheduled Monument (No. 1021420)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Symonds Yat promontory fort, English Bickno	or	
DESIGNATION:	Scheduled Monument (No. 1016760)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Soudley camp, Lower Soudley, Ruspidge and	Soudley	
DESIGNATION:	Scheduled Monument (No. 1005564)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Offa's Dyke: section 240m north east of But	ington Farm,Tid	enham
DESIGNATION:	Scheduled Monument (No. 1020643)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Offa's Dyke: section in Boatwood Plantation,	320m south we	st of Chase Farm, Tidenham
	<b>Offa's Dyke: section in Boatwood Plantation,</b> Scheduled Monument (No. 1020606)	320m south wes	st of Chase Farm, Tidenham Generally unsatisfactory with major localised problems
DESIGNATION:			Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020606)	CONDITION:	Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1020606) Extensive visitor erosion	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1020606) Extensive visitor erosion Government or Agency	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1020606) Extensive visitor erosion Government or Agency Offa's Dyke: section in Caswell Wood, 280m	CONDITION: TREND: CONTACT: west of Beeches	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Farm, Tidenham Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020606) Extensive visitor erosion Government or Agency Offa's Dyke: section in Caswell Wood, 280m Scheduled Monument (No. 1020601)	CONDITION: TREND: CONTACT: west of Beeches CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Farm, Tidenham Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1020606) Extensive visitor erosion Government or Agency Offa's Dyke: section in Caswell Wood, 280m Scheduled Monument (No. 1020601) Extensive visitor erosion	CONDITION: TREND: CONTACT: west of Beeches CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Farm, Tidenham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No. 1020606)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Caswell Wood, 280m         Scheduled Monument (No. 1020601)         Extensive visitor erosion         Government or Agency	CONDITION: TREND: CONTACT: west of Beeches CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Farm, Tidenham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1020606)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Caswell Wood, 280m         Scheduled Monument (No. 1020601)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Chapelhouse Wood, 2	CONDITION: TREND: CONTACT: West of Beechess CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Farm, Tidenham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Recreation Ground, Tidenham Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020606)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Caswell Wood, 280m         Scheduled Monument (No. 1020601)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Chapelhouse Wood, 2         Scheduled Monument (No. 1020601)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Chapelhouse Wood, 2         Scheduled Monument (No. 1020639)	CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONTACT: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Farm, Tidenham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Exerceation Ground, Tidenham Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: OWNER TYPE:	Scheduled Monument (No. 1020606)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Caswell Wood, 280m         Scheduled Monument (No. 1020601)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Chapelhouse Wood, 2         Scheduled Monument (No. 1020639)         Scrub / tree growth	CONDITION: TREND: CONTACT: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Farm, Tidenham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 ERecreation Ground, Tidenham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1020606)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Caswell Wood, 280m         Scheduled Monument (No. 1020601)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Chapelhouse Wood, 2         Scheduled Monument (No. 1020639)         Scrub / tree growth         Private	CONDITION: TREND: CONTACT: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Farm, Tidenham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 ERecreation Ground, Tidenham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020606)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Caswell Wood, 280m         Scheduled Monument (No. 1020601)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Chapelhouse Wood, 2         Scheduled Monument (No. 1020601)         Extensive visitor erosion         Government or Agency         Offa's Dyke: section in Chapelhouse Wood, 2         Scheduled Monument (No. 1020639)         Scrub / tree growth         Private         Offa's Dyke: section in Passage Grove, 660m	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONDITION: TREND: CONDITION: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Farm, Tidenham Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Recreation Ground, Tidenham Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Tot, Tidenham Generally satisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / FOREST OF DEAN / GLOUCESTER

		th west of Sheepcot, Tidenham		Concerelly upontified at a second
DESIGNATION:	Scheduled	Monument (No. 1020604)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive	visitor erosion	TREND:	Declining
DWNER TYPE:	Governme	ent or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Offa's Dyk	ke: section in Worgan's Wood, 800m w	est of Chase	Farm, Tidenham
DESIGNATION:	Scheduled	Monument (No. 1020605)	CONDITION:	Generally satisfactory
		``````````````````````````````````````		but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate	animal burrowing	TREND:	Declining
OWNER TYPE:	Governme	ent or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Roman sit	e I50yds (I40m) east of Palace Cottag	ge, Boughspri	ng,Tidenham
DESIGNATION:	Scheduled	Monument (No. 1002089)	CONDITION:	Generally unsatisfactory
				with major localised problems
PRINCIPAL VULNERABILITY:	Deteriorat	tion — in need of management	TREND:	Declining
DWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Roman vil	la 600yds (550m) south west of Woola	aston station	, Woolaston
DESIGNATION:	Scheduled	Monument (No. 1004860)	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
DWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
GLOUCESTER				
L AT	SITE NAME:	Tanner's Hall, north of city centre, Gouda Way, Gloucester	This is a rare survival of a C13 merchant's house, later converted to a tannery and Tanner's Hall. Surrounding buildings have been removed for the inner relief road. There is a current planning application for development around the building with provision for repair and reuse	
	DESIGNATION:	Scheduled Monument		
	CONDITION:	Very bad	of the stand	ding fabric.
	OCCUPANCY:	N/A		
Contraction of the State	PRIORITY:	В (А)		
	OWNER TYPE:	Private	Contact: Mel Barge 0117 975 1300	
	SITE NAME:	Llanthony Priory, range between Outer and Inner Courts,	Courts of t	the range between the Outer and Inner the Augusting Priory of Llanthony Secunda
		Llanthony Road, Gloucester	vandalism. 7	nd early C16.Vacant buildings subject to Fimber frame decaying; brick and stonework
		Listed Building Grade I, SM	eroded.The	e Llanthony Priory Trust has secured English
	CONDITION:	Very bad		Inding for emergency repairs and there are vestigate the timber frame.
	OCCUPANCY:			
	PRIORITY:	B (B) Truct	Conta -t. M	al Pargo 0117 975 1200
	OWNER TYPE:	Trust	Contact: M	el Barge 0117 975 1300
AND ADDRESS OF THE REAL PROPERTY AND ADDRESS OF THE REAL PROPERTY.	SITE NAME:	Llanthony Priory, remains of precinct wall north of Inner Gatehouse, Llanthony Road, Gloucester	Stone and brick wall on the west and north sides of the Outer Court of the former Augustinian Priory. Built in the C15, it was rebuilt or extended in the C17 and C13	
			i ne Llantho	ony Priory Trust is looking to raise funds and
	DESIGNATION:	Listed Building Grade I, SM		
	DESIGNATION: CONDITION:	Listed Building Grade I, SM Poor		suitable fúture uses for the site.
		Poor		
	CONDITION:	Poor		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

#### HERITAGE AT RISK 2011 / SOUTH WEST / GLOUCESTER / STROUD

		Llanthony Priory, remains of precinct wall south of Outer Gatehouse, Llanthony Road, Gloucester Listed Building Grade I, SM	Early C16 brick wall. Badly eroded especially at low level. Two brick piers constructed 1995 to support wall to provide support in event that condition of wall deteriorates, but these have now rotated away from back of wall. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the site		
	CONDITION:	Very bad	funds a	and investigate suitable future uses for the site.	
	OCCUPANCY:	N/A			
	PRIORITY:	C (C)			
	OWNER TYPE:	Trust	Conta	ct: Mel Barge 0117 975 1300	
	SITE NAME:	Llanthony Priory, remains of range on south side of Inner Court, Llanthony Road, Gloucester	Court Early C	ns of the range on the south side of the Inner of the Augustinian Priory of Llanthony Secunda. CI 6. Subject to vandalism. The Llanthony Priory s looking to raise funds and investigate suitable	
CHARLES STREET, STREET	DESIGNATION:	Listed Building Grade I, SM		uses for the site.	
	CONDITION:	Very bad			
	OCCUPANCY:	N/A			
	PRIORITY:	B (B)			
	OWNER TYPE:		Conta	ct: Mel Barge 0117 975 1300	
A. A.	SITE NAME:	The Fleece Hotel, 19 Westgate Street, Gloucester	Fleece It is in	mber-framed range most recently occupied as the Hotel. The building has been vacant for sometime. poor repair, with some internal decay. A series of	
	DESIGNATION:	Listed Building Grade I, CA		g up works were carried out early summer 2010 vide more information on the condition.The building	
	CONDITION:	Poor		ently being marketed as the body which currently	
	OCCUPANCY:	Vacant		property is being disbanded.	
	PRIORITY:	С (С)			
	OWNER TYPE:		Conta	ct: Justin Ayton 0117 975 0687	
SITE NAME:	Southgate	Street			
	-				
DESIGNATION:	Conservat	ion Area	CONDITI	/	
VULNERABILITY:	Low		TREND:	Improving	
CONTACT:	Charlotte	Lewis (LPA) 01452 396855	NEW ENT	try?: No	
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	St Marys House, London Road, Chalford Listed Building Grade II*, CA Poor Part occupied A (A)	late C	r mill owner's house and weavers' cottages, I6 and late C17. Roof in exceptionally poor ion and is covered with tarpaulin.	
	OWNER TYPE:	DI	Conta	ct: Justin Ayton 0117 975 0687	
	OWNERTHE.	- Trivate	Conta		
	SITE NAME:	Main building at Stanley Mills, Ryeford, Kings Stanley	poor c with Ei	en mill, 1813. Ancillary building (grade II) is in condition and part occupied. Roof repaired nglish Heritage grant. A proposal for repair	
	DESIGNATION:	Listed Building Grade I, CA	anu co	nservation has been agreed.	
	CONDITION:	Fair			
	OCCUPANCY:	Part occupied			
	PRIORITY:	E (E)			
	OWNER TYPE:	Company	Conta	ct: Justin Ayton 0117 975 0687	
	SITE NAME:	Former Saxon church to west of Priory House, Leonard Stanley	of forn agricul	dant Saxon and medieval chapel within core ner priory of St Leonard. Later converted to tural use including dovecotes and forge. Threshing	
A CONTRACTOR OF THE	DESIGNATION:	Listed Building Grade II*, SM, CA	floor in	n situ. Currently used for vehicle/equipment storage. tion survey, funded by English Heritage, will inform	
	CONDITION:	Very bad		lication for repair. Funding options currently	
	OCCUPANCY:			nvestigated.	
	PRIORITY:	B (C)			
	OWNER TYPE:	Private	Conta	ct: Mel Barge 0117 975 1300	
	OTTALKTITE:		Conta		
<ul> <li>PRIORITY (FOR BUILDINGS)</li> <li>A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.</li> <li>B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.</li> <li>C Slow decay; no solution agreed.</li> </ul>	E Under rep repair, but under thre obvious ne	y; solution agreed t implemented. vair or in fair to good no user identified; or aut of vacancy with no ew user (applicable only s capable of beneficial use). F Repair scheme in progre and (where applicable) end use or user identifie functionally redundant bi with new use agreed bu yet implemented.	d; uildings	NOTE: CA Conservation Area If the priority category has changed since the 2010 register, the previous category is given in brackets. USA Conservation Area LB/LBs Listed Building/s LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM/SMs Scheduled Monument/s UA Unitary Authority WHS World Heritage Site	

	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Brownshill Court, Wick Street, Painswick Listed Building Grade II* Very bad Part occupied C (C)	which are r closing ord	d C18 country house converted into flats, now vacant. The house has been the subject of a er and parts are now in a dangerous condition. has recently been inherited by a new owner.
	OWNER TYPE:	D.I.	Contact: Jus	stin Ayton 0117 975 0687
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	A (New entry)	chapel. The 1989 to do and display In 1991 a p roof of the Repairs are the roof ur	854-68 incorporating a magnificent private Woodchester Mansion Trust was formed in a continuous programme of conservation of the uncompleted gothic-style masterpiece. rotective scaffold was built to cover the leaking chapel. The scaffold is now decaying and unsafe. immediately needed to the scaffold or, ideally, aderneath hris Miners 0117 975 0700
SITE NAME:		barrows, known as Climperwell ro th west of Climperwell Farm, Cranh		
DESIGNATION:		Monument (No. 1017074)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plc	oughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	The Mour	nt moated site, Haresfield		
DESIGNATION:	Scheduled	Monument (No. 1020655)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive	animal burrowing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Tresham F	arbarrow round barrows, Hillesley	and Tresham	
DESIGNATION:	Scheduled	Monument (No. 1002115)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barr	ow 450m south east of Upper Hyd	e Farm, Minchin	hampton
DESIGNATION:	Scheduled	Monument (No. 1008626)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plc	oughing	TREND:	Declining
OWNER TYPE:	Other		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Gatcombe	e long barrow, 400m east of Gatcon	nbe Farm, Minch	inhampton
DESIGNATION:	Scheduled	Monument (No. 1008623)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive	animal burrowing	TREND:	Declining
OWNER TYPE:	Other	5	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	West Hill	Romano-Celtic temple, Uley		
DESIGNATION:	Scheduled	Monument (No. 1002076)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable plc	bughing	TREND:	Declining
OWNER TYPE:	Private	-o·····ò	CONTACT:	Business Manager 0117 975 0700
OTHER THE	invate		CONTACT.	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / STROUD / TEWKESBURY

OCCUPANCY:

OWNERTYPE: Private

PRIORITY:

SITE NAME:

CONDITION:

OCCUPANCY:

N/A C (C)

Dovecote 3 metres north of

Bridge House, Bentham,

Badgeworth

DESIGNATION: Listed Building Grade II\*


Poor

N/A

SITE NAME:	Bowl barr	Bowl barrow 720m south east of Longwood Farm, Woodchester				
DESIGNATION:	Scheduled	Monument (No. 1017084)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining		
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Bowl barr	Bowl barrow 330m north of Symonds' Hall Farm, Wotton-under-Edge				
DESIGNATION:	Scheduled	Monument (No. 1017083)	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	Declining		
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700		
TEWKESBURY						
	SITE NAME:	Dovecote approx 75 metres south east of Manor Farm, Fiddington, Ashchurch	north face.	637. Pointing eroded particularly on the Occasional missing roof tiles, although ng works have commenced.		
	DESIGNATION:	Listed Building Grade II*				
	CONDITION:	Poor				

	T	-
T		
		Contra to
	P.M.	1-11-1

		OWNER TYPE:	Private	Contact: Justin Ayton 0117 975 0687
		SITE NAME:	Malthouse to the rear of, 23 Barton Street, Tewkesbury	Workshop, former malthouse. C17. Building has been unoccupied for some time and although discussions have been held with the owner, no applications have
		DESIGNATION:	Listed Building Grade II*, CA	yet been forthcoming.
		CONDITION:	Poor	
	Enter	OCCUPANCY:	Vacant	
		PRIORITY:	C (New entry)	
	AND A CANADA	OWNER TYPE:	Private	Contact: Justin Ayton 0117 975 0687





PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but not yet implemented.
 E Under repair or in fair to go

OWNER TYPE: Private

SITE NAME:

CONDITION:

OCCUPANCY:

PRIORITY:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Former gatehouse to

DESIGNATION: Listed Building Grade II\*, SM, RPG I

Toddington

Poor

N/A

B (A)

Toddington House, Church Lane,

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

to the structure this coming year.

Contact: Mel Barge 0117 975 1300

Contact: Justin Ayton 0117 975 0687

Cement repairs to roof.

Dovecote, C17. Movement of structural timbers on south east and north east walls has caused joints to pull apart,

leading to brick panels falling out. Wattle and daub panels

Ancient Jacobean ruin, a remnant of the old manor house,

of which the ruined fragments remain 300 metres south west of Toddington House. Owners have now employed

conservation architect and builder to undertake repairs

are also fragmenting. Some timber decay on west side.

ABBREVIATIONS CA Conservation Area LB/LBs Listed Building/s LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM/SMs Scheduled Monument/s UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2011 / SOUTH WEST / TEWKESBURY

1	SITE NAME:	Toddington House, Church Lane, Toddington	Manor house, 1820-35, set in C19 formal gardens, on the east side of a late C18 landscape park. The house has been mothballed for more than 15 years, but has recently been
LUL TICK	DESIGNATION:	Listed Building Grade I, RPG II	purchased by a new owner who has installed a temporary
	CONDITION:	Fair	roof and is engaging in an extensive programme of urgent works and repairs in consultation with the Local Planning
	OCCUPANCY:	Vacant	Authority and English Heritage.
- Maria and the base of the second of the	PRIORITY:	E (E)	
C. Proposition of the second	OWNER TYPE:	Private	Contact: Justin Ayton 0117 975 0687
	Nottingha	m Hill camp Cotherington	

SITE NAME:	Nottingham Hill camp, Gotherington		
DESIGNATION:	Scheduled Monument (No. 1004864)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Great Witcombe Romano-British villa, Great	Witcombe	
DESIGNATION:	Scheduled Monument (No. 1014826)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 690m south west of Roel Farm	, Hawling	
designation:	Scheduled Monument (No. 1017076)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 760m south of Roel Farm, Haw	ling	
DESIGNATION:	Scheduled Monument (No. 1017077)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two bowl barrows known as Hawling Down 610m north east of Slade Barn Farm, Hawlin		,
	Two bowl barrows known as Hawling Down 610m north east of Slade Barn Farm, Hawling Scheduled Monument (No. 1017037)		, Extensive significant problems
DESIGNATION:	610m north east of Slade Barn Farm, Hawling	g	
DESIGNATION: PRINCIPAL VULNERABILITY:	610m north east of Slade Barn Farm, Hawlin Scheduled Monument (No. 1017037)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	610m north east of Slade Barn Farm, Hawlin Scheduled Monument (No. 1017037) Arable ploughing	CONDITION: TREND:	Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	610m north east of Slade Barn Farm, Hawling Scheduled Monument (No. 1017037) Arable ploughing Private	CONDITION: TREND:	Extensive significant problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	610m north east of Slade Barn Farm, Hawling Scheduled Monument (No. 1017037) Arable ploughing Private Hailes Abbey and ringwork, Stanway	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	610m north east of Slade Barn Farm, Hawling Scheduled Monument (No. 1017037) Arable ploughing Private Hailes Abbey and ringwork, Stanway Scheduled Monument (No. 1018070)	CONDITION: TREND: CONTACT: CONDITION:	Extensive significant problems Declining Business Manager 0117 975 0700 Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	610m north east of Slade Barn Farm, Hawling Scheduled Monument (No. 1017037) Arable ploughing Private Hailes Abbey and ringwork, Stanway Scheduled Monument (No. 1018070) Arable ploughing	CONDITION: TREND: CONTACT: CONDITION: TREND:	Extensive significant problems Declining Business Manager 0117 975 0700 Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	610m north east of Slade Barn Farm, Hawling Scheduled Monument (No. 1017037) Arable ploughing Private Hailes Abbey and ringwork, Stanway Scheduled Monument (No. 1018070) Arable ploughing Private	CONDITION: TREND: CONTACT: CONDITION: TREND:	Extensive significant problems Declining Business Manager 0117 975 0700 Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	610m north east of Slade Barn Farm, Hawling Scheduled Monument (No. 1017037) Arable ploughing Private Hailes Abbey and ringwork, Stanway Scheduled Monument (No. 1018070) Arable ploughing Private Hailes Wood camp, Hailes, Stanway	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Extensive significant problems Declining Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	610m north east of Slade Barn Farm, Hawling Scheduled Monument (No. 1017037) Arable ploughing Private Hailes Abbey and ringwork, Stanway Scheduled Monument (No. 1018070) Arable ploughing Private Hailes Wood camp, Hailes, Stanway Scheduled Monument (No. 1004843)	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Extensive significant problems Declining Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: OWNER TYPE:	610m north east of Slade Barn Farm, Hawling Scheduled Monument (No. 1017037) Arable ploughing Private Hailes Abbey and ringwork, Stanway Scheduled Monument (No. 1018070) Arable ploughing Private Hailes Wood camp, Hailes, Stanway Scheduled Monument (No. 1004843) Extensive animal burrowing	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: CONTACT:	Extensive significant problems Declining Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	610m north east of Slade Barn Farm, Hawling Scheduled Monument (No. 1017037) Arable ploughing Private Hailes Abbey and ringwork, Stanway Scheduled Monument (No. 1018070) Arable ploughing Private Hailes Wood camp, Hailes, Stanway Scheduled Monument (No. 1004843) Extensive animal burrowing Private	CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT: CONTACT:	Extensive significant problems Declining Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	610m north east of Slade Barn Farm, Hawling Scheduled Monument (No. 1017037) Arable ploughing Private Hailes Abbey and ringwork, Stanway Scheduled Monument (No. 1018070) Arable ploughing Private Hailes Wood camp, Hailes, Stanway Scheduled Monument (No. 1004843) Extensive animal burrowing Private Milhampost Roman site, Stanway	CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: TREND: CONTACT:	Extensive significant problems Declining Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / TEWKESBURY / ISLES OF SCILLY (UA)

SITE NAME:	Wadfield Roman villa, Sudeley	
DESIGNATION:	Scheduled Monument (No. 1004846)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Business Manager 0117 975 0700
SITE NAME:	Moat House moated site, Uckington	
DESIGNATION:	Scheduled Monument (No. 1016835)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND: Stable
OWNER TYPE:	Private	CONTACT: Business Manager 0117 975 0700
SITE NAME:	Deserted medieval village, Walton Ca	
DESIGNATION:	Scheduled Monument (No. 1002071)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Business Manager 0117 975 0700
SITE NAME:	Romano-British villa 170m south west	of Winchcombe School, Greet Road, Winchcombe
DESIGNATION:	Scheduled Monument (No. 1021449)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	trend: Unknown
OWNER TYPE:	Private	CONTACT: Business Manager 0117 975 0700
ISLES OF SCILLY (UA	A)	
	SITE NAME: Post medieval cottages, Samson	Fossilised C18/C19 landscape. The remains of the building are at risk from natural weathering, vegetation and erosio caused by visitors. A management plan has been devised and initial phase of consolidation grant-aided by English
	designation: Scheduled Monument, CA	Heritage is now complete. The result of the consolidation trials are being studied to inform a wider programme
	CONDITION: Poor	of repair.
	occupancy: N/A	
	priority: C (C)	
	ownertype: Trust	Contact: Phil McMahon 0117 975 0699
SITE NAME:	Civil War battery on The Green, Bryh	er
DESIGNATION:	Scheduled Monument (No. 1010176)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND: Declining
	0:1	

			, and the second s
SITE NAME:	Gig shed on the north coast of Great Porth	n, Bryher	
DESIGNATION:	Scheduled Monument (No. 1016173)	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining

CONTACT:

CONTACT:

SITE NAME:	Prehistoric enclosure south east of The Bro	ow, Bryher	
DESIGNATION:	Scheduled Monument (No. 1015649)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700

#### PRIORITY (FOR BUILDINGS)

OWNER TYPE:

OWNER TYPE:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

Other

Other

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

Business Manager 0117 975 0700

Business Manager 0117 975 0700

#### HERITAGE AT RISK 2011 / SOUTH WEST / ISLES OF SCILLY (UA)

SITE NAME:	Prehistoric field system and post-medieval	quay in Great Por	th, Bryher
DESIGNATION:	Scheduled Monument (No. 1014987)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric field system and Romano-British	n cist in Green Ba	y, Bryher
DESIGNATION:	Scheduled Monument (No. 1014989)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric hut circle south of The Brow, B	ryher	
DESIGNATION:	Scheduled Monument (No. 1014990)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric linear boundary and cairns sout		•
designation:	Scheduled Monument (No. 1016170)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric linear boundary SSE of The Islar	nd, Bryher	
DESIGNATION:	Scheduled Monument (No. 1014991)	CONDITION:	Generally satisfactory
DESIGNATION.		CONDITION.	but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
OWNERTIFE:	Unici	CONTACT:	Dusiness Fianager 0117 775 0700
SITE NAME:	Platform cairn on Cruther's Neck, St Martin	n's	
DESIGNATION:	Scheduled Monument (No. 1013806)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric cairn cemetery and field system	on Tinkler's Hill.	St Martin's
	Prehistoric cairn cemetery and field system		
DESIGNATION:	Scheduled Monument (No. 1018109)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION:	Scheduled Monument (No. 1018109) Scrub / tree growth		Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018109)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018109) Scrub / tree growth	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1018109) Scrub / tree growth Other	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Island Carn, St Martin's Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1018109) Scrub / tree growth Other Prehistoric house platform settlement sout Scheduled Monument (No. 1018115)	CONDITION: TREND: CONTACT: h west of English CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Island Carn, St Martin's Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018109) Scrub / tree growth Other Prehistoric house platform settlement sout Scheduled Monument (No. 1018115) Plant growth	CONDITION: TREND: CONTACT: h west of English CONDITION: TREND:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Island Carn, St Martin's Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1018109) Scrub / tree growth Other Prehistoric house platform settlement sout Scheduled Monument (No. 1018115)	CONDITION: TREND: CONTACT: h west of English CONDITION:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Island Carn, St Martin's Generally satisfactory but with significant localised problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / ISLES OF SCILLY (UA)

ITE NAME:	Prehistoric settlement and Romano-British	shrine on Norno	ur, St Martin's
DESIGNATION:	Scheduled Monument (No. 1015674)	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Prehistoric to Romano-British ritual, funera	ry and settlement	remains on Par Beach, St Martin's
DESIGNATION:	Scheduled Monument (No. 1018116)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Ennor Castle, Old Town, St Mary's		
DESIGNATION:	Scheduled Monument (No. 1014994)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Hut circle settlement in Pendrathen, St Mar	ry's	
DESIGNATION:	Scheduled Monument (No. 1015663)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
WNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Iron Age to Romano-British fogou on northern Peninnis Head, I70m south of Carn Gwavel Farm, St Mary's		
DESIGNATION:	Scheduled Monument (No. 1020142)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Collapse	TREND:	Unknown
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Kerbed platform cairn on Helvear Hill, 210	m ENE of Helvear	Farm, St Mary's
DESIGNATION:	Scheduled Monument (No. 1010168)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
DWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Post-medieval breastwork, curtain wall and on the periphery of The Garrison, St Mary?		ive structures
DESIGNATION:	Scheduled Monument (No. 1018370)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
WNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
ite name:	Prehistoric settlement, Romano-British cist northern Toll's Porth, St Mary's	cemetery and Civ	vil War battery in
DESIGNATION:	Scheduled Monument (No. 1015664)	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / ISLES OF SCILLY (UA)

SITE NAME:	Round cairn 137m east of Helvear Farm, St	Mary's	
DESIGNATION:	Scheduled Monument (No. 1010167)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	The Giant's Castle cliff castle, St Mary's		
DESIGNATION:	Scheduled Monument (No. 1011935)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	The Old Quay, Old Town Bay, St Mary's		
DESIGNATION:	Scheduled Monument (No. 1015656)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	World War II pillbox between Thomas' Por	th and Porthaloo,	St Mary's
DESIGNATION:	Scheduled Monument (No. 1016517)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700
	World War II pillbox west of Porth Hellick, 90m north of Drum Rock, St Mary's		
SITE NAME:	vvorid vvar II pillbox west of Porth Hellick,	90m north of Dr	um Rock, St Mary's
designation:	World War II pillbox west of Porth Hellick, Scheduled Monument (No. 1016516)	CONDITION:	um Rock, St Mary's Extensive significant problems i.e. under plough, collapse
DESIGNATION:	•		Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1016516)	CONDITION:	Extensive significant problems i.e. under plough, collapse
	Scheduled Monument (No. 1016516) Plant growth	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1016516) Plant growth Other	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1016516) Plant growth Other Post-medieval animal-driven crushing mill 2	CONDITION: TREND: CONTACT: 70m south west c	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>f Blockhouse Cottage, Tresco</b> Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1016516) Plant growth Other Post-medieval animal-driven crushing mill 2 Scheduled Monument (No. 1016186)	CONDITION: TREND: CONTACT: 70m south west c CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>f Blockhouse Cottage, Tresco</b> Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1016516) Plant growth Other Post-medieval animal-driven crushing mill 2 Scheduled Monument (No. 1016186) Scrub / tree growth	CONDITION: TREND: CONTACT: 70m south west of CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>f Blockhouse Cottage,Tresco</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1016516) Plant growth Other Post-medieval animal-driven crushing mill 2 Scheduled Monument (No. 1016186) Scrub / tree growth Other	CONDITION: TREND: CONTACT: 70m south west of CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>f Blockhouse Cottage,Tresco</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1016516)         Plant growth         Other         Post-medieval animal-driven crushing mill 2         Scheduled Monument (No. 1016186)         Scrub / tree growth         Other         Prehistoric field system and settlement in E	CONDITION: TREND: CONTACT: 70m south west of CONDITION: TREND: CONTACT: Sathinghouse Port	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>Blockhouse Cottage, Tresco</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>h, Tresco</b> Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1016516)         Plant growth         Other         Post-medieval animal-driven crushing mill 2         Scheduled Monument (No. 1016186)         Scrub / tree growth         Other         Prehistoric field system and settlement in B         Scheduled Monument (No. 1016423)	CONDITION: TREND: CONTACT: 70m south west of CONDITION: TREND: CONTACT: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>Blockhouse Cottage,Tresco</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>h,Tresco</b> Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1016516)         Plant growth         Other         Post-medieval animal-driven crushing mill 2         Scheduled Monument (No. 1016186)         Scrub / tree growth         Other         Prehistoric field system and settlement in B         Scheduled Monument (No. 1016423)         Coastal erosion	CONDITION: TREND: CONTACT: 70m south west of CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>f Blockhouse Cottage, Tresco</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>h, Tresco</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1016516)         Plant growth         Other         Post-medieval animal-driven crushing mill 2         Scheduled Monument (No. 1016186)         Scrub / tree growth         Other         Prehistoric field system and settlement in B         Scheduled Monument (No. 1016423)         Coastal erosion         Other	CONDITION: TREND: CONTACT: 70m south west of CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>f Blockhouse Cottage, Tresco</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>h, Tresco</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No. 1016516)         Plant growth         Other         Post-medieval animal-driven crushing mill 2         Scheduled Monument (No. 1016186)         Scrub / tree growth         Other         Prehistoric field system and settlement in B         Scheduled Monument (No. 1016423)         Coastal erosion         Other         Prehistoric field system and settlement nor	CONDITION: TREND: CONTACT: 70m south west of CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: th of Appletree Part	Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>Blockhouse Cottage, Tresco</b> <b>G</b> enerally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>h, Tresco</b> Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 <b>but with significant localised problems</b> Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Prehistoric round cairn 255m south west of Blockhouse Cottages, Tresco				
DESIGNATION:	Scheduled Monument (No. 1016187)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Other	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	St Nicholas' Priory, Tresco				
SITE NAME: DESIGNATION:	<b>St Nicholas' Priory, Tresco</b> Scheduled Monument (No. 1016184)	CONDITION:	Generally satisfactory		
	,. ,.	CONDITION:	Generally satisfactory but with significant localised problems		
	,. ,.	CONDITION: TREND:	, , ,		
DESIGNATION:	Scheduled Monument (No. 1016184)		but with significant localised problems		

#### NORTH SOMERSET (UA)

	CONDITION: OCCUPANCY: PRIORITY:	Ashton Court, Long Ashton Listed Building Grade I, RPG II* Very bad Part occupied C (New entry) Local authority	Large country house dating from C15, C17, C18 and C19. House partly used as hospitality venue and estate offices, but large part remains derelict and subject to slow but ongoing decay. The house has been the subject of negotiations between owners, LPA, EH and other interested parties for many years; the most recent negotiations aimed at achieving an incremental restoration are ongoing. EH grant offered 2011. Contact: Justin Ayton 0117 975 0687
	CONDITION: OCCUPANCY: PRIORITY:	Elms Colliery, Nailsea Scheduled Monument Poor Vacant B (B) Local authority	One of the most complete examples of a late C18 colliery remaining in England. There are three standing structures and further exposed archaeological remains. All buildings are unroofed, derelict and subject to neglect and vandalism. Wall top consolidation completed. Contact: Rob Iles 0117 975 0662
	CONDITION: OCCUPANCY: PRIORITY:	Birnbeck Pier, Weston Super Mare Listed Building Grade II*, CA Very bad Part occupied A (A) Company	Main pier which connects Birnbeck Island to the mainland below the Prince Consort Gardens. Dated 1862, opened 1867. Disused apart from the lifeboat station on the island. Negotiations are ongoing between local planning authority, owner, English Heritage and other interested parties about repair of pier and development of island. Trial repairs have been grant-aided by English Heritage. Contact: Chris Miners 0117 975 0700
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	F (A)	Orangery (1897). Tyntesfield House and estate was acquired in 2002 by the National Trust with funding from the Heritage Lottery Fund. The Trust is in the process of drawing up a strategy for the various elements. A temporary roof has been installed. An application for listed building consent was approved in 2010. Repairs are underway. Contact: Justin Ayton 0117 975 0687
SITE NAME:	Beach Law	ns, Weston-Super-Mare	
DESIGNATION:	Conservat	ion Area	CONDITION: Very bad

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Marianna Porter (LPA) 01934 426250	NEW ENTRY?:	No

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / NORTH SOMERSET (UA) / PLYMOUTH, CITY OF (UA)

SITE NAME: Birnbeck, Weston-Super-Mare			
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Marianna Porter (LPA) 01934 426250	NEW ENTRY?:	No
SITE NAME:	Boulevard / Montpelier		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Marianna Porter (LPA) 01934 426250	NEW ENTRY?:	No
SITE NAME:	Clevedon Triangle		
SITE NAME: DESIGNATION:	<b>Clevedon Triangle</b> Conservation Area	CONDITION:	Very bad
	-	CONDITION: TREND:	Very bad Deteriorating
DESIGNATION:	Conservation Area		
DESIGNATION: VULNERABILITY:	Conservation Area Medium	TREND:	Deteriorating
DESIGNATION: VULNERABILITY:	Conservation Area Medium	TREND:	Deteriorating
DESIGNATION: VULNERABILITY: CONTACT:	Conservation Area Medium Marianna Porter (LPA) 01934 426250	TREND:	Deteriorating
DESIGNATION: VULNERABILITY: CONTACT: SITE NAME:	Conservation Area Medium Marianna Porter (LPA) 01934 426250 Melrose / Grove Park, Weston-Super-Mare	TREND: NEW ENTRY?:	Deteriorating No
DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION:	Conservation Area Medium Marianna Porter (LPA) 01934 426250 Melrose / Grove Park, Weston-Super-Mare Conservation Area	TREND: NEW ENTRY?: CONDITION:	Deteriorating No Poor

#### PLYMOUTH, CITY OF (UA)

SITE NAME:	Agaton Fort, Plymouth
DESIGNATION:	Scheduled Monument
CONDITION:	Fair
OCCUPANCY:	Part occupied
PRIORITY:	C (D)
OWNER TYPE:	Government

	OCCUPANCY:	Part occupied	
	PRIORITY:	C (D)	
And Press	OWNER TYPE:	Government	Contact: Phil McMahon 0117 975 0699
	SITE NAME:	The coastal fortifications of Drakes Island, Plymouth	The Island incorporates numerous defences/military monuments from 1549-C20. It was held for Parliament during the Civil War and used for defence purposes until
And the second	DESIGNATION:	Listed Building Grade II, SM	1958. More recently it was used as an outdoor pursuits centre. All buildings and structures are thought to be in
	CONDITION:	Poor	a poor state. Initial discussions with Plymouth CC and
Contraction of the American	OCCUPANCY:	Vacant	the owner's representatives on a potential regeneration
average and the second	PRIORITY:	C (C)	scheme are at an early stage.
and the second sec	OWNER TYPE:	Private	Contact: Phil McMahon 0117 975 0699



	PRIORITY:	С (С)	scheme are at an early stage.
	OWNER TYPE:	Private	Contact: Phil McMahon 0117 975 0699
	SITE NAME:	Boringdon Arch, Plymbridge Road, Plymouth	Designed by Robert Adam and built in 1783, it is believed the arch was built as a triumphal arch and eye-catcher to be viewed from Saltram House. Its repair was included
	DESIGNATION:	Listed Building Grade II*, SM	in a Section IO6 agreement associated with consent for adjacent golf course, but work on the arch is yet to start.
ALC: NO.	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	D (D)	
	OWNER TYPE:	Private	Contact: Simon Ramsden 0117 975 0676



SITE NAME:	Woodland Fort, Crownhill Road, Crownhill, Plymouth	Palmerston Fort, built 1863-1869. Part of barrack block in use as social club, but the rest is empty. Remedial repairs have been undertaken and some of the heavy vegetation
DESIGNATION:	Scheduled Monument	has recently been cleared. Site is prone to vandalism and rubbish dumping. English Heritage and Plymouth City
CONDITION:	Very bad	Council are undertaking a joint funded study to look
OCCUPANCY:	Part occupied	at regeneration and conservation options.
PRIORITY:	C (C)	
OWNER TYPE:	Local authority	Contact: Phil McMahon 0117 975 0699

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Compared for the rest of the r
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

Heavy Goods Vehicle testing centre is located within

a modern building in the Fort. Some ancillary buildings

are vacant but have been subject to remedial repairs.

ABBREVIATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

#### HERITAGE AT RISK 2011 / SOUTH WEST / PLYMOUTH, CITY OF (UA)

DD FELLOWS HALL	SITE NAME:	Oddfellows Hall,	Hall by Johr	n Foulston, 1823, in the Egyptian style.	
		Ker Street, Devonport, Plymouth	Column. Eg	oup with the Guildhall and Devonport yptian columns flank a central, recessed	
	DESIGNATION:	Listed Building Grade I	porch. Curr	ently used as a social club and in poor repair.	
	CONDITION:	Poor		itage has previously grant-aided a feasibility mergency repairs to the roof.	
	OCCUPANCY:		study and c	inergency repairs to the root.	
	PRIORITY:	C (C)			
		Private	Contact: Sin	non Ramsden 0117 975 0676	
	OWNER TYPE:	rnvale	Contact. Sil		
	SITE NAME:	Efford Fort and Emplacement, Military Road, Efford, Plymouth	parade grou	Fort built 1863-1869. Partially occupied as und is used for storage, but all buildings are dings are suffering from extreme neglect and	
	DESIGNATION:		decay and heavy vegetation growth. Extensive water		
		Very bad	penetration and structural problems are apparent. No solution agreed at present.		
	CONDITION:		INO SOLUTION	i agreed at present.	
· TTTE		Part occupied			
	PRIORITY:	A (A)			
Sand and a second second	OWNER TYPE:	Private	Contact: Ph	il McMahon 0117 975 0699	
	SITE NAME:	South Saw Mills, South Yard, HM Naval Base, Plymouth	as such in l industrial us	856-59. The saw mills ceased to be used 987 but the ground floor remained in light se and for storage until 1997. It remains	
	DESIGNATION:	Listed Building Grade II*	vacant with no identifiable use.		
- STATLITER DODA	CONDITION:	Fair			
	OCCUPANCY:	Vacant			
	PRIORITY:	E (E)			
	OWNER TYPE:	Government	Contact: Michael Turner 020 7973 3808 Dockyard smithery built 1771, modified in the C19 and reconstructed circa 1897. Remained in use until 1987 wh structural faults were discovered. Doors and windows w		
	SITE NAME:	South Smithery, South Yard, HM Naval Base, Plymouth			
	DESIGNATION:	Listed Building Grade II*		hertight in 2007, but much of the roof remair	
	CONDITION:	Very bad	exposed; there is continued deterioration of masonry a internal joinery.		
	OCCUPANCY:				
	PRIORITY:	A (A)			
	OWNER TYPE:	2	Contact: Mi	chael Turner 020 7973 3808	
	SITE NAME:	Amphitheatre in grounds of Saltram House, Merafield Road, Plympton, Plymouth	Late C18 screen wall fronting rock-cut grottos overlooking the River Plym. Surrounding rock faces have become unstable and are subject to collapse.		
CLE HALLES	DESIGNATION:	Listed Building Grade II*, RPG II*	Repair of th	ne amphitheatre has been identified as tive in a draft landscape masterplan for	
	CONDITION:	Fair	the Saltram		
	OCCUPANCY:	N/A			
	PRIORITY:	С (С)			
	OWNER TYPE:		Contact: Sir	non Ramsden 0117 975 0676	
	SITE NAME:	Academy Theatre and Great Western Hotel (Palace Theatre), Union Street, Stonehouse, Plymouth	deterioratin area. English	iety theatre and hotel, I 898. Building gradually 1g. A significant building in a major regeneratic 1 Heritage has offered grant aid in the past,	
ALL INTO	DESIGNATION:	Listed Building Grade II*, CA	which was not taken up. Temporary repairs undertaken in 1997. Currently in very bad condition with water		
	CONDITION:	Penetration causing internal floors to become			
1 1 1 1 1	OCCUPANCY:				
	PRIORITY:	A (A)			
	OWNERTYPE: Private Contact: Simon Ramsden 0117 975 0676				
TE NIAME.	Austin For	t and section of military road, Plymou	th		
		Monument (No. 1021380)		Generally satisfactory	
DESIGNATION:	Jeneduleu		CONDITION:	but with significant localised problems	
	Scrub / tre	e growth	TREND:	Stable	
RINCIPAL VULNERABILITY:	JCI UD / LIC	- 0			

eteroration or loss of tannc; no solution agreed. B Immediate risk of further rapid deterioration or loss of fahric; solution agreed but not yet implemented. C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets. 
 ABBREVIATIONS

 CA
 Conservation Area

 LB/LBs
 Listed Building/s

 LPA
 Local Planning Authority

 NP
 National Park

 RPG
 Registered Park and Garden

 SM/SMs
 Scheduled Monument/s

 UA
 Unitary Authority

 WHS
 World Heritage Site

#### HERITAGE AT RISK 2011 / SOUTH WEST / PLYMOUTH, CITY OF (UA)

SITE NAME:	Efford Fort and Efford Emplacement, Plymouth	1	
DESIGNATION:	Scheduled Monument (No. 1021135)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Egg Buckland keep, Plymouth		
DESIGNATION:	Scheduled Monument (No. 1020543)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Fort Stamford, Plymouth		
DESIGNATION:	Scheduled Monument (No. 1002544)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Knowle battery, Plymouth		
designation:	Scheduled Monument (No. 1002614)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Rain entry	TREND:	Unknown
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Laira Battery, Plymouth		
DESIGNATION:	Scheduled Monument (No. 1021134)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
	-	inches.	Business Manager 0117 975 0700
OWNER TYPE:	Private	CONTACT:	DUSITIESS FIATAGET OF T7 773 0700
OWNER TYPE:	Private	CONTACT:	
	Laira Emplacement, immediately south west of		Plymouth
SITE NAME:			
ITE NAME: DESIGNATION:	Laira Emplacement, immediately south west of	Laira Battery,	Plymouth Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Laira Emplacement, immediately south west of Scheduled Monument (No. 1020686)	Laira Battery,	Plymouth Generally unsatisfactory with major localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Laira Emplacement, immediately south west of Scheduled Monument (No. 1020686) Development requiring planning permission	T Laira Battery, Condition: TREND:	Plymouth Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Laira Emplacement, immediately south west of Scheduled Monument (No. 1020686) Development requiring planning permission Private	T Laira Battery, Condition: TREND:	Plymouth Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE: SITE NAME: DESIGNATION:	Laira Emplacement, immediately south west of         Scheduled Monument (No. 1020686)         Development requiring planning permission         Private         Plympton Castle, Plymouth         Scheduled Monument (No. 1003865)	TLAIRA BATTERY, CONDITION: TREND: CONTACT:	Plymouth Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Laira Emplacement, immediately south west of Scheduled Monument (No. 1020686) Development requiring planning permission Private Plympton Castle, Plymouth	CONDITION: CONTACT: CONDITION:	Plymouth Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Laira Emplacement, immediately south west of         Scheduled Monument (No. 1020686)         Development requiring planning permission         Private         Plympton Castle, Plymouth         Scheduled Monument (No. 1003865)         Plant growth	TLAIRA BATTERY, CONDITION: TREND: CONTACT: CONDITION: TREND:	Plymouth Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Laira Emplacement, immediately south west of         Scheduled Monument (No. 1020686)         Development requiring planning permission         Private         Plympton Castle, Plymouth         Scheduled Monument (No. 1003865)         Plant growth         Local Authority         Plympton Priory, Plymouth	TLAIRA BATTERY, CONDITION: TREND: CONTACT: CONDITION: TREND:	Plymouth Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE:	Laira Emplacement, immediately south west of         Scheduled Monument (No. 1020686)         Development requiring planning permission         Private         Plympton Castle, Plymouth         Scheduled Monument (No. 1003865)         Plant growth         Local Authority	TLAIRA BATTERY, CONDITION: TREND: CONTACT: CONDITION: TREND:	Plymouth Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Laira Emplacement, immediately south west of         Scheduled Monument (No. 1020686)         Development requiring planning permission         Private         Plympton Castle, Plymouth         Scheduled Monument (No. 1003865)         Plant growth         Local Authority         Plympton Priory, Plymouth	CONDITION: CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Plymouth Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / PLYMOUTH, CITY OF (UA) / POOLE (UA)

SITE NAME:	Stonehouse Manor wall, Plymouth		
DESIGNATION:	Scheduled Monument (No. 1003850)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Improving
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	The coastal fortifications of Drake's Island, Ply	mouth	
DESIGNATION:	Scheduled Monument (No. 1010910)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Woodland fort, Plymouth		
DESIGNATION:	Scheduled Monument (No. 1002615)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Improving
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Union Street		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium Milla Danialla (LPA), 01752, 204297	TREND:	Unknown
CONTACT:	Mike Daniells (LPA) 01752 304397	NEW ENTRY?:	Yes
POOLE (UA)			
SITE NAME:	Round barrow cemetery on Barrow Hill 150m	south west of	Brookvale Farm, Poole
	Round barrow cemetery on Barrow Hill 150m Scheduled Monument (No. 1018029)	south west of	Brookvale Farm, Poole Generally unsatisfactory with major localised problems
DESIGNATION:			Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018029)	CONDITION:	Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1018029) Deterioration – in need of management	CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1018029) Deterioration – in need of management Private	CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1018029) Deterioration – in need of management Private Branksome Park, Canford Cliffs	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY:	Scheduled Monument (No. 1018029) Deterioration – in need of management Private Branksome Park, Canford Cliffs Conservation Area	CONDITION: TREND: CONTACT: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Scheduled Monument (No. 1018029) Deterioration – in need of management Private Branksome Park, Canford Cliffs Conservation Area Low	CONDITION: TREND: CONTACT: CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Very bad Deteriorating
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME:	Scheduled Monument (No. 1018029)         Deterioration – in need of management         Private         Branksome Park, Canford Cliffs         Conservation Area         Low         Warren Lever (LPA) 01202 633 331	CONDITION: TREND: CONTACT: CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Very bad Deteriorating
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1018029) Deterioration – in need of management Private Branksome Park, Canford Cliffs Conservation Area Low Warren Lever (LPA) 01202 633 331 Evening Hill, Canford Heath, Poole	CONDITION: TREND: CONTACT: CONDITION: TREND: NEW ENTRY?:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Very bad Deteriorating Yes
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1018029) Deterioration – in need of management Private Branksome Park, Canford Cliffs Conservation Area Low Warren Lever (LPA) 01202 633 331 Evening Hill, Canford Heath, Poole Conservation Area	CONDITION: TREND: CONTACT: CONDITION: TREND: NEW ENTRY?: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Very bad Deteriorating Yes
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Scheduled Monument (No. 1018029) Deterioration – in need of management Private Branksome Park, Canford Cliffs Conservation Area Low Warren Lever (LPA) 01202 633 331 Evening Hill, Canford Heath, Poole Conservation Area Medium	CONDITION: TREND: CONTACT: CONDITION: TREND: NEW ENTRY?: CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Very bad Deteriorating Yes Poor Deteriorating significantly
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1018029)         Deterioration – in need of management         Private         Branksome Park, Canford Cliffs         Conservation Area         Low         Warren Lever (LPA) 01202 633 331         Evening Hill, Canford Heath, Poole         Conservation Area         Medium         Warren Lever (LPA) 01202 633 331	CONDITION: TREND: CONTACT: CONDITION: TREND: NEW ENTRY?: CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Very bad Deteriorating Yes Poor Deteriorating significantly
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1018029) Deterioration – in need of management Private Branksome Park, Canford Cliffs Conservation Area Low Warren Lever (LPA) 01202 633 331 Evening Hill, Canford Heath, Poole Conservation Area Medium Warren Lever (LPA) 01202 633 331 Haven Road, Canford Cliffs, Poole	CONDITION: TREND: CONTACT: CONDITION: TREND: NEW ENTRY?: CONDITION: TREND: NEW ENTRY?:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Very bad Deteriorating Yes Poor Deteriorating significantly No
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY:	Scheduled Monument (No. 1018029)         Deterioration – in need of management         Private         Branksome Park, Canford Cliffs         Conservation Area         Low         Warren Lever (LPA) 01202 633 331         Evening Hill, Canford Heath, Poole         Conservation Area         Medium         Warren Lever (LPA) 01202 633 331	CONDITION: TREND: CONTACT: CONDITION: TREND: NEW ENTRY?: CONDITION: TREND: NEW ENTRY?:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Very bad Deteriorating Yes Poor Deteriorating significantly No
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Scheduled Monument (No. 1018029) Deterioration – in need of management Private Branksome Park, Canford Cliffs Conservation Area Low Warren Lever (LPA) 01202 633 331 Evening Hill, Canford Heath, Poole Conservation Area Medium Warren Lever (LPA) 01202 633 331 Haven Road, Canford Cliffs, Poole Conservation Area Medium	CONDITION: TREND: CONTACT: CONDITION: TREND: NEW ENTRY? CONDITION: TREND: NEW ENTRY?	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Very bad Deteriorating Yes Poor Deteriorating significantly No Very bad No significant change
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: SITE	Scheduled Monument (No. 1018029)         Deterioration – in need of management         Private         Branksome Park, Canford Cliffs         Conservation Area         Low         Warren Lever (LPA) 01202 633 331         Evening Hill, Canford Heath, Poole         Conservation Area         Medium         Warren Lever (LPA) 01202 633 331         Haven Road, Canford Cliffs, Poole         Conservation Area         Medium         Warren Lever (LPA) 01202 633 331	CONDITION: TREND: CONTACT: CONDITION: TREND: NEW ENTRY? CONDITION: TREND: NEW ENTRY?	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Very bad Deteriorating Yes Poor Deteriorating significantly No Very bad No significant change
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY:	Scheduled Monument (No. 1018029) Deterioration – in need of management Private Branksome Park, Canford Cliffs Conservation Area Low Warren Lever (LPA) 01202 633 331 Evening Hill, Canford Heath, Poole Conservation Area Medium Warren Lever (LPA) 01202 633 331 Haven Road, Canford Cliffs, Poole Conservation Area Medium Warren Lever (LPA) 01202 633 331 Haven Road, Canford Cliffs, Poole Conservation Area Medium Warren Lever (LPA) 01202 633 331 Haven Road, Canford Cliffs, Poole Conservation Area Medium Warren Lever (LPA) 01202 633 331	CONDITION: TREND: CONTACT: CONTACT: TREND: NEW ENTRY? CONDITION: TREND: NEW ENTRY? CONDITION: TREND: NEW ENTRY?	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Very bad Deteriorating Yes Poor Deteriorating significantly No Very bad No significant change No

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the solution of the solution

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

SITE NAME:	Sandbanks, Canford Cliffs, Poole		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Warren Lever (LPA) 01202 633 331	NEW ENTRY?:	No

CONDITION: TREND: CONTACT: Od, Carhampto CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 rk, Carhampton, West Somerset Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 on, West Somerset Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Gallox Hill, Dunster, West Somerset Generally satisfactory
CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONDITION: CONDITION: TREND: CONDITION: TREND: CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 rk, Carhampton, West Somerset Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 on, West Somerset Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Gallox Hill, Dunster, West Somerset Generally satisfactory
TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION:	but with significant localised problems Declining Business Manager 0117 975 0700 rk, Carhampton, West Somerset Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 on, West Somerset Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Gallox Hill, Dunster, West Somerset Generally satisfactory
CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: CONDITION: CONDITION:	Declining Business Manager 0117 975 0700 rk, Carhampton, West Somerset Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 on, West Somerset Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Gallox Hill, Dunster, West Somerset Generally satisfactory
CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONTACT:	Business Manager 0117 975 0700 rk, Carhampton, West Somerset Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 on, West Somerset Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Gallox Hill, Dunster, West Somerset Generally satisfactory
CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 on, West Somerset Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Gallox Hill, Dunster, West Somerset Generally satisfactory
TREND: CONTACT: od, Carhampto CONDITION: TREND: CONTACT: ettlement on C	with major localised problems Declining Business Manager 0117 975 0700 <b>Don, West Somerset</b> Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 <b>Gallox Hill, Dunster, West Somerset</b> Generally satisfactory
CONTACT: od, Carhampte CONDITION: TREND: CONTACT: ettlement on C CONDITION:	Declining Business Manager 0117 975 0700 on, West Somerset Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Gallox Hill, Dunster, West Somerset Generally satisfactory
CONTACT: od, Carhampte CONDITION: TREND: CONTACT: ettlement on C CONDITION:	Business Manager 0117 975 0700 on, West Somerset Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Gallox Hill, Dunster, West Somerset Generally satisfactory
CONDITION: TREND: CONTACT: ettlement on ( CONDITION:	Generally satisfactory but with significant localised problems Stable Business Manager 0117 975 0700 Gallox Hill, Dunster, West Somerset Generally satisfactory
TREND: CONTACT: ettlement on ( CONDITION:	but with significant localised problems Stable Business Manager 0117 975 0700 Gallox Hill, Dunster, West Somerset Generally satisfactory
CONTACT: ettlement on ( CONDITION:	Stable Business Manager 0117 975 0700 Gallox Hill, Dunster, West Somerset Generally satisfactory
ettlement on ( condition:	Gallox Hill, Dunster, West Somerset Generally satisfactory
CONDITION:	Generally satisfactory
TREND:	but with significant localised problems
	Declining
CONTACT:	Business Manager 0117 975 0700
CONDITION:	Generally satisfactory but with significant localised problems
TREND:	Declining
CONTACT:	Business Manager 0117 975 0700
m WNW of th	ne sheepfold, Exmoor, West Somerset
CONDITION:	Generally unsatisfactory
	with major localised problems
TREND:	Declining
CONTACT:	Business Manager 0117 975 0700
thy (eastern o	f two), Luccombe, West Somerset
CONDITION:	Generally unsatisfactory with major localised problems
	Declining
CONTACT:	Business Manager 0117 975 0700
	CONTACT: Dm WNW of th CONDITION: TREND: CONTACT: TREND: CONDITION: TREND:

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Concentration

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

#### HERITAGE AT RISK 2011 / SOUTH WEST / EXMOOR (NP)

SITE NAME:	Iron Age defended settlement above Sweet	worthy (western o	of two), Luccombe, West Somerset
DESIGNATION:	Scheduled Monument (No. 1008472)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		00.00.00.00	
SITE NAME:	Sweetworthy deserted medieval settlement	, Luccombe, West	Somerset
DESIGNATION:	Scheduled Monument (No. 1008469)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Berry Castle, Iron Age enclosure in Berry C	Castle Wood, Porlo	ock, West Somerset
DESIGNATION:	Scheduled Monument (No. 1006204)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stone circle, Porlock Common, Porlock, We	est Somerset	
DESIGNATION:	Scheduled Monument (No. 1006189)	CONDITION:	Generally satisfactory
			but with minor localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Allerford New Bridge, Selworthy, West Som	nerset	
DESIGNATION:	Scheduled Monument (No. 1006197)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bury Castle, an Iron Age defended settleme	nt, Selworthy, We	st Somerset
DESIGNATION:	Scheduled Monument (No. 1008808)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		et	
SITE NAME:	Staddon Hill camp, Winsford, West Somerse		
	Scheduled Monument (No. 1021359)	CONDITION:	Generally satisfactory but with minor localised problems
DESIGNATION:	Scheduled Monument (No. 1021359)	CONDITION:	but with minor localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1021359) Plant growth	CONDITION: TREND:	but with minor localised problems Stable
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1021359)	CONDITION:	but with minor localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1021359) Plant growth	CONDITION: TREND: CONTACT:	but with minor localised problems Stable Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1021359) Plant growth Private	CONDITION: TREND: CONTACT:	but with minor localised problems Stable Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1021359) Plant growth Private Brightworthy Barrows on Withypool Comm	CONDITION: TREND: CONTACT:	but with minor localised problems Stable Business Manager 0117 975 0700 A Hawkridge, West Somerset Generally unsatisfactory

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

182

MENDIP						
	SITE NAME:	Kilmersdon Lodges, Kilmersdon	Ammerdov of late C18	es, gate piers and gates, associated with vn House, 1788-94, and situated on the edge to early C19 park.The lodges were ruinous in the 1960s and their potential for reuse is		
	DESIGNATION:	Listed Building Grade II*, RPG II*	limited by t	heir size. A feasibility study has been undertaker		
	condition: Very bad			but the scale of the project indicated was prohibitive. Discussions have commenced with estate owners but		
	OCCUPANCY:			yet agreed.		
LA MARTIN	PRIORITY:	A (A)				
	OWNER TYPE:	Private	Contact: Jer	nny Chesher 0117 975 0686		
	SITE NAME:	Commercial Road, Shepton Mallet occupied at ground floor level, most of has been vacant for many years. A feasil		ow warehouses, built 1864. Whilst partly t ground floor level, most of the building acant for many years. A feasibility study has taken which has identified a substantial		
	DESIGNATION:	Listed Building Grade II*		on deficit. There has been a recent partial		
	CONDITION:	Poor		nich indicates that deterioration of the		
A start have been a feat	OCCUPANCY:	Part occupied	unused eler	ments is accelerating.		
	PRIORITY:	A (C)				
	OWNER TYPE:	Company	Contact: Jer	nny Chesher 0117 975 0686		
	SITE NAME:	Outbuilding about 30 metres west of Higher Southtown Farm, Southtown Lane, West Pennard	now part c lack of mair	imber-framed brewhouse, later cottage, alf shed/hay store. In poor condition due to ntenance and beneficial use for many years.		
	DESIGNATION:	Listed Building Grade II*		me and wattle and daub deteriorating. causing significant problems to building		
	CONDITION:	Poor	structure. A	condition survey has recently been		
A PARA	OCCUPANCY:	Vacant	commission	ned by Mendip District Council.		
	PRIORITY:	C (A)				
	PRIORITY: OWNER TYPE:	. ,	Contact: Jer	nny Chesher 0117 975 0686		
SITE NAME:	OWNER TYPE:	. ,		·		
	OWNER TYPE:	Private	ion, Chewton N	Mendip		
	OWNER TYPE:	Private		<b>Mendip</b> Generally satisfactory		
DESIGNATION:	OWNERTYPE: Round bar Scheduled	Private	ion, Chewton N	<b>Mendip</b> Generally satisfactory but with significant localised problems		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	OWNER TYPE:	Private	ion, Chewton N	<b>Mendip</b> Generally satisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	OWNERTYPE Round bar Scheduled Forestry Private	Private	ion, Chewton N Condition: TREND: CONTACT:	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	OWNER TYPE:       Round bar       Scheduled       Forestry       Private       Bowl barr	Private rrows south west of Cleeve's Plantat Monument (No. 1003027) ow 300m north east of Whitnell Co	ion, Chewton N Condition: TREND: CONTACT: rner, Emboroug	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	OWNER TYPE:       Round bar       Scheduled       Forestry       Private       Bowl barr	Private rrows south west of Cleeve's Plantat Monument (No. 1003027)	ion, Chewton N Condition: TREND: CONTACT:	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700 gh Extensive significant problems		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	OWNERTYPE       Round bar       Scheduled       Forestry       Private       Bowl barr       Scheduled	Private rrows south west of Cleeve's Plantat Monument (No. 1003027) ow 300m north east of Whitnell Co Monument (No. 1011670)	ion, Chewton N CONDITION: TREND: CONTACT: rner, Emboroug CONDITION:	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700 gh Extensive significant problems i.e. under plough, collapse		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	OWNER TYPE:       Round bar       Scheduled       Forestry       Private       Bowl barr	Private rrows south west of Cleeve's Plantat Monument (No. 1003027) ow 300m north east of Whitnell Co Monument (No. 1011670)	ion, Chewton N Condition: TREND: CONTACT: rner, Emboroug	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700 gh Extensive significant problems		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	OWNERTYPE Round bar Scheduled Forestry Private Bowl barr Scheduled Arable plo Private	Private rrows south west of Cleeve's Plantat Monument (No. 1003027) ow 300m north east of Whitnell Co Monument (No. 1011670)	ion, Chewton N CONDITION: TREND: CONTACT: rner, Emboroug CONDITION: TREND: CONTACT:	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700 gh Extensive significant problems i.e. under plough, collapse Declining		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	OWNERTYPE       Round bar       Scheduled       Forestry       Private       Bowl barr       Scheduled       Arable plo       Private       Drying ho	Private rrows south west of Cleeve's Plantat Monument (No. 1003027) ow 300m north east of Whitnell Co Monument (No. 1011670) Pughing	ion, Chewton N CONDITION: TREND: CONTACT: rner, Emboroug CONDITION: TREND: CONTACT:	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700 gh Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	OWNERTYPE         Round ban         Scheduled         Forestry         Private         Bowl barr         Scheduled         Arable plo         Private         Drying ho         Scheduled	Private prows south west of Cleeve's Plantat Monument (No. 1003027) ow 300m north east of Whitnell Co Monument (No. 1011670) pughing use at The Coach House, Willow Val Monument (No. 1016955)	ion, Chewton N CONDITION: TREND: CONTACT: rner, Emboroug CONDITION: TREND: CONDITION: e, Frome CONDITION:	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700 gh Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	OWNERTYPE         Round ban         Scheduled         Forestry         Private         Bowl barr         Scheduled         Arable plo         Private         Drying ho         Scheduled	Private rrows south west of Cleeve's Plantat Monument (No. 1003027) ow 300m north east of Whitnell Co Monument (No. 1011670) Pughing suge at The Coach House, Willow Val	ion, Chewton N CONDITION: TREND: CONTACT: rner, Emboroug CONDITION: TREND: CONDITION: e, Frome CONDITION: TREND:	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700 gh Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Declining		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	OWNER TYPE         Round bar         Scheduled         Forestry         Private         Bowl barr         Scheduled         Arable plo         Private         Drying ho         Scheduled         Deteriorate	Private prows south west of Cleeve's Plantat Monument (No. 1003027) ow 300m north east of Whitnell Co Monument (No. 1011670) pughing use at The Coach House, Willow Val Monument (No. 1016955)	ion, Chewton N CONDITION: TREND: CONTACT: rner, Emboroug CONDITION: TREND: CONDITION: e, Frome CONDITION:	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700 gh Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	OWNERTYPE         Round ban         Scheduled         Forestry         Private         Bowl barr         Scheduled         Arable plo         Private         Drying ho         Scheduled         Deteriorat         Private	Private prows south west of Cleeve's Plantat Monument (No. 1003027) ow 300m north east of Whitnell Co Monument (No. 1011670) pughing use at The Coach House, Willow Val Monument (No. 1016955)	ion, Chewton N CONDITION: TREND: CONTACT: rner, Emboroug CONDITION: TREND: CONDITION: e, Frome CONDITION: TREND:	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700 gh Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Declining		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: OWNER TYPE: OWNER TYPE:	OWNERTYPE         Round ban         Scheduled         Forestry         Private         Bowl barr         Scheduled         Arable plo         Private         Drying ho         Scheduled         Deteriorate         Glastonbu	Private rrows south west of Cleeve's Plantat Monument (No. 1003027) ow 300m north east of Whitnell Co Monument (No. 1011670) mughing use at The Coach House, Willow Val Monument (No. 1016955) tion – in need of management	ion, Chewton N CONDITION: TREND: CONTACT: rner, Emboroug CONDITION: TREND: CONDITION: e, Frome CONDITION: TREND:	Mendip Generally satisfactory but with significant localised problems Unknown Business Manager 0117 975 0700 gh Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Generally satisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME:	OWNERTYPE         Round bar         Scheduled         Forestry         Private         Bowl barr         Scheduled         Arable plo         Private         Drying ho         Scheduled         Deteriorat         Private         Glastonbu         Scheduled	Private rrows south west of Cleeve's Plantat Monument (No. 1003027) ow 300m north east of Whitnell Co Monument (No. 1011670) aughing use at The Coach House, Willow Val Monument (No. 1016955) tion – in need of management iry lake village, Godney	ion, Chewton N CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: e, Frome CONDITION: TREND: CONDITION:	Mendip         Generally satisfactory         but with significant localised problems         Unknown         Business Manager 0117 975 0700         gh         Extensive significant problems         i.e. under plough, collapse         Declining         Business Manager 0117 975 0700         Extensive significant problems         i.e. under plough, collapse         Declining         Business Manager 0117 975 0700		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / MENDIP

SITE NAME:	Vobster Breach colliery, 890m ENE of Twee	ed Farm, Leigh-on-	Mendip
DESIGNATION:	Scheduled Monument (No. 1014867)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Lake villages north west of Oxenpill, Meare	:	
DESIGNATION:	Scheduled Monument (No. 1006160)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Section of the Abbot's Way trackway, 500m	WSW of Honeyg	ar Farm, Meare
DESIGNATION:	Scheduled Monument (No. 1014432)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Sections of the Sweet Track and Post Track,	, 240m south west	t of Sunnyside Farm, Meare
DESIGNATION:	Scheduled Monument (No. 1014440)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Sections of the Sweet Track and Post Track,	, 250m ESE of Stat	tion House, Meare
DESIGNATION:	Scheduled Monument (No. 1014831)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Timber trackway site, 700m west of Honey	rgar Farm, Meare	
DESIGNATION:	Scheduled Monument (No. 1014434)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Fussell's Lower Works: an iron edge tool w	orks, 210m south	east of Wadbury, Mells
DESIGNATION:	Scheduled Monument (No. 1019796)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Whatley Combe Roman villa, Nunney		
designation:	Scheduled Monument (No. 1006188)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 180m south west of Yoxter Fa	ırm, Priddy	
DESIGNATION:	Scheduled Monument (No. 1011532)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / MENDIP

SITE NAME:	Bowl barrow 250m north east of King Dov	vn Farm, Priddy	
DESIGNATION:	Scheduled Monument (No. 1011530)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 260m east of Templedown Fa	rm, Priddy	
DESIGNATION:	Scheduled Monument (No. 1011534)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 300m south west of Moor Vie	ew, Priddy	
DESIGNATION:	Scheduled Monument (No. 1009773)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 70m north east of King Down	n Farm, Priddy	
DESIGNATION:	Scheduled Monument (No. 1011531)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 800m south of Townsend Far	m, Priddy	
Designation:	Scheduled Monument (No. 1009740)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Linear barrow cemetery comprising six boy	wl barrows 510m	south west of Townsend Farm, Priddy
DESIGNATION:	Scheduled Monument (No. 1009744)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	World War II bombing decoy complex, anti round barrow cemetery on Black Down, Pr		ons and Beacon Batch
DESIGNATION:	Scheduled Monument (No. 1020995)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 900m south west of Bristol P	lain Farm:	
	part of a group of round barrows south and		ristol Plain Farm, Rodney Stoke
DESIGNATION:	Scheduled Monument (No. 1008784)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

HERITAGE AT RISK 2011 / SOUTH WEST / MENDIP / SEDGEMOOR

	Romano-B	ritish settlement on Stoke Moor, Rodn	ney Stoke	
DESIGNATION:	Scheduled	Monument (No. 1011125)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	Declining
OWNER TYPE:	Private	-oo	CONTACT:	Business Manager 0117 975 0700
JITE NAME:	Hillfort on	Roddenbury Hill, Selwood		
DESIGNATION:	Scheduled	Monument (No. 1008804)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other		TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
DITE NAME:	Group of	round barrows 750m north west of Ivy	y Cottage, St	: Cuthbert Out
DESIGNATION:	Scheduled	Monument (No. 1020494)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	Declining
	Private	∽6' ''' '6		Business Manager 0117 975 0700
OWNER TYPE:	Frivale		CONTACT:	Dusiness Manager 0117 773 0700
ITE NAME:	Marston M	10at, Trudoxhill		
DESIGNATION:	Scheduled	Monument (No. 1016302)	CONDITION:	Generally unsatisfactory
		( · · · · · · · · · · · · · · · · · · ·		with major localised problems
PRINCIPAL VULNERABILITY:	Moderate	animal burrowing	TREND:	Declining
DWNER TYPE:	Private	0	CONTACT:	Business Manager 0117 975 0700
	CONDITION:	also 7 LBs Generally satisfactory but with significant localised problems	developme garden ranş maintenanc	n house as club-hotel. New build and ancillary nt including car park and conversion of kitche ges. However; encouraging signs of good ee e.g. cultivation of walled garden along avirations.
		Medium	traditional p	principies.
	TREND:	Medium Stable Mixed, multiple owners		m Auston 0117 975 0696
SEDGEMOOR	TREND:	Stable		
	TREND: OWNER TYPE: SITE NAME:	Stable Mixed, multiple owners Castle House, Queen Street, Bridgwater	Contact: Kir House in e Ackerman condition. ( English Her	m Auston 0117 975 0696 arly Tudor Revival style, built for William in 1851. The building is in a precarious Dwned by SAVE Building Preservation Trust. itage has grant-aided scaffolding and project
SEDGEMOOR	TREND: OWNER TYPE: SITE NAME:	Stable Mixed, multiple owners Castle House, Queen Street, Bridgwater Listed Building Grade II*, CA	Contact: Kir House in e Ackerman condition. ( English Her developme	m Auston 0117 975 0696 arly Tudor Revival style, built for William in 1851. The building is in a precarious Dwned by SAVE Building Preservation Trust. itage has grant-aided scaffolding and project nt work. Further discussions regarding grant
SEDGEMOOR	TREND: OWINER TYPE: SITE NAME: DESIGNATION: CONDITION:	Stable Mixed, multiple owners Castle House, Queen Street, Bridgwater Listed Building Grade II*, CA Very bad	Contact: Kin House in e Ackerman condition. ( English Her developme aid are und	m Auston 0117 975 0696 arly Tudor Revival style, built for William in 1851. The building is in a precarious Dwned by SAVE Building Preservation Trust. itage has grant-aided scaffolding and project
SEDGEMOOR	TREND: OWINER TYPE: SITE NAME: DESIGNATION:	Stable Mixed, multiple owners Castle House, Queen Street, Bridgwater Listed Building Grade II*, CA Very bad Vacant	Contact: Kin House in e Ackerman condition. ( English Her developme aid are und	m Auston 0117 975 0696 arly Tudor Revival style, built for William in 1851. The building is in a precarious Dwned by SAVE Building Preservation Trust. itage has grant-aided scaffolding and project nt work. Further discussions regarding grant lerway and a potential end use associated
SEDGEMOOR	TREND: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Stable Mixed, multiple owners Castle House, Queen Street, Bridgwater Listed Building Grade II*, CA Very bad Vacant A (A)	Contact: Kir House in e Ackerman condition. C English Her developme aid are und with Bridgw	m Auston 0117 975 0696 arly Tudor Revival style, built for William in 1851. The building is in a precarious Dwned by SAVE Building Preservation Trust. ritage has grant-aided scaffolding and project nt work. Further discussions regarding grant lerway and a potential end use associated vater Arts Centre.
SEDGEMOOR	TREND: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Stable Mixed, multiple owners Castle House, Queen Street, Bridgwater Listed Building Grade II*, CA Very bad Vacant A (A)	Contact: Kir House in e Ackerman condition. C English Her developme aid are und with Bridgw	m Auston 0117 975 0696 arly Tudor Revival style, built for William in 1851. The building is in a precarious Dwned by SAVE Building Preservation Trust. itage has grant-aided scaffolding and project nt work. Further discussions regarding grant lerway and a potential end use associated
SEDGEMOOR	TREND: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Stable Mixed, multiple owners Castle House, Queen Street, Bridgwater Listed Building Grade II*, CA Very bad Vacant A (A)	Contact: Kin House in e Ackerman condition. C English Her developme aid are und with Bridgy Contact: Ni A former p the Westor to be built	m Auston 0117 975 0696 arly Tudor Revival style, built for William in 1851. The building is in a precarious Dwned by SAVE Building Preservation Trust. ritage has grant-aided scaffolding and project nt work. Further discussions regarding grant lerway and a potential end use associated vater Arts Centre. icola Lauder 0117 975 0674 pumping station (early C19) now preserved by rzoyland Engine Trust. The first pumping statio to lift floodwater from the Somerset Levels a
SEDGEMOOR	TREND: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Stable Mixed, multiple owners Castle House, Queen Street, Bridgwater Listed Building Grade II*, CA Very bad Vacant A (A) Trust Westonzoyland Pumping Station,	Contact: Kin House in e Ackerman condition. C English Her developme aid are und with Bridgv Contact: N A former p the Westor to be built moors, and	m Auston 0117 975 0696 arly Tudor Revival style, built for William in 1851. The building is in a precarious Dwned by SAVE Building Preservation Trust. ritage has grant-aided scaffolding and project nt work. Further discussions regarding grant lerway and a potential end use associated vater Arts Centre. icola Lauder 0117 975 0674 pumping station (early C19) now preserved by rzoyland Engine Trust. The first pumping statio to lift floodwater from the Somerset Levels a the only one to survive with the steam engin
SEDGEMOOR	TREND: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Stable Mixed, multiple owners Castle House, Queen Street, Bridgwater Listed Building Grade II*, CA Very bad Vacant A (A) Trust Westonzoyland Pumping Station, Westonzoyland	Contact: Kin House in e Ackerman condition. C English Her developme aid are und with Bridgw Contact: Ni A former p the Westor to be built moors, and still working	m Auston 0117 975 0696 arly Tudor Revival style, built for William in 1851. The building is in a precarious Dwned by SAVE Building Preservation Trust. ritage has grant-aided scaffolding and project nt work. Further discussions regarding grant lerway and a potential end use associated vater Arts Centre. icola Lauder 0117 975 0674 pumping station (early C19) now preserved by rzoyland Engine Trust. The first pumping statio to lift floodwater from the Somerset Levels a
SEDGEMOOR	TREND: OWNERTYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION:	Stable Mixed, multiple owners Castle House, Queen Street, Bridgwater Listed Building Grade II*, CA Very bad Vacant A (A) Trust Westonzoyland Pumping Station, Westonzoyland Listed Building Grade II* Poor	Contact: Kin House in e Ackerman condition. C English Her developme aid are und with Bridgw Contact: Ni A former p the Westor to be built moors, and still working	m Auston 0117 975 0696 arly Tudor Revival style, built for William in 1851. The building is in a precarious Dwned by SAVE Building Preservation Trust. ritage has grant-aided scaffolding and project nt work. Further discussions regarding grant lerway and a potential end use associated vater Arts Centre. icola Lauder 0117 975 0674 pumping station (early C19) now preserved b to lift floodwater from the Somerset Levels a the only one to survive with the steam enging and the buildings intact. Much work has bee
SEDGEMOOR	TREND: OWNERTYPE SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME: SITE NAME: CONDITION:	Stable Mixed, multiple owners Castle House, Queen Street, Bridgwater Listed Building Grade II*, CA Very bad Vacant A (A) Trust Westonzoyland Pumping Station, Westonzoyland Listed Building Grade II* Poor	Contact: Kin House in e Ackerman condition. C English Her developme aid are und with Bridgw Contact: Ni A former p the Westor to be built moors, and still working	m Auston 0117 975 0696 arly Tudor Revival style, built for William in 1851. The building is in a precarious Dwned by SAVE Building Preservation Trust. ritage has grant-aided scaffolding and project nt work. Further discussions regarding grant lerway and a potential end use associated vater Arts Centre. icola Lauder 0117 975 0674 pumping station (early C19) now preserved b to lift floodwater from the Somerset Levels a the only one to survive with the steam enging and the buildings intact. Much work has bee

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / SEDGEMOOR

DEGLONIATION			thbrook Farm, Ashcott
DESIGNATION:	Scheduled Monument (No. 1014444)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Chandos Glass Cone, at the junction of Nort	hgate and Valett	a Place, Bridgwater
DESIGNATION:	Scheduled Monument (No. 1019899)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Horsey medieval settlement immediately nor	th of Board's Fa	rm, Bridgwater Without
DESIGNATION:	Scheduled Monument (No. 1020438)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Timber trackways 850m east of Catcott Burt	le Farm, Burtle	
DESIGNATION:	Scheduled Monument (No. 1014433)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			5
5ITE NAME:	World War II anti-aircraft rocket battery and 265m north east of Ashridge Farm, Cheddar	bombing decoy	control building
DESIGNATION:	Scheduled Monument (No. 1020994)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
PRINCIPAL VULNERABILITY: OWNER TYPE:	Permitted development Private	TREND: CONTACT:	Declining Business Manager 0117 975 0700
OWNER TYPE:		CONTACT:	Business Manager 0117 975 0700
OWNER TYPE: SITE NAME:	Private	CONTACT:	Business Manager 0117 975 0700
DWNER TYPE: SITE NAME: DESIGNATION:	Private Bronze Age and Iron Age timber trackways, 7	contact: 00m north west	Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Bronze Age and Iron Age timber trackways, 7 Scheduled Monument (No. 1014431)	CONTACT: 00m north west CONDITION:	Business Manager 0117 975 0700 c of Coppice Gate Farm, Shapwick Unknown
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Bronze Age and Iron Age timber trackways, 7 Scheduled Monument (No. 1014431) Drainage/dewatering Private Sections of the Sweet Track, the Post Track ar	CONTACT: 00m north west CONDITION: TREND: CONTACT: ad associated re	Business Manager 0117 975 0700 c of Coppice Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private Bronze Age and Iron Age timber trackways, 7 Scheduled Monument (No. 1014431) Drainage/dewatering Private Sections of the Sweet Track, the Post Track ar 500m north east of Moorgate Farm, Shapwick	CONTACT: 00m north west CONDITION: TREND: CONTACT: ad associated re	Business Manager 0117 975 0700 c of Coppice Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700 mains
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private Bronze Age and Iron Age timber trackways, 7 Scheduled Monument (No. 1014431) Drainage/dewatering Private Sections of the Sweet Track, the Post Track ar	CONTACT: 00m north west CONDITION: TREND: CONTACT: ad associated re	Business Manager 0117 975 0700 c of Coppice Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700 mains Generally satisfactory
OWNER TYPE: SITE NAME: DESIGNATION: OWNER TYPE: SITE NAME: DESIGNATION: DESIGNATION:	Private Bronze Age and Iron Age timber trackways, 70 Scheduled Monument (No. 1014431) Drainage/dewatering Private Sections of the Sweet Track, the Post Track ar 500m north east of Moorgate Farm, Shapwick Scheduled Monument (No. 1014438)	CONTACT: 00m north west CONDITION: TREND: CONTACT: ad associated re	Business Manager 0117 975 0700 c of Coppice Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700 mains
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Bronze Age and Iron Age timber trackways, 7 Scheduled Monument (No. 1014431) Drainage/dewatering Private Sections of the Sweet Track, the Post Track ar 500m north east of Moorgate Farm, Shapwick	CONTACT: 00m north west CONDITION: TREND: CONTACT: ad associated re CONDITION:	Business Manager 0117 975 0700 c of Coppice Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700 mains Generally satisfactory but with minor localised problems
OWNER TYPE:	Private Bronze Age and Iron Age timber trackways, 74 Scheduled Monument (No. 1014431) Drainage/dewatering Private Sections of the Sweet Track, the Post Track ar 500m north east of Moorgate Farm, Shapwick Scheduled Monument (No. 1014438) Drainage/dewatering	CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 c of Coppice Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700 mains Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  SITE NAME:	Private Bronze Age and Iron Age timber trackways, 74 Scheduled Monument (No. 1014431) Drainage/dewatering Private Sections of the Sweet Track, the Post Track ar 500m north east of Moorgate Farm, Shapwick Scheduled Monument (No. 1014438) Drainage/dewatering Private	CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 c of Coppice Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700 mains Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:	Private Bronze Age and Iron Age timber trackways, 7 Scheduled Monument (No. 1014431) Drainage/dewatering Private Sections of the Sweet Track, the Post Track ar 500m north east of Moorgate Farm, Shapwick Scheduled Monument (No. 1014438) Drainage/dewatering Private Prehistoric timber trackways, 670m SSE of Pa Scheduled Monument (No. 1014430)	CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT:	Business Manager 0117 975 0700 c of Coppice Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700 mains Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 awell
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Bronze Age and Iron Age timber trackways, 70 Scheduled Monument (No. 1014431) Drainage/dewatering Private Sections of the Sweet Track, the Post Track ar 500m north east of Moorgate Farm, Shapwick Scheduled Monument (No. 1014438) Drainage/dewatering Private Prehistoric timber trackways, 670m SSE of Pa	CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: CONTACT:	Business Manager 0117 975 0700 Coppice Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700 Commains Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Commains Commai
OWNER TYPE:	Private Bronze Age and Iron Age timber trackways, 74 Scheduled Monument (No. 1014431) Drainage/dewatering Private Sections of the Sweet Track, the Post Track ar 500m north east of Moorgate Farm, Shapwick Scheduled Monument (No. 1014438) Drainage/dewatering Private Prehistoric timber trackways, 670m SSE of Pa Scheduled Monument (No. 1014430) Drainage/dewatering	CONTACT: CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONTACT: TREND: CONTACT:	Business Manager 0117 975 0700  Complete Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700  mains Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700  awell Unknown Unknown Unknown
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Bronze Age and Iron Age timber trackways, 74 Scheduled Monument (No. 1014431) Drainage/dewatering Private Sections of the Sweet Track, the Post Track ar 500m north east of Moorgate Farm, Shapwick Scheduled Monument (No. 1014438) Drainage/dewatering Private Prehistoric timber trackways, 670m SSE of Pa Scheduled Monument (No. 1014430) Drainage/dewatering	CONTACT: CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONTACT: TREND: CONTACT:	Business Manager 0117 975 0700  Complete Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700  mains Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700  awell Unknown Unknown Unknown
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private         Bronze Age and Iron Age timber trackways, 70         Scheduled Monument (No. 1014431)         Drainage/dewatering         Private         Sections of the Sweet Track, the Post Track ar 500m north east of Moorgate Farm, Shapwick         Scheduled Monument (No. 1014438)         Drainage/dewatering         Private         Prehistoric timber trackways, 670m SSE of Pa         Scheduled Monument (No. 1014430)         Drainage/dewatering         Government or Agency         Alstone lake settlement site, West Huntspill         Scheduled Monument (No. 1012311)	CONTACT: CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONTACT: TREND: CONTACT:	Business Manager 0117 975 0700 Complete Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700 mains Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 awell Unknown Business Manager 0117 975 0700 Unknown Business Manager 0117 975 0700 Unknown
	Private         Bronze Age and Iron Age timber trackways, 70         Scheduled Monument (No. 1014431)         Drainage/dewatering         Private         Sections of the Sweet Track, the Post Track ar         500m north east of Moorgate Farm, Shapwick         Scheduled Monument (No. 1014438)         Drainage/dewatering         Private         Prehistoric timber trackways, 670m SSE of Pa         Scheduled Monument (No. 1014430)         Drainage/dewatering         Government or Agency         Alstone lake settlement site, West Huntspill	CONTACT: CONDITION: TREND: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION: CONDITION:	Business Manager 0117 975 0700 Complete Gate Farm, Shapwick Unknown Unknown Business Manager 0117 975 0700 Commains Generally satisfactory but with minor localised problems Declining Business Manager 0117 975 0700 Commains Commandation Com

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event the near the intermediate

C Slow decay; no solution agreed.

Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

OTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

187

#### HERITAGE AT RISK 2011 / SOUTH WEST / SEDGEMOOR / SOUTH SOMERSET

HERITAGE AT RISK 2011 / SOUT	"H WEST / <b>SE</b> I	DGEMOOR / SOUTH SOMERSET			
	SITE NAME:	Halswell Park, Goathurst	An C18 landscape park. Local preservation trusts have instigated the restoration and maintenance of two important garden buildings. Other structures are		
	DESIGNATION:	Registered Park and Garden Grade II, also 17 LBs	still at risk. The main house is a commercial venue. The majority of the park is under intensive cultivation.		
	CONDITION	Extensive significant problems	The centrepiece of the design, Mill Wood, is largely		
	VULNERABILITY		denuded of trees and the structures within it are in a very poor state of repair.		
	TREND:	Stable			
The state of the	OWNER TYPE:	Mixed, multiple owners	Contact: Kim Auston 0117 975 0696		
SOUTH SOMERSET					
SOUTH SOMEKSET					
	SITE NAME:	The Grotto at Jordans, NGR ST 3388 1601, Ashill	Early C19 grotto within a designed landscape whose principle house was demolished in the mid C20.The building has been subject to vandalism and although now rethatched, elements are still in need		
	DESIGNATION:	Listed Building Grade II*	of repair.		
	CONDITION:	Poor			
Same March	OCCUPANCY:	N/A			
	PRIORITY:	C (C)			
	OWNER TYPE:	Private	Contact: Jenny Chesher 0117 975 0686		
	SITE NAME:	Cosenes monument, Church of All Saints, Church Street, Castle Cary	Late CI6 monument. Rusting iron cramps have caused serious damage and threaten further loss of stone.		
A REAL PROPERTY OF THE	DESIGNATION:				
A ME	CONDITION:	Very bad			
AT SIT	OCCUPANCY:	N/A			
	PRIORITY:	A (A)			
	OWNER TYPE:	Religious organisation	Contact: Chris Miners 0117 975 0700		
	SITE NAME:	Top mill building, Higher Flax Mills,Torbay Road, Castle Cary	This mid C19 former mill has been empty for several years. The building has now been sold and an application for conversion to one live/work unit has now been approved.		
and the second	DESIGNATION:				
	CONDITION:	Poor			
	OCCUPANCY:	Vacant			
	PRIORITY:	D (B)			
	OWNER TYPE:	Private	Contact: Jenny Chesher 0117 975 0686		
	SITE NAME:	Waterloo House and Manor Court House, 7A, 7B, 9, 11, 13 and 13A Fore Street, Chard, Chard Town	Late CI6/early CI7 group of shops/offices, houses and flats with two prominent projecting two and three storey porches. Partly occupied with consent for conversion to		
	DESIGNATION:	Listed Building Grade I	part of building granted but not yet implemented. A recent planning appeal refused subdivision to smaller units and		
	CONDITION:	Poor	pre-application discussions on a revised scheme are		
	OCCUPANCY:	Part occupied	currently underway.		
	PRIORITY:	C (C)			
	OWNER TYPE:	Company	Contact: Jenny Chesher 0117 975 0686		
	SITE NAME:	Madey Mill, East Street, Martock	Water mill with medieval origins, although current buildings are largely C17. The building is situated on a working farm, is under-used and is suffering from		
	DESIGNATION:	Listed Building Grade II*	lack of maintenance.Viable new uses and/or funding opportunities need to be investigated to obtain adequate		
ALT THE AL	CONDITION:	Poor	funding for repairs. English Heritage funded condition		
	OCCUPANCY:	Part occupied	survey has been completed, identifying urgent repairs.		
M III AN AN	PRIORITY:	C (C)			
	OWNER TYPE:	Private	Contact: Jenny Chesher 0117 975 0686		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Concentration
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### HERITAGE AT RISK 2011 / SOUTH WEST / SOUTH SOMERSET

	SITE NAME:	Prankerd chest tomb in churchyard 7m south east of south door, St John the Evangelist, Bathwell Lane, Milborne Port	causing sti further da	chest tomb. Subsidence at the northern end is ructural instability. Rusting iron cramps threaten mage. Surface deterioration of the south panel further loss of the inscription.
PONINDS TO BE AND REMAIN	DESIGNATION:	Listed Building Grade II*, CA		
IEN ROBERT HOMAS JOHN AN	CONDITION:	Poor		
The second second second	OCCUPANCY:	N/A		
A straight of the straight of	PRIORITY:	B (B)		
Contraction of the N	OWNER TYPE:	Religious organisation	Contact: (	Chris Miners 0117 975 0700
	SITE NAME:	Secular college at Parsonage Farm Stoke Sub Hamdon	and CI6 f	to this chantry college is a group of medieval arm buildings most of which are in poor and unroofed.
	DESIGNATION:	Listed Building Grade II, SM, CA		
A PROPERTY A	CONDITION:	Poor		
The second second second	OCCUPANCY:	Vacant		
	PRIORITY:	С (С)		
	OWNER TYPE:	Charity	Contact: F	Rob Iles 0117 975 0662
	SITE NAME:	Two monuments in churchyard, approx 6 and 8 metres S of S transept, St Mary the Virgin, East Stoke, Stoke Sub Hamdon	damp thre	monument. Subsidence has resulted in rising eatening the inscriptions, through increased Ilisation in the ledger slabs.
A Part of the second second	DESIGNATION:	Listed Building Grade II*, CA		
and and the second	CONDITION:	Poor		
A Contraction of the second	OCCUPANCY:	N/A		
	PRIORITY:	A (A)		
	OWNER TYPE:	Religious organisation	Contact: (	Chris Miners 0117 975 0700
	SITE NAME:	The former Ropewalk, 75 metres north east of Millbrook House, High Street, West Coker	with C20 purchase	vine works, now store and workshop. Late C19, alterations and extensions. Following compulsory of the site by the District Council a lease was the building by the Industrial Building Preservation
9	DESIGNATION:	Listed Building Grade II*	Trust. A gi	rant has been given by English Heritage for urgent
AMERICAN STRATE	CONDITION:	Very bad	repairs wh	nich have been undertaken and supporting
	OCCUPANCY:	Vacant	scaffolding	has been erected.
A CONTRACTOR OF A CONTRACTOR A	PRIORITY:	E (A)		
a sector of the sec	OWNER TYPE:	Trust	Contact: N	Nicola Lauder 0117 975 0674
	SITE NAME:	St Peter and St Paul, Church Street, Wincanton	concerts a medieval and 1887-	n centre church, well used for worship, occasional and events. The tower is all that remains from a church. Major enlargement and rebuilding in 1735 89. English Heritage grant-aided lead work to SE in recent past. All other lead roofs are showing
	DESIGNATION:	Listed Place of Worship Grade II*, CA	signs of ag	ge and there will need to be a rolling repair
	CONDITION:	Poor	programm	he to these. A grant was offered 2010 for
The second in	PRIORITY:	B (New entry)	works to	northern nave.
	OWNER TYPE:	Religious organisation	Contact: N	Nicola Lauder 0117 975 0674
and the second se		0 0		
SITE NAME:	Roman ho	use south of Fair View House, Curry R	livel	
DESIGNATION:	Scheduled	Monument (No. 1006185)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Roman vill	a north of Dunnock's Lane, East Coke	r	
DESIGNATION:	Scheduled	Monument (No. 1003029)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Developm	ent requiring planning permission	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
PRIORITY (FOR BUILDINGS)         A         Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.         B         Immediate risk of further rapid deterioration or loss of fabric; solution	but not ye E Under rep repair; but	r, solution agreed t implemented. air or in fair to good no user identified; or at of varancy with no	d; has uildings regi	ABBREVIATIONS TE: CA Conservation Area LB/LBs Listed Building/s changed since the 2010 LPA Local Planning Authority ster, the previous category wen in brackets. RPG Registered Park and Garden

agreed but not yet implemented. C Slow decay; no solution agreed.

under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

yet implemented.

SM/SMs Scheduled Monument/s UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2011 / SOUTH WEST / SOUTH SOMERSET

SITE NAME:	Low Ham Roman villa, High Ham	
DESIGNATION:	Scheduled Monument (No. 1006192)	CONDITION: Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Business Manager 0117 975 0700
SITE NAME:	Pill Bridge, Ilchester	
DESIGNATION:	Scheduled Monument (No. 1006214)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND: Declining
OWNER TYPE:	Local Authority	CONTACT: Business Manager 0117 975 0700
SITE NAME:	Roman villa north of Stowey Hill, Pitney	
DESIGNATION:	Scheduled Monument (No. 1006183)	CONDITION: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Business Manager 0117 975 0700
SITE NAME:	Melbury Roman villa, Somerton	
DESIGNATION:	Scheduled Monument (No. 1002954)	CONDITION: Extensive significant problems
		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable clipping	TREND: Declining
OWNER TYPE:	Private	CONTACT: Business Manager 0117 975 0700
SITE NAME:	Large multivallate hillfort and associated earthwo	orks at South Cadbury, South Cadbury
DESIGNATION:	Scheduled Monument (No. 1011980)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND: Stable
OWNER TYPE:	Private	CONTACT: Business Manager 0117 975 0700
SITE NAME:	Chessels Roman villa, West Coker	
DESIGNATION:	Scheduled Monument (No. 1006186)	сонытом: Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Business Manager 0117 975 0700
	SITE NAME: Redlynch Park, Bruton DESIGNATION: Registered Park and Garden Grade II,	Formerly the principal seat of the earls of Ilchester, Redlynch is a large landscape park near Wincanton. The main house has gone and the stables and ancilla buildings are now in multiple ownership. The majority of the parkland planting has disappeared, boundary
	also 9 LBs	walls and estate railings are in a poor state and there
	CONDITION: Extensive significant problems	are ongoing development pressures. A surviving gatel
Manage Marine Billing	VULNERABILITY: MEDIUM TREND: Stable	is a building at risk.
Carl and	OWNER TYPE: Private, multiple owners	Contact: Kim Auston 0117 975 0696
A DESTRUCTION	SITE NAME: Cricket House, Cricket St Thomas	C18 landscape park and pleasure grounds surroundir
	DESIGNATION: Registered Park and Garden Grade II*, also 8 LBs	listed mansion, partly by Soane. Pressure for develop from large hotel and farm diversification. However, pa of the park are being restored through Natural Engla
	CONDITION: Generally satisfactory but with significant localised problems	Environmental Stewardship scheme.
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	VULNERABILITY: Medium	
The state	TREND: Stable	
AN AN	OWNER TYPE: Mixed, multiple owners	Contact: Kim Auston 0117 975 0696
RIORITY (FOR BUILDINGS)	D Slow deeps rolition served	ABBREVIATIONS ss NOTE: CA Conservation Area
deterioration or loss of fabric; no solution agreed.	D Slow decay; solution agreed but not yet implemented. F Repair scheme in program and (where applicable) end use or user identific	If the priority category LB/LBs Listed Building/s

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

If the priority category has changed since the 2010 register, the previous category is given in brackets.

Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site LB/LBs LPA NP RPG SM/SMs UA WHS

### HERITAGE AT RISK 2011 / SOUTH WEST / SOUTH SOMERSET / TAUNTON DEANE

	SITE NAME: Hazlegrove House, Queen Camel		ape park with formal garden in front of house.		
	DESIGNATION: Registered Park and Garden Grade II also 3 LBs	a range of school facilities. Sports pitches encroachir			
	CONDITION: Generally satisfactory but with minor localised problems	parkland. Pa	parkland. Park bisected by main road in 1980s, severing lodge and drive.		
	VULNERABILITY: Medium				
	TREND: Stable				
	OWNER TYPE: Mixed, multiple owners	Contact: Kim Auston 0117 975 0696			
SITE NAME:	Donyatt				
DESIGNATION:	Conservation Area	CONDITION:	Very bad		
VULNERABILITY:	Medium	TREND:	No significant change		
CONTACT:	Adron Duckworth (LPA) 01935 462595	NEW ENTRY?:	No		
SITE NAME:	Henstridge				
DESIGNATION:	Conservation Area	CONDITION:	Very bad		
VULNERABILITY:	Medium	TREND:	No significant change		
CONTACT:	Adron Duckworth (LPA) 01935 462595	NEW ENTRY?:	No		
site name:	llchester				
DESIGNATION:	Conservation Area	CONDITION:	Very bad		
VULNERABILITY:	Medium	TREND:	No significant change		
CONTACT:	Adron Duckworth (LPA) 01935 462595	NEW ENTRY?:	No		
SITE NAME:	Misterton				
			D		
DESIGNATION:	Conservation Area	CONDITION:	Poor		
DESIGNATION: VULNERABILITY:	Conservation Area Medium	CONDITION: TREND:	Poor Deteriorating		


CONTACT:

### TAUNTON DEANE

A REAL PROPERTY OF	CONDITION: OCCUPANCY: PRIORITY:	Sandhill Park, Bishops Lydeard Listed Building Grade II* Fair Vacant D (D) Private	Country house, circa 1720. Later used as a hospital, now unoccupied. A new use is required for the house and associated outbuildings. A revised application for conversion of the house to apartments and the construction of enabling development in its grounds has now been approved subject to a Section 106 agreement. Discussions are underway with a prospective purchaser about amendments to that scheme. Contact: Jenny Chesher 0117 975 0686
	SITE NAME:	Gatehouse at Cothelstone Manor, Cothelstone	A mid C16 gatehouse. Part of a much larger estate. Urgent holding repairs undertaken. Consent has been granted for use as holiday let with associated repairs



		_
SITE NAME:	Gatehouse at Cothelstone Manor, Cothelstone	A mid C16 gatehouse. Part of a much larger estate. Urgent holding repairs undertaken. Consent has been granted for use as holiday let with associated repairs, but this has not yet been implemented. A meeting has
DESIGNATIO	N: Listed Building Grade I, CA, RPG II	been held with the owners to explore the potential
CONDITION	Poor	for grant aid.
OCCUPANC	n N/A	
PRIORITY:	D (D)	
OWNER TYPE	Private	Contact: Jenny Chesher 0117 975 0686



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Adron Duckworth (LPA) 01935 462595

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

No

NEW ENTRY?:

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2011 / SOUTH WEST / TAUNTON DEANE

	SITE NAME:	Cloth finishing works at Tone Mills, north range, Langford Budville	finishing wo c1920. An a	pplete example of a C19 cloth dyeing and orks which developed between c1830 and application for new development is being up dialog graces upple site with the intertion	
	DESIGNATION:	Listed Building Grade II*	of facilitation	or adjoining grease works site with the intention g the transfer of ownership to a dedicated	
	CONDITION:	Poor	building pre	eservation trust. The Trust is in discussion with	
	OCCUPANCY:	N/A	funding boo	lies including the Heritage Lottery Fund.	
	PRIORITY:	A (A)			
	OWNER TYPE:	Private	Contact: Jer	nny Chesher 0117 975 0686	
	site name:	Castle House, The Castle, Castle Green, Taunton	C17 house, within castle courtyard but in separate occupation, incorporating medieval fabric. Its forme use as workshop and administrative building for the museum has ceased and it is now vacant. The build		
	DESIGNATION:	Listed Building Grade I, SM, CA	has been leased by Somerset Building Preservation Trus		
	CONDITION:	Poor	who are pr	eparing a scheme for its reuse for educational	
	OCCUPANCY:			let purposes and are making funding The castle is not at risk.	
	PRIORITY:	C (New entry)			
	OWNER TYPE:	Trust	Contact: Jer	nny Chesher 0117 975 0686	
	SITE NAME:	Tonedale Mills (west complex), Wellington	textile facto Consent gra	omplex of an integrated multi-component wool ory, now in partial use as small industrial estate. anted for mixed use redevelopment of the order batted on site in 2008 and owners wort	
CALL CA	DESIGNATION:	Listed Building Grade II*	complex. Works halted on site in 2008 and owner into receivership leaving some buildings in a very		
	CONDITION:	Poor	condition. S	ite has now been sold and discussions are	
I m Russer	OCCUPANCY:	Part occupied	underway v	vith new owners.	
A POULENEE E	PRIORITY:	A (A)			
	OWNER TYPE:	Private	Contact: Jer	nny Chesher 0117 975 0686	
SITE NAME:	Two cross	es in St Mary's churchyard, Bishop's L	ydeard		
DESIGNATION:	Scheduled	Monument (No. 1016708)	CONDITION:	Generally unsatisfactory	
				with major localised problems	
PRINCIPAL VULNERABILITY:	Deteriorat	ion – in need of management	TREND:	Declining	
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700	
SITE NAME:		os of World War II pillboxes in the no the former airfield of RAF Culmheac			
DESIGNATION:	Scheduled	Monument (No. 1019846)	CONDITION:	Generally satisfactory	
				but with significant localised problems	
PRINCIPAL VULNERABILITY:	Deteriorat	ion – in need of management	TREND:	Declining	
OWNER TYPE:	Private	, i i i i i i i i i i i i i i i i i i i	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:		d War II air traffic control buildings, 6 mer airfield of RAF Culmhead, Trickey			
DESIGNATION:	Scheduled	Monument (No. 1019845)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Deteriorat	ion – in need of management	TREND:	Declining	
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700	
SITE NAME:		r II fighter pens and other airfield rer field of RAF Culmhead, at Trickey Wa			
DESIGNATION:		Monument (No. 1020492)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Deteriorat	ion – in need of management	TREND:	Declining	
				Business Manager 0117 975 0700	
OWNER TYPE:	Private		CONTACT:	DUSINESS Manager UT 17 773 UTUU	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2011 / SOUTH WEST / TAUNTON DEANE / WEST SOMERSET

SITE NAME:	Norton Camp large univallate hillfort, Norton Fitzwarren				
DESIGNATION:	Scheduled Monument (No. 1008467)	CONDITION:	Extensive significant problems		
			i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable		
OWNER TYPE:	Private con		Business Manager 0117 975 0700		
SITE NAME:	Camp south of Manor Farm, Wiveliscombe				
SITE NAME: DESIGNATION:	<b>Camp south of Manor Farm, Wiveliscombe</b> Scheduled Monument (No. 1006167)	CONDITION:	Extensive significant problems		
	•	CONDITION:	Extensive significant problems i.e. under plough, collapse		
	•	CONDITION: TREND:	<b>C</b> .		

### WEST SOMERSET

	SITE NAME: Remains of Chantry at Kilve, Sea Lane, Kilve DESIGNATION: Listed Building Grade II*, SM CONDITION: Very bad OCCUPANCY: N/A	Sea Lane, Kilve       to be the remains of collegiate dwelling of An English Heritage survey has shown the part of an important manorial complex. funded emergency repairs were underta more works to be undertaken 2011. Dis its future are continuing.	
<b>利用用的</b>	PRIORITY: A (A)		
	owner type: Private	Contact: N	icola Lauder 0117 975 0674
SITE NAME:	Carnarvon New Pit iron mine and section 300m south west of Heather House, Brom		trackbed,
DESIGNATION:	Scheduled Monument (No. 1021352)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Clatworthy hillfort, Clatworthy		
DESIGNATION:	Scheduled Monument (No. 1006149)	CONDITION:	Generally satisfactory
	``````````````````````````````````````		but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Four cairns on Hurley Beacon, Crowcomb	e	
DESIGNATION:	Scheduled Monument (No. 1017218)	CONDITION:	Generally satisfactory
	× ,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Entrenchment on Heydon Hill, Huish Chan	npflower	
DESIGNATION:	Scheduled Monument (No. 1006173)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	1 0 0		J

CONTACT:	Business Manager 0117 975 0700
----------	--------------------------------

SITE NAME: Four medieval fish weirs 500m east of the Harbour, Minehead					
DESIGNATION:	Scheduled Monument (No. 1020017)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		

#### PRIORITY (FOR BUILDINGS)

OWNER TYPE:

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the solution of the solution

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Private

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Malmsmea	d Bridge, Oare		
DESIGNATION:	Scheduled	Monument (No. 1006229)	CONDITION:	Generally unsatisfactory
				with major localised problems
PRINCIPAL VULNERABILITY:	Extensive \	ehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Local Auth	ority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stringston	churchyard cross, Stringston		
DESIGNATION:	Scheduled	Monument (No. 1006171)	CONDITION:	Generally satisfactory
				but with significant localised problems
RINCIPAL VULNERABILITY:	Deteriorat Private	on – in need of management	TREND:	Declining
DWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
	SITE NAME:	St Audries (House), West Quantoxhead	C19 gardens	and pleasure grounds, surrounding a C19
	DESIGNATION:	Registered Park and Garden Grade II, also 16 LBs	mid CI8 and	ether with parkland developed from the d improved in the mid C19. St Audries has sion of institutional uses and derelict former
	CONDITION:	Generally unsatisfactory	school buildi	ngs remain in the walled garden.The parkland
		with major localised problems	is mostly cult Currently St	tivated and few parkland trees survive. Audries house and gardens are used as
	VULNERABILITY:	Medium	a wedding ve	
	TREND:	Stable		
	OWNER TYPE:	Mixed, multiple owners	Contact: Kim	Auston 0117 975 0696
SOUTH GLOUCESTER	RSHIRE (L	JA)		
A.	SITE NAME:	Monument to Lord Robert Edward Somerset, Hawkesbury	Vulliamy date cast iron balo	ng stone tower ashlar monument by Lewis ed 1846. Repairs needed at high-level to cony and stonework. The council has been with the owners to source repairs to
E.	DESIGNATION:	Listed Building Grade II*, CA	in discussions with the owners to secure repairs to the monument.	
4	CONDITION:	Poor		
	OCCUPANCY:	N/A		
A. I	PRIORITY:	C (C)		
	OWNER TYPE:	Private	Contact: Sara	ah Ball 0117 975 0666
	SITE NAME:	Ragged Castle or Keeper's Lodge, Badminton Park, Hawkesbury	Folly Castle. Set on motte at end of a main drive fro Badminton House. Circa 1750 by Thomas Wright of Durham. Largely hidden by trees. Shell of structure i	
A ST A BRACK	DESIGNATION:	Listed Building Grade II*, RPG I		on. Interior has been lost. The council is in it is the owners regarding the repair and
	CONDITION:	Poor	stabilisation of	of the walls. There has been clearance of
	OCCUPANCY:	Vacant	vegetation o	n and around the structure.
	PRIORITY:	C (C)		
	OWNER TYPE:	Private	Contact: Just	in Ayton 0117 975 0687
	SITE NAME:	Whitfields Tabernacle, Park Road, Kingswood	redundant fo in an even m	hapel, built in 1741. The building has been or many years and a fire has placed the buildin ore vulnerable position. The owners have
		Park Road, Kingswood	redundant for in an even m recently with	or many years and a fire has placed the buildin nore vulnerable position. The owners have ndrawn their application for redevelopment
		Park Road,	redundant for in an even m recently with	or many years and a fire has placed the buildin nore vulnerable position. The owners have
	DESIGNATION:	Park Road, Kingswood Listed Building Grade I, CA Very bad	redundant for in an even m recently with	or many years and a fire has placed the buildin nore vulnerable position. The owners have ndrawn their application for redevelopment
	DESIGNATION: CONDITION:	Park Road, Kingswood Listed Building Grade I, CA Very bad	redundant for in an even m recently with	or many years and a fire has placed the buildin nore vulnerable position. The owners have ndrawn their application for redevelopment
	DESIGNATION: CONDITION: OCCUPANCY:	Park Road, Kingswood Listed Building Grade I, CA Very bad Vacant A (A)	redundant fc in an even m recently with of the site an	or many years and a fire has placed the buildin nore vulnerable position. The owners have ndrawn their application for redevelopment
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Park Road, Kingswood Listed Building Grade I, CA Very bad Vacant A (A)	redundant fc in an even m recently with of the site an Contact: Just A former CI of C18 collie commissione	or many years and a fire has placed the buildin hore vulnerable position. The owners have adrawn their application for redevelopment ad revised schemes are under discussion. in Ayton 0117 975 0687 9 steam-powered colliery built on the site ery. The Avon Industrial Buildings Trust have ed an historical study of the site to inform
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Park Road, Kingswood Listed Building Grade I, CA Very bad Vacant A (A) Private Brandy Bottom Colliery,	redundant fc in an even m recently with of the site an Contact: Just A former CI of C18 collie commissione future work.	9 steam-powered colliery built on the site rry. The Avon Industrial Buildings Trust have drawn their application for redevelopment drawn their application f
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Park Road, Kingswood Listed Building Grade I, CA Very bad Vacant A (A) Private Brandy Bottom Colliery, Pucklechurch	redundant fc in an even m recently with of the site an Contact: Just A former CI of C18 collie commissione future work.	or many years and a fire has placed the buildin hore vulnerable position. The owners have adrawn their application for redevelopment ad revised schemes are under discussion. in Ayton 0117 975 0687 9 steam-powered colliery built on the site ery. The Avon Industrial Buildings Trust have ed an historical study of the site to inform
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION:	Park Road, Kingswood         Listed Building Grade I, CA         Very bad         Vacant         A (A)         Private         Brandy Bottom Colliery, Pucklechurch         Scheduled Monument         Very bad	redundant fc in an even m recently with of the site an Contact: Just A former CI of C18 collie commissione future work.	9 steam-powered colliery built on the site rry. The Avon Industrial Buildings Trust have drawn their application for redevelopment drevised schemes are under discussion.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Park Road, Kingswood         Listed Building Grade I, CA         Very bad         Vacant         A (A)         Private         Brandy Bottom Colliery, Pucklechurch         Scheduled Monument         Very bad         N/A         D (C)	redundant fc in an even m recently with of the site an Contact: Just A former CI of C18 collie commissione future work. clearance an	9 steam-powered colliery built on the site rry. The Avon Industrial Buildings Trust have drawn their application for redevelopment drawn their application f

PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C Slow document activity agreed

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets. ABBREVIATIONS CA Conservation Area LB/LBs Listed Building/s LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM/SMs Scheduled Monument/s UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2011 / SOUTH WEST / SOUTH GLOUCESTERSHIRE (UA)

	SITE NAME:	Coach House and stables north east of Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar	provincial b hands and a	se and stables, built 1722 in a mannered aroque.The building has recently changed an extensive repair programme has been
	DESIGNATION:	Listed Building Grade II*	agreed and	is well underway.
	CONDITION:	Very bad		
	OCCUPANCY:	N/A		
And the second s	PRIORITY:	E (A)		
	OWNER TYPE:	Private	Contact: Jus	tin Ayton 0117 975 0687
Alex	SITE NAME:	Oxwick Farmhouse, Oxwick Lane,Yate, Wickwar	mannerist/b has serious	dated 1722, in flamboyant artisan paroque style. Part occupied. Vacant part decay of floor structures and in areas is
10,0	DESIGNATION:	sted Building Grade II* unsate, but emergency repairs have co		emergency repairs have commenced. The farr / changed hands and negotiations have begun
1 121 1	CONDITION:	Poor		w owner over repair and refurbishment.
Call Com	OCCUPANCY:	Part occupied		··· -····
	PRIORITY:	C (C)		
	OWNER TYPE:		Contact: Jus	tin Ayton 0117 975 0687
	SITE NAME:	Church of St James the Great, Church Road, Westerleigh	Large church with distinctive tall tower at edge of the village of Westerleigh. The roofs are covered with a lo sandstone slate, many of which are slipped or missing. especially bad over the porch which now has a tarpau	
	DESIGNATION:	Listed Place of Worship Grade I		north valley gutter is a temporary repair, now imperils the nave and aisle roofs. A Repair
	CONDITION:	Very bad	Grant for P	laces of Worship for repair of the roofs has
" A strange when and "	PRIORITY:	B (New entry)	been offere	ed.
	OWNER TYPE:	Religious organisation	Contact: Ch	nris Miners 0117 975 0700
ITE NAME:	Round bar	row on Barrow Hill, Bitton		
DESIGNATION:	Scheduled	Monument (No. 1004521)	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Moderate	animal burrowing	TREND:	Declining
WNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Roman vil	a at Cromhall north west of Tapwell E	Bridge, Croml	hall
		-	CONDITION:	
				Extensive significant problems
ESIGNATION:	Scheduled	Monument (No. 1003045)	CONDITION.	Extensive significant problems
				i.e. under plough, collapse
INCIPAL VULNERABILITY:	Arable plo		TREND:	i.e. under plough, collapse Declining
RINCIPAL VULNERABILITY:				i.e. under plough, collapse
RINCIPAL VULNERABILITY: WNER TYPE:	Arable plo Private		TREND:	i.e. under plough, collapse Declining
NINCIPAL VULNERABILITY: WINER TYPE: TE NAME:	Arable plo Private Starveall lo	ughing	TREND:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems
NNCIPAL VULNERABILITY: WNER TYPE: TE NAME: ESIGNATION:	Arable plo Private Starveall k	ughing ong barrow, Hawkesbury Monument (No. 1002473)	TREND: CONTACT: CONDITION:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY: WNER TYPE: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY:	Arable plo Private Starveall lo Scheduled Extensive s	ughing ong barrow, Hawkesbury	TREND: CONTACT: CONDITION: TREND:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining
NINCIPAL VULNERABILITY: WINER TYPE: TE NAME: ESIGNATION: NINCIPAL VULNERABILITY:	Arable plo Private Starveall k	ughing ong barrow, Hawkesbury Monument (No. 1002473)	TREND: CONTACT: CONDITION:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:  WINER TYPE:  ESIGNATION:  RINCIPAL VULNERABILITY:  WINER TYPE:	Arable plo Private Starveall lo Scheduled Extensive s Private	ughing ong barrow, Hawkesbury Monument (No. 1002473)	TREND: CONTACT: CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
RINCIPAL VULNERABILITY: WHER TYPE: ITE NAME: RINCIPAL VULNERABILITY: WHER TYPE: ITE NAME: ITE NAME:	Arable plo Private Starveall k Scheduled Extensive s Private Hillfort an	ughing <b>ong barrow, Hawkesbury</b> Monument (No. 1002473) stock erosion	TREND: CONTACT: CONDITION: TREND: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 bbey, Alveston, Thornbury Generally satisfactory
RINCIPAL VULNERABILITY: WNER TYPE: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNER TYPE: TE NAME: ESIGNATION:	Arable plo Private Starveall lo Scheduled Extensive s Private Hillfort an Scheduled	ughing ong barrow, Hawkesbury Monument (No. 1002473) stock erosion d associated Romano-British occupatio	TREND: CONTACT: CONDITION: TREND: CONTACT: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 <b>bbey, Alveston, Thornbury</b> Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: DOWNER TYPE:	Arable plo Private Starveall k Scheduled Extensive s Private Hillfort an	ughing ong barrow, Hawkesbury Monument (No. 1002473) stock erosion d associated Romano-British occupatio	TREND: CONTACT: CONDITION: TREND: CONTACT: CONTACT:	i.e. under plough, collapse Declining Business Manager 0117 975 0700 Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 bbey, Alveston, Thornbury Generally satisfactory

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the solution of the solution

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / SOUTH GLOUCESTERSHIRE (UA) / SWINDON (UA)

SITE NAME: Wickwar Roman small town 680m WNW of Hall End Farm, Wickwar				
DESIGNATION:	Scheduled Monument (No. 1021404)	CONDITION:	Extensive significant problems	
			i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	

States -	SITE NAME:	Stoke Park, Stoke Gifford	Dramatic location on a hill overlooking the city of Bristol. Mid C18 park laid out around crenellated Dower House. Park embellished by monuments and eye-catchers. Now
	DESIGNATION:	Registered Park and Garden Grade II, also CA, I I LBs, I SM	bisected by the M32 motorway. Setting compromised by dense residential development. Park under pressure from heavy and occasionally anti-social use. Future now appears
the day of the	CONDITION:	Extensive significant problems	more settled following acquisition by Bristol City Council
THE PARTY AND A THE	VULNERABILITY	Medium	in 2010.
	TREND:	Improving	
Contract of the second	OWNER TYPE:	Mixed, multiple owners	Contact: Kim Auston 0117 975 0696
SITE NAME:	Warmley,	Siston	

SITE NAME:	Whitfield Tabernacle						
CONTACT:	Rebecca Anthony (LPA) 01454 863465	NEW ENTRY?:	No				
VULNERABILITY:	Low	TREND:	No significant change				
DESIGNATION:	Conservation Area	CONDITION:	Very bad				
SHERVILL							

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Unknown
CONTACT:	Rebecca Anthony (LPA) 01454 863465	NEW ENTRY?:	No

### SWINDON (UA)



		Emlyn Square, Swindon	example at heart of railway village. End use limited by internal features, including a large lecture theatre. Sold 2003 and discussions are continuing regarding the futu		
	DESIGNATION:	Listed Building Grade II*, CA	of the building. Repairs to the southern part of the roof		
	CONDITION:	Poor	have been undertaken. The council served an UWN on the owner in 2009 and implemented works in 2010 to		
	OCCUPANCY:	Vacant	secure the building.		
	PRIORITY:	A (A)			
	OWNER TYPE:	Company	Contact: Isla Macneal 0117 975 0742		
	SITE NAME:	Chain Test House, Rodbourne Road, Swindon	A rare example of a railway chain testing house, 1873. Building currently vacant and in poor condition. Now part of application for mixed use development.		
		Rodbourne Road,	1873. Building currently vacant and in poor condition.		
- 1 - P		Rodbourne Road, Swindon	1873. Building currently vacant and in poor condition.		
I. I.	DESIGNATION:	Rodbourne Road, Swindon Listed Building Grade II*, CA Poor	1873. Building currently vacant and in poor condition.		
	DESIGNATION: CONDITION:	Rodbourne Road, Swindon Listed Building Grade II*, CA Poor	1873. Building currently vacant and in poor condition.		
	DESIGNATION: CONDITION: OCCUPANCY:	Rodbourne Road, Swindon Listed Building Grade II*, CA Poor Vacant D (D)	1873. Building currently vacant and in poor condition.		



and the second second	OWNER TYPE:	Company	Contact: Isia Macheal 0117 975 0742
	SITE NAME:	Church of St Mary, Lydiard Tregoze	Church dates from C13, with C15, C17 and C19 phases. Restored C20. Exceptional interior with high quality monuments, wall and ceiling paintings from C13-C19. Roof to St John's Chapel is leaking and has damaged painted ceiling. Rainwater goods and drainage
1310	DESIGNATION:	Listed Place of Worship Grade I	throughout building are defective and damaging medieval
1	CONDITION:	Very bad	wall paintings. A Repair Grant for Places of Worship has been offered for roof repairs.
a porte	PRIORITY:	B (New entry)	been ollered for root repairs.
100	OWNER TYPE:	Religious organisation	Contact: Sarah Ball 0117 975 0666

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

Mechanics Institute, 1853-1855; now vacant. Outstanding

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2011 / SOUTH WEST / SWINDON (UA)

ITE NAME:	Bowl barrow 280m north of Downs Barn, I	Bishopstone	
DESIGNATION:	Scheduled Monument (No. 1010419)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow on Hinton Downs, Bishopstor	ne	
DESIGNATION:	Scheduled Monument (No. 1010461)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Roman villa 630m south west of Starveall F	arm, Bishopstone	
DESIGNATION:	Scheduled Monument (No. 1016309)	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Disc barrow on Burderop Down, Ikm nort	h east of Upper H	lerdswick Farm, Chiseldon
designation:	Scheduled Monument (No. 1010457)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
	0		0
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Private Field system and earthwork enclosure on E		
SITE NAME: DESIGNATION:	Field system and earthwork enclosure on E	Burderop Down, C	Chiseldon Generally satisfactory
SITE NAME:	Field system and earthwork enclosure on E Scheduled Monument (No. 1016383)	Burderop Down, C	Chiseldon Generally satisfactory but with significant localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE:	Field system and earthwork enclosure on E Scheduled Monument (No. 1016383) Extensive vehicle damage/erosion	Burderop Down, C Condition: Trend: Contact:	Chiseldon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Field system and earthwork enclosure on B Scheduled Monument (No. 1016383) Extensive vehicle damage/erosion Private	Burderop Down, C Condition: Trend: Contact:	Chiseldon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Field system and earthwork enclosure on B Scheduled Monument (No. 1016383) Extensive vehicle damage/erosion Private Site of Roman town, west of Wanborough I	Burderop Down, C CONDITION: TREND: CONTACT: House, Covinghan	Chiseldon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Field system and earthwork enclosure on E         Scheduled Monument (No. 1016383)         Extensive vehicle damage/erosion         Private         Site of Roman town, west of Wanborough         Scheduled Monument (No. 1004684)	Burderop Down, C CONDITION: TREND: CONTACT: House, Covinghan CONDITION:	Chiseldon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Field system and earthwork enclosure on E         Scheduled Monument (No. 1016383)         Extensive vehicle damage/erosion         Private         Site of Roman town, west of Wanborough         Scheduled Monument (No. 1004684)         Other	Burderop Down, C CONDITION: TREND: CONTACT: House, Covinghan CONDITION: TREND: CONTACT:	Chiseldon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Unknown Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Field system and earthwork enclosure on E         Scheduled Monument (No. 1016383)         Extensive vehicle damage/erosion         Private         Site of Roman town, west of Wanborough I         Scheduled Monument (No. 1004684)         Other         Private	Burderop Down, C CONDITION: TREND: CONTACT: House, Covinghan CONDITION: TREND: CONTACT:	Chiseldon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Unknown Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION:	Field system and earthwork enclosure on E         Scheduled Monument (No. 1016383)         Extensive vehicle damage/erosion         Private         Site of Roman town, west of Wanborough I         Scheduled Monument (No. 1004684)         Other         Private         Four Highworth circles 150m north east of	Burderop Down, C CONDITION: TREND: CONTACT: House, Covinghan CONDITION: TREND: CONTACT: Pickett's Copse, H	Chiseldon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Unknown Business Manager 0117 975 0700 
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Field system and earthwork enclosure on E         Scheduled Monument (No. 1016383)         Extensive vehicle damage/erosion         Private         Site of Roman town, west of Wanborough I         Scheduled Monument (No. 1004684)         Other         Private         Four Highworth circles 150m north east of         Scheduled Monument (No. 1016386)	Burderop Down, C CONDITION: TREND: CONTACT: House, Covinghan CONDITION: TREND: CONTACT: Pickett's Copse, H CONDITION:	Chiseldon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Unknown Business Manager 0117 975 0700 Highworth Extensive significant problems i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Field system and earthwork enclosure on E         Scheduled Monument (No. 1016383)         Extensive vehicle damage/erosion         Private         Site of Roman town, west of Wanborough I         Scheduled Monument (No. 1004684)         Other         Private         Four Highworth circles I50m north east of         Scheduled Monument (No. 1016386)         Arable ploughing	Burderop Down, C CONDITION: TREND: CONTACT: House, Covinghan CONDITION: TREND: CONTACT: Pickett's Copse, H CONDITION: TREND: CONTACT:	Chiseldon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Unknown Business Manager 0117 975 0700 Highworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Field system and earthwork enclosure on E         Scheduled Monument (No. 1016383)         Extensive vehicle damage/erosion         Private         Site of Roman town, west of Wanborough I         Scheduled Monument (No. 1004684)         Other         Private         Four Highworth circles I50m north east of         Scheduled Monument (No. 1016386)         Arable ploughing         Private	Burderop Down, C CONDITION: TREND: CONTACT: House, Covinghan CONDITION: TREND: CONTACT: Pickett's Copse, H CONDITION: TREND: CONTACT:	Chiseldon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Unknown Business Manager 0117 975 0700 Highworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700
STE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME:	Field system and earthwork enclosure on E         Scheduled Monument (No. 1016383)         Extensive vehicle damage/erosion         Private         Site of Roman town, west of Wanborough I         Scheduled Monument (No. 1004684)         Other         Private         Four Highworth circles I50m north east of         Scheduled Monument (No. 1016386)         Arable ploughing         Private         Highworth circle 520m north west of North	Burderop Down, C CONDITION: TREND: CONTACT: House, Covinghan CONDITION: TREND: CONTACT: Pickett's Copse, H CONDITION: TREND: CONTACT:	Chiseldon Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory with major localised problems Unknown Business Manager 0117 975 0700 Highworth Extensive significant problems i.e. under plough, collapse Declining Business Manager 0117 975 0700 Highworth Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

197

#### HERITAGE AT RISK 2011 / SOUTH WEST / SWINDON (UA) / TORBAY (UA)

SITE NAME:	Three Highworth circles 600m east of North Leaze Farm, Highworth					
DESIGNATION:	Scheduled Monument (No. 1018221)	CONDITION:	Extensive significant problems			
			i.e. under plough, collapse			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable			
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700			
SITE NAME:	Bowl barrow 700m south west of Liddingto	on Warren Farm, L	iddington			
DESIGNATION:	Scheduled Monument (No. 1009634)	CONDITION:	Generally satisfactory			
			but with significant localised problems			
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700			
SITE NAME:	Liddington Castle, Liddington					
DESIGNATION:	Scheduled Monument (No. 1016312)	CONDITION:	Generally satisfactory			
PRINCIPAL VULNERABILITY:	Extensive stock erosion		but with significant localised problems Declining			
OWNER TYPE:	Private	TREND: CONTACT:	Business Manager 0117 975 0700			
Owner Hre:	Trivate	CONTACT:				
SITE NAME:	Long barrow 700m north of Liddington Wa	rren Farm, Lidding	gton			
DESIGNATION:	Scheduled Monument (No. 1009631)	CONDITION:	Generally unsatisfactory			
			with major localised problems			
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700			
SITE NAME:	Remains of Holy Rood Church, The Lawn, O	Old Town, Swindor	n			
DESIGNATION:	Scheduled Monument (No. 1018057)	CONDITION:	Generally unsatisfactory			
	``````````````````````````````````````		with major localised problems			
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining			
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700			
SITE NAME:	Bowl barrow I50m north of Half Moon Wc	ood, Wanborough				
DESIGNATION:	Scheduled Monument (No. 1011811)	CONDITION:	Extensive significant problems			
	`````		i.e. under plough, collapse			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown			
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700			
SITE NAME:	Bowl barrow 850m north west of North Fa	arm, Wanborough				
DESIGNATION:	Scheduled Monument (No. 1016381)	CONDITION:	Extensive significant problems			
			i.e. under plough, collapse			
PRINCIPAL VULNERABILITY:	Arable ploughing Private	TREND: CONTACT:	Unknown Business Manager 0117 975 0700			

### TORBAY (UA)



SITE NAME:	Lupton House (Gramercy Hall School), Brixham
DESIGNATION:	Listed Building Grade II*, RPG II*
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	D (D)
OWNER TYPE:	Trust

C18 and C19 country house remodelled by G Wightwick c1840, with extensive ancillary buildings and fine Italianate Garden. Altered after a fire in 1928. In use as school from mid C20 to 2004. The house was empty and its condition deteriorating until 2009 when it was acquired by a charitable trust with the aim of using it for a wide range of community activities. Much of the roof is in poor condition and leaking.

Contact: Simon Ramsden 0117 975 0676

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

C

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### HERITAGE AT RISK 2011 / SOUTH WEST / TORBAY (UA)

	SITE NAME:	Torbay Cinema, Torbay Road, Paignton	example of has been va	ensed in 1912. An extremely well preserved an early purpose-built cinema. The building acant for 10 years. Torbay Council has served btice, much of which was implemented in
	DESIGNATION:	Listed Building Grade II*		7. Ongoing maintenance is being undertaken
	condition: Fair a		and discuss	ions on the re-use of the building are continuing
	OCCUPANCY:	Vacant		
	PRIORITY:	C (C)		
1	OWNER TYPE:	Company	Contact: Sir	mon Ramsden 0117 975 0676
	SITE NAME:	Ilsham Manor Oratory, Ilsham Road, Ilsham, Torquay	Redundant Manor: Neg current use	oratory, part of the demolished medieval IIsham glected and in poor condition, the chapel has no e.
1	DESIGNATION:	Listed Building Grade II*		
	CONDITION:	Poor		
	OCCUPANCY:	Vacant		
	PRIORITY:	A (A)		
	OWNER TYPE:	Educational Body	Contact: Sir	mon Ramsden 0117 975 0676
SITE NAME:	Ashhole C	avern, Torbay		
DESIGNATION:	Scheduled	Monument (No. 1019133)	CONDITION:	Generally satisfactory
	Scheduled		CONDITION.	but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism		TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Prehistoric	field system at Walls Hill, Torbay		
DESIGNATION:	Scheduled	Monument (No. 1019134)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate	visitor erosion	TREND:	Declining
OWNER TYPE:	Local Autho	ority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	St Michael	's Chapel, Chapel Hill, Torbay		
DESIGNATION:	Scheduled	Monument (No. 1019131)	CONDITION:	Extensive significant problems i.e. under plough, collapse
	Collanco		TREND	
PRINCIPAL VULNERABILITY:	Collapse	ority	TREND:	Stable Business Manager 0117 975 0700
OWNER TYPE:	Local Auth	onty	CONTACT:	Business Manager 0117 975 0700
site name:	The Bishop	o's Palace, Tower Road, Torbay		
DESIGNATION:	Scheduled	Monument (No. 1020764)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growt	th	TREND:	Improving
OWNER TYPE:	Local Autho		CONTACT:	Business Manager 0117 975 0700
	SITE NAME:	Oldway Mansion	Formal gard	dens laid out to complement a grand house
A STATE OF THE STA		Registered Park and Garden Grade II,	inspired by	Versailles. Built by the Singer sewing machine
Contraction of the second	DESIGNATION:	also 12 LBs	dynasty, the	e property has been in local authority ownership
	CONDITION	Generally satisfactory		ears. The grounds have been steadily rationalised ed. The future of both house and grounds is
	CONDITION:	but with significant localised problems	currently ur	
	VULNERABILITY:	High		
		CLU		

Contact: Kim Auston 0117 975 0696

- PRIORITY (FOR BUILDINGS)
- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Stable

OWNER TYPE: Local Authority, single owner

TREND:

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

199

#### HERITAGE AT RISK 2011 / SOUTH WEST / TORBAY (UA) / WILTSHIRE (UA)

	SITE NAME:	Princess Gardens and Royal Terrace Gardens	Important formal Victorian seaside park with interesti later phases and additions. Ongoing structural probler related to seafront location. Proposals for major	
	DESIGNATION:	Registered Park and Garden Grade II, also part in CA, 4 LBs	developmen	nt believed to have been dropped.
	CONDITION:	Generally satisfactory but with significant localised problems		
	VULNERABILITY			
	TREND:	Declining		
	OWNER TYPE:	Local Authority, single owner	Contact: Kin	n Auston 0117 975 0696
SITE NAME:	Brixham T	own		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Low		TREND:	No significant change
CONTACT:	Hal Bishop	o (LPA) 01803 207787	NEW ENTRY?:	No

SITE NAME:	Torre, Tormohun, Torquay		
CONTACT:	Hal Bishop (LPA) 01803 207787	NEW ENTRY?:	No
VULNERABILITY:	Low	TREND:	Improving significantly
DESIGNATION:	Conservation Area	CONDITION:	Very bad

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Hal Bishop (LPA) 01803 207787	NEW ENTRY?:	No

### WILTSHIRE (UA)

SITE NAME:



and the second	SITE NAME:	Gay's Cave and Diamond (Amesbury Abbey), Amesbury	Gay's Cave or Seat, circa 1734-38, with gateway and wrought iron gates, attributed to Henry Flitcroft, and situated on the axis of Amesbury Abbey and tumulus beyond the River Avon. Some of the shrubbery has
	DESIGNATION:	Listed Building Grade II*, CA, RPG II*, WHS	been cleared; however, the Diamond pattern paths are overgrown and unrecognisable. One gate has been removed from the Grotto and it is suffering
	CONDITION:	Fair	from vandalism and neglect.
	OCCUPANCY:	N/A	0
	PRIORITY:	C (C)	
int colo	OWNER TYPE:	Private	Contact: Isla Macneal 0117 975 0742
All and a second	SITE NAME:	Rudloe Manor, Box	Late CI7 manor house surrounded by ancillary buildings including a grade II listed barn.The house was part of a larger MOD site which was vacated in 1998.The house
		Listed Building Grade II* CA	has remained vacant. The current owners have consent



	SITE NAME:	Rudloe Manor, Box	Late C17 manor house surrounded by ancillary buildings including a grade II listed barn. The house was part of a larger MOD site which was vacated in 1998. The house
1	DESIGNATION:	Listed Building Grade II*, CA	has remained vacant. The current owners have consent for a residential scheme with enabling development but
SIL	CONDITION:	Poor	this has not yet been implemented.
	OCCUPANCY:	Vacant	
	PRIORITY:	B (B)	
35	OWNER TYPE:	Company	Contact: Isla Macneal 0117 975 0742
	SITE NAME:	Buildings to the rear of the Lansdowne Hotel, The Strand, Calne	Former coach house, stable and brewhouse to rear of Lansdowne Arms Hotel. Buildings range from mid C17 to mid C19. Condition of roofs and coverings are continuing to degenerate leading to further internal
	DESIGNATION:	Listed Building Grade II*, CA	decay. Urgent Works Notices have previously been

	CI/ to mid CI9. Condition of roots and coverings are
Grade II*, CA	continuing to degenerate leading to further internal decay. Urgent Works Notices have previously been
	complied with; however, the condition of these buildings
	continues to decline. The property has new owners who have indicated an intent to use the buildings.
	who have indicated an intent to use the buildings.

Contact: Isla Macneal 0117 975 0742

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

OWNER TYPE: Private

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Poor

Vacant C (C)

CONDITION: OCCUPANCY:

PRIORITY:

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS

	SITE NAME:	Two former hangars at Yatesbury Airfield, Cherhill, Compton Bassett	Two aircraft hangars, built circa 1917 as part of a training centre. Two of a group of three hangars from the first years of military flying. One hangar has been partially repaired
	DESIGNATION:	Listed Building Grade II*, CA	and the owner was served with an Urgent Works Notice to arrest further decline of the condition of the other
	CONDITION:	Very bad	hangar. Unfortunately before the works were implemented
	OCCUPANCY:	Part occupied	there was a substantial roof collapse.
all the second states and and the	PRIORITY:	A (A)	
Shard Playmont and the	OWNER TYPE:	Private	Contact: Isla Macneal 0117 975 0742
	SITE NAME:	Devizes Castle, Devizes	Grade I house, 1842, sited on top of a Norman motte and encircling moat. Site included on the register because of the precarious condition of the motte, though the Victorian house is occupied and in fair condition. Failure of the motte
	DESIGNATION:	Listed Building Grade I, SM	has resulted in cracking of the upper Victorian wall and
	CONDITION:	Very bad	could have a deleterious effect on the remains of the
	OCCUPANCY:	N/A	Orangery of Devizes Castle.
	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: Shane Gould 0117 975 0671
	SITE NAME:	Garden pavilion to the south east of Hillworth House, Hillworth Road, Devizes	Attractive brick structure located in what is now a public park. External sheeting applied to windows has reduced breathability and windows are beginning to rot. Minor stone defects are apparent and external ground
	DESIGNATION:	Listed Building Grade II*	conditions are poor due to absence of rainwater disposal
	CONDITION:	Poor	system. The Town Council has drawn up a scheme for
	OCCUPANCY:		repair in association with works to the park and $\pounds$ 1.2m of funding has been offered by HLF.
	PRIORITY:	D (D)	
	OWNER TYPE:	Local authority	Contact: Isla Macneal 0117 975 0742
-	SITE NAME:	Former Law Courts and County Police Station, Northgate Street, Devizes	Law courts and police station, 1835. Wind and weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use
		County Police Station,	weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented.
		County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA	weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice
	DESIGNATION:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad	weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C)	weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant	weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C)	<ul> <li>weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C) Company Stable block to Tottenham House, Great Bedwyn	<ul> <li>weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C) Company Stable block to Tottenham House,	<ul> <li>weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted for conversion into a spa, in association with a hotel in</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C) Company Stable block to Tottenham House, Great Bedwyn Listed Building Grade II*, RPG II* Poor	<ul> <li>weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C) Company Stable block to Tottenham House, Great Bedwyn Listed Building Grade II*, RPG II* Poor	<ul> <li>weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted for conversion into a spa, in association with a hotel in</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C) Company Stable block to Tottenham House, Great Bedwyn Listed Building Grade II*, RPG II* Poor Vacant B (B)	<ul> <li>weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted for conversion into a spa, in association with a hotel in</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C) Company Stable block to Tottenham House, Great Bedwyn Listed Building Grade II*, RPG II* Poor Vacant B (B) Private Tottenham House, Great Bedwyn	<ul> <li>weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted for conversion into a spa, in association with a hotel in the main house. The condition of the building is declining.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Contact: Isla Macneal 0117 975 0742</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C) Company  Stable block to Tottenham House, Great Bedwyn Listed Building Grade II*, RPG II* Poor Vacant B (B) Private  Tottenham House, Great Bedwyn Listed Building Grade I, RPG II*	<ul> <li>weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted for conversion into a spa, in association with a hotel in the main house. The condition of the building is declining.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Contact: Isla Macneal 0117 975 0742</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C) Company Stable block to Tottenham House, Great Bedwyn Listed Building Grade II*, RPG II* Poor Vacant B (B) Private Tottenham House, Great Bedwyn	<ul> <li>weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted for conversion into a spa, in association with a hotel in the main house. The condition of the building is declining.</li> <li>Contact: Isla Macneal 0117 975 0742</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C) Company  Stable block to Tottenham House, Great Bedwyn Listed Building Grade II*, RPG II* Poor Vacant B (B) Private  Tottenham House, Great Bedwyn Listed Building Grade I, RPG II* Poor Vacant Vacant	<ul> <li>weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted for conversion into a spa, in association with a hotel in the main house. The condition of the building is declining.</li> <li>Contact: Isla Macneal 0117 975 0742</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	County Police Station, Northgate Street, Devizes Listed Building Grade II*, CA Very bad Vacant C (C) Company  Stable block to Tottenham House, Great Bedwyn Listed Building Grade II*, RPG II* Poor Vacant B (B) Private  Tottenham House, Great Bedwyn Listed Building Grade I, RPG II* Poor Vacant B (B) Private	<ul> <li>weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have ever been implemented. Temporary repairs carried out as a consequence of Urgent Works Notice. Further Urgent Works Notice served 2003 but vandalism remains a constant threat. A feasibility study has been undertaken.</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted for conversion into a spa, in association with a hotel in the main house. The condition of the building is declining.</li> <li>Contact: Isla Macneal 0117 975 0742</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

A	SITE NAME:	Early wing at Brook Hall, Brokerswood, Heywood	An important C15 lodging range, attached to the grade Il listed house which contains some medieval remnants. Following the issuing of an Urgent Works Notice by the
THE THE THE	DESIGNATION:	Listed Building Grade I	Local Planning Authority, a supporting scaffold was erected in Spring 2002. Discussions for reuse ongoing. English
	CONDITION:	Poor	Heritage has grant-aided condition survey. Local Planning
	OCCUPANCY:	Vacant	Authority is actively considering serving a Repairs Notice.
	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: Sarah Ball 0117 975 0666
	SITE NAME:	Chapel at Knowle House, Little Bedwyn	Redundant early C15 chapel in curtilage of a listed house. In poor condition and needs some work and repair.
	DESIGNATION:	Scheduled Monument	
The second se	CONDITION:	Poor	
	OCCUPANCY:	N/A	
A. A. C. 金属 別、開設	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Shane Gould 0117 975 0671
	SITE NAME:	93 and 94 Bradenstoke, Lyneham	Timber framed building, CI5 to CI6, upgraded to II* in 2002. Last known use as a private residence but is now unoccupied. The council is monitoring the condition.
	DESIGNATION:	Listed Building Grade II*, CA	Listed building consent was granted in 2010 for some repair works.
	CONDITION:	Fair	-
	OCCUPANCY:	Vacant	
	PRIORITY:	E (E)	
	OWNER TYPE:	Private	Contact: Isla Macneal 0117 975 0742
	SITE NAME:	Medieval undercroft at Bradenstoke Priory, Bradenstoke, Lyneham	CI4 undercroft to priory. The building above removed in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage to provent collapse There has
		Bradenstoke Priory, Bradenstoke,	in 1920s to the United States of America by Randolph
		Bradenstoke Priory, Bradenstoke, Lyneham	in 1920s to the United States of America by Randolph Hearst.The undercroft has been propped with grant aid from English Heritage, to prevent collapse.There has
	DESIGNATION:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A	in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual
	DESIGNATION: CONDITION:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C)	in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.
	DESIGNATION: CONDITION: OCCUPANCY:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C)	in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road,	in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall. Contact: Veryan Heal 0117 975 0717 Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne	in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall. Contact: Veryan Heal 0117 975 0717 Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne Listed Building Grade II*	<ul> <li>in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.</li> <li>Contact: Veryan Heal 0117 975 0717</li> <li>Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne Listed Building Grade II* Poor	in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall. Contact: Veryan Heal 0117 975 0717 Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne Listed Building Grade II* Poor	<ul> <li>in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.</li> <li>Contact: Veryan Heal 0117 975 0717</li> <li>Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne Listed Building Grade II* Poor N/A C (C)	<ul> <li>in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.</li> <li>Contact: Veryan Heal 0117 975 0717</li> <li>Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the planning inspector.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne Listed Building Grade II* Poor N/A C (C)	<ul> <li>in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.</li> <li>Contact: Veryan Heal 0117 975 0717</li> <li>Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne Listed Building Grade II* Poor N/A C (C)	<ul> <li>in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.</li> <li>Contact: Veryan Heal 0117 975 0717</li> <li>Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the planning inspector:</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Roman Villa, C1 to C4 AD. The owners have erected a new permanent cover over the mosaic. English Heritage is working with the owners over a long term management</li> </ul>
	DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne Listed Building Grade II* Poor N/A C (C) Private Littlecote Roman Villa,	<ul> <li>in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.</li> <li>Contact: Veryan Heal 0117 975 0717</li> <li>Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the planning inspector:</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Roman Villa, C1 to C4 AD. The owners have erected a new permanent cover over the mosaic. English Heritage is</li> </ul>
	DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	Bradenstoke Priory, Bradenstoke, Lyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne Listed Building Grade II* Poor N/A C (C) Private Listed Eurida Grade II* Poor N/A C (C) Private	<ul> <li>in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.</li> <li>Contact: Veryan Heal 0117 975 0717</li> <li>Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the planning inspector:</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Roman Villa, C1 to C4 AD. The owners have erected a new permanent cover over the mosaic. English Heritage is working with the owners over a long term management</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Bradenstoke Priory, Bradenstoke, Jyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne Listed Building Grade II* Poor N/A C (C) Private Littlecote Roman Villa, Ramsbury Scheduled Monument Poor	<ul> <li>in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.</li> <li>Contact: Veryan Heal 0117 975 0717</li> <li>Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the planning inspector:</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Roman Villa, C1 to C4 AD. The owners have erected a new permanent cover over the mosaic. English Heritage is working with the owners over a long term management</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Bradenstoke Priory, Bradenstoke, Jyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne Listed Building Grade II* Poor N/A C (C) Private Littlecote Roman Villa, Ramsbury Scheduled Monument Poor	<ul> <li>in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.</li> <li>Contact: Veryan Heal 0117 975 0717</li> <li>Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the planning inspector:</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Roman Villa, C1 to C4 AD. The owners have erected a new permanent cover over the mosaic. English Heritage is working with the owners over a long term management</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Bradenstoke Priory, Bradenstoke, Jyneham Scheduled Monument Poor N/A C (C) Private The Red House at Eastwell Manor, Eastwell Road, Potterne Listed Building Grade II* Poor N/A C (C) Private Littlecote Roman Villa, Ramsbury Scheduled Monument Poor N/A	<ul> <li>in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.</li> <li>Contact: Veryan Heal 0117 975 0717</li> <li>Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the planning inspector:</li> <li>Contact: Isla Macneal 0117 975 0742</li> <li>Roman Villa, C1 to C4 AD. The owners have erected a new permanent cover over the mosaic. English Heritage is working with the owners over a long term management</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

202

	SITE NAME:	Chapel, immediately north of Pythouse, Pythouse Park, West Tisbury	Built by Joh Lambert of	private chapel to country house circa 1827. In Bennett of Pythouse for his wife nee Lucy f Boyton. The chapel is derelict and overgrown
	DESIGNATION:	Listed Building Grade II*	and the sto	nework has been vandalised. The building is Ided. Some of the vegetation has been
	CONDITION:	Very bad		nd a repair schedule is being prepared.
	OCCUPANCY:	Vacant		
- De Kara La	PRIORITY:	A (A)		
	OWNER TYPE:	Private	Contact: Isl	a Macneal 0117 975 0742
4	SITE NAME:	Phipps Mausoleum, Westbury Cemetery, Bratton Road, Westbury		privately owned mausoleum, cal authority municipal cemetery.
	DESIGNATION:	Listed Building Grade II*		
	CONDITION:	Poor		
STATE ALLAND	OCCUPANCY:	N/A		
A AL A	PRIORITY:	С (С)		
	OWNER TYPE:	Private	Contact: Fr	rancis Kelly 0117 975 0725
SITE NAME:	Banjo enc	losure 480m south west of Cheldene	, Aldbourne	
DESIGNATION:	Scheduled	Monument (No. 1017363)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable plc		TREND:	Unknown
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Lewisham	Castle, Aldbourne		
DESIGNATION:	Scheduled	Monument (No. 1017364)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clip	pring	TREND:	Unknown
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barr	ow 800m south east of Tanhill Pennin	g, All Canning	75
		Monument (No. 1013023)	-	Generally unsatisfactory
DESIGNATION:	JUIEUUIEU	Fiondment (No. 1013023)	CONDITION:	with major localised problems
PRINCIPAL VULNERABILITY:	Arable clip	ping	TREND:	Unknown
DWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two bowl	barrows 400m south of Tanhill Penni	ng, All Cannin	ıgs
DESIGNATION:		Monument (No. 1013024)	CONDITION:	Generally satisfactory
				but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clip	pping	TREND:	Unknown
OWNER TYPE:	Governme	ent or Agency	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Earth Burg	gh (or Eorth Burh) north west of Ne	w Town Farm,	, Alton
DESIGNATION:	Scheduled	Monument (No. 1004717)	CONDITION:	Generally satisfactory
				but with significant localised problems
PRINCIPAL VULNERABILITY: DWNER TYPE:	Extensive Private	animal burrowing	TREND: CONTACT:	Declining Business Manager 0117 975 0700
SITE NAME:	Two Saxo	n boundary stones 450yds (410m) we	est of New To	wn. Alton
DESIGNATION:		Monument (No. 1005646)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Other		TREND:	Unknown
OWNER TYPE:	Private		CONTACT:	Business Manager 0117 975 0700
Gwiner I I FE	Trivale		CONTACT:	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Wermere pond, Alvediston		
DESIGNATION:	Scheduled Monument (No. 1004774)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
site name:	A bell barrow and two bowl barrows east of part of a linear round barrow cemetery, An		Countess Farm:
DESIGNATION:	Scheduled Monument (No. 1010331)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bell barrow 550m east of New Barn, Earl's	Farm Down, Ame	sbury
DESIGNATION:	Scheduled Monument (No. 1009872)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 170m south east of Strangway	rs on Countess Fa	ırm, Amesbury
DESIGNATION:	Scheduled Monument (No. 1009145)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 400m SSE of Strangways on C	Countess Farm, Ar	nesbury
DESIGNATION:	Scheduled Monument (No. 1021348)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 60m west of A345 on Counte	ess Farm, Amesbu	ry
DESIGNATION:	Scheduled Monument (No. 1009141)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 70m west of A345 on Counte	ess Farm, Amesbu	ry
DESIGNATION:	Scheduled Monument (No. 1009131)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	Henge monument 400m south of Stonehen	ge Cottages, Ame	esbury
SITE NAME:			
	Scheduled Monument (No. 1012376)	CONDITION:	Extensive significant problems
DESIGNATION:	Scheduled Monument (No. 1012376) Arable ploughing	CONDITION: TREND:	Extensive significant problems Unknown
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	× ,		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable ploughing	TREND: CONTACT:	Unknown Business Manager 0117 975 0700
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Arable ploughing Private	TREND: CONTACT:	Unknown Business Manager 0117 975 0700 ury
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing Private Linear boundary earthwork 250m west of S	trend: contact: Stockport, Amesb	Unknown Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

	Linear boundary earthwork on Amesbury [		·
DESIGNATION:	Scheduled Monument (No. 1015218)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		CONTRET.	
SITE NAME:	Pond barrow 400m south east of Strangway	ys, Amesbury	
DESIGNATION:	Scheduled Monument (No. 1009136)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Pond barrow 480m west of Olddown Barn	on Amesbury Do	wn, Amesbury
DESIGNATION:	Scheduled Monument (No. 1015027)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Three bell barrows 300m north east of New	w Barn, Earl's Farı	n Down, Amesbury
DESIGNATION:	Scheduled Monument (No. 1009572)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Settlement east of Ashtonfield (Cotswold C	Community), Ashto	on Keynes
DESIGNATION:	Scheduled Monument (No. 1004691)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Local Authority	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	A henge, four Bronze Age barrows and part	t of a Roman road	500m south west of Fox Covert Aven
DESIGNATION:	Scheduled Monument (No. 1007491)	CONDITION:	Extensive significant problems
		TDENID.	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	
	Government or Agency	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	1 0 0	CONTACT:	
DWNER TYPE:	Government or Agency	CONTACT:	e 'Waggon and Horses', Avebury Generally satisfactory
OWNER TYPE:	Government or Agency Beckhampton round barrow cemetery 150r Scheduled Monument (No. 1008221)	CONTACT: n north east of th	e 'Waggon and Horses', Avebury Generally satisfactory
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Government or Agency Beckhampton round barrow cemetery 150r	CONTACT: n north east of th CONDITION:	e 'Waggon and Horses', Avebury Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Government or Agency Beckhampton round barrow cemetery 150r Scheduled Monument (No. 1008221) Extensive animal burrowing Private Bell barrow forming part of a round barrow	CONTACT: n north east of th CONDITION: TREND: CONTACT: v cemetery	e 'Waggon and Horses', Avebury Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Government or Agency Beckhampton round barrow cemetery 150r Scheduled Monument (No. 1008221) Extensive animal burrowing Private Bell barrow forming part of a round barrow 400m north east of West Kennett Farm on	CONTACT: n north east of th CONDITION: TREND: CONTACT: v cemetery	e 'Waggon and Horses', Avebury Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Government or Agency Beckhampton round barrow cemetery 150r Scheduled Monument (No. 1008221) Extensive animal burrowing Private Bell barrow forming part of a round barrow	CONTACT: n north east of th CONDITION: TREND: CONTACT: v cemetery	e 'Waggon and Horses', Avebury Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:	Government or Agency Beckhampton round barrow cemetery 150r Scheduled Monument (No. 1008221) Extensive animal burrowing Private Bell barrow forming part of a round barrow 400m north east of West Kennett Farm on	CONTACT: m north east of th CONDITION: TREND: CONTACT: v cemetery Overton Hill, Ave	e 'Waggon and Horses', Avebury Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Government or Agency Beckhampton round barrow cemetery 150r Scheduled Monument (No. 1008221) Extensive animal burrowing Private Bell barrow forming part of a round barrow 400m north east of West Kennett Farm on Scheduled Monument (No. 1008099)	CONTACT: n north east of th CONDITION: TREND: CONTACT: v cemetery Overton Hill, Ave CONDITION:	e 'Waggon and Horses', Avebury Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 ebury Generally satisfactory but with significant localised problems
OWNER TYPE:	Government or Agency Beckhampton round barrow cemetery 150r Scheduled Monument (No. 1008221) Extensive animal burrowing Private Bell barrow forming part of a round barrow 400m north east of West Kennett Farm on Scheduled Monument (No. 1008099) Vandalism Private Bowl barrow 200m south of Green Street a	CONTACT: m north east of the CONDITION: TREND: CONTACT: v cemetery Overton Hill, Ave CONDITION: TREND: CONTACT: and I 100m east of	e 'Waggon and Horses', Avebury Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 ebury Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
OWNER TYPE:	Government or Agency Beckhampton round barrow cemetery 150r Scheduled Monument (No. 1008221) Extensive animal burrowing Private Bell barrow forming part of a round barrow 400m north east of West Kennett Farm on Scheduled Monument (No. 1008099) Vandalism Private Bowl barrow 200m south of Green Street a forming part of a round barrow cemetery of	CONTACT: m north east of the CONDITION: TREND: CONTACT: v cemetery Overton Hill, Ave CONDITION: TREND: CONTACT: and I 100m east of pon Avebury Down	e 'Waggon and Horses', Avebury Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 ebury Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 the Avebury henge monument, , Avebury
OWNER TYPE:	Government or Agency Beckhampton round barrow cemetery 150r Scheduled Monument (No. 1008221) Extensive animal burrowing Private Bell barrow forming part of a round barrow 400m north east of West Kennett Farm on Scheduled Monument (No. 1008099) Vandalism Private Bowl barrow 200m south of Green Street a	CONTACT: m north east of the CONDITION: TREND: CONTACT: v cemetery Overton Hill, Ave CONDITION: TREND: CONTACT: and I 100m east of	e 'Waggon and Horses', Avebury Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700 ebury Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

DESIGNATION: PRINCIPAL VULNERABILITY:	forming part of the Seven Barrow Hill round Scheduled Monument (No. 1007489)	CONDITION:	Generally satisfactory
PRINCIPAL VULNERABILITY:	· /		Generally satisfactory
PRINCIPAL VULNERABILITY:			but with significant localised problems
	Extensive animal burrowing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 770m south west of the juncti forming part of a round barrow cemetery c		
DESIGNATION:	Scheduled Monument (No. 1008107)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 900m SSE of Green Bank, Ave	bury	
DESIGNATION:	Scheduled Monument (No. 1014029)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
DITE NAME:	Bowl barrow forming part of a Bronze Age West Kennett Farm on Overton Hill, Avebu		north east of
DESIGNATION:	Scheduled Monument (No. 1008100)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow immediately west of the Ridge	eway, 400m north	east of its junction with Green Street. Av
	Scheduled Monument (No. 1008500)	-	Extensive significant problems
DESIGNATION:	Arable ploughing	CONDITION:	Unknown
RINCIPAL VULNERABILITY:	Private	TREND:	Business Manager 0117 975 0700
OWNER TYPE:		CONTACT:	
SITE NAME:	Earthwork enclosure 950m SSE of Manor Fa	arm, Avebury	
DESIGNATION:	Scheduled Monument (No. 1014031)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of six round barrows forming part o 400m north east of West Kennett Farm, Av	•	emetery
DESIGNATION:	Scheduled Monument (No. 1008102)	CONDITION:	Generally satisfactory
		Containion	but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
DITE NAME:	Pair of round barrows 400m west of the Riv forming part of a round barrow cemetery s		ry Down, Avebury
DESIGNATION:	Scheduled Monument (No. 1008075)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Pair of round barrows forming part of the E 400m north east of West Kennett Farm, Av		l barrow cemetery
DESIGNATION:	Scheduled Monument (No. 1008101)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
RIORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	D         Slow decay; solution agreed but not yet implemented.         F         Repair scheme in and (where appi end use or user           E         Under repair or in fair to good         end use or user functionally redu	icable) If the identified; has c	E: CA priority category hanged since the 2010 ter the previous category NP National Park

no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

has changed since the 2010 register, the previous category is given in brackets.

LPA NP RPG SM/SMs UA WHS Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

Scheduled Monument (No. 1008109) Arable ploughing Private Round barrow cemetery 400m south of Avebu Scheduled Monument (No. 1008216) Arable ploughing Private Ten barrows forming part of Fox Covert round Scheduled Monument (No. 1008293) Extensive animal burrowing Private West Kennet Avenue and an earthwork bank e Scheduled Monument (No. 1015547) Extensive vehicle damage/erosion Private	CONDITION: TREND: CONTACT: d barrow ceme CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 etery, West Down, Avebury Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
Private Round barrow cemetery 400m south of Avebu Scheduled Monument (No. 1008216) Arable ploughing Private Ten barrows forming part of Fox Covert round Scheduled Monument (No. 1008293) Extensive animal burrowing Private West Kennet Avenue and an earthwork bank e Scheduled Monument (No. 1015547) Extensive vehicle damage/erosion	CONTACT: ry henge mon CONDITION: TREND: CONTACT: d barrow ceme CONDITION: TREND: CONDITION: ast of West K	Business Manager 0117 975 0700 ument on Waden Hill, Avebury Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 etery, West Down, Avebury Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ennett Farm, Avebury Generally satisfactory but with significant localised problems
Round barrow cemetery 400m south of Avebur         Scheduled Monument (No. 1008216)         Arable ploughing         Private         Ten barrows forming part of Fox Covert round         Scheduled Monument (No. 1008293)         Extensive animal burrowing         Private         West Kennet Avenue and an earthwork bank end         Scheduled Monument (No. 1015547)         Extensive vehicle damage/erosion	ry henge mon CONDITION: TREND: CONTACT: d barrow ceme CONDITION: TREND: CONTACT: ast of West K	ument on Waden Hill, Avebury Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 etery, West Down, Avebury Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ennett Farm, Avebury Generally satisfactory but with significant localised problems
Scheduled Monument (No. 1008216)         Arable ploughing         Private         Ten barrows forming part of Fox Covert round         Scheduled Monument (No. 1008293)         Extensive animal burrowing         Private         West Kennet Avenue and an earthwork bank end         Scheduled Monument (No. 1015547)         Extensive vehicle damage/erosion	CONDITION: TREND: CONTACT: d barrow ceme CONDITION: TREND: CONTACT: ast of West K CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 etery, West Down, Avebury Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ennett Farm, Avebury Generally satisfactory but with significant localised problems
Arable ploughing Private Ten barrows forming part of Fox Covert round Scheduled Monument (No. 1008293) Extensive animal burrowing Private West Kennet Avenue and an earthwork bank e Scheduled Monument (No. 1015547) Extensive vehicle damage/erosion	TREND: CONTACT: d barrow ceme CONDITION: TREND: CONTACT: ast of West K	with major localised problems Declining Business Manager 0117 975 0700 etery, West Down, Avebury Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ennett Farm, Avebury Generally satisfactory but with significant localised problems
Arable ploughing Private Ten barrows forming part of Fox Covert round Scheduled Monument (No. 1008293) Extensive animal burrowing Private West Kennet Avenue and an earthwork bank e Scheduled Monument (No. 1015547) Extensive vehicle damage/erosion	CONTACT: d barrow ceme CONDITION: TREND: CONTACT: ast of West K CONDITION:	Declining Business Manager 0117 975 0700 etery, West Down, Avebury Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ennett Farm, Avebury Generally satisfactory but with significant localised problems
Private Ten barrows forming part of Fox Covert round Scheduled Monument (No. 1008293) Extensive animal burrowing Private West Kennet Avenue and an earthwork bank e Scheduled Monument (No. 1015547) Extensive vehicle damage/erosion	CONTACT: d barrow ceme CONDITION: TREND: CONTACT: ast of West K CONDITION:	Business Manager 0117 975 0700 etery, West Down, Avebury Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ennett Farm, Avebury Generally satisfactory but with significant localised problems
Ten barrows forming part of Fox Covert round         Scheduled Monument (No. 1008293)         Extensive animal burrowing         Private         West Kennet Avenue and an earthwork bank end         Scheduled Monument (No. 1015547)         Extensive vehicle damage/erosion	d barrow ceme CONDITION: TREND: CONTACT: ast of West K CONDITION:	etery, West Down, Avebury Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ennett Farm, Avebury Generally satisfactory but with significant localised problems
Scheduled Monument (No. 1008293) Extensive animal burrowing Private West Kennet Avenue and an earthwork bank e Scheduled Monument (No. 1015547) Extensive vehicle damage/erosion	CONDITION: TREND: CONTACT: Past of West K CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ennett Farm, Avebury Generally satisfactory but with significant localised problems
Extensive animal burrowing Private West Kennet Avenue and an earthwork bank e Scheduled Monument (No. 1015547) Extensive vehicle damage/erosion	TREND: CONTACT: ast of West K CONDITION:	with major localised problems Declining Business Manager 0117 975 0700 ennett Farm, Avebury Generally satisfactory but with significant localised problems
Private West Kennet Avenue and an earthwork bank e Scheduled Monument (No. 1015547) Extensive vehicle damage/erosion	contact: ast of West K condition:	Declining Business Manager 0117 975 0700 ennett Farm, Avebury Generally satisfactory but with significant localised problems
Private West Kennet Avenue and an earthwork bank e Scheduled Monument (No. 1015547) Extensive vehicle damage/erosion	contact: ast of West K condition:	Business Manager 0117 975 0700 ennett Farm, Avebury Generally satisfactory but with significant localised problems
West Kennet Avenue and an earthwork bank e Scheduled Monument (No. 1015547) Extensive vehicle damage/erosion	condition:	ennett Farm, Avebury Generally satisfactory but with significant localised problems
Scheduled Monument (No. 1015547) Extensive vehicle damage/erosion	CONDITION:	Generally satisfactory but with significant localised problems
Extensive vehicle damage/erosion		but with significant localised problems
-	TREND:	
-	TREND:	Declining
Private		0
	CONTACT:	Business Manager 0117 975 0700
West Kennett Farm palisaded enclosures, Aveb	ury	
Scheduled Monument (No. 1015157)	CONDITION:	Extensive significant problems
Arable ploughing	TREND:	Unknown
Private	CONTACT:	Business Manager 0117 975 0700
Grovely Ditch, Barford St Martin		
Scheduled Monument (No. 1005584)	CONDITION:	Generally unsatisfactory
	CONDITION.	with major localised problems
Arable ploughing	TREND:	Unknown
Private	CONTACT:	Business Manager 0117 975 0700
Berwick Coombe ditch, Berwick St John		
Scheduled Monument (No. 1005587)	CONDITION:	Generally satisfactory
		but with minor localised problems
Arable clipping	TREND:	Declining
Private	CONTACT:	Business Manager 0117 975 0700
Bowl barrow west of Rotherley Wood, 750m V	VNW of Park	Cottage, Berwick St John
Scheduled Monument (No. 1020464)	CONDITION	Extensive significant problems
		Unknown
Private	CONTACT:	Business Manager 0117 975 0700
Winkelbury Hill earthworks, Berwick St John		
	CONDITION	Generally unsatisfactory
	CONDITION:	Generally unsatisfactory with major localised problems
Arable ploughing	TREND	Unknown
		Business Manager 0117 975 0700
	Scheduled Monument (No. 1015157) Arable ploughing Private Grovely Ditch, Barford St Martin Scheduled Monument (No. 1005584) Arable ploughing Private Berwick Coombe ditch, Berwick St John Scheduled Monument (No. 1005587) Arable clipping Private Bowl barrow west of Rotherley Wood, 750m V Scheduled Monument (No. 1020464) Arable ploughing Private	Scheduled Monument (No. 1015157) CONDITION: Arable ploughing TREND: Private CONTACT: Grovely Ditch, Barford St Martin CONDITION: Scheduled Monument (No. 1005584) CONDITION: Arable ploughing TREND: Private CONTACT: Berwick Coombe ditch, Berwick St John CONDITION: Scheduled Monument (No. 1005587) CONDITION: Arable clipping TREND: Private CONTACT: Bowl barrow west of Rotherley Wood, 750m WW of Park Scheduled Monument (No. 1020464) CONDITION: Arable ploughing TREND: Private CONTACT: Minkelbury Hill earthworks, Berwick St John Scheduled Monument (No. 1005585) CONDITION:

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Winkelbury Hill round barrows, Berwick St	: John		
DESIGNATION:	Scheduled Monument (No. 1003002)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
OWNER TYPE:	Private	CONTACT:	Business Manage	er 0117 975 0700
TE NAME:	Bell barrow situated between Bishop's Can	nings Down and E	aston Down, Bisho	ops Cannings
ESIGNATION:	Scheduled Monument (No. 1013229)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
WNER TYPE:	Government or Agency	CONTACT:	Business Manage	er 0117 975 0700
ITE NAME:	Bowl barrow 1070m NNW of Baltic Farm f on North Down, Bishops Cannings	orming part of a b	parrow cemetery	
ESIGNATION:	Scheduled Monument (No. 1013772)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
WNER TYPE:	Government or Agency	CONTACT:	Business Manage	er 0117 975 0700
TE NAME:	Bowl barrow I 50m east of the wireless stat	tion on Morgan's I	Hill, Bishops Canni	ngs
		-		-
ESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1014040) Arable ploughing	CONDITION: TREND:	Extensive signific Unknown	
RINCIPAL VULNERABILITY:	Government or Agency	CONTACT:		er 0117 975 0700
WINER TIFE.	dovernment of Agency	CONIACI.	Dusiness Filanage	
TE NAME:	Bowl barrow 300m east of Furze Knoll, Bis	hops Cannings		
ESIGNATION:	Scheduled Monument (No. 1013068)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
WNER TYPE:	Government or Agency	CONTACT:	Business Manage	er 0117 975 0700
TE NAME:	Bowl barrow 550m north east of Baltic Far	m, Bishops Cannir	ıgs	
ESIGNATION:	Scheduled Monument (No. 1012629)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
WNER TYPE:	Government or Agency	CONTACT:		er 0117 975 0700
TE NAME:	Bowl barrow 840m north east of Baltic Far	m. Bishops Cannir	ngs	
ESIGNATION:	Scheduled Monument (No. 1013066)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
WNER TYPE:	Government or Agency	CONTACT:		er 0117 975 0700
				, , ,
TE NAME:	Bowl barrow 950m SSW of Beckhampton F forming part of a round barrow cemetery of	,	Bishops Cannings	
ESIGNATION:	Scheduled Monument (No. 1012983)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
WNER TYPE:	Government or Agency	CONTACT:		er 0117 975 0700
	5 /		0	
TE NAME:	Bowl barrow at east end of Morgan's Hill, E	Bishops Cannings		
ESIGNATION:	Scheduled Monument (No. 1013070)	CONDITION:	Extensive signific	cant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
WNER TYPE:	Government or Agency	CONTACT:	Business Manage	er 0117 975 0700
TE NAME:	Bowl barrow situated 500m SSW of Shephe	erds' Shore, Bishop	os Cannings	
ESIGNATION:	Scheduled Monument (No. 1013756)	CONDITION:	Extensive signific	ant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
WNER TYPE:	Government or Agency	CONTACT:	Business Manage	er 0117 975 0700
IORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; no solution agreed.	D Slow decay; solution agreed but not yet implemented.       F       Repair scheme i and (where app end use or user functionally redu- vith new use agr under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).	licable) If the identified; has cl indant buildings regist greed but not is give	E: priority category nanged since the 2010 er, the previous category en in brackets.	ABBREVIATIONS CA Conservation Area LB/LBs Listed Building/s LPA Local Planning Authorit NP National Park RPG Registered Park and Ga SM/SMs Scheduled Monument/s UA Unitary Authority WHS World Heritage Site

DITE NAME:	Eleven round barrows 1000m north of Balti and a probable enclosed Iron Age farmstead		
DESIGNATION:	Scheduled Monument (No. 1013773)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Enclosed Iron Age farmstead 450m south o	f Down Barn on I	Bishop's Cannings Down, Bishops Canning
DESIGNATION:	Scheduled Monument (No. 1013230)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Four bowl barrows forming part of a ceme 270m east of long barrow on Roughridge H		ngs
DESIGNATION:	Scheduled Monument (No. 1014027)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of small enclosures on Horton Dow 910m north east of Easton Down long barr		ings
DESIGNATION:	Scheduled Monument (No. 1014561)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
			5
SITE NAME:	Group of three bowl barrows 250m north	east of Shepherds	s' Shore, Bishops Cannings
DESIGNATION:	Scheduled Monument (No. 1013232)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Kitchen Barrow: a long barrow on Kitchen	Barrow Hill, Bisho	ops Cannings
DESIGNATION:	Scheduled Monument (No. 1012519)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
	····· ·· ·· ·· ·· ·· ·· ·· ·· ·· ·· ··		
SITE NAME:	Linear earthworks forming part of a field sy	vstem on Bishop's	Cannings Down, Bishops Cannings
DESIGNATION:	Scheduled Monument (No. 1013233)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Long barrow 650m WSW of Shepherds' Sho	ore, Bishops Cann	ings
designation:	Scheduled Monument (No. 1014030)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
			U C
SITE NAME:	Long barrow on Easton Down, Bishops Car	nings	
DESIGNATION:	Scheduled Monument (No. 1013366)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
FRINCIPAL VULINERABILITT:	-	I RENU:	-
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Long barrow on Horton Down, Bishops Ca	annings	
DESIGNATION:	Scheduled Monument (No. 1013141)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Roundway Hill Farm round barrows, Bishop	os Cannings	
DESIGNATION:	Scheduled Monument (No. 1004773)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Saucer barrow 600m west of Beckhampton	ı Buildings, Bishop	s Cannings
DESIGNATION:	Scheduled Monument (No. 1012193)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Saucer barrow on North Down, Bishops C	annings	
DESIGNATION:	Scheduled Monument (No. 1012627)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
	Square enclosure 350m north of Wansdyke	on Bishon's Can	nings Down Bichops Cannings
SITE NAME:	· · ·	•	
DESIGNATION:	Scheduled Monument (No. 1013231)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
	Two saucer barrows and a pair of bowl bar	rows 750m SSW	
site name:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery o	rows 750m SSW	of Beckhampton Plantation, Bishops Cannings
SITE NAME: DESIGNATION:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982)	rows 750m SSW o on Horton Down,	of Beckhampton Plantation,
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery o	rows 750m SSW on Horton Down, condition:	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency	condition: condition: trend: contact:	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency Croucheston Down Barn round barrow, Bis	rows 750m SSW on Horton Down, Condition: TREND: CONTACT: shopstone	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency Croucheston Down Barn round barrow, Bis Scheduled Monument (No. 1004772)	rows 750m SSW on Horton Down, CONDITION: TREND: CONTACT: shopstone CONDITION:	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700 Extensive significant problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency Croucheston Down Barn round barrow, Bis	rows 750m SSW on Horton Down, Condition: TREND: CONTACT: shopstone	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700 Extensive significant problems Declining
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency         Croucheston Down Barn round barrow, Bis Scheduled Monument (No. 1004772) Arable ploughing Private	condition: condition: trend: contact: shopstone condition: trend: contact:	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency         Croucheston Down Barn round barrow, Bis Scheduled Monument (No. 1004772) Arable ploughing Private         Knighton Roman road (stretching from Record)	condition: TREND: CONDITION: TREND: CONTACT: shopstone CONDITION: TREND: CONTACT: ddish Gore to rese	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 ervoir), Bishopstone
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency         Croucheston Down Barn round barrow, Bis Scheduled Monument (No. 1004772) Arable ploughing Private	condition: condition: trend: contact: shopstone condition: trend: contact:	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency         Croucheston Down Barn round barrow, Bis Scheduled Monument (No. 1004772) Arable ploughing Private         Knighton Roman road (stretching from Record)	condition: TREND: CONDITION: TREND: CONTACT: shopstone CONDITION: TREND: CONTACT: ddish Gore to rese	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 ervoir), Bishopstone Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982)         Arable clipping         Government or Agency         Croucheston Down Barn round barrow, Bis         Scheduled Monument (No. 1004772)         Arable ploughing         Private         Knighton Roman road (stretching from Records)         Scheduled Monument (No. 1003728)	condition: condition: TREND: contact: shopstone condition: TREND: contact: dish Gore to rese	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 ervoir), Bishopstone Generally unsatisfactory with major localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency         Croucheston Down Barn round barrow, Bis Scheduled Monument (No. 1004772) Arable ploughing Private         Knighton Roman road (stretching from Reconstruction Scheduled Monument (No. 1003728)         Arable ploughing Private	condition: TREND: CONDITION: TREND: CONTACT: shopstone CONDITION: TREND: CONTACT: ddish Gore to reso CONDITION: TREND: CONTACT:	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 ervoir), Bishopstone Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: SITE NAME:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency         Croucheston Down Barn round barrow, Bis Scheduled Monument (No. 1004772) Arable ploughing Private         Knighton Roman road (stretching from Rec Scheduled Monument (No. 1003728)         Arable ploughing Private         Bowl barrow 85m north of Bishopstrow Here	rows 750m SSW on Horton Down, CONDITION: TREND: CONTACT: shopstone CONDITION: TREND: CONTACT: ddish Gore to reso CONDITION: TREND: CONTACT:	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 ervoir), Bishopstone Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency         Croucheston Down Barn round barrow, Bis Scheduled Monument (No. 1004772) Arable ploughing Private         Knighton Roman road (stretching from Reconstruction Scheduled Monument (No. 1003728)         Arable ploughing Private	condition: TREND: CONDITION: TREND: CONTACT: shopstone CONDITION: TREND: CONTACT: ddish Gore to reso CONDITION: TREND: CONTACT:	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 Ervoir), Bishopstone Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Two saucer barrows and a pair of bowl bar forming part of a round barrow cemetery of Scheduled Monument (No. 1012982) Arable clipping Government or Agency         Croucheston Down Barn round barrow, Bis Scheduled Monument (No. 1004772) Arable ploughing Private         Knighton Roman road (stretching from Rec Scheduled Monument (No. 1003728)         Arable ploughing Private         Bowl barrow 85m north of Bishopstrow Here	rows 750m SSW on Horton Down, CONDITION: TREND: CONTACT: shopstone CONDITION: TREND: CONTACT: ddish Gore to reso CONDITION: TREND: CONTACT:	of Beckhampton Plantation, Bishops Cannings Extensive significant problems Unknown Business Manager 0117 975 0700 Extensive significant problems Declining Business Manager 0117 975 0700 ervoir), Bishopstone Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Enclosure and linear earthworks between B	ishopstrow Dowi	and south Down sleight, bishopstrow
DESIGNATION:	Scheduled Monument (No. 1010283)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Woodminton Down round barrow, Bower (	Chalke	
DESIGNATION:	Scheduled Monument (No. 1003729)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Corton long barrow, Boyton		
DESIGNATION:	Scheduled Monument (No. 1010518)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Long barrow 250m east of Boyton Field Bar	n, Boyton	
DESIGNATION:	Scheduled Monument (No. 1010520)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Scrubbed Oak enclosure and linear bounda	ry earthwork, Boy	rton
DESIGNATION:	Scheduled Monument (No. 1017713)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow on Cold Kitchen Hill, 740m no	orth east of Seagr	am's Barn, Brixton Deverill
DESIGNATION:	Scheduled Monument (No. 1016908)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing		, ,
		TREND:	Unknown
OWNER TYPE:	Private	TREND: CONTACT:	Unknown Business Manager 0117 975 0700
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	Private Bowl barrow on Cold Kitchen Hill, 910m no	CONTACT:	Business Manager 0117 975 0700 ram's Barn, Brixton Deverill
SITE NAME:	Private Bowl barrow on Cold Kitchen Hill, 910m no Scheduled Monument (No. 1016909)	CONTACT:	Business Manager 0117 975 0700 am's Barn, Brixton Deverill Extensive significant problems
SITE NAME: DESIGNATION:	Private Bowl barrow on Cold Kitchen Hill, 910m nd Scheduled Monument (No. 1016909) Arable ploughing	CONTACT:	Business Manager 0117 975 0700 am's Barn, Brixton Deverill Extensive significant problems Unknown
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Bowl barrow on Cold Kitchen Hill, 910m no Scheduled Monument (No. 1016909)	CONTACT: Drth east of Seagr CONDITION:	Business Manager 0117 975 0700 am's Barn, Brixton Deverill Extensive significant problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Bowl barrow on Cold Kitchen Hill, 910m nd Scheduled Monument (No. 1016909) Arable ploughing	CONTACT: TREND: CONDITION: CONTACT:	Business Manager 0117 975 0700 am's Barn, Brixton Deverill Extensive significant problems Unknown Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private Bowl barrow on Cold Kitchen Hill, 910m nd Scheduled Monument (No. 1016909) Arable ploughing Private	CONTACT: TREND: CONDITION: CONTACT:	Business Manager 0117 975 0700 am's Barn, Brixton Deverill Extensive significant problems Unknown Business Manager 0117 975 0700 er Pertwood, Brixton Deverill Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Private Bowl barrow on Cold Kitchen Hill, 910m nd Scheduled Monument (No. 1016909) Arable ploughing Private Long barrow on Pertwood Down, 1400m nd Scheduled Monument (No. 1010463)	CONTACT: orth east of Seagr CONDITION: TREND: CONTACT: orth west of Lower	Business Manager 0117 975 0700 am's Barn, Brixton Deverill Extensive significant problems Unknown Business Manager 0117 975 0700 er Pertwood, Brixton Deverill Generally satisfactory but with significant localised problems
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Bowl barrow on Cold Kitchen Hill, 910m nd Scheduled Monument (No. 1016909) Arable ploughing Private Long barrow on Pertwood Down, 1400m nd	CONTACT: orth east of Seagr CONDITION: TREND: CONTACT: orth west of Low CONDITION:	Business Manager 0117 975 0700 am's Barn, Brixton Deverill Extensive significant problems Unknown Business Manager 0117 975 0700 er Pertwood, Brixton Deverill Generally satisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private Bowl barrow on Cold Kitchen Hill, 910m nd Scheduled Monument (No. 1016909) Arable ploughing Private Long barrow on Pertwood Down, 1400m nd Scheduled Monument (No. 1010463) Extensive animal burrowing	CONTACT: orth east of Seagr CONDITION: TREND: CONTACT: orth west of Lowe CONDITION: TREND:	Business Manager 0117 975 0700 am's Barn, Brixton Deverill Extensive significant problems Unknown Business Manager 0117 975 0700 er Pertwood, Brixton Deverill Generally satisfactory but with significant localised problems Declining
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private Bowl barrow on Cold Kitchen Hill, 910m nd Scheduled Monument (No. 1016909) Arable ploughing Private Long barrow on Pertwood Down, 1400m nd Scheduled Monument (No. 1010463) Extensive animal burrowing Private Knowle Hill round barrow, Broad Chalke	CONTACT: orth east of Seagr CONDITION: TREND: CONTACT: orth west of Lowe CONDITION: TREND:	Business Manager 0117 975 0700 am's Barn, Brixton Deverill Extensive significant problems Unknown Business Manager 0117 975 0700 er Pertwood, Brixton Deverill Generally satisfactory but with significant localised problems Declining Business Manager 0117 975 0700
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private Bowl barrow on Cold Kitchen Hill, 910m nd Scheduled Monument (No. 1016909) Arable ploughing Private Long barrow on Pertwood Down, 1400m nd Scheduled Monument (No. 1010463) Extensive animal burrowing Private	CONTACT: orth east of Seagr CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONTACT:	Business Manager 0117 975 0700 am's Barn, Brixton Deverill Extensive significant problems Unknown Business Manager 0117 975 0700 er Pertwood, Brixton Deverill Generally satisfactory but with significant localised problems Declining

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Round barrow 860yds (786m) south east o	of Knighton Hill Bu	ildings, Broad Chalke
DESIGNATION:	Scheduled Monument (No. 1004771)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Roman road in Spye Park, Bromham		
DESIGNATION:	Scheduled Monument (No. 1003010)	CONDITION:	Generally unsatisfactory
		Condition	with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	A group of five bowl barrows south of Bulford Camp, Bulford		
DESIGNATION:	Scheduled Monument (No. 1009576)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bell barrow 770m north west of New Barr	n, Bulford	
	Scheduled Monument (No. 1015214)		Generally unsatisfactory
DESIGNATION:	Scheduled Monument (No. 1015216)	CONDITION:	Generally unsatisfactory with major localised problems
	Arable clipping	TRENE	With major localised problems Unknown
PRINCIPAL VULNERABILITY:	Private	TREND:	Business Manager 0117 975 0700
OWNER TYPE:	TIVALE	CONTACT:	
SITE NAME:	Bowl barrow: one of a group of round barr	rows south of Bulf	ord, Bulford
DESIGNATION:	Scheduled Monument (No. 1009545)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow: one of a group of round barr	rows south of Bulf	ord. Bulford
DESIGNATION:	Scheduled Monument (No. 1009602)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow: one of a group of round barr	ows south of Bulf	ord, Bulford
DESIGNATION:	Scheduled Monument (No. 1009604)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow: one of a group of round barr	rows south of Bulf	ord Bulford
STILL IN VILLE			
DESIGNATION:	Scheduled Monument (No. 1009564)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow: one of a group of round barr	ows south of Bulf	ord, Bulford
DESIGNATION:	Scheduled Monument (No. 1009605)	CONDITION:	Generally unsatisfactory
		CONDITION:	with major localised problems
	Ample plaughing		Declining
PRINCIPAL VUL NER ARIUTY		I REVILY	
PRINCIPAL VULNERABILITY:	Arable ploughing Government or Agency	TREND: CONTACT:	Business Manager 0117 975 0700

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Nuthills Roman villa, Calne Without		
DESIGNATION:	Scheduled Monument (No. 1004723)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Long barrow 240m south west of Green Bar	row Farm, Castl	e Combe
DESIGNATION:	Scheduled Monument (No. 1018419)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 190m north east of Nolands Farm, Yatesbury, Cherhill		
DESIGNATION:	Scheduled Monument (No. 1015808)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 350m north east of White Hor	rse Plantation, C	herhill
DESIGNATION:	Scheduled Monument (No. 1010134)	CONDITION:	Generally unsatisfactory
SESIGRATION.		CONDITION:	with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			-
SITE NAME:	Bowl barrow 700m south east of Field Barn,	Chicklade	
DESIGNATION:	Scheduled Monument (No. 1015937)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow on Berril Down, Chitterne		
DESIGNATION:	Scheduled Monument (No. 1009589)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Fussell's long barrow, Clarendon Park		
DESIGNATION:	Scheduled Monument (No. 1005611)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl Barrow, part of the round barrow cem	etery south of C	Codford Down, Codford
DESIGNATION:	Scheduled Monument (No. 1016557)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Three bowl barrows in Colerne Park, 450m	north of Keeper	-
DESIGNATION:	Scheduled Monument (No. 1010758)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

DESIGNATION:	Scheduled Monument (No. 1012510)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 650m east of Summer Down	Farm, Collingbour	ne Kingston
DESIGNATION:	Scheduled Monument (No. 1012544)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Crowdown Clump earthwork (Godsbury),	Collingbourne Kir	ngston
DESIGNATION:	Scheduled Monument (No. 1004759)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two bowl barrows 400m south of Summer	Down Farm, Coll	ingbourne Kingston
DESIGNATION:	Scheduled Monument (No. 1012518)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 430m north west of Northdo	own Barn, Coombe	e Bissett
DESIGNATION:	Scheduled Monument (No. 1017705)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow on Little Toyd Down, 650m so	outh west of Grim	is Lodge Farm, Coombe Bissett
DESIGNATION:	Scheduled Monument (No. 1015704)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Moated site and surrounding earthwork en	closure, 100m sou	th of Chelworth Farm, Cricklade
DESIGNATION:	Scheduled Monument (No. 1013353)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Long barrow on Ashmore Down, 775m noi	rth of Ashgrove C	ottages, Donhead St Mary
DESIGNATION:	Scheduled Monument (No. 1015938)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Clearbury Down round barrow, Downton		
DESIGNATION:	Scheduled Monument (No. 1003003)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Trivate	CONTACT.	

PRIORITY (FOR BUILDINGS)
 A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decays as calculate agreed.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Long barrow 600yds (550m) south east of	Vanity, Downton	
DESIGNATION:	Scheduled Monument (No. 1003004)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			Ŭ
ITE NAME:	Wick Down round barrow, Downton		
DESIGNATION:	Scheduled Monument (No. 1004776)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Ogbury camp, Durnford		
DESIGNATION:	Scheduled Monument (No. 1005677)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
DITE NAME:	Nine round barrows forming a round barro 400m north of the eastern end of The Cur		
DESIGNATION:	Scheduled Monument (No. 1009067)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Improving
DWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow I20m west of East Kennett Io	ng barrow forming	g part of a cemetery, East Kennett
DESIGNATION:	Scheduled Monument (No. 1014035)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 200m east of East Kennett long barrow forming part of a barrow cemetery, East Kennett		
DESIGNATION:	Scheduled Monument (No. 1014036)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 200m north of East Kennett I	ong barrow formi	ng part of a cemetery, East Kennett
DESIGNATION:	Scheduled Monument (No. 1014038)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 40m north west of East Kennett long barrow forming part of a cemetery, East Kennett		
DESIGNATION:	Scheduled Monument (No. 1014037)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 50m north east of East Kenne	ett long barrow fo	rming part of a cemetery, East Kennett
SITE NAME: DESIGNATION:	Bowl barrow 50m north east of East Kenne Scheduled Monument (No. 1014039)	ett long barrow fo	rming part of a cemetery, East Kennett Extensive significant problems
		-	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Easton Clump settlement, Easton			
DESIGNATION:	Scheduled Monument (No. 1004761)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Improving	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Round barrow on Easton Down, Easton			
DESIGNATION:	Scheduled Monument (No. 1005693)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Medieval moated site and Romano-British settlement at White Walls Wood, Easton Grey			
DESIGNATION:	Scheduled Monument (No. 1013354)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Barrow on Fifield Down 700yds (640m) ESE	of North Barn, I	Ebbesborne Wake	
DESIGNATION:	Scheduled Monument (No. 1003744)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Edington Priory (site of), Edington			
DESIGNATION:	Scheduled Monument (No. 1004709)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Long barrow, Tinhead Hill, Edington			
DESIGNATION:	Scheduled Monument (No. 1009783)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive natural erosion	TREND:	Declining	
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Round barrow south west of Compton Farm, Enford			
DESIGNATION:	Scheduled Monument (No. 1017936)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining	
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Bowl barrow north east of Everleigh Ashes,	Everleigh		
DESIGNATION:	Scheduled Monument (No. 1009557)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700	
SITE NAME:	Barrow Clump, bowl barrow, east of Ablingto	on, Figheldean		
DESIGNATION:	Scheduled Monument (No. 1009697)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining	
	Government or Agency		Business Manager 0117 975 0700	

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Three round barrows west of Netheravon A	erodrome, Fittlet	ton
DESIGNATION:	Scheduled Monument (No. 1010192)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 540m north of Woodbine Barn	, Fonthill Bishop	
DESIGNATION:	Scheduled Monument (No. 1015943)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 100m north of Great Botley Co	opse, Grafton	
designation:	Scheduled Monument (No. 1012301)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		contract.	
ITE NAME:	Great Botley Copse long barrow, and disc ba	rrow near it, Gr	afton
DESIGNATION:	Scheduled Monument (No. 1005692)	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	North Hill round barrows, Grafton		
DESIGNATION:	Scheduled Monument (No. 1004746)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Romano-British kilns 150yds (135m) SSW of <sup>-</sup>	Tottenham Hous	e, Great Bedwyn
DESIGNATION:	Scheduled Monument (No. 1004706)	CONDITION:	Generally unsatisfactory
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	with major localised problems Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		contracti	
SITE NAME:	Grovely Castle and earthworks north of Gro	vely Wood, Grea	at Wishford
DESIGNATION:	Scheduled Monument (No. 1005604)	CONDITION:	Generally unsatisfactory
	Arable ploughing		with major localised problems Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing Private	TREND: CONTACT:	Business Manager 0117 975 0700
Swiner TIFE.	Thvate	CONTACT.	
SITE NAME:	Bowl barrow 340m east of Holly Bush Farm,	Grittleton	
DESIGNATION:	Scheduled Monument (No. 1018418)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Medieval settlement immediately north west	of Upper Littlec	ott Farm, Hilmarton
DESIGNATION:	Scheduled Monument (No. 1018420)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
RIORITY (FOR BUILDINGS)         Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.         Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.         Slow decay; no solution agreed.	<ul> <li>D Slow decay; solution agreed but not yet implemented.</li> <li>F Repair scheme in p and (where applica end use or user ide repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).</li> </ul>	ble) If the entified; has ch ant buildings registe	E: CA Conservation Area priority category hanged since the 2010 m in brackets. CA Conservation Area LB/LBs Listed Building/s LPA Local Planning Authorit NP National Park RPG Registered Park and Ga SM/SMs Scheduled Monument/s UA Unitary Authority WHS World Heritage Site

	Bell barrow 250m NNE of the sports groun one of a group of round barrows north we		wn, Idmiston
DESIGNATION:	Scheduled Monument (No. 1013971)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
	Government or Agency		Business Manager 0117 975 0700
WNER TYPE:	Government of Agency	CONTACT:	Business Manager 0117 775 0700
TE NAME:	Bell barrow, bowl barrow and section of ho	llow way 600m N	NW of Long Orchard, Idmiston
DESIGNATION:	Scheduled Monument (No. 1013983)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
WNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
TE NAME:	Bell barrow, three bowl barrows and gas te	sting trenches on	Idmiston Down, Idmiston
DESIGNATION:	Scheduled Monument (No. 1014818)	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
	5 /		0
TE NAME:	Bowl barrow 260m SSE of the southern co one of a group of round barrows on Porto		is's Clump:
DESIGNATION:	Scheduled Monument (No. 1014096)	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
WNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
WVINEN I I F E.	Government of Agency	CONIACI.	
ITE NAME:	Bowl barrow 440m SSW of the southern co one of a group of round barrows on Porto		
ESIGNATION:			
DESIGNATION:	Scheduled Monument (No. 1014094)	CONDITION:	Generally unsatisfactory
	Scheduled Monument (No. 1014094)		
RINCIPAL VULNERABILITY:		CONDITION:	Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: TTE NAME:	Scheduled Monument (No. 1014094) Extensive animal burrowing Government or Agency	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
'RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1014094) Extensive animal burrowing Government or Agency Bowl barrow 530m SSW of the southern co one of a group of round barrows on Porto	CONDITION: TREND: CONTACT: Dorner of Moll Har	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump:
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Scheduled Monument (No. 1014094) Extensive animal burrowing Government or Agency Bowl barrow 530m SSW of the southern co	CONDITION: TREND: CONTACT: Dorner of Moll Har	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory
RINCIPAL VULNERABILITY: WWNER TYPE: ITE NAME: DESIGNATION:	Scheduled Monument (No. 1014094) Extensive animal burrowing Government or Agency Bowl barrow 530m SSW of the southern co one of a group of round barrows on Portor Scheduled Monument (No. 1014092)	CONDITION: TREND: CONTACT: TREND: CONTACT: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY: WNER TYPE: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1014094) Extensive animal burrowing Government or Agency Bowl barrow 530m SSW of the southern co one of a group of round barrows on Porton Scheduled Monument (No. 1014092) Extensive animal burrowing	CONDITION: TREND: CONTACT: Dorner of Moll Har n Down, Idmiston CONDITION: TREND:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining
RINCIPAL VULNERABILITY: WWNER TYPE: ITE NAME: PESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1014094) Extensive animal burrowing Government or Agency Bowl barrow 530m SSW of the southern co one of a group of round barrows on Portor Scheduled Monument (No. 1014092)	CONDITION: TREND: CONTACT: TREND: CONTACT: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining
RINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No. 1014094) Extensive animal burrowing Government or Agency Bowl barrow 530m SSW of the southern co one of a group of round barrows on Porton Scheduled Monument (No. 1014092) Extensive animal burrowing	CONDITION: TREND: CONTACT: Ormer of Moll Har n Down, Idmiston CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No. 1014094) Extensive animal burrowing Government or Agency Bowl barrow 530m SSW of the southern co one of a group of round barrows on Porton Scheduled Monument (No. 1014092) Extensive animal burrowing Government or Agency Bowl barrow 535m SSW of the southern co	CONDITION: TREND: CONTACT: Ormer of Moll Har n Down, Idmiston CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
RINCIPAL VULNERABILITY: WWNER TYPE: ITE NAME: ESIGNATION: WWNER TYPE: ITE NAME: ESIGNATION:	Scheduled Monument (No. 1014094)         Extensive animal burrowing         Government or Agency         Bowl barrow 530m SSW of the southern coone of a group of round barrows on Porton         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern coone of a group of round barrows on Porton         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern coone of a group of round barrows on Porton         Scheduled Monument (No. 1014093)	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Scheduled Monument (No. 1014094)         Extensive animal burrowing         Government or Agency         Bowl barrow 530m SSW of the southern composition on of a group of round barrows on Porton         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern composition         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern composition         Scheduled Monument (No. 1014093)         Extensive animal burrowing	CONDITION: TREND: CONTACT: TREND: CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1014094)         Extensive animal burrowing         Government or Agency         Bowl barrow 530m SSW of the southern coone of a group of round barrows on Porton         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern coone of a group of round barrows on Porton         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern coone of a group of round barrows on Porton         Scheduled Monument (No. 1014093)	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONDITION: CONDITION: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument (No. 1014094)         Extensive animal burrowing         Government or Agency         Bowl barrow 530m SSW of the southern composition on of a group of round barrows on Porton         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern composition         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern composition         Scheduled Monument (No. 1014093)         Extensive animal burrowing	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: DWNER TYPE:	Scheduled Monument (No. 1014094)         Extensive animal burrowing         Government or Agency         Bowl barrow 530m SSW of the southern coone of a group of round barrows on Portor         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern coone of a group of round barrows on Portor         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern coone of a group of round barrows on Portor         Scheduled Monument (No. 1014093)         Extensive animal burrowing         Government or Agency         Bronze Age enclosure and two bowl barrow	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700
RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME: RINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Scheduled Monument (No. 1014094)         Extensive animal burrowing         Government or Agency         Bowl barrow 530m SSW of the southern coone of a group of round barrows on Portor         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern coone of a group of round barrows on Portor         Scheduled Monument (No. 1014092)         Extensive animal burrowing         Government or Agency         Bowl barrow 535m SSW of the southern coone of a group of round barrows on Portor         Scheduled Monument (No. 1014093)         Extensive animal burrowing         Government or Agency         Bronze Age enclosure and two bowl barrow         S20m north east of Moll Harris's Clump on	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION:	Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 ris's Clump: Generally unsatisfactory with major localised problems Declining Business Manager 0117 975 0700 Idmiston Generally unsatisfactory

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

WVNER TYPE:	Scheduled Monument (No. 1014089) Extensive animal burrowing	CONDITION:	Generally unsatisfactory with major localised problems
	~		·····
WWNER TYPE:	~	TREND:	Declining
ITE NAME:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Sauran hannour 100m namh annt af tha ann		
	Saucer barrow 400m north east of the spor one of a group of round barrows north we		wn, Idmiston
DESIGNATION:	Scheduled Monument (No. 1013970)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
ite name:	Two bowl barrows 265m south of the south part of a group of round barrows on Porto		
DESIGNATION:	Scheduled Monument (No. 1014095)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
DITE NAME:	Two disc barrows and two bowl barrows 90	00m north of Mol	I Harris's Clump on Idmiston Down, Idmi
DESIGNATION:	Scheduled Monument (No. 1015557)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Barrow north east of Mere Down Farm, Ki	ngston Deverill	
DESIGNATION:	Scheduled Monument (No. 1003005)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 140m west of Cleeve, Kingston	n Deverill	
DESIGNATION:	Scheduled Monument (No. 1015805)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 1480m east of Keysley Farm, k	Kingston Deverill	
DESIGNATION:	Scheduled Monument (No. 1019738)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow 200m south west of Keysley F	arm, Kingston De	verill
DESIGNATION:	Scheduled Monument (No. 1010405)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 670m SSE of Kingston Dairy, I	Kingston Deverill	
DESIGNATION:	Scheduled Monument (No. 1016903)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Expediate Content of the second of the secon

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

nerally unsatisfactory
h major localised problems
clining
iness Manager 0117 975 0700
ensive significant problems
clining
iness Manager 0117 975 0700
nerally satisfactory with significant localised problems
clining
iness Manager 0117 975 0700
er-Shaftesbury Road, Kingston Devei
nerally unsatisfactory
h major localised problems
clining
iness Manager 0117 975 0700
n Deverill
ensive significant problems
known
iness Manager 0117 975 0700
nerally unsatisfactory
h major localised problems
iness Manager 0117 975 0700
nerally satisfactory
with significant localised problems
clining
iness Manager 0117 975 0700
ensive significant problems
known
iness Manager 0117 975 0700
ensive significant problems
clining
iness Manager 0117 975 0700
e

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Medieval pottery kilns, Milford Farm, Lavers	stock	
DESIGNATION:	Scheduled Monument (No. 1003252)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bell barrow on Rook Hill, 200m west of Pe	rtwood Wood, Lo	ngbridge Deverill
DESIGNATION:	Scheduled Monument (No. 1010470)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Round barrow south west of Parsonage Do	own, Longbridge D	Deverill
DESIGNATION:	Scheduled Monument (No. 1005622)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Long barrow 600m north of Hebden Farm,	, Luckington	
DESIGNATION:	Scheduled Monument (No. 1010395)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Enclosure on the summit of Rodmead Hill,	Maiden Bradley w	ith Yarnfield
DESIGNATION:	Scheduled Monument (No. 1017704)	CONDITION:	Generally satisfactory
			but with significant localised problems
RINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two saucer barrows 775m south east of R	odmead Farm, Mai	den Bradley with Yarnfield
DESIGNATION:	Scheduled Monument (No. 1017697)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bohune Down round barrow, Manningford		
DESIGNATION:	Scheduled Monument (No. 1003036)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Two bowl barrows north of Rowbury Lane	, Market Lavingtor	1
DESIGNATION:	Scheduled Monument (No. 1012191)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
	Bowl barrow 190m north east of Burton Fa	arm, Mere	
SITE NAME:		CONDITION:	Generally unsatisfactory
SITE NAME: DESIGNATION:	Scheduled Monument (No. 1017711)	CONDITION.	with major localised problems
	Scheduled Monument (No. 1017711) Arable clipping	TREND:	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Bowl barrow 760m north west of The Dov	vn House, Mere	
DESIGNATION:	Scheduled Monument (No. 1016300)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Pond Bottom round barrow, Mere		
DESIGNATION:	Scheduled Monument (No. 1005620)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two round barrows in Chaddenwick Furze	, Mere	
DESIGNATION:	Scheduled Monument (No. 1015945)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Black Field Roman site, Mildenhall		
DESIGNATION:	Scheduled Monument (No. 1004726)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 800m south east of Ogbourn	e St Andrew Farm	ı, Mildenhall
DESIGNATION:	Scheduled Monument (No. 1012296)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Camp on Forest Hill, Mildenhall		
DESIGNATION:	Scheduled Monument (No. 1004697)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow: one of three round barrows	west of The Belt,	Milston
DESIGNATION:	Scheduled Monument (No. 1009636)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 200m north east of Everleigh	Ashes, Milton Lilb	ourne
DESIGNATION:	Scheduled Monument (No. 1009543)	CONDITION:	Generally satisfactory
	Ample dissing		but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown Rusinger Managor 0117 975 0700
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Roman tile and brick kiln site 1000yds (900	m) west of Tidling	g Corner, Minety
DESIGNATION:	Scheduled Monument (No. 1004702)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bowl barrow 900m north of Down Farm, N	Nettleton	
DESIGNATION:	Scheduled Monument (No. 1018391)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Long barrow 400m north west of Fox Cov	ert, Nettleton	
designation:	Scheduled Monument (No. 1010396)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Long barrow 500m north of Lugbury Farm	, Nettleton	
DESIGNATION:	Scheduled Monument (No. 1010397)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SWINERT IT E.	Thrace	CONTACT.	
ITE NAME:	Early medieval settlement, palace, church ar	nd Bronze Age ring	g ditches 340m east of Cowage Farm, N
DESIGNATION:	Scheduled Monument (No. 1018389)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow: one of a group of dispersed l	parrows south eas	t of Norton Plantation, Norton Bavant
designation:	Scheduled Monument (No. 1009830)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow on the south side of Cotley	Hill, Norton Bava	Int
DESIGNATION:	, Scheduled Monument (No. 1009835)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SWINER I IFE.	Government of 7 gency	CONTACT.	
SITE NAME:	Barrow on Coombe Down,1070yds (980m	) north east of Up	oper Poughcombe, Ogbourne St Andrev
DESIGNATION:	Scheduled Monument (No. 1005670)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Barrow on Smeathe's Ridge, Ogbourne St A	ndrew	
DESIGNATION:	Scheduled Monument (No. 1005679)	CONDITION:	Extensive significant problems
	Arable ploughing	TREND:	Unknown
"RINCIPAL VULINERABILI I T:	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Bell barrow 200m north of Rockley Plantat	ion, Ogbourne St	Andrew
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:		ion, Ogbourne St	
OWNER TYPE:	<b>Bell barrow 200m north of Rockley Plantat</b> Scheduled Monument (No. 1012195) Extensive animal burrowing	-	Andrew Extensive significant problems Declining

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Bowl barrow 375m east of Wick Bottom B	arn, Ogbourne St	Andrew
DESIGNATION:	Scheduled Monument (No. 1015814)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 630m north east of Wick Bo	tom Barn, Ogbou	rne St Andrew
DESIGNATION:	Scheduled Monument (No. 1015803)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
ITE NAME:	Bowl barrow and a saucer barrow 200m no	orth of Rockley Pl	antation, Ogbourne St Andrew
DESIGNATION:	Scheduled Monument (No. 1012197)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Ogbourne Maizey Down round barrow, Og	bourne St Andrev	v
DESIGNATION:	Scheduled Monument (No. 1004762)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow 750yds (690m) south east o	f Smeathe's Planta	tion, Ogbourne St Andrew
DESIGNATION:	Scheduled Monument (No. 1004733)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow SSE of Greenland Camp, Or	cheston	
designation:	Scheduled Monument (No. 1010023)	CONDITION:	Generally unsatisfactory
	×		with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow cemetery 320m south east	of Down Farm, Pe	wsey
DESIGNATION:	Scheduled Monument (No. 1016779)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	The Spectacles, Pewsey		
DESIGNATION:	Scheduled Monument (No. 1005638)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Long barrow, Winterbourne, Pitton and Far	ley	
DESIGNATION:	Scheduled Monument (No. 1005623)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
	Private	CONTACT:	Business Manager 0117 975 0700

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bell barrow 350m south west of Barbury B	arn, Preshute	
DESIGNATION:	Scheduled Monument (No. 1012190)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 300m east of Ivy House Farm	, Preshute	
DESIGNATION:	Scheduled Monument (No. 1012294)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Group of round barrows on Rough Hill, Pre	eshute	
DESIGNATION:	Scheduled Monument (No. 1003034)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Preshute Down field system, Preshute		
DESIGNATION:	Scheduled Monument (No. 1004763)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Sharpridge field system, Preshute		
DESIGNATION:	Scheduled Monument (No. 1004764)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Membury Camp (part in West Berkshire), F	amsbury	
DESIGNATION:	Scheduled Monument (No. 1002994)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 450m north of Cross Droves	Shalbourne	
	Scheduled Monument (No. 1012274)		Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	CONDITION: TREND:	Extensive significant problems Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Long barrow on Smay Down, 300m east of	The Hassock, Sha	lbourne
DESIGNATION:	Scheduled Monument (No. 1010467)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Wansdyke: Daniel's Lane section, Shalbourn	e	
DESIGNATION:	Scheduled Monument (No. 1005594)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
OWNERTHE.			
OWNERTH L.			

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Newton Barrow, South Newton		
DESIGNATION:	Scheduled Monument (No. 1005687)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Earthwork enclosure on Milk Hill, Stanton S	St Bernard	
DESIGNATION:	Scheduled Monument (No. 1004735)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Stapleford Castle, Stapleford		
DESIGNATION:	Scheduled Monument (No. 1005686)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Barrow north of 'The Spectacles', Steeple L	angford	
DESIGNATION:	Scheduled Monument (No. 1004742)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
			5
SITE NAME:	Bowl barrow 240m east of The Penning, Steeple Langford		
DESIGNATION:	Scheduled Monument (No. 1015025)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Deptford Down round barrow, Steeple Lan	gford	
DESIGNATION:	Scheduled Monument (No. 1005615)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	East Castle, Steeple Langford		
DESIGNATION:	Scheduled Monument (No. 1005599)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Little Langford round barrow, north of Upp	er Farm Down, St	eeple Langford
DESIGNATION:	Scheduled Monument (No. 1005605)	CONDITION:	Generally unsatisfactory
		CONDITION.	with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Round barrow 230yds (210m) north west o	of New Field Plant	ation, Steeple Langford
	$C_{\rm rel} = d_{\rm rel} = d_{\rm rel} = M_{\rm rel} = r_{\rm rel} + (N_{\rm rel} = 100472 {\rm F})$		Extensive significant problems
DESIGNATION:	Scheduled Monument (No. 1004725)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Orchard Castle, Stourton with Gasper		
DESIGNATION:	Scheduled Monument (No. 1005639)	CONDITION:	Generally unsatisfactory
	Deterioretica is accel of accessored		with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bell barrow 350m north of Haydon Farm, Su	itton Veny	
DESIGNATION:	Scheduled Monument (No. 1010517)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bell barrow on Parsonage Down, I.3km sout	h east of Lord's	Hill Farm, Sutton Veny
DESIGNATION:	Scheduled Monument (No. 1016677)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
		CONTACT.	
SITE NAME:	Bowl barrow on Littlecombe Down, Sutton	Veny	
DESIGNATION:	Scheduled Monument (No. 1005683)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Pair of bowl barrows 1050m NNW of Pertw	ood Wood, Sutto	on Veny
DESIGNATION:	Scheduled Monument (No. 1019739)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Fosbury camp, Tidcombe and Fosbury		
DESIGNATION:	Scheduled Monument (No. 1005682)	CONDITION:	Generally satisfactory
DESIGNATION:	Scheduled Hondment (No. 1005002)	CONDITION:	but with significant localised problems
	Localised/limited stock erosion	TREND:	Declining
PRINCIPAL VULNERABILITY:	Private		Business Manager 0117 975 0700
OWNER TYPE:	Trivate	CONTACT:	
SITE NAME:	Bowl barrow south east of Sidbury Hill, Tidw	vorth	
DESIGNATION:	Scheduled Monument (No. 1010022)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Castle Ditches camp, Tisbury		
DESIGNATION:	Scheduled Monument (No. 1005701)	CONDITION:	Generally satisfactory
		CONDITION.	but with significant localised problems
	Arable ploughing	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Private	CONTACT:	Business Manager 0117 975 0700
OWNER TYPE:	Romano-British villa complex 330m north w	rest of Queen Co	ourt Farm, Tockenham
OWNER TYPE:		rest of Queen Co	purt Farm, Tockenham Extensive significant problems
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Romano-British villa complex 330m north w		

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bowl barrow on Woodley Down 675m NN	IE of Ashmore Far	m,Tollard Royal
DESIGNATION:	Scheduled Monument (No. 1020465)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Casterley Camp and associated monument	s, Upavon	
DESIGNATION:	Scheduled Monument (No. 1010074)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Two saucer barrows 250m west of John's P	lanting, Upton Lov	vell
DESIGNATION:	Scheduled Monument (No. 1007564)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 500m south of Upton Scudan	nore, Upton Scuda	amore
	Scheduled Monument (No. 1010398)	•	Generally satisfactory
DESIGNATION:		CONDITION:	but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Barrow I/4 mile (400m) north west of Will	oughby Hedge, W	est Knoyle
DESIGNATION:	Scheduled Monument (No. 1005666)	CONDITION:	Generally satisfactory
			but with significant localised problems
RINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow in The Belt, 350m north east	of Hill Barn, West	Overton
DESIGNATION:	Scheduled Monument (No. 1019901)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 100m north of Rox Hill Clum	p. Wilsford cum L	ake
DESIGNATION:	Scheduled Monument (No. 1013813) Arable ploughing	CONDITION: TREND:	Extensive significant problems Unknown
PRINCIPAL VULNERABILITY:	Private		Business Manager 0117 975 0700
JVVINER I TPE:	TIVALE	CONTACT:	
SITE NAME:	Bowl barrow 250m south of Westfield Far	n buildings, Wilsfo	ord cum Lake
DESIGNATION:	Scheduled Monument (No. 1010835)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700
SITE NAME:	Bowl barrow 350m south west of Norman	ton Gorse, Wilsfo	rd cum Lake
DESIGNATION:	Scheduled Monument (No. 1013812)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
I NINCI AL VOLINEI ADIEI I I.			

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Bowl barrow 400m west of Normanton Ge	orse, Wilsford cun	n Lake		
DESIGNATION:	Scheduled Monument (No. 1010831)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Bowl barrow 450m east of The Diamond south of the A303, Wilsford cum Lake				
DESIGNATION:	Scheduled Monument (No. 1011709)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Bowl barrow 50m south west of Rox Hill C	Clump, Wilsford cu	um Lake		
DESIGNATION:	Scheduled Monument (No. 1010836)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Bowl barrow south of the A303 and north	west of Normant	on Gorse, Wilsford cum Lake		
DESIGNATION:	Scheduled Monument (No. 1010832)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Pond barrow south of the A303 and 400m west of Normanton Gorse containing the 'Wilsford Shaft', Wilsford cum Lake				
DESIGNATION:	Scheduled Monument (No. 1010833)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Seven bowl barrows and a pond barrow fo 200m north of The Diamond on Wilsford I	-			
DESIGNATION:	Scheduled Monument (No. 1010834)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Horse Barrow, Winterbourne				
DESIGNATION:	Scheduled Monument (No. 1005610)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700		
	Bowl barrow 350m north west of Greenland Farm, Winterbourne Stoke				
SITE NAME:	Bowl barrow 350m north west of Greenlar	nd Farm, Winterbo	burne stoke		
		,			
DESIGNATION:	Scheduled Monument (No. 1010892)	nd Farm, Winterbo condition: trend:	Extensive significant problems Unknown		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:		CONDITION:	Extensive significant problems Unknown		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1010892) Arable ploughing	CONDITION: TREND: CONTACT:	Extensive significant problems Unknown Business Manager 0117 975 0700		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1010892) Arable ploughing Private Bowl barrow 830m south west of Greenlar	CONDITION: TREND: CONTACT:	Extensive significant problems Unknown Business Manager 0117 975 0700		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1010892) Arable ploughing Private	CONDITION: TREND: CONTACT:	Extensive significant problems Unknown Business Manager 0117 975 0700 c of Shrewton, Winterbourne Stoke		

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bronze Age enclosure and bowl barrow 100m west of Longbarrow Cross Roads on Winterbourne Stoke Down, Winterbourne Stoke				
DESIGNATION:	Scheduled Monument (No. 1011048)	CONDITION:	Extensive significant problems		
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown		
WNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
ITE NAME:	Disc barrow and pond barrow 350m NNW of C	Greenland Farr	n, Winterbourne Stoke		
DESIGNATION:	Scheduled Monument (No. 1010891)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown		
DWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
ITE NAME:	Bell barrow and bowl barrow 500m NNW of Long Orchard, Winterslow				
DESIGNATION:	Scheduled Monument (No. 1013984)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining		
OWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Bowl barrow 750m NNE of Easton Down Farm	, Winterslow			
DESIGNATION:	Scheduled Monument (No. 1013986)	CONDITION:	Generally unsatisfactory		
	· /		with major localised problems		
RINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining		
DWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Heale Hill round barrows and earthworks, Woodford				
DESIGNATION:	Scheduled Monument (No. 1005609)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable		
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700		
SITE NAME:	Bowl barrow 175m west of Square Copse: part of the Square Copse barrow cemetery, Wootton Rivers				
DESIGNATION:	Scheduled Monument (No. 1013352)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700		
DITE NAME:	Bowl barrow 275m west of Square Copse: part	of the Square	Copse barrow cemetery, Wootton River		
DESIGNATION:	Scheduled Monument (No. 1013364)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNER TYPE:	Government or Agency	CONTACT:	Business Manager 0117 975 0700		
	SITE NAME Tottenham House and Savernake Forest, Burbage and Savernake	with orname	Extensive landscape of rides linking Savernake Forest with ornamental parkland and pleasure grounds around the house. Exemplifies the work of Burlington, Brown, Cundy and others. Main house has planning permission for hotel development, including building over Brown's walled garden and laying out a golf course in the park. Forestry Commission manages Savenake Forest on		
	DESIGNATION: Registered Park and Garden Grade II*, also 20 LBs, 7 SMs	Cundy and of for hotel dev			
	CONDITION: Extensive significant problems	Forestry Co			
A REAL PROPERTY AND A REAL		a long lease.			
	VULNERABILITY: High				
	VULNERABILITY: High TREND: Declining				

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS IATIONS Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Pewsey – Wilcot Road		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Helen Garside (LPA) 01380 724911	NEW ENTRY?:	No

### WILTSHIRE (UA) / NEW FOREST (NP)

SITE NAME:	Barrows in Bath Hole and Bury Hill Plantations, Redlynch			
DESIGNATION:	Scheduled Monument (No. 1004754)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Business Manager 0117 975 0700	

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the solution of the solution
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at **www.english-heritage.org.uk/risk** 

HERITAGE AT RISK

Published October 2011 by English Heritage 1 Waterhouse Square, 138-142 Holborn, London ECIN 2ST

© Copyright English Heritage 2011