

## PEWSEY AREA BOARD – ISSUES UPDATE REPORT – SEPTEMBER 2010

ID	Category	Division	Summary of Issue	Status
1017	Highways	Pewsey	Dangerous to cross Wilcot Road, Pewsey outside of the school entrance	A Community Area Transport Group is to be set up and a workshop is due to be held with highway officers to discuss all of the potential schemes in the area.
1003	Highways	Vale	Wilcot – Speeding Traffic	Awaiting results of speed survey.
969	Highways	Vale	Danger spot at the 4-way junction outside the Golden Swan public house, Wilcot. Request for a roundabout.	A Community Area Transport Group is to be set up and a workshop is due to be held with highway officers to discuss all of the potential schemes in the area.
918	Highways	B&B	Excessive speeding of cars along Eastcourt Road, Burbage.	A speed survey was carried out between 16/06/2010 and 22/06/2010. A total of 3189 vehicles were checked. The 85%ile was 30.9 mph (the 85% ile is the speed at which 85% of the traffic is travelling at or below). The average speed of the vehicles checked was 25.4 mph.
846	Highways	B&B	Lack of footpath from the Burbage roundabout to the Farm Shop on the A338 and signs are too low.	A Community Area Transport Group is to be set up and a workshop is due to be held with highway officers to discuss all of the potential schemes in the area. Request for signage to be altered has been sent to department but may take some time as demand for signage is high.
782	Highways	B&B	Speeding vehicles in Marten, dangerous road for pedestrians	The results of the survey for the area of Mill Farm, Marten and for Tidcombe Road, Marten found that the 85% ile was 27.2 mph and 31.8 mph respectively. This is a 60mph road. The road does not meet the criteria for the camera unit or for community speed watch. Highways Officers have contacted the Parish Council regarding lining and signage.
538	Highways	Vale	Speeding through Chirton. The village has very narrow roads and a couple of tight bends one of which is where the primary school is sited, and there have been a few near misses at this point.	A Community Area Transport Group is to be set up and a workshop is due to be held with highway officers to discuss all of the potential schemes in the area.

## PEWSEY AREA BOARD – ISSUES UPDATE REPORT – SEPTEMBER 2010

97	Highways	Vale	Chirton the 50 mph speed limit on the A342 on the stretch between the turn-off to the village of Conock to the boundary limit of the village of Chirton. Parish Council would like a 40mph limit.	Speed Survey carried out on A342 between 28 Jan-4 Feb. This is a 50 mph limit. A total of 37375 vehicles were checked - the 85%ile was 45.9 (85%ile is speed at which 85% of traffic is travelling at or below) the average speed of vehicles checked was 36.8 mph. The road does not meet the criteria for enforcement by the camera unit or speed watch. The Parish Council are responding to the Speed Limit Review.
515	Highways	Pewsey	Speeding and Rat Running Sharcott	The person who raised this issue has not made any further contact.
264	Highways	Pewsey	Speeding through the village on B3087 Easton Royal. The 40 mph speed limit is too high.	The speed limit review suggests a reduction to 30mph along this road.
108	Highways	B&B	Road flooding, Grafton	Divisional Highways have stated that they cleared out the ditch on the A338 near the Wilton junction at Grafton last year and are not aware of any further problems. The Parish Steward has been asked by the Parish Council to advise if the issue has been resolved or not.
101	Highways	Pewsey	St Francis School Vehicles speeding past the entrance to, and exit from, St. Francis School, Marlborough	The speed survey was carried out between the 28th January and 4th February 2010 A total of 29295 vehicles were checked. The 85%ile was 43.4 mph (the 85%ile is the speed at which 85% of the traffic is travelling at or below). The average speed of the vehicles checked was 38 mph. The speeding does not meet the criteria for enforcement by the camera unit or for community speed watch. The Parish Council have requested through the speed limit review process that the limit along this road be reduced to 30mph.
93	Highways	Pewsey	Swan Road, Pewsey Lack of pavement - need to make it safe for pedestrians and elderly to cross	A Community Area Transport Group is to be set up and a workshop is due to be held with highway officers to discuss all of the potential schemes in the area. The Parish Council have forwarded a request to the speed limit review for the speed limit to be reduced or for better road markings to keep traffic within the limit.
91	Highways	Vale	Rushall pedestrian safety.	A Community Area Transport Group is to be set up and a workshop is due to be held with highway officers to discuss all of the potential schemes in the area

## PEWSEY AREA BOARD – ISSUES UPDATE REPORT – SEPTEMBER 2010

87	Highways	Pewsey	Drivers continually contravening the one way system in Wilcot Road Pewsey	This problem is still occurring although it is thought to be now due to local drivers who are well aware that they are travelling the wrong way down a one way road. The matter has been raised at PANG (Pewsey Area Neighbourhood Group) and residents have been advised to note registrations and pass these to the Police.
82	Highways	Pewsey	The state of the pavements in Pewsey (The Crescent and Broadfields)	Officer dealing with the problems – issue now closed
80	Highways	All	Highway Maintenance (A345)	The road has monthly safety inspections and sections are due to be resurfaced.
72	Highways	Pewsey	Pedestrian Access to Pewsey Station	A Community Area Transport Group is to be set up and a workshop is due to be held with highway officers to discuss all of the potential schemes in the area.
917	Leisure	Pewsey	One of the local residents in Pewsey owns an anti-social dog, which she cannot control if it meets other dogs. The owner exercises the dog in a play area.	Wiltshire Council is in the process of preparing new dog control orders and intends to include a dog exclusion area order (there are no exclusion areas at present). Once this has gone through the process and we have our new dog control orders in place we would be able to help in this situation but until then we could not enforce this. The dog control orders will go to cabinet for approval but they are unlikely to be adopted until January 2011
1049	Highways	Pewsey	Speeding in Great Bedwyn	Have asked the parish clerk if he would be willing to identify a suitable position for the survey equipment - awaiting response.
1053	Highways	Pewsey	Speeding within 30mph area in Bottlesford	PC Richard Barratt has agreed to periodic enforcement. Caroline has forwarded concerns re: repeater signs legislation to Highways - a response has been provided, discussions ongoing.
1139	Highways	Pewsey	Speeding in Woodborough	Pewsey Community Area Manager has identified a location for speed survey and is waiting for confirmation from the Parish Council. She will then request the installation of survey equipment (which is laid in the road for one week) - the reason for this is because Community Speed Watch can only be done if the speeding reaches a certain threshold.