

Warminster Area Board Issues Report for 8 January

New issues reported:

No. Location Issue Latest update

3753	Chitterne	Speeding on B390	Topographical surveys to be costed
3712	Crockerton Little Hill	Signage	With Highways team
3698	Prestbury Drive (Bishopstrow side)	Footpath safety concerns	Streetscene looking at ownership and location
	Groveland Way	Parked cars potential hazard	WR1 form to be submitted

Ongoing issues under investigation:

No. Location Issue Latest update

3421	Longbridge Deverill A350	Speeding on road through village which is 40mph with many junctions.	Topographical survey funded by CATG and in progress
3397	Norton Road & High Street Sutton Veny	•	Hatching / double yellow lines CATG report to Area Board requesting agreement for £500 – see separate CATG report.
3396	Norton Road off Cotley Hill A36		Highways engineer liaising with Parish Council regarding prepared lining and signing options
2990	Warminster	Longleat site	Parish Council, Longleat and the Caravan Club continue to meet to find a long term solution
	Warminster	Victoria Fields	Unfinished play area ongoing

Recently resolved issues now closed

No.	Location	Issue	Resolution
3658	Sherrington	Potential Speeding	"Slow" to be marked on highway entrance to village
3621	Sherrington	Request for additional grit bin	Grit bin funded by Area Board
3581	Bapton	Narrow road at Bapton with speeding issue	Streetscene team to talk to resident.
3729	Corsley Memorial Playing Fields	Entrance to playing field potentially dangerous	"Slow to be marked on highway at entrance /exit to playing field
3728	Corsley	Sat Nav sends HGV through narrow lanes	With Highways team to mark "unsuitable for wide vehicles"
3496	Codford	Speeding on High Street, Codford.	Project now with Highways team

Further details including actions and outcomes can be viewed at www.wiltshire.gov.uk/areaboards including reporting of issues.

Report Author: Jacqui Abbott, Community Area Manager Jacqui.abbott@wiltshire.gov.uk 07771 844 530