

## APPENDIX 2

### Proposed Highways Major Maintenance 2016/17 – Southern Wiltshire Area Board

Road	Location	Recommended Treatment	Estimated Length (m)
A354	A354 Coombe Bissett. Gateway on Blandford Road	High Friction	35
A338	Braemore Road, Downton at junction with The Borough	High Friction	44
B3079	Lyndhurst Road, Landford – junction A36 to near its junction with Hamptworth Road	Resurfacing	705
A338	Downton Road	Resurfacing	1150
C12	West of Odstock to junction A338	Resurfacing	1893
A27	Romsey Road, Whiteparish	Skid Resistance Improvements	60
C12	Stratford Toney Road, Combe Bissett	Skid Resistance Improvements	71
C328	Odstock Road, Salisbury	Skid Resistance Improvements	100
U/C	Bodenham Loop Road	Carriageway Repairs	1800