

Warminster Area Board Issues Report for 11 September

New issues reported:

No.	Location	Issue	Latest update
3549	Upton Lovell	Request for bus shelter Upton Lovell A36 Warminster bound side	This will be discussed at the CATG (Community Area Transport Group) meeting on 7 October.
3496	Codford	Speeding on High Street, Codford.	Speeding occurs mainly from the junction with The Grove when travelling west towards the New Road Garage and from St. Peter's Church when travelling east towards the junction with Green Road. A metro count has been ordered to assess speeds in the first instance. For CATG on 7 October.
	Warminster	Bore Hill Farm biodigester omitting fumes and alleged failed tests	Cllr Davis has discussed the situation with the owner and will report back to the Area Board on 11 September.

Ongoing issues under investigation:

No.	Location	Issue	Latest update
3421	Longbridge Deverill A350	Speeding on road through village which is 40mph with many junctions.	The metro count has been re-ordered on 3 September following suspected incorrect readings. Highways engineer has inspected the area. For further discussion at CATG on 7 October.
3397	Norton Road & High Street Sutton Veny	Request for no waiting restriction as cars parking inappropriately	Wiltshire Council traffic engineer looking at options; liaising with Parish Council & pass to NPT (Neighbourhood Policing Team) also. CATG 7 October.
3396	Norton Road off Cotley Hill A36	Safety concerns re: narrow pavement & bend; visibility poor	Highway engineer to cost lining and signing options and report back to CATG on 7 October.

3387	Codford Road junction, Chitterne	Bridge railings interfere with line of sight.	Highway engineer to speak to structures team in first instance and report back to CATG on 7 October.
3237	Victoria Fields estate	Numerous issues including unfinished pavements, narrow pavements, problem parking and issues with the play area.	CATG will look at lining and signing options as soon as the area is adopted by Wiltshire Council. Inspections are currently taking place for all of the defects and Wiltshire Council will be asking that they are all rectified. Cllr Ridout leading on this for the Area Board.
3146	Warminster	Imber Road & Woodcock Road traffic near schools	The Town Council is contacting Waitrose to explore improving the staff parking situation. The Town Council has also requested further work on the traffic model. St Georges school has submitted an application on Taking Action to School Journeys which is in progress. This issue will remain on the CATG agenda.
3092	Warminster	Woodcock Road towards Boreham Road traffic issue	Metro count results for the length of Woodcock Road is 35.8 for the 85 th percentile. The next steps are to consider a community speedwatch scheme.
2990	Warminster	Caravans entering Longleat site narrow lanes	The Parish Council has been liaising with Caravan Club. There is a need to re-engage the Longleat estate to look at possible solutions to this issue.

Recently resolved issues now closed

No.	Location	Issue	Latest update
3186	Warminster	Houghton Close with Boreham Road junction – congestion and access issues	Lining and signing installed

Further details including actions and outcomes can be viewed at www.wiltshire.gov.uk/areaboards including reporting of issues.

Report Author: Jacqui Abbott, Community Area Manager
Jacqui.abbott@wiltshire.gov.uk 07771 844 530