

WILTSHIRE COUNCIL

Item 7

SOUTHERN WILTSHIRE AREA BOARD  
4 DECEMBER 2014

---

## Your Local Issues

### Purpose of the Report

To update the board on the issues **in progress** since the last meeting in October.

To report highway maintenance issues go to: [www.wiltshire.gov.uk/mywiltshireregister](http://www.wiltshire.gov.uk/mywiltshireregister)

### Southern Wiltshire Area Board - Issues in progress

Issue No	Electoral Division	Summary of Issue / scheme	Latest Update
3695	Laverstock Ford and Old Sarum	Damage to Milford Mill Bridge, Milford Mill Road	Highways team update: Structures team are raising a ticket for its repair
3692	Alderbury and Whiteparish	Speeding in East Grimstead outside Reading Room	Metrocount requested
3587	Winterslow	No road sign on Black Lane Pitton	Highways: We are currently waiting for it and as soon as we have it we will get it erected.
3573	Downton and Ebble Valley	Flooding in Coombe Bissett	Danny Everett is overseeing modification to existing highway drainage network and clean drain.
3541	Winterslow	No Through Road sign needed Farley Farm Rd	On signing list for consideration.
3429	Winterslow	Flooding across the road - Farley	Ditches have been dug. Highways to re-check
3395	Winterslow	Blocked sight line at Dunstable Corner in Winterslow	To be discussed at CATG
3363	Winterslow	Signage at Glebe Close, Pitton	This is part of a council housing estate therefore this has been passed to the Housing Manager to look into it.
3338	Alderbury and Whiteparish	Speeding, Common Road from Riding School to A27	This was put forward as a potential location for 20mph speed limit – awaiting report to CATG
3306	Downton and Ebble Valley	Visibility for drivers entering A338 at Charton All-Saints	Highways: There is currently a safety scheme being drawn up for this location due to a number of minor collisions, (primarily in the

			daylight). Await details of this scheme at CATG
3183	Laverstock Ford and Old Sarum	HGVs using Milford Mill Road, Laverstock	HGV action group
3121	Downton and Ebble Valley	Heavy vehicles accessing Pound Bottom	HGV action group
3115	Downton and Ebble Valley	Cycle path problems A338 between Downton and Salisbury	CATG list
3109	Downton and Ebble Valley	7.5t weight limit not observed through villages	HGV action group
3057		Silted up ditches along the Pitton/Winterslow road	This is on the programme and will be done when the resources are available.
3055	Winterslow	Inconsiderate school parking on the roads around Pitton	Parish Council's option has not been advanced. Situation still remains
3054	Redlynch and Landford	Speeding on New Road, Landford	A further metrocount has been done at the results were: The survey was carried out between 04/09/2014 and 11/09/2014. A total of 12930 vehicles were checked. The 85th percentile was 45.0mph (the 85th percentile is the speed at which 85% of the traffic is travelling at or below). Below threshold for CSW or SID.
2940	Laverstock Ford and Old Sarum	Very muddy footpath - Medieval Bridge to Milford House	Diversion Order is in progress and Rights of Way warden is looking at design to raise the path to make it all weather. Funding sought – project needs advancing.
2779	Downton & Ebble Valley	Speed limit reduction C12, Coombe Bissett to Homington	Coombe Bissett village was put forward for a potential 20mph location. Officers will bring back proposal to CATG in due course.
2773	Redlynch	Parking at Apple Tree Road	Bollards to be installed w/c 24 <sup>th</sup> November
2754	Laverstock Ford and Old Sarum	Flooding regularly takes place in Milford Mill Road	There has been investigation carried out by the Drainage team. Waiting to hear feedback from this.
2740	Alderbury and Whiteparish	Old Road, Alderbury Where road meets Southampton Rd the road is subsiding. This has happened before	Works being planned to solve further issues
2687	Alderbury and Whiteparish	Destruction of verges and gullies on Miles Lane	Verge to be hardened by masonry gang by the end of the

			financial year.
2259	Winterslow	road subsidence on narrow bend Church Road, Farley	Patching to be done at this location in this financial year.
2182	Redlynch and Landford	Poor road surface in School Road, Nomansland	Road has been put forward for surfacing work as one of the ten priority sites for Salisbury and South Wiltshire.
1992	Redlynch and Landford	HGVs in Landford	HGV action group
1905	Laverstock Ford and Old Sarum	School traffic in Laverstock	On CATG list

**Updates for the above issues:**

Full details on the issues are available online here:

[www.wiltshire.gov.uk/southernwiltshireareaboard](http://www.wiltshire.gov.uk/southernwiltshireareaboard)

You then click on **issue tracking**. If you would like to be sent hard copies of the issues and updates contact Tom Bray on tom.bray@wiltshire.gov.uk or 01722 434252.

**Reporting an issue:**

To report an issue go to [www.wiltshire.gov.uk/southernwiltshireareaboard](http://www.wiltshire.gov.uk/southernwiltshireareaboard) and click on "report an issue in your community now".

---

Report Author: Tom Bray – Community Area Manager, Tel No: 01722 434252 E-Mail: tom.bray@wiltshire.gov.uk