

Report to	South West Wiltshire Area Board
Date of Meeting	5 October 2011
Title of Report	Purchase of Speed Indicator Device

Purpose of Report

To propose the purchase a Speed Indicator Device (SID), to be managed by Tisbury Community Safety Partnership.

- 1.1. At the meeting of the Community Areas Transport Group (CATG) on 19 July a recommendation was made to purchase a Speed Indicator Device (SID) to supplement the equipment already held by Wiltshire Council for use in south west Wiltshire. This would deliver a 100% increase in SID deployment throughout the Areas, thereby making a significant impact on road safety.
- 1.2. The minutes of the CATG meeting are attached.
- 1.3. The equipment would be held and managed by Tisbury Community Safety Partnership (TCSP) but deployed by Wiltshire Council's Highways Department to supplement their existing schedule.
- 1.4. At the meeting of the South West Wiltshire Area Board on 24 August the recommendation was accepted in principle, pending notification of actual costs.
- 1.5. Wiltshire Council Highways Department has laid down the specification of the equipment to be compatible with existing stock. This is available from only one supplier. A breakdown of costs is attached, in the form of an invoice from that supplier. The total figure is £7,349.00 excl VAT.

Recommendation

It is recommended that the Area Board approve the purchase of a SID to be managed by TCSP and deployed by Wiltshire Council Highways Department.

Richard Munro
Community Area Manager

Appendix:

- A. CATG minutes 19 July 2011
- B. Traffic Technology invoice for SID