Pewsey Area Board – Issues Update May 2010

ID	Category	Division	Summary of Issue	Update
918	Highways	B&B	Excessive speeding of cars along Eastcourt Road, Burbage	Speed Survey to be undertaken
846	Highways	B&B	Lack of footpath from the Burbage roundabout to the Farm Shop on the A338 and Signs are too low	Footpath Request added to list for Local Transport Plan 2011 assessment. Request for signage to be altered has been sent to department but may take some time as demand for signage is high.
782	Highways	B&B	Speeding vehicles in Marten, dangerous road for pedestrians	Speed Survey to be undertaken
538	Highways	Vale	Speeding on the A342 and through Chirton.	A Speed Survey has been carried out and neither road meets the threshold for camera unit enforcement or Community Speed Watch. Wiltshire Council is meeting with the School to discuss their needs. CAM liaising with Sarsen. The Parish Council to liaise with the Police if they require them to visit with a speed gun. Speed Limit Review of A & B Roads not yet complete – Parish Council requested reduction. Speed Limit Review of C and unclassified roads to take place in the future.
515	Highways	Pewsey	Speeding and Rat Running Sharcott	A meeting to take place in Sharcott between Highways and CAM.
536	Highways	Vale	Speeding Manningford	A Speed Survey has been undertaken and the location meets the criteria for Community Speed Watch, the Parish Council will progress with this.
497	Highways	Pewsey	Consideration for Community Speed Watch Prospect/Marlborough Road, Pewsey	A Speed Survey has been undertaken and the location did not meet threshold for camera unit enforcement or Community Speed Watch. Parish Council to liaise with the Police if they require them to visit with a speed gun.
494	Highways	Pewsey	Consideration for Community Speed Watch Speeding on Milton Road, Pewsey	A Speed Survey has been undertaken and the location meets the criteria for Community Speed Watch, the Parish Council will progress with this.

Division Abbreviations B&B: Burbage & Bedwyns Vale: Pewsey Vale

ID	Category	Division	Summary of Issue	Update
264	Highways	Pewsey	Speeding through the village on B3087 Easton Royal. The 40 mph speed limit is too high.	A Speed Survey has been undertaken and the location did not meet threshold for camera unit enforcement or Community Speed Watch. However the speed limit review has recommended that limit be reduced to 30mph.
108	Highways	B&B	Road flooding, Grafton	Parish Council in liaison with Officers
105	Highways	B&B	Speeding through narrow village lanes (HAM)	A Speed Survey has been undertaken and the Buttermere road qualifies for Community Speed Watch. The Parish Council will progress with this.
104	Highways	B&B	Speeding through East Grafton on the A338 on the Fairmile, Hollow Lane and Wilton Road.	A Speed Survey has been undertaken and the location did not meet threshold for camera unit enforcement or Community Speed Watch.
101	Highways	Pewsey	Vehicles speeding past the entrance to, and exit from, St. Francis School	A Speed Survey has been undertaken and the location did not meet threshold for camera unit enforcement or Community Speed Watch. However as part of the Speed Limit Review the Parish Council have requested the limit be reduced to 30mph. Waiting for the outcome of the review.
99	Highways	Vale	Speeding on the Alton to Devizes Road, Stanton St Bernard	A Speed Survey has been undertaken and the location did not meet threshold for camera unit enforcement or Community Speed Watch
98	Highways	Vale	Beechingstoke Speeding through the village. There is a 30mph zone along Broad Street, Beechingstoke	A Speed Survey has been undertaken and Broad Street qualifies for Community Speed Watch. The Parish Council will progress with this.
95	Highways	B&B	Burbage speeding under Westcourt Bridge on Bypass	A Speed Survey has been undertaken and the location did not meet threshold for camera unit enforcement or Community Speed Watch.
93	Highways	Pewsey	Swan Road Lack of pavement - need to make it safe for pedestrians and elderly to cross Swan Road	Being assessed by officers – recommendations will go to cabinet member March/April

Division Abbreviations B&B: Burbage & Bedwyns Vale: Pewsey Vale

ID	Category	Division	Summary of Issue	Update
91	Highways	Vale	Rushall pedestrian safety	Parish Council have consulted on proposals for a footpath through the village and are negotiating with the School
88	Highways	Vale	Oare speeding A345 Huish Corner, Oare and through the village	A Speed Survey has been undertaken and Oare qualifies for Community Speed Watch. The Parish Council will progress with this.
87	Highways	Pewsey	Drivers continually contravening the one way system in Wilcot Road	This is still causing problems – it appears that the people doing this are local and doing it on purpose to access the shop. Residents will monitor and note registrations.
86	Highways	All	The need to increase traffic Police, highway maintenance in general, more car driver pullover checks	Parish Councils can request action by Police to enforce speed limits in areas that do not qualify for Community Speed Watch.
82	Highways	Pewsey	The state of the pavements in Pewsey (Broadfields and the Crescent)	Highways Officer liaising with resident.
80	Highways	All	Highway Maintenance (A345)	The recently published schedule of works has only identified the stretch from Upavon to North Newnton to be resurfaced.
72	Highways	Pewsey	Pedestrian Access to Pewsey Station	Being assessed by officers – recommendations will go to cabinet member March/April
917	Leisure	Pewsey	Dog being exercised in children's play area as owner can't control it around other dogs.	Wiltshire Council is in the process of preparing new dog control orders and intends to include a dog exclusion area order (there are no exclusion areas at present). Once this has gone through the process and new dog control orders are in place then we will be able to help in this situation but until then the Council cannot enforce this. Estimated timescale is June.

Division Abbreviations B&B: Burbage & Bedwyns Vale: Pewsey Vale