Malmesbury Area Board Issues – 5 September 2012 Update

ID	Category	Division	Summary of Issue	Status
1074	Car Parking	Malmesbury	Access to car parking by Glovers Courts residents	The application to stop up the highway will be heard at the Magistrates Court, Chippenham on Tuesday 9 October 2012.
1783	Car Parking	Minety	Parking problems at Hillside, Leigh	The 4 July area board endorsed the recommendation of the Malmesbury Community Area Transport Group (CATG) to undertake some interim measures; however a response from Greensquare is required before any significant progress can be made.
2172	Car Parking	Malmesbury	Parking in Cross Hayes by Hyams garage	This matter continues to be under investigation.
562	Highways	Malmesbury	Crossing needed on Tetbury Hill Road near Filands.	Malmesbury CATG received an update on 12 June 2012. A 30mph entry sign is being considered together with improving the crossing island. CATG may be asked for more funding to ensure that the scheme can be completed, however councillors are recommended to close this issue now that it is being resolved by CATG.
1608	Highways	Brinkworth	Speeding vehicles and HGVs on Wood Lane Brinkworth	On 4 July 2012 the area board agreed to close this issue as it was felt nothing further could be done at this stage as there were other priority areas for freight management. Since the area board made that decision a request has been made to reverse that decision.
1808	Highways	Malmesbury	Improve visibility of speed bumps in Station Road car park	As an interim measure until the speed bumps are painted, a sign has been erected adjacent to the bump on entry to the car park.
1863	Highways	Sherston	Car blocking dropped kerbs in Malmesbury	White bar markings at the dropped kerbs in Barley Close and Parliament Row were installed in early July. It is hoped that this will improve access for users of wheelchairs, mobility scooter prams and pushchairs. Councillors are recommended to close this issue.
1895	Highways	Minety	Speeding in Minety on B4040	The metro count results for Sawyers Hill showed that the 85th percentile (the speed at which 85% of the traffic was travelling at or below) was 33.6mph. This suggests the site is inappropriate for Community Speed Watch or a SID. The Parish Council have agreed that the SID will be placed on B4040 at the West end of the village where the metro count recorded a 85th percentile of 39.60mph making it a suitable

				site for a SID as well as Community Speedwatch should the community wish to set up a Community Speedwatch Scheme.
1948 and 2092	Highways	Brinkworth	Persistent speeding through Startley	As this issue is now being effectively managed by Malmesbury CATG, the area board is recommended to close the issue.
1955	Highways	Minety	Lack of and poor condition of pavements in Minety	The area board on 4 July endorsed the recommendations of Malmesbury CATG. Since then the results of the 2012/13 substantive highways funding scheme bidding process have been received and Silver Street footway has been successful, being awarded £15,000 towards the scheme. Councillors are recommended to close this issue now that it is being resolved by CATG.
2070	Highways	Sherston	Vehicular access to Malmesbury Primary Health Care Centre	This issue has also been raised via a letter from St Paul Malmesbury Without Parish Council to the head of sustainable transport at Wiltshire council.
2232, 2236, 2268 and 2436	Highways	Minety	Concerns about speed, road safety and HGV in Leigh on B4040	A meeting is taking place between Leigh Community Speedwatch group members and Leigh parish council Chairman on 14 August to discuss the CSW group's report and the officers' response to it (this being an action from the June meeting of Malmesbury CATG.
2397	Highways	Minety	Create passing place on The Green, Oaksey and maintain verges	On 4 July 2012 Malmesbury area board referred this issue to the Malmesbury CATG. The CATG next meets on 23 October and a representative of the parish council is invited to attend.
2417	Highways	Sherston	Traffic calming needed on A429 Burton Hill, Malmesbury	The average speed of traffic travelling towards Corston was 26.4mph, with 85% of all traffic travelling at or below 32.3mph. The average speed of traffic travelling towards the roundabout (from Corston) was 25.1mph, with 85% of all traffic at or below 30.0mph.
2419	Highways	Sherston	Severe and prolonged flooding in Back Lane, Alderton	Highway engineers have inspected the issue. Following clearance of gully gratings the water near the crossroads was flowing away. It would appear that the problem may originate from ponds outside New Farm which are overflowing on to the road. Local landowners will be contacted and the councils land drainage experts involved.
2429	Highways	Malmesbury	Traffic Regulation Order needed for Mill Lane	The 4 July area board endorsed the Malmesbury CATG recommendation to contribute £2,800 towards a Traffic Regulation Order for Mill Lane, conditional on the town council contributing £700. The town council has agreed to do so once the

				legality of contributing has been clarified.
2453	Highways	Malmesbury	Cars blocking Pool Gastons and Burnham Road junction	The police will undertake some local advisory work with drivers of cars in the area. It is recommended that this issue is referred to Malmesbury CATG.
2466	Highways	Malmesbury	Road Safety concerns at junction of Blicks Hill and Holloway	This issue has been forwarded to highways officers and the police for consideration. It is recommended that this issue is referred to Malmesbury CATG.
2498	Highways	Minety	Perceived speeding on B4696 in Ashton Keynes	A metro count will be undertaken to identify the speed of vehicles.
2503	Highways	Malmesbury	Vehicular problems relating to Dark Lane, Malmesbury	This issue has been forwarded in the first instance to the council's highways department and police for comment. It is recommended that this issue is referred to Malmesbury CATG.
1896	Transport	Minety	HGV damage to the bridge by Vale of White Horse Inn, Minety	A review has been carried out of the warning signs by the bridge and 'Road Narrows' and 'Pedestrians in the road' signs will be replaced on either side of the bridge. It is felt that no other signs are required at the site other than the ones already there. It is expected that contractors will complete the work no later than the 26th September.
2313	Transport	Malmesbury	Perceived speeding through Eastcourt on the Hankerton Road	The necessary information to undertake the metro count has been received from the parish council and a count has been requested.
2131	Waste	Malmesbury	Shrubs or fence required round recycling bins in Station yard	Following consultation about mini-recycling sites a decision has been made to remove plastic bottle and card collection bins from this site now that there are kerbside collections. As the issue of littering was associated with these bins the problem should be significantly reduced. Councillors are recommended to close this issue.