

## Highways Major Maintenance 2014 -2015 – Chippenham Area Board

Road	Location	Area Board	Recommended Treatment	Average Width (m)	Estimated Length (m)	Est Area of Site (m <sup>2</sup> )
UC	Parklands, Hullavington	Chippenham	Resurfacing and footway reconstruction	5	150	750
U/C	Nettleton Loop.	Chippenham	Resurfacing	4	760	3,040
U/C	Ford to Biddestone.	Chippenham	Patching and Surface dressing	4	2,400	9,600
U/C	Chippenham A350 Dual Off slip to Plough Pub.	Chippenham	Resurfacing	7.2	510	3,672
U/C	Biddestone Weavern Ln.	Chippenham	Patching and Surface dressing	4	1,820	7,280
U/C	Chippenham Lords Mead.	Chippenham	Resurfacing	6	464	2,784
C181	Jacksoms Lane	Chippenham	Resurfacing	4.5	1,560	7,020
C367	Station Hill / Cocklebury	Chippenham	Resurfacing	9.5	380	3,610
C367	Station Hill / Cocklebury	Chippenham	7 Resurfacing	7.8	520	4,056
B4122	B4122 Heading southeast from Junction 17 M4	Chippenham	Resurfacing	6.1	200	1,220
B4122	B4122 Heading south from Junction 17 M4	Chippenham	Resurfacing	3.8	90	338
A420	A420 Bristol Road, Bumpers Farm Rbt, Chippenham	Chippenham	Resurfacing	7.2	210	1,512
B4122	B4122, Junction 17 M4	Chippenham	Resurfacing	9.4	260	2,444

Road	Location	Area Board	Recommended Treatment	Average Width (m)	Estimated Length (m)	Est Area of Site (m <sup>2</sup> )
B4122	B4122, Junction 17 M5	Chippenham	Resurfacing	9.4	110	1,034
C86	C86, Yatton Road, Biddestone	Chippenham	Resurfacing	6.2	50	310
C86	C86 Biddestone Road, Biddestone	Chippenham	Resurfacing	5.7	80	456
B4039	B4039 Horsedown, near Littleton Drew	Chippenham	Resurfacing	6	180	1,080

\* Sites highlighted in yellow involve skid resistance improvements.