

## Warminster Area Board Issues Report for 3 July 2014

## **New issues reported since last Area Board:**

3421	Longbridge Deverill A350	Difficult road through village – 40mph & junctions	Highway engineer to check major maintenance schedule and then consider options. Also look at Northern section. CATG 4 Sep.
3397	Norton Road & High Street Sutton Veny	Request for no waiting restriction – few cars parking inappropriately	Wiltshire Council traffic engineer looking at options; liaising with Parish Council & pass to NPT also. CATG 4 Sep.
3396	Norton Road off Cotley Hill A36	Safety concerns re: narrow pavement & bend; visibility poor	Highway engineer to cost lining and signing options.
3387	Codford Road junction, Chitterne	Bridge railings interfere with line of sight.	Highway engineer to speak to structures team in first instance. CATG 4 Sep.

## Ongoing issues under investigation:

No.	Category	Issue	Latest update
3237	Victoria Fields estate	Numerous issues  – unfinished pavements, narrow pavements, problem parking	Cllr Ridout leading on unfinished areas of estate including Swaledale Road. Community Area Transport Group will be able to consider lining and signing options on Southdown Way when the road is adopted by Wiltshire Council
3186	Warminster	Houghton Close with Boreham Road junction – congestion and access issues	Wiltshire Council traffic engineer costing lining options. For CATG on 4 September 2014.

3146	Warminster	Imber Road & Woodcock Road traffic near schools	A large scale traffic survey is being undertaken to include this area. There will then be modelling of different scenarios to help improve the problems. Outcomes dependent on results and funding options.
3092	Warminster	Woodcock Road towards Boreham Road traffic issue	Metro count being undertaken in 2 areas. Large scale traffic survey being undertaken to include this area. Schools involved in Taking Action on School Journeys initiatives via School Travel Plans and Wiltshire Council.
2990	Warminster	Caravans entering Longleat site narrow lanes	Parish Council has been liaising with Caravan Club. There is a need to reengage the Longleat estate to look at possible solutions to this issue.
2835	Warminster	More dropped kerbs required en route to Tesco metro	Area Manager chasing progress with Streetscene team.

## Recently resolved issues now closed

No.	Cate	gory	Issue	Latest update
	3100	Warminster	Drivers cutting through Sambourne cul-de-sacs – previous bollards removed.	Bollards have been ordered and will be installed shortly.
3235		Warminster	Migratory Toad Crossing sign required Smallbrook Lane	Approval received from Town Council. Mark Stansby, Wiltshire Council commissioning signs for next season. A volunteer will put up and take down the sign.
3237		Warminster	Flood risk Chitterne  – long term flood risk planning required	Danny Everett working with Parish Council
3229		Warminster	Boyton & Corton Parish maintenance particularly drains	Imogen Burgess working with Parish Council. Ongoing but many issues already resolved.

3225	Warminster	IIB.590 IN MONIIONNO	This has been agreed and is in the programme.
3034	Warminster		Funding agreed by CATG / Area Board to make this no waiting.

Further details / actions and outcomes c an be viewed at <a href="www.wiltshire.gov.uk/areaboards">www.wiltshire.gov.uk/areaboards</a> including reporting of issues.

Report Author: Jacqui Abbott, Community Area Manager Jacqui.abbott@wiltshire.gov.uk 07771 844 530