Wiltshire Council

Where everybody matters

WILTSHIRE COUNCIL

Item 7

SOUTHERN WILTSHIRE AREA BOARD 31 JULY 2014

Your Local Issues

Purpose of the Report

To update the board on the issues in progress since the last meeting in May 2014.

To report highway maintenance issues go to: www.wiltshire.gov.uk/mywiltshireregister

Southern Wiltshire Area Board - Issues in progress

Highways Maintenance:

Issue No & link	Electoral Division	Summary of Issue / scheme	Latest Update
3429	Winterslow	Flooding across the road - Farley	Highways: Have asked drainage engineer to look at this, but because it is not a high speed road or properties are flooded, it would not be a high priority.
3057	Winterslow	Silted up ditches along the Pitton/Winterslow road	This is on the programme and will be done when the resources are available.
2754	Laverstock Ford and Old Sarum	Flooding regularly takes place in Milford Mill Road	There has been investigation carried out by the Drainage team. Waiting to hear feedback from this.
2746	Alderbury and Whiteparish	Condition of roads in Alderbury	Patching on Old Southampton Road due at the end of the month. Patching marked up on Clarendon Road. The two surfacing sites were not on this coming Years programme. Will resubmit for the next financial year. In the meantime, any patching required will be requisitioned.
2740	Alderbury and Whiteparish	Old Road, Alderbury Where road meets Southampton Rd the road is subsiding. This has happened before	Correction - This was done on Friday 14th March. I therefore close this issue. Contractors visited the site on 14 March 2014 and have found further issues with this road whilst onsite. So works are being planned to solve the issue.
2687	Alderbury and Whiteparish	Destruction of verges and gullies on Miles Lane	Verge to be hardened by masonry gang by the end of the financial year.
2259	Winterslow	road subsidence on narrow bend Church Road, Farley	Patching to be done at this location in this financial year.
2182	Redlynch and Landford	Poor road surface in School Road, Nomansland	Road has been put forward for surfacing work as one of the ten priority sites for Salisbury and South Wiltshire.

On CATG, HGV and other issues:

Issue No &	Electoral Division	Summary of Issue / scheme	Latest Update
link 3401	Alderbury and Whiteparish	I am the coordinator of the local speedwatch team. We have identified two additional speeding sites	I have requested the metrocount and will be in touch when I have got the results.
3395	Winterslow	Blocked sight line at Dunstable Corner in Winterslow	I will forward this to our Transport Officer to look into it. This will be a CATG issue and will need to go on the CATG.
3363	Winterslow	Signage at Glebe Close, Pitton	This is part of a council housing estate therefore this has been passed to the Housing Manager to look into it.
3338	Alderbury and Whiteparish	Speeding, Common Road from Riding School to A27	This was put forward as a potential location for 20mph speed limit.
3306	Downton and Ebble Valley	Visibility for drivers entering A338 at Charton All-Saints	Highways: There is currently a safety scheme being drawn up for this location due to a number of minor collisions, (primarily in the daylight). Await details of this scheme.
3183	Laverstock Ford and Old Sarum	HGVs using Milford Mill Road, Laverstock	No further actions to date on this issue.
3121	Downton and Ebble Valley	Heavy vehicles accessing Pound Bottom	HGV meetings with Hants CC hosted by New Forest National Park Authority still undertaking actions
3115	Downton and Ebble Valley	Cycle path problems A338 between Downton and Salisbury	The Community Area Transport Group have looked at this issue and are proposing to improve the lining for cyclists at Church lane where there is a specific sight issue for cyclists.
3109	Downton and Ebble Valley	7.5t weight limit not observed through villages	HGV meetings with Hants CC hosted by New Forest National Park Authority still undertaking actions
3055	Winterslow	Inconsiderate school parking on the roads around Pitton	This is being advanced by the Parish Council working with the school. When they have advanced this solution the CATG might have a role to play. Until then the actions are with the Pitton and Farley PC
3054	Redlynch and Landford	Speeding on New Road, Landford	I have arranged for a metrocount to be done on this road in September to provide comparable data with the metrocount done last year.
2940	Laverstock Ford and Old Sarum	Very muddy footpath - Mediaeval Bridge to Milford House	Diversion Order is in progress and Rights of Way warden is looking at design to raise the path to make it all weather. This will go to the next CATG to seek funding to get the project underway this year.
2779	Downton and Ebble Valley	Speed limit reduction C12, Coombe Bissett to	Coombe Bissett village was put forward for a

		Homington	potential 20mph location. Officers will bring back costed proposal to CATG in due course.
2773	Redlynch and Landford	Parking at Apple Tree Road	The scheme to implement bollards has been given the go ahead by the Parish Council. Highways technicians will soon be ordering the works.
1992	Redlynch and Landford	HGVs in Landford	HGV meetings with Hants CC hosted by New Forest National Park Authority still undertaking actions.
1905	Laverstock Ford and Old Sarum	School traffic in Laverstock	This issue remains on the Community Area Transport Groups list Cllr McLennan is ensuring that this remains on the list and the CATG is endeavouring to seek a solution.

Updates for the above issues:

Full details on the issues are available online here: www.wiltshire.gov.uk/southernwiltshireareaboard

You then click on **issue tracking**. If you would like to be sent hard copies of the issues and updates contact Tom Bray on tom.bray@wiltshire.gov.uk or 01722 434252.

Reporting an issue:

To report an issue go to <u>www.wiltshire.gov.uk/southernwiltshireareaboard</u> and click on "report an issue in your community now".

Report Author: Tom Bray – Community Area Manager, Tel No: 01722 434252 E-Mail: tom.bray@wiltshire.gov.uk