

APPENDIX 3

Highways Major Maintenance 2015/16 – Warminster Area Board

Road	Location	Recommended Treatment	Estimated Length (m)
U/C	Longhedge into Sydnalls Lane to junction Lands End Hill A362	Surface Dressing	1,020
B3092	Church Street Junction with Kingston Lane south to Long Knoll, Maiden Bradley	Surface Dressing	1,590
B3092	Frome Road (Junction with Bradley Lane north to junction with Forest Road)	Surface Dressing	2,923
U/C	The Stalls, Corsley	Surface Dressing	831
U/C	Junction Geys Hill to Whitbourne Moor, Corsley	Surface Dressing	668
U/C	The Stalls (Dertfords junction with Lanes End Hill A362)	Surface Dressing	1,031
U/C	Sturford Lane (Whitbourne Moor to junction Lands End Hill A362)	Surface Dressing	1,774
U/C	Springhead, Sutton Veny	Resurfacing	1,470
U/C	Chancery Lane, Warminster	Resurfacing	437
A350	Bends at Lower Pertwood	Skid Resistance Improvements	990
B3414	Bath Road, junction with Roman Way	Skid Resistance Improvements	140

Road	Location	Recommended Treatment	Estimated Length (m)
B3414	Bath Road near Brick Hill	Skid Resistance Improvements	100
A350	A350 northbound approach to roundabout with A36	Skid Resistance Improvements	120
A350	A350 Lords Hill Barn	Skid Resistance Improvements	980
A350	A350 bend south of Lords Hill Barn	Skid Resistance Improvements	350
A350	A350, Longbridge Deverill	Skid Resistance Improvements	160
B3092	Frome Road north of Mill Lane	Skid Resistance Improvements	230
A362	A362 Picket Post Roundabout to Warminster Bypass	Repairs and resurfacing	tbc