

APPENDIX 1

Completed Highways Major Maintenance 2014/16 – Warminster Area Board

Road	Location	Recommended Treatment
U/C	Junction Gey's Hill to Whitbourne Moor, Corsley	Surface Dressing
U/C	The Stalls - Dertfords Junction with Lanes End Hill A362	Surface Dressing
U/C	Sturford Lane (Whitbourne Moor to junction Lands End Hill A362)	Surface Dressing
U/C	Springhead, Sutton Veny	Resurfacing
U/C	Chancery Lane, Warminster	Resurfacing
A350	Bends at Lower Pertwood	Skid Resistance Improvements
B3414	Bath Road, Junction with Roman Way	Skid Resistance Improvements
B3414	Bath Road near Brick Hill	Skid Resistance Improvements
A350	A350 northbound approach to roundabout with A36	Skid Resistance Improvements
A350	Lords Hill Barn	Skid Resistance Improvements
A350	Bend south of Lords Hill Barn	Skid Resistance Improvements
A350	Longbridge Deverill	Skid Resistance Improvements

Road	Location	Recommended Treatment
B3092	Frome Road north of Mill Lane	Skid Resistance Improvements
A350	Longbridge Deverill	Resurfacing
A3098	A3098 - A36 to Westbury	Resurfacing
U/C	Southcroft, Chapmanslade	Resurfacing