

APPENDIX 2

Proposed Highways Major Maintenance 2016/17 – Royal Wootton Bassett & Cricklade Area Board

Road	Location	Recommended Treatment	Estimated Length (m)
C120	Greenway	Surface Dressing	3622
C130	Primrose Hill, Tockenham	Surface Dressing	1209
U/C	Cheddington Lane, (opposite Sally Pussey Inn to Bincknoll)	Surface Dressing	3045
U/C	Witts Lane, Purton	Resurfacing	773
U/C	Morstone Road, Royal Wootton Bassett	Resurfacing	188
U/C	Borough Fields, Royal Wootton Bassett	Resurfacing	190
U/C	Hallsfield, cricklade	Resurfacing	527
U/C	30 mph gateway on southern approach – Hook	High Friction	35
A4361	Swindon boundary, Broad Hinton	Skid Resistance Improvements	280
A4361	A4361 at junction with High Street, Winterbourne Bassett	Skid Resistance Improvements	80

Road	Location	Recommended Treatment	Estimated Length (m)
C414	Cricklade Road, Purton	Skid Resistance Improvements	350
C415	Broad Town Road near Marston Farm, Broad Town	Skid Resistance Improvements	70
A3102	Calne Road, Lyneham	Skid Resistance Improvements	190