

APPENDIX 2

<b>Road</b>	<b>Melksham</b>	<b>Recommended Treatment</b>	<b>Estimated Length (m)</b>	<b>Est Area of Site (m<sup>2</sup>)</b>
A361	A361 Seend Bends north of Baldham Bridge	Retexture	100	500
A361	A361 The Strand	Retexture	150	600
A350	A350 Beanacre at Halfway Farm	Retexture	170	646
B3107	B3107 Bradford Rd at Melksham Lane	Retexture	100	500
B3107	B3107 Melksham Rd at East Lane	Retexture	70	238
B3107	B3107 Melksham Rd at Mill Lane	Retexture	280	952
B3107	B3107 Melksham Rd at Old Milestone Nursery	Retexture	100	340
B3353	B3353 Corsham Road Whitley at First Lane & Middle Lane	Surfacing	200	1,280
C226	Seend Cleeve	Surface Dressing	835	4,115
C20	C20 Bell Hill Seend at Inmarsh Lane	Retexture	100	590
C165	New Road Melksham	Recycling	1,195	5,280
C395	Semington Road, Melksham	Surfacing	99	659

<b>Road</b>	<b>Melksham</b>	<b>Recommended Treatment</b>	<b>Estimated Length (m)</b>	<b>Est Area of Site (m<sup>2</sup>)</b>
UC	Coronation Road, Melksham	Reconstruction	337	2,497
UC	Ruskin Avenue, Melksham	Reconstruction	331	1,797