

Highways Major Maintenance 2014 -2015 – Pewsey Area Board

Road	Location	Area Board	Recommended Treatment	Average Width (m)	Estimated Length (m)	Est Area of Site (m ²)
U/C	Stanton St Bernard	Pewsey	Carriageway repairs and surface dressing	4	3,100	12,400
U/C	Hollybush Lane	Pewsey	Resurfacing	4	600	2,400
C30	Wilton Village	Pewsey	Resurfacing	5.5	1,250	6,875
C198	Ham	Pewsey	Resurfacing	5.3	1,800	9,540
U/C	Church Rd, Rushall	Pewsey	Resurfacing	4	510	2,040
C8	C8 Devizes to Pewsey	Pewsey & Devizes	Surface dressing	5.4	11,000	59,400
B3087	B3087 Near Burbage bypass rbt, Burbage	Pewsey	Retexture	7.3	250	1,825
A342	A342 Devizes Road, Upavon	Pewsey	Resurfacing	5.9	50	295
C74	C74 Oxenwood Road, Great Bedwyn	Pewsey	Resurfacing	4.8	100	480
C74	C74 Jockey Green, Great Bedwyn	Pewsey	Resurfacing	5.6	360	2,016
C74	C74 Bedwyn Common, Great Bedwyn	Pewsey	Resurfacing	2.7	80	216
C74	C74 Great Bedwyn	Pewsey	Resurfacing	5.4	370	1,998
A4	A4 East of Marlborough	Marlborough	Resurfacing	8.5	590	5,015
B3087	Pewsey High Street – Junction of A345 North Street/River Street to Pewsey 30mph terminal speed limit signs	Pewsey	Resurfacing and approx 25% footways	6.5	580	3,770

* Sites highlighted in yellow involve skid resistance improvements.