

Highways Major Maintenance 2014 -2015 – Southern Wiltshire Area Board

Road	Location	Area Board	Recommended Treatment	Average Width (m)	Estimated Length (m)	Est Area of Site (m ²)
B3080	B3080 Lode Hill, Redlynch	Southern Wiltshire	Carriageway repairs	6.8	250	1,700
A354	Coombe Bissett – North Junction C12 south to 50mph limit	Southern Wiltshire	Carriageway repairs	0	0	200
B3080	The Borough Downton – A338 to junction Barford Lane	Southern Wiltshire	Resurfacing	7.4	1,250	9,250
C12	C12 Fifield Bavant to Coombe Bissett	South West & Southern Wiltshire	Surface dressing & carriageway repairs junction to junction	6.1	9,360	57,096

* Sites highlighted in yellow involve skid resistance improvements.