

Report to	Southern Area Board
Date of Meeting	29 January 2015
Title of Report	Your Local Issues

Purpose of Report

To update the board on issues in progress since the last meeting in December.

NB: To report highway maintenance issues go to :

www.wiltshire.gov.uk/parkingtransportandstreets/roadhighwaysstreetcare/mywiltshirelogin.htm

Issue No	Electoral Division	Summary of Issue / scheme	Latest Update
3790	Laverstock Ford and Old Sarum	Request to reduce speed of traffic on Roman Rd, Ford due to recent head on collision	Have asked parish council and transport engineer to assess
3692	Alderbury and Whiteparish	Speeding in East Grimstead outside Reading Room	Metrocount carried out between 20/11/2014 and 27/11/2014. A total of 3891 vehicles were checked. The 85 th percentile was 30.0mph (below threshold for CSW).
3587	Winterslow	No road sign on Black Lane Pitton	Highways: Sign is ready to be put up – hope to put up before the end of February 2015
3573	Downton and Ebble Valley	Flooding in Coombe Bissett	Drains cleaned and majority of modifications complete.
3541	Winterslow	No Through Road sign needed Farley Farm Rd	Highways: it will go on signing list for consideration. Chasing for update
3429	Winterslow	Flooding across the road - Farley	Ditches have been dug. Highways hope to complete by end of February 2015
3363	Winterslow	Signage at Glebe Close, Pitton	This is part of a council housing estate therefore this has been passed to the Housing Manager who has ordered new signs - chasing
3057	Winterslow	Silted up ditches along the Pitton/Winterslow road	This is on the programme and will be done when the resources are available.
3054	Redlynch and Landford	Speeding on New Road, Landford	The transport engineer has liaised with the Parish Council over options to mitigate the speed of traffic with road markings / signage. Currently the parish council have asked for no further action until more cost-effective solutions can be devised.

2740	Alderbury / Whiteparish	Old Road, Alderbury Where road meets Southampton Rd the road is subsiding. This has happened before	Works are now complete
2687	Alderbury/ Whiteparish	Destruction of verges and gullies on Miles Lane	Work remains outstanding, Highways Engineer will ask Balfour Beatty to expedite
2259	Winterslow	road subsidence on narrow bend Church Road, Farley	Balfour Beatty being chased to complete this work in this financial year
2182	Redlynch and Landford	Poor road surface in School Road, Nomansland	Will try to remedy with works during the February 2015 half term holiday, if unable, this will proceed as part of the programme of works in 2015/16

Being progressed through the Community Area Transport Group (CATG)

3801	Alderbury	Pedestrian Crossing Request, Recreation Ground, West Grimstead	Issue forwarded to Transport Engineer and discussion scheduled for February 2015 CATG meeting
3793	Downton and Ebble Valley	No Through Rd Sign needed for The Lanes A338 Nunton	Transport engineers are assessing this request, hope to have a solution to report to the next CATG meeting
3792	Downton and Ebble Valley	Reconfigure Traffic Lights at Britford Park and Ride to permit free flow of traffic when P & R is closed	Consulting with relevant parish councils and officers to find the most appropriate solution - hope to have a meaningful update for the Feb CATG meeting
3791	Redlynch and Landford	School Run Parking Issues on School Rd, Nomansland	Have advised the parish council and school to ensure the travel plan is up to date to assess if assistance can be obtained from the Taking Action on Schools Journey Budget. Subject to this, the CATG may also need to consider this matter
3338	Alderbury and Whiteparish	Speeding, Common Road from Riding School to A27	20mph assessment recommendations due to be reported to the 25th February CATG meeting
3306	Downton and Ebble Valley	Visibility for drivers entering A338 at Charton All-Saints	Highways: A safety scheme has been devised and is being implemented
3183	Laverstock Ford and Old Sarum	HGVs using Milford Mill Road, Laverstock	HGV Action Group – chasing for update
3121	Downton and Ebble Valley	Heavy vehicles accessing Pound Bottom	HGV Action Group – a multi-agency group continues to examine the issues, and has devised a map and proposals intended to strengthen required restrictions

3115	Downton and Ebble Valley	Cycle path problems A338 between Downton and Salisbury	CATG has assessed and requested improved lining for cyclists at Church lane where there is a specific sight issue for cyclists (issue related to 3306 above)
3109	Downton and Ebble Valley	7.5t weight limit not observed through villages	HGV Action Group – chasing for update
3055	Winterslow	Inconsiderate school parking on the roads around Pitton	CATG has asked the school and parish council to come up with some alternative solutions
2940	Laverstock Ford and Old Sarum	Very muddy footpath - Mediaeval Bridge to Milford House	Diversion Order is in progress and Rights of Way warden is looking at design to raise the path to make it all weather.
2779	Downton & Ebble Valley	Speed limit reduction (20mph) C12, Coombe Bissett to Homington	Recommendations on this will be presented to the 25th February 2015 meeting of the CATG
2773	Redlynch	Parking at Apple Tree Road	Bollards put in place, funded in part by the CATG and Parish Council
2754	Laverstock Ford and Old Sarum	Flooding regularly takes place in Milford Mill Road	There has been investigation carried out by the Drainage team. Waiting to hear feedback from this.
1992	Redlynch and Landford	HGVs in Landford	HGV Action Group – a multi-agency group continues to examine the issues, and has devised a map and proposals intended to strengthen required restrictions
1905	Laverstock Ford and Old Sarum	School traffic in Laverstock	CATG suggest - remove until proposals for improvement devised

Full details on the issues are available online here:

www.wiltshire.gov.uk/southernwiltshireareaboard

You then click on issue tracking. If you would like to be sent hard copies of the issues and updates contact Karen Linaker on karen.linaker@wiltshire.gov.uk or 01722 434697.

To report an issue go to www.wiltshire.gov.uk/southernwiltshireareaboard and click on “report an issue in your community now”.

Report Author: Karen Linaker – Community Area Manager, Tel No: 01722 434697 E-Mail: karen.linaker@wiltshire.gov.uk