


APPENDIX 3



The lowest point to cross makes it the longest time on the actual road

The direct route to cross but an unsafe jump up /down on/off the bank

No visibility around the hedge at this height and depth

No visibility around the sign due to overgrown trees above the culvert

Crossing correctly by bike or horse means standing in the middle of the A342  
**TOTALLY UNACCEPTABLE**

West on A342

centre

East on A342

10 July 2021