Highways Major Maintenance 2014 - 2015 – Chippenham Area Board

Road	Location	Area Board	Recommended Treatment	Average Width (m)	Estimated Length (m)	Est Area of Site (m ²)
UC	Parklands, Hullavington	Chippenham	Resurfacing and footway reconstruction	5	150	750
U/C	Nettleton Loop.	Chippenham	Resurfacing	4	760	3,040
U/C	Ford to Biddestone.	Chippenham	Patching and Surface dressing	4	2,400	9,600
U/C	Chippenham A350 Dual Off slip to Plough Pub.	Chippenham	Resurfacing	7.2	510	3,672
U/C	Biddestone Weavern Ln.	Chippenham	Patching and Surface dressing	4	1,820	7,280
U/C	Chippenham Lords Mead.	Chippenham	Resurfacing	6	464	2,784
C181	Jacksoms Lane	Chippenham	Resurfacing	4.5	1,560	7,020
C367	Station Hill / Cocklebury	Chippenham	Resurfacing	9.5	380	3,610
C367	Station Hill / Cocklebury	Chippenham	7 Resurfacing	7.8	520	4,056
B4122	B4122 Heading southeast from Junction 17 M4	Chippenham	Resurfacing	<mark>6.1</mark>	<mark>200</mark>	<mark>1,220</mark>
B4122	B4122 Heading south from Junction 17 M4	Chippenham	Resurfacing	<mark>3.8</mark>	<mark>90</mark>	<mark>338</mark>
<mark>A420</mark>	A420 Bristol Road, Bumpers Farm Rbt, Chippenham	Chippenham	Resurfacing	<mark>7.2</mark>	<mark>210</mark>	<mark>1,512</mark>
B4122	B4122, Junction 17 M4	Chippenham	Resurfacing	<mark>9.4</mark>	<mark>260</mark>	<mark>2,444</mark>

Road	Location	Area Board	Recommended Treatment	Average Width (m)	Estimated Length (m)	Est Area of Site (m ²)
<mark>B4122</mark>	B4122, Junction 17 M5	Chippenham	Resurfacing	<mark>9.4</mark>	<mark>110</mark>	<mark>1,034</mark>
C86	C86, Yatton Road, Biddestone	Chippenham	Resurfacing	<mark>6.2</mark>	<mark>50</mark>	<mark>310</mark>
<mark>C86</mark>	C86 Biddestone Road, Biddestone	Chippenham	Resurfacing	<mark>5.7</mark>	<mark>80</mark>	<mark>456</mark>
<mark>B4039</mark>	B4039 Horsedown, near Littleton Drew	Chippenham	Resurfacing	<mark>6</mark>	<mark>180</mark>	<mark>1,080</mark>

* Sites highlighted in yellow involve skid resistance improvements.