



## Appendix A Examples of Voluntary activity on the rights of way network



**Beautiful Views and five locations all within the upper reaches of the Nadder Valley**





**Volunteers arriving**



**Rights of Way Officer Alex outlines his plans for the day**

**Initial Muster at Park Gate Farm**  
Installing 5 gates over a larger site than usual, plus adding a few steps and general tidying to improve access here and there as well as organising 11 volunteers and 4 council officers meant some serious logistical planning - and it worked beautifully!



**A well packed trailer!**







**Difficult access**



**Tight entrance**



**New access for pedestrian gate**



**New Gate 1  
FP DSTA14**

**Dismantling  
old stile**



**Digging gate foundations**



**Nearly deep enough?**



**Offering the gate to check depth of  
holes for the H bar frame**





Replaced the soil and barbed wire and job is completed!



Gate dropped in, concrete mix added to secure gate and posts



Walkers appear to test completed job! Great work – thank you!









**Final tamping down; replacing the soil, post barbed wire and old metal frame**



**A magnificent job!**





**Stile needs replacing**



**C.A.T. Safety Check**



**Cutting barbed wire back**



**Unloading supplies**



**Removing unsuitable stile**



**Posts took a time to lever out!**



**Digging footings for metal gate frame**



**Checking the depth and levels before 'fixing' the gate**





**Now ready to drop gate frame in**



**Mixing ballast with cement and squaring up the gate**



**Dropping in the concrete and tamping down firmly**



**Bracing the fence work and reinstating the barbed wire**



