

APPENDIX A

Sign No.	Location	Arm Direction	Destination	Issues
1	Queen Street (side of Guildhall)	North	Central Salt Lane College Street Bus Station Arts Centre Culver Street	Post locking mechanism is broken meaning signs can easily be rotated to point in wrong direction South arm missing Central (Car Park) is on the wrong destination arm
		North West	Shopmobility Market Place Toilets	Shopmobility finger is illegible
		South	Tourist Information Brown Street Culver Street	Sign post is in poor condition
2	Fish Row / Queen Street	North	Central Market Place Salt Lane College Street Bus Station Arts Centre Toilets Shopmobility	South arm missing and needs to be replaced Shopmobility and Millstream Coach Park fingers are slightly faded Sign is in poor condition
		South	Brown Street Culver Street Youth Hostel	
		West	Tourist Information Cathedral Museums Taxis Poultry Cross Toilets (Disabled) Millstream Coach Park	

Sign No.	Location	Arm Direction	Destination	Issues
3	Poultry Cross	East	Tourist Information Bus Station Salt Lane Brown Street Culver Street	Post locking mechanism is broken meaning signs can easily be rotated to point in wrong direction West arm missing Central (Car Park) finger is slightly faded Sign post is in poor condition
		South	New Street Toilets (Disabled) Taxis	
		West	Cathedral Museums City Hall / Playhouse Railway Station	
		North	Shopmobility	
		North East	Market Place Toilets	
		North West	Central Millstream Coach Park St Thomas's Church	
4	Cheese Market	North	Post Office	Post office finger slightly bent Toilets and Riverside Walk fingers quite faded Shopmobility finger slightly faded Sign post is in reasonable condition
		East	Tourist Information Cathedral Bus Station Market Place Toilets	
		South	Lush House St Thomas's Church	
		West	Central Railway Station City Hall / Playhouse Millstream Coach Park Riverside Walk Toilets (Disabled) Shopmobility	

Sign No.	Location	Arm Direction	Destination	Issues
5	St Thomas's Square	North	Tourist Information Market Place Library Toilets	Tourist Information, Millstream Coach Park and Riverside Walk fingers are slightly faded
		West	Central Millstream Coach Park Riverside Walk	
6	Catherine St / Milford Street	North	Tourist Information Market Place Bus Station Toilets	Locking system and finial are missing
		East	Youth Hostel Brown Street Culver Street Toilets (Disabled)	New Street fingers is illegible Cinema finger is slightly faded Taxi arm missing
		South	Cathedral Museums New Street	Sign post is in reasonable condition
		West	Cinema Taxis	
7	New Canal / Old George Mall	North	Tourist Information Market Place Bus Station Shopmobility	Tourist Information arm missing New Street finger slightly faded
		South	New Street Toilets (Disabled)	Sign post is in reasonable condition

Sign No.	Location	Arm Direction	Destination	Issues
8	Old George Mall	North	Tourist Information Market Place Bus Station Taxis Shopmobility	Cathedral finger slightly faded Sign post is in reasonable condition
		East	Toilets (Disabled) New Street Culver Street	
		West	Cathedral Museums	
9	High Street / New Street	North	Millstream Coach Park Central Tourist Information City Hall / Playhouse Shopmobility Market Place Toilets (Disabled)	Sign post is in good condition
		South	Cathedral Museums	
		West	Railway Station Riverside Walk Toilets Lush House	
10	Brown Street / Milford Street	East	Youth Hostel Culver Street	East and south arms need realigning
		South	Brown Street	
		West	City Centre Tourist Information Cathedral	

Sign No.	Location	Arm Direction	Destination	Issues
11	Old George Mall / High Street	North	Bus Station Market Place Tourist Information Railway Station City Hall / Central Playhouse Shopmobility Millstream Coach Park	East arm broken Millstream Coach Park and Riverside Walk fingers missing Sign is in good condition
		East	New Street Brown Street Culver Street Toilets (Disabled)	
		South	Cathedral Museums Crane Street Riverside Walk	
12	Silver St / Bridge St	North	Central Millstream Coach Park Riverside Walk St Thomas's Church Toilets Shopmobility	Shopmobility and Millstream Coach Park fingers are missing Market Place finger needs realigning. Fingerpost is leaning slightly Sign post is in reasonable condition
		East	Tourist Information Market Place	
		West	Railway Station City Hall / Playhouse	

Sign No.	Location	Arm Direction	Destination	Issues
13	Bridge St / Riverside Walk	North	Central Millstream Coach Park Toilets (Disabled)	Central Car Park finger is slightly faded Sign post is in good condition
		East	Tourist Information Market Place New Street St Thomas's Church Toilets	
		South	Cathedral Museums Riverside Walk Lush House Toilets	
		West	Railway Station City Hall / Playhouse	
14	Crane St / Crane Bridge Road	North	Central Millstream Coach Park City Hall / Playhouse	Sign needs cleaning Citizens Advice Bureau & City Hall Playhouse (West arm) need to be blacked out Sign post is in reasonable condition
		East	Market Place New Street Brown Street Culver Street Tourist Information Cathedral Museums Citizens Advice Bureau	
		West	Railway Station Lush House Toilets City Hall / Playhouse Riverside Walk	
15	Central Car Park (Wall Mounted)		Railway Station City Hall / Playhouse Fisherton Street	Sign is in good condition

Sign No.	Location	Arm Direction	Destination	Issues
16	Central Car Park (Wall Mounted)		Railway Station City Hall / Playhouse Fisherton Street	Sign is in good condition
17	Maltings / Central Car Park	South	City Hall / Playhouse	West arm is slightly bent and needs realigning Sign post is in reasonable condition
		West	Railway Station Fisherton Street	
		North	Central	
18	Summerlock Approach	South	Railway Station Fisherton Street	Sign is in good condition
		North	Central	
19	Summerlock Approach / Fisherton Street	North	Central	Sign is in good condition
		East	Playhouse / City Hall Cathedral City Centre Tourist Information	
		West	Railway Station	
20	Fisherton Street / South Western Road	East	City Centre Cathedral Tourist Information Playhouse / City Hall	East arm needs realigning Sign is in good condition
		West	Railway Station	
21	Railway Station	North	Cycle Parking	Sign is leaning significantly Cycle parking and Taxi arms missing Sign post is in poor condition.
		North East	City Centre Cathedral Tourist Information City Hall/Playhouse	
		West	Taxis	
22	Central Car Park	South East	Tourist Information Cathedral Market Place St Tomas's Square	Sign is to all intents is missing only City Hall / Playhouse & Fisherton Street are signed via a misaligned road sign.
		South	City Hall / Playhouse Fisherton Street Railway Station	

Sign No.	Location	Arm Direction	Destination	Issues
23	Malthouse Lane / Fisherton Street	North	Central City Hall / Playhouse	Cathedral and City Centre arms are slightly faded Sign post is in reasonable condition
		South East	City Centre Tourist Information Cathedral	
		North West	Railway Station	
24	Priory Square	North East	Central Toilets (Disabled)	Railway station arm is broken
		North West	Shopmobility	Toilets and Central arms are slightly faded
		South	Railway Station	Sign post is in good condition
		West	City Hall / Playhouse	
25	Riverside Walk / St Thomas's Square	North	Library Toilets (Disabled) Central Millstream Coach Park Riverside Walk Shopmobility	East finger is missing Central (Car Park) arm is slightly faded Sign post is in good condition
		East	St Thomas's Church Lush House New Street	
		South	Cathedral Museums Riverside Walk	



Sign No.	Location	Arm Direction	Destination	Issues
26	Riverside Walk / Market Walk	North	Millstream Coach Park Riverside Walk	Post locking mechanism is broken meaning signs can easily be rotated to point in wrong direction North arm missing Shopmobility finger missing Sign is leaning slightly Sign post is in poor condition
		East	Market Place Brown Street Culver Street Tourist Information Bus Station Library Post Office	
		South	Cathedral Museums St Thomas's Church Riverside Walk Lush House New Street	
		West	Central Railway Station City Hall / Playhouse Toilets (Disabled) Shopmobility	
27	Maltings / Priory Square	North	Central Toilets (Disabled)	Riverside Walk and Shopmobility fingers are slightly faded. Sign post is in good condition
		East	Tourist Information Cathedral Museums Bus Station Market Place New Street Millstream Coach Park Library Riverside Walk	
		South West	Shopmobility	
		West	City Hall / Playhouse Railway Station	

Sign No.	Location	Arm Direction	Destination	Issues
28	Maltings Car Deck / River Avon	North	Central Millstream Coach Park Toilets (Disabled)	South arm is missing. Toilets and Central (Car Park) are slightly faded
		South	Tourist Information City Centre Cathedral	Sign post is in good condition
29	Maltings Car Deck (North East)	North	Millstream Coach Park Toilets (Disabled)	South arm is slightly faded and been covered with stickers
		South	Tourist Information City Centre Cathedral	Sign post is in poor condition
30	Central Car Park / Avon Approach	East	Bus Station Arts Centre Post Office Millstream Coach Park Riverside Walk	East arm needs realigning Riverside Walk finger is slightly faded Sign is leaning slightly
		South	City Centre Cathedral Toilets (Disabled)	Sign post is in poor condition
31	Millstream Approach / Riverside Walk	North	Riverside Walk	Central (Car Park) and Riverside Walk fingers are missing Sign needs cleaning Sign post is in good condition
		South	Central City Centre Cathedral Millstream Coach Park Toilets	
32	Millstream Coach Park / Riverside Walk	North	Riverside Walk	Tourist Information finger is slightly faded Sign needs cleaning Sign post is in good condition
		South	City Centre Cathedral Riverside Walk Tourist Information	
		West	Toilets	

Sign No.	Location	Arm Direction	Destination	Issues
33	Avon Approach / Riverside Walk	North	Millstream Coach Park Toilets Riverside Walk	North arm is slightly faded Sign partially obscured by overhanging foliage Sign post is in reasonable condition
		East	Arts Centre Bus Station Post Office	
		South	Tourist Information Cathedral Market Place Library Riverside Walk	
		West	Central Toilets (Disabled)	
34	Millstream Coach Park (Wall Mounted)	East	City Centre Tourist Information Cathedral	Sign is in good condition
35	Milford Street / Guilder Lane	East	Youth Hostel	All arms missing Sign post is in good condition
		South	Culver Street Toilets (Disabled)	
		West	City Centre Tourist Information Cathedral	
36	Gigant Street / Brewery Lane	East	Culver Street	Culver Street and Cathedral fingers are slightly faded Sign post is in good condition
		West	City Centre Tourist Information Cathedral	
37	Brown Street / Brewery Lane	North	City Centre Tourist Information Cathedral	Culver Street finger is slightly faded Sign post is in good condition
		East	Culver Street	
38	Brown Street Car Park Walkway	South	Culver Street	West arms are slightly faded Sign partially obscured by overhanging foliage Sign post in reasonable condition
		West	City Centre Tourist Information Cathedral	

Sign No.	Location	Arm Direction	Destination	Issues
39	Catherine Street / Antelope Square	North	Tourist Information Market Place	Sign needs cleaning Sign post is in poor condition
		East	Brown Street Culver Street	
		West	Cathedral Museums New Street Toilets (Disabled)	
40	Fisherton Street Zebra Crossing	North West	Railway Station	Tourist Information finger is slightly faded Sign needs cleaning Sign post is in reasonable condition
		South East	City Hall / Playhouse City Centre Tourist Information Cathedral	
41	South Western Road / Mill Road	South	City Centre City Hall / Playhouse Tourist Information Cathedral	Sign is in good condition
		West	Railway Station	
42	Cathedral – North-East Corner	East	Malmesbury House St Anne's Gate	Sign is in reasonable condition
		South West	Cathedral Entrance Salisbury Museum Medieval Hall Refectory Restaurant	
		West	Mompesson House Military Museum City Centre	

Sign No.	Location	Arm Direction	Destination	Issues
43	Cathedral – North	North	City Centre Mompesson House	Sign is in good condition
		East	Malmesbury House St Anne's Gate	
		South	Cathedral Entrance Shop Refectory Restaurant	
		North West	Military Museum Salisbury Museum Medieval Hall	
44	Queen Street / Blue Boar Row	North	Arts Centre Bus Station	Sign finial is missing
		West	City Centre Cathedral Central Tourist Information	North arm needs realigning West arm needs to be split into two arms to provide better direction. Sign post is in good condition



Reproduced from the Ordnance Survey map with the permission of the Controller of Her Majesty's Stationary Office, Crown Copyright Reserved. Licence No. LA 76910

Salisbury Joint
Transportation
Team

A	FIRST ISSUE	PS 02/10/06	PS 02/10/06
Version	Amendment	Originated by and date	Checked by and date
		Approved by and date	



Client	Salisbury Joint Transportation Team		
Project	Salisbury City Centre Pedestrian Signage		
Drawing Title	Locations of Existing Pedestrian Fingerpost Signage		
Issuing Office	Salisbury	Draft	Scale Not To Scale
Telephone	01722 434671	Issue	✓
File Ref.	JTT/12.06.03	Drawing No.	SCPPFP0001
		Version	A