



KEY:

- BOUNDARY OF PERMISSION AS SHOWN
- - - BOUNDARY OF PERMISSION AS SHOWN
- EXISTING PROTECTOR BANS
- ▨ RESTORATION BANS (PHASE 1)
- ▧ RESTORATION BANS (PHASE 2 AND 4)
- ⊙ PHASE NUMBER
- PERIMETER MONITORING BOUNDARIES
- ▨ SUBSIDIARY WOODLAND CORSE
- SURROUNDING FIELDS AND WOODSTOCK

KEY: FOR NON-SITE RELATED INDICATIVE LOCATIONS

- SUBSIDIARY WOODLAND CORSE
- ▨ SURROUNDING FIELDS AND WOODSTOCK
- ⊙ PERIMETER MONITORING BOUNDARIES

NOTES:

1. THIS DRAWING IS DERIVED FROM OUR PERSONAL PLANNING SERVICES DRAWING NO. WQ/SP/01/001
2. PROTECTION TO THE PERIMETER TO BE IN ACCORDANCE WITH LOCAL AUTHORITY (L.A.) COMPANY REQUIREMENTS
3. EXISTING PERIMETER DERIVED FROM BRICKWORTH QUARRY COMPANY LIMITED DRAWING NO. 44/05/01/001. THESE COORDINATES MUST BE VERIFIED BY E.P.C.L. PRIOR TO ANY EXCAVATION OR CONSTRUCTION WORK.

APPROVED FOR THE COMPANY BY:
 CONTROLLED BY THE SURVEYING OFFICE,
 LONDON NO. 141 2344

		Client: CLEANSING SERVICE GROUP LTD	
Project: BRICKWORTH QUARRY PROGRESSIVE RESTORATION PLAN & SITE SURVEY		Date: MAY 2005	
Scale: 1:2000 @ A2	Drawn by: RMF	Checked by: MJ	Client No.:
Dwg No.: CSC/BWQ/PR/01		Date:	
www.rlong.co.uk Robert Long, 13 Empire Road, Lymington, Hampshire, SO40 7NE Tel: 01534 852424 Fax: 01534 852425 Email: info@rlong.co.uk			
ROBERT LONG CONSULTANCY LIMITED • Survey Management • Materials • Soil Value • Environment			
Revised:	Drawn by:	Approved by:	Date: