

Area Board Highways Defect Dashboard



Completed P1-4 Defects by Area Board:
02/04/2024 to 29/01/2025




Table 1

Area Board Highways Defect Dashboard



Potholes Last Month and This Month



Potholes Reported and Repaired since 1 Dec 2024 to 29 Jan 2025					
Area Board	Reported (This Month)	Reported (Last month)	Repaired (This Month)	Repaired (Last Month)	
Bradford-on-Avon	72	54	70	54	
Calne	50	30	49	28	
Chippenham and Villages	144	50	111	62	
Corsham	57	52	51	50	
Devizes	152	120	136	102	
Malmesbury	70	55	62	56	
Marlborough	72	84	63	79	
Melksham	41	67	40	66	
Pewsey	107	57	91	52	
Royal Wootton Bassett and Cricklade	139	85	129	91	
Salisbury	35	38	40	27	
South West Wiltshire	127	111	128	78	
Southern Wiltshire	87	110	108	55	
Stonehenge	42	32	28	23	
Tidworth	19	25	15	14	
Trowbridge	38	38	32	37	
Warminster	99	42	83	47	
Westbury	27	29	24	30	

Table 2

Area Board Highways Defect Dashboard

Supporting Notes:

1. Table 1 breaks down defects by response time as laid out in the Wiltshire Highways Safety Inspection manual. In addition to this there is a breakdown between Defect Types - Potholes are typically small surface defects to tarmac surfaces, masonry type defects are those such as damaged kerbs, flagstones and slabs. https://www.wiltshire.gov.uk/media/12952/Wiltshire-Council-Highways-Safety-Inspection-Manual/default/Wiltshire_Highways_Safety_Inspection_Manual_5tf2s8ptwasn.odt?m=1710487628513
2. Table 1 contains data for the financial year running from 1 April 2024 until 29 January 2025.
3. Table 2 looks in more detail at potholes specifically and compares reports received against repairs made over December 2024 and January 2025.
4. When looking at numbers reported it is possible that there can be multiple reports for a single defect repair hence the figure for repairs will be lower than the overall reported figure.