Whiteparish Rights of Way Survey January 2012

The survey was undertaken in early January. The weather had been wet before the survey started, so this was taken into account when assessing the condition of the surface of each right of way. The main issues from 2011 have been included for information.

There are 3 footpaths that were impassable when inspected, these being 1, 2 and 28, and bridleway 39. I have not included those rights of way with, for example, trees fallen across the path but with a way available round the obstruction. A number of paths are restricted by growth of brambles etc. particularly at stiles. This is surprising at this time of year and it would be sensible to do something about this before the growing season. There is a requirement for additional waymarking in many locations in the Parish, and many of the stiles are in a state of disrepair with broken or missing treads, steps missing altogether or unstable posts.

Footpaths close to the village are used by people of a wide age range and often just to get about the village. I think existing stiles should be replaced by gates as soon as possible as a matter of Parish Council policy, as stiles are a barrier to some. For example the stiles on footpaths 4 and 8 should be replaced with gates.

| ROW | Map lo | cation | length | Description |
|-----|--------|---------------------|-----------------------------------|---|
| 1 | (B2) | | 3.0km | footpath |
| | 2011 | | row at Welstea | |
| | | | | ermissive path near Whelpley Farm, footpath sign removed. |
| | 2012 | | | o overgrown hedge and brambles at Welsteads corner. |
| | | | | npost heap for grass cuttings, not possible to avoid. |
| | | Unable t | o find the foot | tpath at Whelpley Farm, needs waymarkers. |
| 2 | (B3) | | 2.7km | footpath |
| | 2011 | Impassa Path not | ble on the prop restored after | per route due to permanent electric fencing near junction with path 11. agricultural operations near Moor Farm. |
| | 2012 | | | cing erected near junction with path 11, had to pull out fencing to get |
| | | | | e across stile posts. |
| | | Conditio | n of path poor | r near Moor Farm, very deep mud. Pathway used to feed cattle. |
| 3 | (C3) | | 0.4km | footpath |
| | 2012 | No signi | ficant issues. | |
| 4 | (C3) | | 1.7km | footpath |
| | 2012 | Broken | stile at caravan | n park means waymarkers are on the ground. |
| 5 | (C4) | | 1.1km | footpath |
| | 2011 | | | e useful near Chadwell Farm. |
| | | | | undary, impassable in wet conditions without wellies. |
| | 2012 | New bri | dge constructed | ed by Wiltshire Council over stream. |
| | | Still no v | waymarkers. | |
| 6 | (D3) | | 1.3km | footpath |
| | 2011 | | | g path in garden of Lion Cottage. |
| | | | | ction with path 4, not able to follow path, no easy way round. |
| | | | stile near Comi | |
| | | | | n with path 10 would be useful. |
| | 2012 | | no waymarkin | |
| | | | er step broken | |
| | | Flooding | g issue not yet | addressed. |
| 7 | (D3) | | 0.9km | footpath |
| | 2012 | No signi | ficant issues. | |
| 8 | (D3) | | 0.7km | footpath |
| | 2012 | Stile nea | r to the west o | of Common Road needs attention. |
| 10 | (D3) | | 1.7km | footpath |
| | 2011 | | | on with path 6, post and rail section but no proper stile. (a) |
| | 2012 | | | e near junction with path 6. (a) |
| | | | | near junction with path 7. (a) |
| | | No wayı | narker though | gateway into farmyard/garden. |
| 11 | (C3) | | 1.1km | footpath |
| | | | | |

| | 2011 2012 | Path covered in heaps of rotting horse manure near junction with path 2. Still problems with heaps of horse manure dumped on right of way. Fencing alongside path angled into path severely restricting access over horse manure. Electric fencing across right of way. Line of right of way appears to have been moved. |
|----|-------------------------------------|--|
| 12 | (B3) 2011 | 1.8km footpath Way marker near Moor Farm fixed to post laying on ground. Clearance of vegetation around stile at Moor Road end. |
| | 2012 | Way marker post still on the ground. No clearance of stile. 2 trees blocking path near back of quarry. |
| 13 | (C4) 2011 2012 | 0.9km footpath Electric fence at Holmere Cottage severely restricting width of path for some distance. Electric fence now less of a problem as hedge has been cut back. |
| 16 | (A3) | 3.4km footpath |
| | 20112012 | West and south of Pepperbox Quarry would benefit from clearance work to bring the path back to width, and removal of signs for deep pit etc. Signage clutter still to be removed |
| 17 | (A2) 2012 | 0.5km footpath Barbed wire on side of stile at junction with footpath 11. |
| 20 | (D1) | 2.6km footpath |
| | 2011 2012 | Does not follow the line of the definitive map. Lack of waymarking along route. Electric fence across footpath near Dean mast. Waymarkers near Dean mast - secured to post lying on the ground. Land ploughed up to hedge on line of path. |
| 21 | (E1) 2011 2012 | 3.9km footpath Unable to follow line of path on last section near Parish boundary due to undergrowth. Waymarker damaged on stile at junction with footpath 23. |
| | | Unable to follow line of path on last section near Parish boundary due to undergrowth. no waymarkers though Gatmore Copse. |
| 22 | (D2) 2011 | 1.2km bridleway/footpath Poor state of ground towards Miles Lane and raised water main cover in bridleway. Broken stile in Cowesfield Park. |
| | 2012 | Water main cover not now evident due to muddy conditions. Electric fence across footpath near Miles Lane. Stile in dangerous condition in Cowesfield Park. Electric fence across footpath next to stile in Cowesfield Park. Broken stile near farmhouse. Sign on stile at end of path saying "beware of the bull". |
| 23 | (D2) 2011 | 1.7km footpath First section of path alongside Miles Lane is not visible. Broken stiles each side of Miles Lane. |
| | 2012 | No change since 2011. |
| 24 | (E2) 2011 | 2.5km footpath Signage error near junction with path 22. Ploughed field near Miles Lane, the path has not been restored. Poor going near Rowdens Farm, looks like field used to over winter cattle. |
| | 2012 | Broken stile at junction with path 38. Signage error still evident near junction with path 22. Poor going near Rowdens Farm, looks like field used to over winter cattle. Broken stile at junction with path 38. |
| 25 | (E2) 2011 | 0.7km footpath Deep mud in gateway half way along path. |
| | | No mud in gateway this year, but gate unopenable effectively blocking the footpath. |

| | (Ta) | |
|-----------------------------|--------------|---|
| 26 | (E3) 2011 | 0.5km footpath Broken stile half way along the path. |
| | 2011 | Style now repaired by Wiltshire Council. |
| | 2012 | Overgrown hedging and damaged iron and barbed wire fencing restricting access. |
| 27 | (E3) | 0.7km footpath |
| | 2011 | No evidence of path on first section after a few metres due to undergrowth. |
| | 2012 | Waymarking now in evidence, but incorrect marking near junction with WP36 |
| 28 | (F3) | 0.7km footpath |
| | 2011 | Track impassable near Morris Holt Farm, deep mud due to muck cart operations. |
| | 2012 | Still impassable, track used as run-off for farmyard slurry, no alternative way round. Signpost from A27 needs cleaning and repair, dominated by private road sign. |
| | | |
| 30 | (C2) | 2.7km bridleway |
| | 2012 | Difficult for walkers because of patches of deep mud. |
| | | Gate onto Grimstead 14 too narrow (ref: section 145 of the Highways Act 1980) Impossible to open or keep open gate from horseback. |
| | | When surveyed, fallen trees due to previous storm blocking right of way for horses. |
| | | |
| 31 | (C3) | 0.8km footpath (Clay St./ Hop Gardens) |
| | 2012 | No significant issues. |
| 32 | (D1) | 1.3km bridleway |
| | 2011 | Not visible on the ground, existing track being used. |
| | 2012 | No change from 2011. |
| 33 | (C1) | 1.2km bridleway |
| | 2012 | No significant issues. |
| 34 | (A4) | 0.2km footpath |
| | 2011 | Path in poor state and ill defined when it goes into Langley Wood on Redlynch 9. |
| | 2012 | |
| 35 | (E3) | 0.3km footpath |
| | 2011 | Path much narrower than the 3m specified for this path. |
| | 2012 | Junction with WP36 and WP27 incorrect. |
| 36 | (E3) | 1.1km footpath |
| | 2011 | Path much narrower than the 3m specified for this path. |
| | 2012 | Junction with WP36 and WP27 incorrect path not on the line of the footpath. |
| 37 | (E3) | 0.4km footpath |
| | 2011 | No significant issues. |
| 38 | (F2) | 1.2km footpath |
| | 2011 | Waymarkers would help define the route across the open field. |
| | 2012 | No waymarkers, difficult to find the route though the Gatmore Copse. |
| 39 | | 2.5km bridleway |
| 39 | (E2) | • |
| 39 | (E2) 2011 | Bridleway above Upper Cowesfield Farm incorrectly marked. |
| 39 | | Bridleway above Upper Cowesfield Farm incorrectly marked. Gate on waymarked route too narrow at 1.2m (ref: section 145 of the Highways Act 1980) |
| 39 | 2011 | Bridleway above Upper Cowesfield Farm incorrectly marked. Gate on waymarked route too narrow at 1.2m (ref: section 145 of the Highways Act 1980) blocked by fallen trees towards the Bunny Land end. |
| 39 | 2011 | Gate on waymarked route too narrow at 1.2m (ref: section 145 of the Highways Act 1980) |
| 39 40 | 2011 | Gate on waymarked route too narrow at 1.2m (ref: section 145 of the Highways Act 1980) blocked by fallen trees towards the Bunny Land end. |

There are 2 other short public paths not on the definitive map; these are the path from Green Close to Ashmore Close and from Green Close to the Housing Association access road.

(a) Does the new fence across the path have the approval that is required from the Highways Authority? ref: Highways Act 1980 section 147. This also applies to a number of other electric fences that appear to be permanent, for example on paths 17 and 22.